



**BUREAU  
VERITAS**

# FACILITY CONDITION ASSESSMENT

*prepared for*

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4000  
Rockville, MD 20850



Brooke Grove Elementary School  
2700 Spartan Road  
Olney, MD 20832

**PREPARED BY:**

*Bureau Veritas*  
6021 University Boulevard, Suite 200  
Ellicott City, MD 21043  
800.733.0660  
[www.bvna.com](http://www.bvna.com)

**BV CONTACT:**

*Bill Champion*  
Senior Program Manager  
443.622.5067  
[Bill.Champion@bureauveritas.com](mailto:Bill.Champion@bureauveritas.com)

**BV PROJECT #:**

*172559.25R000-012.354*

**DATE OF REPORT:**

*May 1, 2026*

**ON SITE DATE:**

*January 17, 2026*

**Bureau Veritas**



### Building: Systems Summary

<b>Address</b>	2700 Spartan Road; Olney, MD	
<b>GPS Coordinates</b>	39.1569484, -77.0501011	
<b>Constructed/Renovated</b>	1990	
<b>Building Area</b>	73,080 SF	
<b>Number of Stories</b>	2 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Structure</b>	Masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system	Good
<b>Façade</b>	Primary Wall Finish: Brick Windows: Aluminum	Fair
<b>Roof</b>	Primary: Flat construction with modified bituminous finish Secondary: Hip with standing seam metal	Fair
<b>Interiors</b>	Walls: Painted gypsum board, ceramic tile, and painted CMU Floors: Carpet, VCT, ceramic tile, quarry tile, wood strip, terrazzo and coated concrete Ceilings: Painted gypsum board, ACT and Unfinished/exposed	Fair
<b>Elevators</b>	Passenger: 1 hydraulic car serving all floors	Good
<b>Plumbing</b>	Distribution: Copper supply and PVC waste & venting Hot Water: Gas water heater with integral tank Fixtures: Toilets, urinals, and sinks in all restrooms	Fair

## Building: Systems Summary

<b>HVAC</b>	Central System: Boilers and chiller feeding fan coil units Non-Central System: Packaged units, split systems Supplemental components: Ductless split systems and suspended unit heaters	Fair
<b>Fire Suppression</b>	Wet-pipe sprinkler system and fire extinguishers	Fair
<b>Electrical</b>	Source & Distribution: Main switchboard panel with copper wiring Interior Lighting: Linear fluorescent and CFL Exterior Building-Mounted Lighting: HPS and halogen Emergency Power: Natural gas generator with automatic transfer switch	Fair
<b>Fire Alarm</b>	Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
<b>Equipment/Special</b>	Commercial kitchen equipment	Fair

## Site Information

<b>Site Area</b>	10.96 acres (estimated)	
<b>Parking Spaces</b>	80 total spaces all in open lots; 2 of which are accessible	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Site Pavement</b>	Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs	Fair
<b>Site Development</b>	Building-mounted and Property entrance signage; chain link fencing. Playgrounds and sports fields and courts Limited Park benches, picnic tables, trash receptacles	Fair
<b>Landscaping &amp; Topography</b>	Significant landscaping features including lawns, trees, bushes, and planters Irrigation not present Low to moderate site slopes throughout	Fair
<b>Utilities</b>	Municipal water and sewer Local utility-provided electric and natural gas	Fair
<b>Site Lighting</b>	Pole-mounted: HPS and metal halide	Fair

## Historical Summary

The elementary school campus was originally constructed in 1990 and has not undergone any significant renovations throughout its history. Minor modernization projects have been implemented, including updates to the interior finishes of the main office suite in 2020. Since the original construction, the facility has maintained its core infrastructure, with only incremental, non-structural improvements undertaken.

## Architectural

Due to good maintenance practices, the elementary school appears structurally sound, with no structural-related deficiencies reported or observed. The exterior finishes comprise brick and aluminum windows, complemented by a built-up roof. Though staff reported it was replaced in 2016. Reports of leaks in localized areas were noted, potentially originating from the roof or other sources, prompting the inclusion of a comprehensive study to investigate the issue. Additionally, potential mold growth was reported in rooms 18 and 11H, with a study included for further evaluation. Interior finishes are generally in fair condition, though the VCT flooring in the cafeteria exhibits several patches and widespread wear, with recommended replacement. Typical roof, interior, and exterior finish replacements are budgeted and anticipated based on useful life and normal wear.

## Mechanical, Electrical, Plumbing and Fire (MEPF)

The MEPF systems and components appear to have been adequately maintained. Most HVAC equipment was reportedly replaced in 2016, comprising boilers, chiller, split systems and packaged units for heating and cooling. Boiler #1 exhibited water leaking from its bottom, and pump #4 has been out of service awaiting repairs. Reports of leaking pipes in the ceiling between the first and second floor in room 9 have prompted the inclusion of a study to mitigate the issue. The plumbing system is reportedly adequate, with equipment and fixtures updated as needed, and hot water supplied by a gas water heater replaced in 2020. Electrical systems provide generally adequate service, though potentially undersized or outdated, as more than one large piece of equipment cannot be used simultaneously. Upgrades to the electrical system are recommended. Emergency power is supplied by an exterior generator and automatic transfer switch, replaced in 2021. A facility-wide fire suppression and fire alarm system adequately serves the site. Ongoing routine maintenance of MEPF equipment is recommended.

## Site

Site maintenance appeared to be adequate. The asphalt pavement and concrete sidewalk appeared to be in fair condition. It was reported that mulch from the playground surface was clogging the drain, causing a drainage issue. Replacement with pour-in-place rubber is recommended to mitigate the problem.

## Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

**The FCI Depleted Value of this school is 0.438899.**