FACILITY CONDITION ASSESSMENT



prepared for

Montgomery County Public Schools 45 West Gude Drive, Suite 4000 Rockville, MD 20850



Capt. James E. Daly Jr. Elementary School 20301 Brandermill Drive Germantown, MD 20876

PREPARED BY:

Bureau Veritas 6021 University Boulevard, Suite 200 Ellicott City, MD 21043 800.733.0660

www.bvna.com BV CONTACT:

Bill Champion Senior Program Manager 443.622.5067 Bill.Champion@bureauveritas.com

BV PROJECT #: 172559.25R000-033.354

DATE OF REPORT: August 14, 2025

ON SITE DATE: April 29, 2025

TABLE OF CONTENTS

| Executive Summary | 1 |
|--|-------------------|
| Property Overview and Assessment Details | |
| | |
| Facility Characteristic Survey | 3 |
| | |
| | |
| Key Findings | F |
| Plan Types | 🤇 |
| | |
| | |
| | |
| • | |
| | |
| | |
| | |
| Certification | |
| | |
| | ADA Accessibility |



1. Executive Summary

Property Overview and Assessment Details

| General Information | |
|-----------------------------------|--|
| Property Type | Elementary school campus |
| Number of Buildings | 1 |
| Main Address | 20301 Brandermill Drive, Germantown, MD 20876 |
| Site Developed | 1989 |
| Outside Occupants / Leased Spaces | None |
| Date(s) of Visit | April 29, 2025 |
| Management Point of Contact | Montgomery County Public Schools Mr. Greg Kellner Facilities Manager, Office of Facilities Management Direct 240.740.7746 Gregory Kellner@mcpsmd.org |
| On-site Point of Contact (POC) | Lisa Nia Laura |
| Assessment & Report Prepared By | Alexander Rockafellow |
| Reviewed By | Adrian Reth, <i>Technical Report Reviewer for</i> , Bill Champion Program Manager 443.622.5067 Bill.Champion@bureauveritas.com |
| AssetCalc Link | Full dataset for this assessment can be found at: https://www.assetcalc.net/ |



Campus Findings and Deficiencies

Historical Summary

The building was constructed in 1989. The building is currently used as an elementary school.

Architectural

The school building features a diverse exterior cladding of brick, terra cotta, and concrete. The roof primarily consists of modified bituminous material, with some sections covered in asphalt shingles. Windows are aluminum-framed, and exterior doors are painted steel.

Interior finishes show a mix of materials typical of educational facilities. Flooring is predominantly vinyl composition tile (VCT), with areas of carpet, ceramic tile, wood strip, and painted concrete. Walls are mainly painted gypsum board and concrete masonry units (CMU), with ceramic tile in some areas. Ceilings alternate between acoustical ceiling tiles (ACT), painted gypsum board, and exposed metal. Interior doors are a combination of wood and steel.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The school's HVAC system combines heating and cooling elements. Heating is provided by three gas-fired boilers that feed air handling units throughout the building. Cooling is primarily supplied by a large roof-mounted chiller. The HVAC system is supplemented by RTUs and ductless split systems.

The electrical system is centered around a large switchboard, with smaller panels and transformers distributed throughout the building. Emergency power is provided by a natural gas generator, ensuring critical systems remain operational during outages.

Plumbing needs are met by a gas-fired water heater for hot water supply. Plumbing fixtures have been updated and replaced as needed over time, indicating ongoing maintenance.

Fire safety is addressed by an addressable fire alarm system installed throughout the building, providing comprehensive coverage for early detection and warning.

Site

The school occupies a 10-acre site, featuring typical amenities for an elementary school campus. The property includes asphalt parking areas and concrete sidewalks. The parking lots are in poor overall condition, with potholes and cracks throughout sections. The campus includes playgrounds and sports courts. Site lighting is provided by pole-mounted and building-mounted fixtures.



Facility Characteristic Survey

The facility characteristics of school and associated buildings are shown below.

Indoor air quality, including temperature and relative humidity level are monitored centrally. Most instructional spaces are equipped with IAQ sensors. Each general and specialty classroom has a heating, ventilation, and air conditioning (HVAC) system capable of maintaining a temperature between 68°F and 75°F and a relative humidity between 30% and 60% at full occupancy. Each general, science, and fine-arts classroom had an HVAC system that continuously moves air and is capable of maintaining a carbon dioxide level of not more than 1,200 parts per million. The temperature, relative humidity and air quality were measured at a work surface in the approximate center of the classroom.

The acoustics with the exception of physical-education spaces, each general and specialty classroom are maintainable at a sustained background sound level of less than 55 decibels. The sound levels were measured at a work surface in the approximate center of the classroom.

Each general and specialty classroom had a lighting system capable of maintaining at least 50 foot-candles of well-distributed light. The school has appropriate task lighting in specialty classrooms where enhanced visibility is required. The light levels measured at a work surface located in the approximate center of the classroom, between clean light fixtures. The school makes efficient use of natural light for students, teachers, and energy conversation.

Classroom spaces, including those for physical education, were sufficient for educational programs that are appropriate for the class-level needs. With the exception of physical-education spaces, each general and specialty classroom contained a work surface and seat for each student in the classroom. The work surface and seat were appropriate for the normal activity of the class conducted in the room.

Each general and specialty classroom had an erasable surface and a surface suitable for projection purposes, appropriate for group classroom instruction, and a display surface.

Each general and specialty classroom had storage for classroom materials or access to conveniently located storage.

With the exception of physical-education spaces and music-education spaces, each general and specialty classroom had a work surface and seat for the teacher and for any aide assigned to the classroom. The classroom had secure storage for student records that is located in the classroom or is conveniently accessible to the classroom.

The school was constructed with sustainable design practices. The schools use durable, timeless, low-maintenance exterior materials. The school's materials (particularly shell) should withstand time as well as potential impacts related to structural, site and climate changes.

The school is functionally equitable. All students in this school have access to safe, well-maintained, and appropriately equipped learning environments as students in other MCPS schools.



Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values. A School Facility with full estimated life of all systems (a brand new school) would have a 0 FCI. The FCIs cannot exceed 1.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

The FCI Depleted Value of this school is 0.543057.



Immediate Needs

| Facility/Building | Total Items | Total Cost |
|--|-------------|------------|
| Capt. James E. Daly Jr. Elementary School / Main Building | 3 | \$32,600 |
| Capt. James E. Daly Jr. Elementary School / Site | 2 | \$57,000 |
| Total | 5 | \$89,600 |

Main Building

| <u>ID</u> | <u>Location</u> <u>Description</u> | <u>UF Code</u> | <u>Description</u> | <u>Condition</u> | <u>Plan Type</u> | <u>Cost</u> |
|-----------------|---------------------------------------|----------------|--|------------------|-----------------------|-------------|
| 9318681 | Boiler Room | D3050 | Pump, Distribution, HVAC Heating Water, Replace | Failed | Performance/Integrity | \$5,100 |
| 9377020 | Throughout | Y1090 | ADA Miscellaneous, Level III Study, Includes Measurements, Evaluate/Report | NA | Accessibility | \$7,500 |
| 9377022 | Throughout | Y1090 | ADA Miscellaneous, Lump Sum Budget, Allowance, Upgrade | NA | Accessibility | \$20,000 |
| Total (3 items) | | | | | | \$32,600 |

Site

| <u>ID</u> | <u>Location</u> <u>Description</u> | UF Code | <u>Description</u> | <u>Condition</u> | <u>Plan Type</u> | <u>Cost</u> |
|-----------------|---------------------------------------|---------|---|------------------|-----------------------|-------------|
| 9306783 | Site Parking Areas | G2020 | Parking Lots, Pavement, Asphalt, Cut & Patch | Failed | Performance/Integrity | \$55,000 |
| 9377007 | Parking Lot | Y1010 | ADA Parking, Designated Stall, Pavement Markings & Signage, Install | NA | Accessibility | \$2,000 |
| Total (2 items) | | | | | | \$57,000 |



Key Findings



Secondary Transformer in Poor Condition.

Dry, Stepdown Main Building Capt. James E. Daly Jr. Elementary School Electrical Shed

Uniformat Code: D5020

Recommendation: Replace in 2027

Priority Score: 87.7

Plan Type:

Performance/Integrity

Cost Estimate: \$25,000

\$\$\$\$

Rusted electrical unit. Equipment is located in a shed that's possibly subjected to outside elements. - AssetCALC ID: 9307001



Pump in Failed Condition.

Distribution, HVAC Heating Water Main Building Capt. James E. Daly Jr. Elementary School Boiler Room

Uniformat Code: D3050

Recommendation: Replace in 2025

Priority Score: **85.9**

Plan Type:

Performance/Integrity

Cost Estimate: \$5,100

\$\$\$\$

Pump is leaking - AssetCALC ID: 9318681



Parking Lots in Failed Condition.

Pavement, Asphalt Site Capt. James E. Daly Jr. Elementary School Site Parking Areas

Uniformat Code: G2020

Recommendation: Cut & Patch in 2025

Priority Score: 84.9

Plan Type:

Performance/Integrity

Cost Estimate: \$55,000

\$\$\$\$

Large holes and loose asphalt throughout certain sections of the parking lot - AssetCALC ID: 9306783



Parking Lots in Poor Condition.

Pavement, Asphalt Site Capt. James E. Daly Jr. Elementary School Site Parking Areas

Uniformat Code: G2020

Recommendation: Mill & Overlay in 2027

Priority Score: 84.7

Plan Type:

Performance/Integrity

Cost Estimate: \$63,700

\$\$\$\$

Several large cracks throughout the parking lot. - AssetCALC ID: 9306785





Ancillary Building in Poor Condition.

Wood-Framed or CMU, Basic/Minimal Main Building Capt. James E. Daly Jr. Elementary School Building Exterior

Uniformat Code: F1020

Recommendation: Replace in 2026

Priority Score: 81.8

Plan Type:

Performance/Integrity

Cost Estimate: \$12,000

\$\$\$\$

Dry rotted wood throughout structure. - AssetCALC ID: 9307000



Distribution Panel in Poor Condition.

120/208 V Main Building Capt. James E. Daly Jr. Elementary School Electrical Shed

Uniformat Code: D5020

Recommendation: Replace in 2027

Priority Score: 81.7

Plan Type:

Performance/Integrity

Cost Estimate: \$7,000

\$\$\$\$

Rusted electrical unit. Equipment is located in a shed that's possibly subjected to outside elements. - AssetCALC ID: 9307004



Site Lighting in Poor Condition.

Wall Pack or Walkway Ceiling/Pole-Mounted, any type w/ LED, Higher-Lumen Site Capt. James E. Daly Jr. Elementary School Site General

Uniformat Code: G4050

Recommendation: Replace in 2027

Priority Score: 81.7

Plan Type:

Performance/Integrity

Cost Estimate: \$8,800

\$\$\$\$

Light lens cover is faded - AssetCALC ID: 9306789



Signage in Poor Condition.

Property, Monument Site Capt. James E. Daly Jr. Elementary School Site General

Uniformat Code: G2060

Recommendation: Replace/Install in 2027

Priority Score: 81.7

Plan Type:

Performance/Integrity

Cost Estimate: \$3,000

\$\$\$\$

Hazey outer cover - AssetCALC ID: 9306780





ADA Parking

Designated Stall, Pavement Markings & Signage
Site Capt. James E. Daly Jr. Elementary School Parking Lot

Uniformat Code: Y1010

Recommendation: Install in 2025

Priority Score: 63.9

Plan Type: Accessibility

Cost Estimate: \$2,000

\$\$\$\$

Lacking accessible van parking and aisle - AssetCALC ID: 9377007



ADA Miscellaneous

Lump Sum Budget, Allowance Main Building Capt. James E. Daly Jr. Elementary School Throughout

Uniformat Code: Y1090

Recommendation: Upgrade in 2025

Priority Score: 63.9

Plan Type: Accessibility

Cost Estimate: \$20,000

\$\$\$\$

Ramps, door handles, elevator signage, and restrooms do not appear to be compliant - AssetCALC ID: 9377022



ADA Miscellaneous

Level III Study, Includes Measurements Main Building Capt. James E. Daly Jr. Elementary School Throughout

Uniformat Code: Y1090

Recommendation: Evaluate/Report in 2025

Priority Score: 63.9

Plan Type: Accessibility

Cost Estimate: \$7,500

\$\$\$\$


A detailed follow-up accessibility study is included as a recommendation because potential moderate to major issues were observed at the subject site. - AssetCALC ID: 9377020



Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the "why" part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the "best" fit, typically the one with the greatest significance and highest on the list below.

| Plan Type Descriptions & Distribution | | | | | |
|---------------------------------------|---|---|--|--|--|
| Safety | • | An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. | | | |
| Performance/Integrity | | Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability. | | | |
| Accessibility | | Does not meet ADA, UFAS, and/or other accessibility requirements. | | | |
| Environmental | | Improvements to air or water quality, including removal of hazardous materials from the building or site. | | | |
| Retrofit/Adaptation | | Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs. | | | |
| Aged But Functional | | Any component or system that has aged past its industry-average expected useful life (EUL) but is not currently deficient or problematic. | | | |
| Lifecycle/Renewal | | Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted. | | | |



10-YEAR TOTAL: \$5,619,100



2. Elementary School Building





| Building or Bldg Cluste | er 1: Systems Summary | |
|-------------------------|---|-----------|
| Address | 20301 Brandermill Drive, Gaithersburg, MD 20876 | |
| GPS Coordinates | 39.1894072, -77.2329397 | |
| Constructed/Renovated | 1989 | |
| Building Area | 78,386 SF | |
| Number of Stories | 2 above grade with no below-grade basement levels | |
| System | Description | Condition |
| Structure | Steel frame with concrete-topped metal decks over concrete pad column footings | Fair |
| Façade | Primary Wall Finish: Brick Secondary Wall Finish: Terracotta Windows: Aluminum | Fair |
| Roof | Primary: Flat construction with modified bituminous finish Secondary: Hip construction with asphalt shingles | Fair |
| Interiors | Walls: Painted gypsum board, painted CMU, fabric, quarry tile, ceramic tile Floors: Carpet, VCT, faux wood plank, ceramic tile, quarry tile, wood strip, coated concrete Ceilings: Painted gypsum board and ACT, Unfinished/exposed | Fair |
| Elevators | Passenger: 1 hydraulic car serving all 2 floors | Fair |



| Plumbing | Distribution: Copper supply and cast-iron waste & venting | Fair |
|--------------------|---|-----------|
| i idilibilig | Hot Water: Gas water heaters with integral tanks | ı alı |
| | Fixtures: Toilets, urinals, and sinks in all restrooms | |
| | Tixtures. Tollets, utiliais, and sinks in all restrooms | |
| HVAC | Central System: Boilers, chiller, air handlers feeding VAV terminal units | Fair |
| | Non-Central System: Packaged units | |
| | Supplemental components: Ductless split-systems, suspended | |
| | unit heaters | |
| Fire Suppression | Fire extinguishers only | Fair |
| Electrical | Source & Distribution: Main switchboard with copper wiring | Fair |
| | Interior Lighting: LED, linear fluorescent | |
| | Exterior Building-Mounted Lighting: LED, HPS | |
| | Emergency Power: Natural gas generator with automatic transfer | |
| | switch | |
| Fire Alarm | Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs | Fair |
| | Strobes, pair stations, back-up emergency lights, and exit signs | |
| Equipment/Special | Commercial kitchen equipment | Fair |
| Accessibility | Presently it does not appear an accessibility study is needed for this See the appendix for associated photos and additional information. | building. |
| | | |
| Additional Studies | No additional studies are currently recommended for the building. | |
| Areas Observed | The interior spaces were observed to gain a clear understanding of t | |
| | facility's overall condition. Other areas accessed and assessed inclu exterior equipment and assets directly serving the buildings, the exterior the facility, and the roofs. | |
| Key Spaces Not | All key areas of the facility were accessible and observed. | |



The table below shows the anticipated costs by trade or building system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|------------------------------------|-----------|---------------------------|-----------------------|-----------------------|----------------------------|--------------|
| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
| Facade | - | - | \$53,000 | - | \$1,077,200 | \$1,130,200 |
| Roofing | - | - | - | \$478,400 | - | \$478,400 |
| Interiors | - | - | \$1,179,500 | \$20,200 | \$1,804,600 | \$3,004,300 |
| Conveying | - | - | \$78,000 | - | \$16,300 | \$94,200 |
| Plumbing | - | - | \$32,000 | \$579,100 | \$102,800 | \$714,000 |
| HVAC | \$5,100 | - | \$269,800 | \$531,300 | \$1,137,000 | \$1,943,200 |
| Fire Protection | - | - | - | - | \$130,700 | \$130,700 |
| Electrical | - | \$33,900 | \$504,800 | \$575,400 | \$410,100 | \$1,524,200 |
| Fire Alarm & Electronic Systems | - | - | \$290,000 | \$210,700 | \$228,600 | \$729,300 |
| Equipment & Furnishings | - | - | \$145,300 | \$265,100 | \$115,000 | \$525,400 |
| Special Construction & Demo | - | \$12,400 | - | - | - | \$12,400 |
| Accessibility | \$27,500 | - | - | - | - | \$27,500 |
| TOTALS (3% inflation) | \$32,600 | \$46,300 | \$2,552,400 | \$2,660,100 | \$5,022,100 | \$10,313,500 |

^{*}Totals have been rounded to the nearest \$100. The darker the shading, the higher the cost.



3. Site Summary





| Site Information | | |
|--------------------------|---|-----------|
| Site Area | 10 acres (estimated) | |
| Parking Spaces | 91 total spaces all in open lots; 4 of which are accessible | |
| System | Description | Condition |
| Site Pavement | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs | Fair |
| Site Development | Building-mounted signage; chain link fencing Playgrounds and sports fields and courts Heavily furnished with park benches, picnic tables, trash receptacles | Fair |
| Landscaping & Topography | Significant landscaping features including lawns, trees, bushes, and planters Irrigation not present Low to moderate site slopes throughout | Fair |
| Utilities | Municipal water and sewer Local utility-provided electric and natural gas | Fair |
| Site Lighting | Pole-mounted: LED | Fair |
| Ancillary Structures | Prefabricated modular buildings | Fair |



| Site Information | |
|---------------------------------|---|
| Site Accessibility | Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information. |
| Site Additional Studies | No additional studies are currently recommended for the exterior site areas. |
| Site Areas Observed | The exterior areas within the property boundaries were observed to gain a clear understanding of the site's overall condition. |
| Site Key Spaces Not Observed | All key areas of the exterior site were accessible and observed. |

The table below shows the anticipated costs by trade or site system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|-----------------------------|-----------|------------------------|-----------------------|-----------------------|-------------------------|-------------|
| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
| Special Construction & Demo | - | - | \$6,000 | - | \$537,800 | \$543,900 |
| Site Development | - | \$6,600 | \$21,600 | \$48,500 | \$243,200 | \$319,900 |
| Site Pavement | \$55,000 | \$81,000 | Ξ | \$15,600 | \$159,800 | \$311,400 |
| Site Utilities | - | \$9,300 | - | \$82,000 | - | \$91,300 |
| Accessibility | \$2,000 | - | - | - | - | \$2,000 |
| TOTALS (3% inflation) | \$57,000 | \$97,000 | \$27,600 | \$146,100 | \$940,900 | \$1,268,600 |

^{*}Totals have been rounded to the nearest \$100. The darker the shading, the higher the cost.



4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of "areas of public accommodations" and "public facilities" on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

- 1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
- 2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
- 3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any "none" boxes checked or reference to "no issues" identified, that alone does not guarantee full compliance



The following table summarizes the accessibility conditions of the general site and each significant building or building group included in this report:

| Accessibility Summary | | | | |
|-----------------------|--------------------------|--------------------------|------------------------------------|--|
| Facility | Year Built/ Renovated | Prior Study Provided? | Major/Moderate Issues Observed? | |
| General Site | 1989 | No | Yes | |
| Building | 1989 | No | Yes | |

A detailed follow-up accessibility study is included as a recommendation because potential moderate to major issues were observed at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.



5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

| Condition Ratings | |
|-------------------|---|
| Excellent | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Good | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Fair | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life. |
| Poor | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| Failed | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required. |
| Not Applicable | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present. |



Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available
 construction documents in order to familiarize ourselves with, and be able to comment on, the in-place
 construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built
 environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.



6. Opinions of Probable Costs

Cost estimates are embedded throughout this report, including the detailed Replacement Reserves report in the appendix. The cost estimates are predominantly based on construction rehabilitation costs developed by the *RSMeans data from Gordian*. While the *RSMeans data from Gordian* is the primary reference source for the Bureau Veritas cost library, secondary and supporting sources include but are not limited to other industry experts work, such as *Marshall & Swift* and *CBRE Whitestone*. For improved accuracy, additional research integrated with Bureau Veritas's historical experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions also come into play when deemed necessary. Invoice or bid documents provided either by the owner or facility construction resources may be reviewed early in the process or for specific projects as warranted.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

To account for differences in prices between locations, the base costs are modified by geographical location factors to adjust for market conditions, transportation costs, or other local contributors. When requested by the client, the costs may be further adjusted by several additional factors including; labor rates (prevailing minimum wage), general contractor fees for profit and overhead, and insurance. If desired, costs for design and permits, and a contingency factor, may also be included in the calculations.



Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.



7. Certification

Montgomery County Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Capt. James E. Daly Jr. Elementary School, 20301 Brandermill Drive, Germantown, MD 20876, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: Alexander Rockafellow

Project Assessor

Reviewed by:

Adrian Reth

Technical Report Reviewer

for

Bill Champion

Program Manager

443.622.5067

bill.champion@bureauveritas.com



8. Appendices

Appendix A: Photographic Record

Appendix B: Site Plan(s)

Appendix C: Pre-Survey Questionnaire(s)

Appendix D: Accessibility Review and Photos

Appendix E: Component Condition Report

Appendix F: Replacement Reserves

Appendix G: Equipment Inventory List



Appendix A: Photographic Record





1 - FRONT ELEVATION



2 - LEFT ELEVATION



3 - RIGHT ELEVATION



4 - REAR ELEVATION




5 - COURTYARD



6 - LOBBY




7 - ATRIUM



8 - GYMNASIUM



9 - OFFICE



10 - CLASSROOM




11 - CLASSROOM



12 - CLASSROOM



13 - STORAGE



14 - CAFETERIA




15 - KITCHEN




16 - LIBRARY




17 - LIBRARY WORK AREA



18 - STAIRWELL



19 - NURSES OFFICE



20 - RESTROOM



21 - ELEVATOR



22 - BOILERS



23 - AIR HANDLER




24 - SWITCHBOARD

CAPT. JAMES E. DALY JR. ELEMENTARY SCHOOL



25 - GENERATOR



26 - WATER HEATER



27 - FIRE ALARM PANEL



28 - SHED



29 - ANCILLARY BUILDING



30 - ANCILLARY BUILDING



31 - PLAYGROUND



32 - SPORTS COURT



33 - PARKING LOT



34 - SIGNAGE

Appendix B: Site Plan(s)







| Project Number | Project Name |
|-----------------------|--|
| 172559.25R000-033.354 | Capt. James E. Daly Jr. Elementary School |
| Source | On-Site Date |
| Google | April 29, 2025 |



Appendix C:
Pre-Survey Questionnaire(s)



BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

| Capt. James E. Daly Jr. Elementary School | | | |
|---|--|--|--|
| Lisa Nia Laura | | | |
| | | | |
| 9 months | | | |
| 4/29/2025 | | | |
| | | | |
| DURING - verbally completed during assessment | | | |
| | | | |

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

| Data Overview | | Response | | | |
|--------------------------------|--|---------------------|-----------|-------------------|--|
| 1 | Year(s) constructed | Constructed 1989 | Renovated | | |
| 2 | Building size in SF | 78,386 | SF | | |
| | | | Year | Additional Detail | |
| | | Facade | | Original | |
| | | Roof | | Unk | |
| | | Interiors | | Unk | |
| 3 Major Renovation/Rehabilitat | Major Renovation/Rehabilitation | HVAC | 2016 | 2016 | |
| | | Electrical | | Original | |
| | | Site Pavement | t | Unk | |
| | | Accessibility | | | |
| 4 | List other significant capital improvements (focus on recent years; provide approximate date). | | | | |
| 5 | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? | | | | |
| 6 | Describe any on-going extremely problematic, historically chronic, or immediate facility needs. | | | | |

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "*Not Applicable*", **Unk** indicates "*Unknown*")

| | Question | | Resp | onse | | Comments |
|----|--|-----|------|------|----|--|
| | | Yes | No | Unk | NA | |
| 7 | Are there any problems with foundations or structures, like excessive settlement? | | × | | | |
| 8 | Are there any wall, window, basement or roof leaks? | | × | | | |
| 9 | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints? | | × | | | Before |
| 10 | Are your elevators unreliable, with frequent service calls? | | × | | | |
| 11 | Are there any plumbing leaks, water pressure, or clogging/backup issues? | | × | | | 2 months ago. Replaced cast iron pipes |
| 12 | Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service? | | × | | | Leak in may with flooding in hallway. |
| 13 | Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas? | | × | | | |
| 14 | Is the electrical service outdated, undersized, or problematic? | | × | | | |
| 15 | Are there any problems or inadequacies with exterior lighting? | | × | | | |
| 16 | Is site/parking drainage inadequate, with excessive ponding or other problems? | | × | | | |
| 17 | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? | | × | | | |
| 18 | ADA: Has an accessibility study been previously performed? If so, when? | | | | × | |
| 19 | ADA: Have any ADA improvements been made to the property since original construction? Describe. | | | | × | |
| 20 | ADA: Has building management reported any accessibility-based complaints or litigation? | | | | × | |
| 21 | Are any areas of the property leased to outside occupants? | | | | | |

| nplaints or litigation? | | | ^ | |
|---|--|--|---|------------------|
| any areas of the property leased outside occupants? | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| Signature of Assessor | | | | Signature of POC |
| ū | | | | · · |
| | | | | |

Appendix D:
Accessibility Review and Photos



Visual Checklist - 2010 ADA Standards for Accessible Design


Property Name: Capt. James E. Daly Jr. Elementary School

BV Project Number: 172559.25R000-033.354

| | Abbreviated Accessibility Checklist | | | | | | | | |
|---|--|-----|----|-----|----------|--|--|--|--|
| | Facility History & Interview | | | | | | | | |
| | Question | Yes | No | Unk | Comments | | | | |
| 1 | Has an accessibility study been previously performed? If so, when? | | | × | | | | | |
| 2 | Have any ADA improvements been made to the property since original construction? Describe. | | | × | | | | | |
| 3 | Has building management reported any accessibility-based complaints or litigation? | | | × | | | | | |

Parking








CLOSE-UP OF STALL

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Does the required number of standard ADA designated spaces appear to be provided? | × | | | |
| 2 | Does the required number of van-accessible designated spaces appear to be provided? | | × | | |
| 3 | Are accessible spaces on the shortest accessible route to an accessible building entrance ? | | × | | |
| 4 | Does parking signage include the International Symbol of Accessibility? | × | | | |
| 5 | Does each accessible space have an adjacent access aisle ? | | × | | |
| 6 | Do parking spaces and access aisles appear to be relatively level and without obstruction? | × | | | |

Exterior Accessible Route




ACCESSIBLE PATH


CURB CUT

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property? | | | × | |
| 2 | Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances? | × | | | |
| 3 | Are curb ramps present at transitions through raised curbs on all accessible routes? | × | | | |
| 4 | Do curb ramps appear to have compliant slopes for all components ? | × | | | |
| 5 | Do ramp runs on an accessible route appear to have compliant slopes ? | | | × | |
| 6 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | | | × | |

| 7 | Do ramps on an accessible route appear to have compliant end and intermediate landings? | | × | |
|---|---|--|---|--|
| 8 | Do ramps and stairs on an accessible route appear to have compliant handrails? | | × | |
| 9 | For stairways that are open underneath, are permanent barriers present that prevent or discourage access? | | × | |

Building Entrances





MAIN ENTRANCE

ADDITIONAL ENTRANCE

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Do a sufficient number of accessible entrances appear to be provided ? | × | | | |
| 2 | If the main entrance is not accessible, is an alternate accessible entrance provided? | | | × | |
| 3 | Is signage provided indicating the location of alternate accessible entrances? | | | × | |
| 4 | Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ? | × | | | |
| 5 | Do doors at accessible entrances appear to have compliant hardware ? | × | | | |
| 6 | Do doors at accessible entrances appear to have a compliant clear opening width ? | × | | | |

| 7 | Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ? | × | | |
|---|---|---|--|--|
| 8 | Do thresholds at accessible entrances appear to have a compliant height? | × | | |

Interior Accessible Route







DOOR HARDWARE

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Does an accessible route appear to connect all public areas inside the building ? | × | | | |
| 2 | Do accessible routes appear free of obstructions and/or protruding objects? | × | | | |
| 3 | Do ramps on accessible routes appear to have compliant slopes ? | | × | | |
| 4 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | × | | | |
| 5 | Do ramps on accessible routes appear to have compliant end and intermediate landings? | × | | | |
| 6 | Do ramps on accessible routes appear to have compliant handrails ? | × | | | |

| 7 | Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage? | × | | | |
|----|--|---|---|---|--|
| 8 | Do public transaction areas have an accessible, lowered service counter section ? | | | × | |
| 9 | Do public telephones appear mounted with an accessible height and location ? | | | × | |
| 10 | Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ? | × | | | |
| 11 | Do doors at interior accessible routes appear to have compliant hardware ? | | × | | |
| 12 | Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ? | × | | | |
| 13 | Do doors on interior accessible routes appear to have a compliant clear opening width ? | × | | | |

Elevators



LOBBY LOOKING AT CABS (WITH DOORS OPEN)



IN-CAB CONTROLS

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Are hallway call buttons configured with the "UP" button above the "DOWN" button? | × | | | |
| 2 | Is accessible floor identification signage present on the hoistway sidewalls on each level ? | | × | | |
| 3 | Do the elevators have audible and visual arrival indicators at the lobby and hallway entrances? | × | | | |
| 4 | Do the elevator hoistway and car interior appear to have a minimum compliant clear floor area ? | × | | | |
| 5 | Do the elevator car doors have automatic reopening devices to prevent closure on obstructions? | × | | | |
| 6 | Do elevator car control buttons appear to be mounted at a compliant height ? | × | | | |

| 7 | Are tactile and Braille characters mounted to the left of each elevator car control button? | × | | |
|---|---|---|---|--|
| 8 | Are audible and visual floor position indicators provided in the elevator car? | | × | |
| 9 | Is the emergency call system on or adjacent to the control panel and does it not require voice communication? | × | | |

Public Restrooms







SINK, FAUCET HANDLES AND ACCESSORIES

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Do publicly accessible toilet rooms appear to have a minimum compliant floor area ? | × | | | |
| 2 | Does the lavatory appear to be mounted at a compliant height and with compliant knee area ? | × | | | |
| 3 | Does the lavatory faucet have compliant handles ? | × | | | |
| 4 | Is the plumbing piping under lavatories configured to protect against contact? | | × | | |
| 5 | Are grab bars provided at compliant locations around the toilet ? | | × | | |
| 6 | Do toilet stall doors appear to provide the minimum compliant clear width ? | × | | | |

| 7 | Do toilet stalls appear to provide the minimum compliant clear floor area ? | × | | |
|---|---|---|--|--|
| 8 | Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width? | × | | |
| 9 | Do accessories and mirrors appear to be mounted at a compliant height ? | × | | |

Playgrounds & Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

| | Question | Yes | No | NA | Comments |
|---|---|-----|----|----|----------|
| 1 | Is there an accessible route to the play area / s? | × | | | |
| 2 | Has the play area been reviewed for accessibility? | | × | | |
| 3 | Are publicly accessible swimming pools equipped with an entrance lift ? | | | × | |

Appendix E:
Component Condition Report



| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|---------------------|-----------|--|------------|-----|---------|
| Structure | | | | | | |
| A1010 | Substructure | Fair | Foundation System, Concrete Strip/Pad Footings w/ Slab, 1-2 Story Building | 57,000 SF | 39 | 9318670 |
| B1010 | Superstructure | Fair | Structural Framing, Steel Columns & Beams, 1-2 Story Building | 78,386 SF | 39 | 9318741 |
| Facade | | | | | | |
| B2010 | Building Exterior | Fair | Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain | 24,570 SF | 5 | 9307003 |
| B2020 | Building Exterior | Fair | Glazing, any type by SF | 10,600 SF | 15 | 9307005 |
| B2050 | Hallway | Fair | Overhead/Dock Door, Steel, 12'x12' (144 SF) | 1 | 11 | 9318708 |
| B2050 | Building Exterior | Fair | Exterior Door, Steel, Commercial | 26 | 15 | 9306998 |
| Roofing | | | | | | |
| B3010 | Roof | Fair | Roofing, Modified Bitumen | 24,500 SF | 10 | 9318732 |
| B3010 | Roof | Fair | Roofing, Asphalt Shingle, 20-Year Standard | 29,200 SF | 10 | 9318769 |
| Interiors | | | | | | |
| C1010 | Gymnasium | Fair | Movable Partition, Gym Divider, Deluxe/Operable | 2,000 SF | 15 | 9318697 |
| C1010 | 128 | Fair | Movable Partition, Movable Partitions, Fabric 6' Height | 1,500 SF | 5 | 9318794 |
| C1030 | Throughout Building | Fair | Interior Door, Wood, Solid-Core | 35 | 4 | 9318798 |
| C1030 | Hallways | Fair | Interior Door, Steel, w/ Extensive Glazing | 6 | 4 | 9318767 |
| C1030 | Throughout Building | Fair | Interior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 40 | 4 | 9318738 |
| C1070 | Throughout Building | Fair | Suspended Ceilings, Acoustical Tile (ACT) | 70,600 SF | 15 | 9318810 |
| C1090 | Locker room | Fair | Lockers, Steel-Baked Enamel, 12" W x 15" D x 72" H | 50 LF | 5 | 9318709 |
| C1090 | Restrooms | Fair | Toilet Partitions, Plastic/Laminate | 20 | 10 | 9318698 |
| C2010 | Throughout Building | Fair | Wall Finishes, Ceramic Tile | 12,500 SF | 4 | 9318699 |
| C2010 | Gymnasium | Fair | Wall Finishes, Gym Wall Pads, Secured and 1.5" Thick | 500 SF | 5 | 9318724 |
| C2010 | Commercial Kitchen | Fair | Wall Finishes, Quarry Tile | 4,700 SF | 14 | 9318751 |
| C2010 | Throughout Building | Fair | Wall Finishes, any surface, Prep & Paint | 133,300 SF | 5 | 9318743 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|-------------------------|-----------|---|-----------|-----|---------|
| C2030 | Throughout Building | Fair | Flooring, Vinyl Tile (VCT) | 62,700 SF | 5 | 9318739 |
| C2030 | Commercial Kitchen | Fair | Flooring, Quarry Tile | 2,400 SF | 14 | 9318764 |
| C2030 | Restrooms | Fair | Flooring, Ceramic Tile | 4,700 SF | 4 | 9318785 |
| C2030 | Gymnasium | Fair | Flooring, Wood, Strip | 3,600 SF | 20 | 9318745 |
| C2030 | Throughout Building | Fair | Flooring, Carpet, Commercial Standard | 3,900 SF | 5 | 9318801 |
| C2030 | Mechanical rooms | Fair | Flooring, any surface, w/ Paint or Sealant, Prep & Paint | 800 SF | 5 | 9318734 |
| C2030 | Mechanical room | Fair | Flooring, any surface, w/ Paint or Sealant, Prep & Paint | 1,600 SF | 3 | 9318664 |
| C2050 | Throughout Building | Fair | Ceiling Finishes, any flat surface, Prep & Paint | 1,600 SF | 5 | 9318768 |
| C2050 | Gymnasium | Fair | Ceiling Finishes, exposed irregular elements, Prep & Paint | 6,300 SF | 5 | 9318710 |
| Conveying | | | | | | |
| D1010 | Elevator Shafts/Utility | Fair | Elevator Cab Finishes, Standard | 1 | 5 | 9318682 |
| D1010 | 115 | Fair | Elevator Controls, Automatic, 1 Car | 1 | 4 | 9318789 |
| D1010 | 115 | Fair | Passenger Elevator, Hydraulic, 2 Floors, Renovate | 1 | 4 | 9318799 |
| Plumbing | | | | | | |
| D2010 | Utility closet | Fair | Sink/Lavatory, Service Sink, Wall-Hung | 3 | 4 | 9318749 |
| D2010 | Kitchen | Good | Sink/Lavatory, Wall-Hung, Enameled Steel | 1 | 25 | 9318779 |
| D2010 | Restrooms | Fair | Urinal, Standard | 11 | 10 | 9318760 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Wall-Hung | 33 | 10 | 9318782 |
| D2010 | Nurse's station | Fair | Shower, Ceramic Tile | 1 | 10 | 9318702 |
| D2010 | Hallways & Common Areas | Fair | Drinking Fountain, Wall-Mounted, Single-Level | 1 | 5 | 9318752 |
| D2010 | Boiler Room | Fair | Water Heater, Gas, Commercial (200 MBH) | 1 | 5 | 9318719 |
| D2010 | Throughout Building | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 7 | 15 | 9318662 |
| D2010 | Throughout Building | Fair | Plumbing System, Supply & Sanitary, Low Density (excludes fixtures) | 78,386 SF | 6 | 9318807 |
| D2010 | Restrooms | Fair | Toilet, Commercial Water Closet | 30 | 15 | 9318806 |
| D2010 | Hallways & Common Areas | Fair | Drinking Fountain, Wall-Mounted, Bi-Level | 1 | 5 | 9318774 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|---------------------|-----------|---|----------|-----|---------|
| D2010 | Boiler Room | Fair | Backflow Preventer, Domestic Water | 1 | 15 | 9318808 |
| D2020 | Kitchen | Fair | Grease Trap/Interceptor, Grease Trap/Interceptor, Underground | 1 | 10 | 9318737 |
| D2030 | Boiler Room | Fair | Pump, Sump | 1 | 5 | 9318750 |
| HVAC | | | | | | |
| D3020 | Boiler Room | Fair | Boiler Supplemental Components, Expansion Tank [ET 1] | 1 | 25 | 9318696 |
| D3020 | Boiler Room | Good | Boiler, Gas, HVAC [B-1] | 1 | 21 | 9318805 |
| D3020 | Boiler Room | Good | Boiler, Gas, HVAC | 1 | 21 | 9318669 |
| D3020 | Boiler Room | Fair | Unit Heater, Hydronic | 1 | 11 | 9318676 |
| D3020 | Boiler Room | Fair | Boiler Supplemental Components, Expansion Tank | 1 | 25 | 9318677 |
| D3020 | Boiler Room | Good | Boiler, Gas, HVAC | 1 | 21 | 9318817 |
| D3030 | Courtyard | Fair | Split System Ductless, Single Zone [DSS 2] | 1 | 5 | 9318819 |
| D3030 | Hallways | Fair | Unit Ventilator, approx/nominal 2 Ton, 300 to 750 CFM | 5 | 10 | 9318665 |
| D3030 | Building Exterior | Fair | Heat Pump, Packaged & Wall-Mounted | 1 | 5 | 9318773 |
| D3030 | Courtyard | Fair | Split System Ductless, Single Zone | 1 | 5 | 9318680 |
| D3030 | Entryways | Fair | Unit Ventilator, approx/nominal 2 Ton | 3 | 10 | 9318777 |
| D3030 | Throughout Building | Fair | Unit Ventilator, approx/nominal 2 Ton | 15 | 3 | 9318812 |
| D3030 | Building Exterior | Fair | Split System Ductless, Single Zone | 1 | 5 | 9318725 |
| D3030 | Courtyard | Fair | Split System Ductless, Single Zone [DSS 3] | 1 | 5 | 9318735 |
| D3030 | Courtyard | Fair | Split System Ductless, Single Zone [DSS 6] | 1 | 5 | 9318781 |
| D3030 | Building Exterior | Fair | Heat Pump, Packaged & Wall-Mounted | 1 | 5 | 9318797 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone [DSS 4] | 1 | 5 | 9318795 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump | 1 | 5 | 9318657 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone | 1 | 5 | 9318811 |
| D3030 | Roof | Fair | Chiller, Air-Cooled | 1 | 16 | 9318671 |
| D3030 | Courtyard | Fair | Split System Ductless, Single Zone [DSS 7] | 1 | 5 | 9318661 |

| UF L3 Code | Location | Condition | Asset/Component/Repair Q | uantity | RUL | ID |
|------------|---------------------|-----------|--|-----------|-----|---------|
| D3030 | Courtyard | Fair | Split System, Condensing Unit/Heat Pump [ACCU 6] | 1 | 5 | 9318784 |
| D3030 | Roof | Fair | Heat Pump, Var Refrig Vol (VRV) | 1 | 5 | 9318695 |
| D3030 | Building Exterior | Fair | Split System Ductless, Single Zone | 1 | 5 | 9318766 |
| D3050 | Throughout Building | Good | HVAC System, Hydronic Piping, 2-Pipe | 78,386 SF | 31 | 9318720 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water | 1 | 16 | 9318655 |
| D3050 | Roof | Fair | Air Handler, Exterior AHU | 1 | 11 | 9318765 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-2] | 1 | 16 | 9318809 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water [P-7] | 1 | 6 | 9318666 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted [RTU 1] | 1 | 11 | 9318744 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water [P-6] | 1 | 16 | 9318700 |
| D3050 | 205A | Fair | Air Handler, Interior AHU, Easy/Moderate Access [AHU 1] | 1 | 16 | 9318688 |
| D3050 | Throughout Building | Fair | HVAC System, Ductwork, Medium Density | 78,386 SF | 10 | 9318778 |
| D3050 | 220A | Good | Air Handler, Interior AHU, Easy/Moderate Access | 1 | 21 | 9318771 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water [P-4] | 1 | 16 | 9318772 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water [P-8] | 1 | 6 | 9318770 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water [P-1] | 1 | 16 | 9318675 |
| D3050 | Roof | Good | Air Handler, Exterior AHU, 4001 to 6000 CFM | 1 | 11 | 9318816 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water [P-3] | 1 | 16 | 9318736 |
| D3050 | Boiler Room | Failed | Pump, Distribution, HVAC Heating Water | 1 | 0 | 9318681 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 12" Damper | 1 | 9 | 9318815 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 10 | 9318800 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 10" Damper [FAN 2] | 1 | 10 | 9318716 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper [EF-25] | 1 | 10 | 9318679 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU) | 1 | 11 | 9318687 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper [EF-27] | 1 | 10 | 9318715 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|-----------------|---------------------|-----------|--|-----------|-----|---------|
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 10 | 9318747 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 12" Damper [EF-3] | 1 | 10 | 9318706 |
| Fire Protection | 1 | | | | | |
| D4010 | Throughout Building | Fair | Fire Suppression System, Existing Sprinkler Heads, by SF | 78,386 SF | 15 | 9318693 |
| Electrical | | | | | | |
| D5010 | Elec 111 | Good | Automatic Transfer Switch, ATS | 1 | 20 | 9318796 |
| D5010 | Building Exterior | Good | Generator, Gas or Gasoline | 1 | 17 | 9318691 |
| D5010 | Elec 111 | Good | Automatic Transfer Switch, ATS | 1 | 20 | 9318658 |
| D5020 | Elec 113 | Fair | Distribution Panel, 277/480 V | 1 | 4 | 9318684 |
| D5020 | Elec 111 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 15 | 9318713 |
| D5020 | 212 | Fair | Distribution Panel, 277/480 V | 1 | 4 | 9318714 |
| D5020 | Electrical Shed | Poor | Secondary Transformer, Dry, Stepdown | 1 | 2 | 9307001 |
| D5020 | Elec 111 | Fair | Switchboard, 277/480 V | 1 | 4 | 9318763 |
| D5020 | Boiler Room | Good | Secondary Transformer, Dry, Stepdown | 1 | 21 | 9318783 |
| D5020 | Elec 111 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 3 | 9318761 |
| D5020 | 232 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 4 | 9318746 |
| D5020 | Elec 111 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 20 | 9318678 |
| D5020 | Elec 113 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 4 | 9318740 |
| D5020 | Electrical Shed | Poor | Distribution Panel, 120/208 V [DALY] | 1 | 2 | 9307004 |
| D5020 | Elec 130 | Fair | Distribution Panel, 277/480 V | 1 | 4 | 9318659 |
| D5020 | Elec 130 | Fair | Secondary Transformer, Dry, Stepdown | 1 | 4 | 9318683 |
| D5020 | Elec 113 | Fair | Distribution Panel, 120/208 V [RP #1] | 1 | 4 | 9318776 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 8] | 1 | 10 | 9318793 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 5] | 1 | 10 | 9318685 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 1 | 11 | 9318780 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|----------------|---------------------|-----------|--|-----------|-----|---------|
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 9] | 1 | 10 | 9318668 |
| D5030 | 205A | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 12] | 1 | 11 | 9318717 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 7] | 1 | 11 | 9318756 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 2] | 1 | 11 | 9318727 |
| D5030 | Throughout Building | Fair | Electrical System, Wiring & Switches, Average or Low Density/Complexity | 78,386 SF | 4 | 9318667 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 3] | 1 | 11 | 9318804 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 4] | 1 | 10 | 9318728 |
| D5030 | 220A | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD 18] | 1 | 10 | 9318705 |
| D5030 | Boiler Room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 1 | 11 | 9318656 |
| D5040 | Throughout Building | Fair | Interior Lighting System, Full Upgrade, High Density & Standard Fixtures | 78,386 SF | 10 | 9318742 |
| D5040 | Building Exterior | Fair | Exterior Light, any type, w/ LED Replacement | 10 | 10 | 9318730 |
| D5040 | Auditorium | Fair | Stage Lighting System, Full Upgrade, Specialty Fixtures | 1,500 SF | 5 | 9318788 |
| D5040 | Throughout Building | Fair | Emergency & Exit Lighting System, Full Interior Upgrade, LED | 78,386 SF | 5 | 9318721 |
| D5040 | Gymnasium | Good | High Intensity Discharge (HID) Fixtures, Metal Halide, Gymnasium Lighting, 400 W | 16 | 15 | 9318775 |
| Fire Alarm & E | lectronic Systems | | | | | |
| D6060 | Throughout Building | Good | Intercom/PA System, Public Address Upgrade, Facility-Wide | 78,386 SF | 15 | 9318802 |
| D7030 | Throughout Building | Fair | Security/Surveillance System, Full System Upgrade, Average Density | 78,386 SF | 10 | 9318704 |
| D7050 | 109 | Fair | Fire Alarm Panel, Fully Addressable | 1 | 5 | 9318814 |
| D7050 | Throughout Building | Fair | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 78,386 SF | 5 | 9318757 |
| Equipment & F | Furnishings | | | | | |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 5 | 9318694 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Condenser for Refigerator/Freezer | 1 | 9 | 9318748 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Single | 1 | 5 | 9318674 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refigerator/Freezer | 1 | 5 | 9318803 |
| E1030 | Roof | Fair | Foodservice Equipment, Walk-In, Condenser for Refigerator/Freezer | 1 | 5 | 9318660 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|---------------|-------------------------|-----------|--|----------|-----|---------|
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 5 | 9318755 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 5 | 9318786 |
| E1030 | Kitchen | Good | Foodservice Equipment, Commercial Kitchen, 3-Bowl | 1 | 25 | 9318707 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refigerator/Freezer | 1 | 5 | 9318703 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 8 LF | 4 | 9318731 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Double | 1 | 5 | 9318718 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Freezer | 1 | 5 | 9318672 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Walk-In, Refrigerator | 1 | 5 | 9318792 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 6 LF | 4 | 9318813 |
| E1040 | Hallways & Common Areas | Fair | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted | 1 | 5 | 9318787 |
| E1070 | Gymnasium | Fair | Basketball Backboard, Ceiling-Mounted, Operable | 4 | 10 | 9318723 |
| E1070 | Gymnasium | Fair | Basketball Backboard, Wall-Mounted, Fixed | 4 | 10 | 9318663 |
| E1070 | Auditorium | Fair | Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour | 2,000 SF | 5 | 9318733 |
| E2010 | Library | Fair | Library Shelving, Double-Faced, up to 90" Height | 75 LF | 10 | 9318711 |
| E2010 | Library | Fair | Library Shelving, Single-Faced, up to 90" Height | 150 LF | 10 | 9318762 |
| E2010 | Throughout Building | Fair | Casework, Cabinetry, Standard | 200 LF | 10 | 9318689 |
| E2010 | Library | Fair | Casework, Cabinetry, Standard | 20 LF | 5 | 9318791 |
| Special Const | ruction & Demo | | | | | |
| F1020 | Building Exterior | Poor | Ancillary Building, Wood-Framed or CMU, Basic/Minimal | 200 SF | 1 | 9307000 |
| Accessibility | | | | | | |
| Y1090 | Throughout | NA | ADA Miscellaneous, Level III Study, Includes Measurements, Evaluate/Report | 1 | 0 | 9377020 |
| Y1090 | Throughout | NA | ADA Miscellaneous, Lump Sum Budget, Allowance, Upgrade | 1 | 0 | 9377022 |

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | . ID |
|----------------|-----------------------------|-----------|--|-----------|-----|---------|
| Special Const | truction & Demo | | | | | |
| F1020 | Site | Fair | Ancillary Building, Classroom/Office Module, Basic/Portable | 1,600 SF | 15 | 9318758 |
| F1020 | Site General | Fair | Covered Walkway, Metal-Framed, Light/Medium Gauge, Prep & Paint | 1,900 SF | 5 | 9306794 |
| F1020 | Site | Fair | Ancillary Building, Classroom/Office Module, Standard/Permanent | 900 SF | 15 | 9318722 |
| Pedestrian Pla | azas & Walkways | | | | | |
| G2020 | Site Parking Areas | Failed | Parking Lots, Pavement, Asphalt, Cut & Patch | 10,000 SF | 0 | 9306783 |
| G2020 | Site Parking Areas | Fair | Parking Lots, Pavement, Asphalt, Seal & Stripe | 28,195 SF | 2 | 9306792 |
| G2020 | Site Parking Areas | Poor | Parking Lots, Pavement, Asphalt, Mill & Overlay | 18,195 SF | 2 | 9306785 |
| G2030 | Site Parking Areas | Fair | Sidewalk, Concrete, Large Areas | 8,871 SF | 14 | 9306768 |
| Athletic, Recr | reational & Playfield Areas | | | | | |
| G2050 | Site Sports Fields & Courts | Fair | Sports Apparatus, Basketball, Backboard w/ Pole | 4 | 10 | 9306773 |
| G2050 | Site Sports Fields & Courts | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe | 7,190 SF | 2 | 9306784 |
| G2050 | Site Sports Fields & Courts | Fair | Sports Apparatus, Baseball, Backstop Chain-Link | 1 | 3 | 9306779 |
| G2050 | Site Playground Areas | Good | Play Structure, Multipurpose, Small | 1 | 15 | 9306775 |
| G2050 | Site Playground Areas | Good | Play Structure, Multipurpose, Large | 1 | 15 | 9306776 |
| G2050 | Site Playground Areas | Good | Play Structure, Multipurpose, Medium | 1 | 15 | 9306791 |
| G2050 | Site Playground Areas | Good | Play Structure, Multipurpose, Large | 1 | 15 | 9306774 |
| G2050 | Site Playground Areas | Fair | Playground Surfaces, Engineered Wood Fiber Chips, 3" Depth | 9,650 SF | 3 | 9306778 |
| G2050 | Play Area | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay | 7,190 SF | 15 | 9306787 |
| Sitework | | | | | | |
| G2060 | Site General | Fair | Fences & Gates, Fence, Chain Link 4' | 173 LF | 20 | 9306782 |
| G2060 | Site General | Poor | Signage, Property, Monument, Replace/Install | 1 | 2 | 9306780 |
| G2060 | Site | Fair | Flagpole, Metal | 2 | 10 | 9306771 |
| G2060 | Exterior | Fair | Signage, Property, Building-Mounted Individual Letters, Replace/Install | 32 | 5 | 9306770 |
| G2060 | Site General | Good | Bike Rack, Fixed 1-5 Bikes | 2 | 18 | 9306793 |

| UF L3 Code | e Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|---------------|--------------------|-----------|--|----------|-----|---------|
| G4050 | Site General | Poor | Site Lighting, Wall Pack or Walkway Ceiling/Pole-Mounted, any type w/ LED, Higher-Lumen | 11 | 2 | 9306789 |
| G4050 | Site General | Fair | Site Lighting, Wall Pack or Walkway Ceiling/Pole-Mounted, any type w/ LED, Higher-Lumen | 15 | 10 | 9306786 |
| G4050 | Site Parking Areas | Fair | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, 150 W, Replace/Install | 13 | 8 | 9306769 |
| Accessibility | , | | | | | |
| Y1010 | Parking Lot | NA | ADA Parking, Designated Stall, Pavement Markings & Signage, Install | 2 | 0 | 9377007 |

Appendix F: Replacement Reserves



5/28/2025

| Location | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | Total Escalated Estimate |
|---|----------|----------|-----------|-----------|-----------|-------------|-----------|----------|----------|----------|-------------|-----------|----------|----------|-----------|-------------|-----------|-----------|----------|------|-------------|--------------------------|
| Capt. James E. Daly Jr. Elementary School | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | |
| Capt. James E. Daly Jr. Elementary School / Main Building | \$32,600 | \$12,360 | \$33,949 | \$134,843 | \$947,639 | \$1,469,970 | \$480,164 | \$0 | \$0 | \$10,047 | \$2,169,949 | \$302,178 | \$0 | \$3,524 | \$279,224 | \$2,502,175 | \$700,294 | \$109,088 | \$0 | \$0 | \$1,125,695 | \$10,313,699 |
| Capt. James E. Daly Jr. Elementary School / Site | \$57,000 | \$0 | \$96,972 | \$16,008 | \$0 | \$11,600 | \$0 | \$19,584 | \$78,096 | \$0 | \$48,381 | \$0 | \$22,703 | \$14,171 | \$120,764 | \$732,823 | \$0 | \$26,319 | \$18,471 | \$0 | \$5,624 | \$1,268,516 |
| Grand Total | \$89,600 | \$12,360 | \$130,921 | \$150,851 | \$947,639 | \$1,481,570 | \$480,164 | \$19,584 | \$78,096 | \$10,047 | \$2,218,330 | \$302,178 | \$22,703 | \$17,696 | \$399,988 | \$3,234,998 | \$700,294 | \$135,407 | \$18,471 | \$0 | \$1,131,319 | \$11,582,215 |

Capt. James E. Daly Jr. Elementary School

| niformat Location Descrip | otion ID Cost Description | Lifespan (EUL) | Age R | UL | QuantityU | Jnit Uni | it Cost* Sub | ototal 2025 | 2026 2027 | 2028 | 2029 203 | 0 2031 203 | 2 2033 20 | 34 203 | 5 2036 20 | 37 2038 2 | 2039 2040 | 2041 2042 | 2043 2044 | 2045 | Deficienc Repa |
|------------------------------|--|-------------------|-------|----|-----------|----------|-----------------|-------------|-----------|---------|-----------|------------|-----------|----------|-----------|-----------|-----------|-----------|-----------|---------|---------------------|
| Building Exterior | 9307003 Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain | 20 | 15 | 5 | 24570 | SF | \$1.86 \$4 | 15,700 | | | \$45,700 | | | | | | | | | | Estimat \$45,700 |
| 32020 Building Exterior | 9307005 Glazing, any type by SF, Replace | 30 | 15 | 15 | 10600 | SF | \$55.00 \$58 | 33,000 | | | | | | | | | \$583,000 | | | | \$583,000 |
| Building Exterior | 9306998 Exterior Door, Steel, Commercial, Replace | 40 | 25 | 15 | 26 | EA S | \$4,060.00 \$10 | 05,560 | | | | | | | | | \$105,560 | | | | \$105,56 |
| 32050 Hallway | 9318708 Overhead/Dock Door, Steel, 12'x12' (144 SF), Replace | 30 | 19 | 11 | 1 | EA S | \$3,200.00 \$ | \$3,200 | | | | | | | \$3,200 | | | | | | \$3,20 |
| 33010 Roof | 9318769 Roofing, Asphalt Shingle, 20-Year Standard, Replace | 20 | 10 | 10 | 29200 | SF | \$3.80 \$11 | 10,960 | | | | | | \$110,96 | | | | | | | \$110,96 |
| 33010 Roof | 9318732 Roofing, Modified Bitumen, Replace | 20 | 10 | 10 | 24500 | SF | \$10.00 \$24 | 15,000 | | | | | | \$245,00 | | | | | | | \$245,00 |
| 01010 128 | 9318794 Movable Partition, Movable Partitions, Fabric 6' Height, Replace | 25 | 20 | 5 | 1500 | SF | \$5.00 \$ | \$7,500 | | | \$7,500 | | | | | | | | | | \$7,50 |
| C1010 Gymnasium | 9318697 Movable Partition, Gym Divider, Deluxe/Operable, Replace | 25 | 10 | 15 | 2000 | SF | \$22.30 \$4 | 14,600 | | | | | | | | | \$44,600 | | | | \$44,60 |
| C1030 Throughout Build | ling 9318798 Interior Door, Wood, Solid-Core, Replace | 40 | 36 | 4 | 35 | EA | \$700.00 \$2 | 24,500 | | | \$24,500 | | | | | | | | | | \$24,50 |
| C1030 Hallways | 9318767 Interior Door, Steel, w/ Extensive Glazing, Replace | 40 | 36 | 4 | 6 | EA | \$950.00 \$ | | | | \$5,700 | | | | | | | | | | \$5,70 |
| C1030 Throughout Build | | 40 | 36 | 4 | 40 | | \$2,100.00 \$8 | | | | \$84,000 | | | | | | | | | | \$84,00 |
| C1070 Throughout Build | | 25 | 10 | 15 | 70600 | SF | \$3.50 \$24 | | | | | | | | | | \$247,100 | | | | \$247,10 |
| C1090 Restrooms | 9318698 Toilet Partitions, Plastic/Laminate, Replace | 20 | 10 | 10 | 20 | EA | \$750.00 \$1 | | | | | | | \$15,00 | | | | | | | \$15,00 |
| C1090 Locker room | 9318709 Lockers, Steel-Baked Enamel, 12" W x 15" D x 72" H, Replace | 20 | 15 | 5 | 50 | LF | \$500.00 \$2 | | | | \$25,000 | | | | | | | | | | \$25,00 |
| C2010 Throughout Build | ling 9318699 Wall Finishes, Ceramic Tile, Replace | 40 | 36 | 4 | 12500 | SF | \$18.00 \$22 | 25,000 | | | \$225,000 | | | | | | | | | | \$225,00 |
| C2010 Commercial Kitch | | 50 | 36 | 14 | 4700 | SF | \$26.00 \$12 | 22,200 | | | | | | | | \$122, | 200 | | | | \$122,20 |
| C2010 Gymnasium | 9318724 Wall Finishes, Gym Wall Pads, Secured and 1.5" Thick, Replace | 15 | 10 | 5 | 500 | SF | \$16.80 \$ | 88,400 | | | \$8,400 |) | | | | | | | | \$8,400 | \$16,80 |
| C2010 Throughout Build | | 10 | 5 | 5 | | SF | \$1.50 \$19 | 99,950 | | | \$199,950 |) | | | | | \$199,950 | | | | \$399,90 |
| C2030 Mechanical room | | 10 | 7 | 3 | 1600 | SF | \$1.50 \$ | \$2,400 | | \$2,400 | | | | | | \$2,400 | | | | | \$4,80 |
| C2030 Mechanical room | | 10 | 5 | 5 | | SF | \$1.50 \$ | | | | \$1,200 | | | | | | \$1,200 | | | | \$2,40 |
| C2030 Restrooms | 9318785 Flooring, Ceramic Tile, Replace | 40 | 36 | 4 | | SF | \$18.00 \$8 | 34.600 | | | \$84,600 | | | | | | | | | | \$84,60 |
| C2030 Commercial Kitch | | 50 | 36 | 14 | 2400 | SF | \$26.00 \$6 | 62,400 | | | | | | | | \$62, | 400 | | | | \$62,40 |
| C2030 Gymnasium | 9318745 Flooring, Wood, Strip, Replace | 30 | 10 | 20 | | SF | \$15.00 \$5 | | | | | | | | | | | | \$5 | 54,000 | \$54,00 |
| C2030 Throughout Build | | 15 | 10 | 5 | 62700 | SF | \$5.00 \$31 | 13,500 | | | \$313,500 |) | | | | | | | \$31 | 13,500 | \$627,00 |
| C2030 Throughout Build | | 10 | 5 | 5 | | SF | \$7.50 \$2 | | | | \$29,250 | | | | | | \$29,250 | | | | \$58,50 |
| C2050 Throughout Build | | 10 | 5 | 5 | | SF | \$2.00 \$ | | | | \$3,200 | | | | | | \$3,200 | | | | \$6,40 |
| C2050 Gymnasium | 9318710 Ceiling Finishes, exposed irregular elements, Prep & Paint | 10 | 5 | 5 | 6300 | SF | \$2.50 \$1 | 15,750 | | | \$15,750 |) | | | | | \$15,750 | | | | \$31,50 |
| 01010 115 | 9318789 Elevator Controls, Automatic, 1 Car, Replace | 20 | 16 | 4 | 1 | EA S | \$5,000.00 \$ | \$5,000 | | | \$5,000 | | | | | | | | | | \$5,00 |
| 01010 115 | 9318799 Passenger Elevator, Hydraulic, 2 Floors, Renovate | 30 | 26 | 4 | 1 | EA \$5 | 55,000.00 \$5 | 55,000 | | | \$55,000 | | | | | | | | | | \$55,00 |
| 01010 Elevator Shafts/L | | 15 | 10 | 5 | 1 | EA S | \$9,000.00 \$ | \$9,000 | | | \$9,000 | | | | | | | | 4 | \$9,000 | \$18,00 |
| 02010 Boiler Room | 9318719 Water Heater, Gas, Commercial (200 MBH), Replace | 20 | 15 | 5 | 1 | EA \$ | 16,600.00 \$1 | 16,600 | | | \$16,600 | | | | | | | | | | \$16,60 |
| D2010 Throughout Build | | 40 | 34 | 6 | 78386 | SF | \$5.00 \$39 | 91,930 | | | | \$391,930 | | | | | | | | | \$391,93 |
| D2010 Boiler Room | 9318808 Backflow Preventer, Domestic Water, Replace | 30 | 15 | 15 | 1 | EA \$ | 10,500.00 \$1 | 10,500 | | | | | | | | | \$10,500 | | | | \$10,50 |
| 02010 Utility closet | 9318749 Sink/Lavatory, Service Sink, Wall-Hung, Replace | 35 | 31 | 4 | 3 | EA S | \$1,400.00 \$ | \$4,200 | | | \$4,200 | | | | | | | | | | \$4,20 |
| 02010 Hallways & Comi | mon Areas 9318752 Drinking Fountain, Wall-Mounted, Single-Level, Replace | 15 | 10 | 5 | 1 | EA S | \$1,200.00 \$ | \$1,200 | | | \$1,200 |) | | | | | | | \$ | \$1,200 | \$2,40 |
| | mon Areas 9318774 Drinking Fountain, Wall-Mounted, Bi-Level, Replace | 15 | 10 | 5 | 1 | EA S | \$1,500.00 \$ | \$1,500 | | | \$1,500 | | | | | | | | | \$1,500 | \$3,00 |
| 02010 Restrooms | 9318760 Urinal, Standard, Replace | 30 | 20 | 10 | 11 | EA S | \$1,100.00 \$1 | 12,100 | | | | | | \$12,10 | | | | | | | \$12,10 |
| 02010 Restrooms | 9318782 Sink/Lavatory, Wall-Hung, Replace | 30 | 20 | 10 | 33 | EA S | \$1,700.00 \$5 | 56,100 | | | | | | \$56,10 | | | | | | | \$56,10 |
| 02010 Nurse's station | 9318702 Shower, Ceramic Tile, Replace | 30 | 20 | 10 | 1 | EA S | \$2,500.00 \$ | \$2,500 | | | | | | \$2,50 | | | | | | | \$2,50 |
| D2010 Throughout Build | | 30 | 15 | 15 | 7 | EA S | \$1,200.00 \$ | \$8,400 | | | | | | | | | \$8,400 | | | | \$8,400 |
| 02010 Restrooms | 9318806 Toilet, Commercial Water Closet, Replace | 30 | 15 | 15 | 30 | EA S | \$1,300.00 \$3 | 30,000 | | | | | | | | | \$39,000 | | | | \$39,000 |

5/28/2025

| Uniformat Location Description | ID Cost Description | Lifespan (EUL) | EAge F | RUL | Quantity | Jnit | Unit Cost* Subtotal 2025 | 2026 2027 | 2028 2029 | 2030 | 0 203 | 1 2032 203 | 33 2034 | 4 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 204 | 2043 | 2044 2045 | Defi 5 Es |
|-----------------------------------|--|-------------------|--------|-----|----------|------|----------------------------|-----------|-----------|----------|--------|------------|---------|-----------|----------|------|------|------|------|----------------|---------|-----------|------------------|
| D2020 Kitchen | 9318737 Grease Trap/Interceptor, Grease Trap/Interceptor, Underground, Replace | 20 | 10 | 10 | 1 | EA | \$12,000.00 \$12,000 | | | | | | | \$12,000 | | | | | | | | | \$ |
| D2030 Boiler Room | 9318750 Pump, Sump, Replace | 15 | 10 | 5 | 1 | EA | \$4,270.00 \$4,270 | | | \$4,270 | | | | | | | | | | | | \$4,270 | , , |
| D3020 Boiler Room | 9318676 Unit Heater, Hydronic, Replace | 20 | 9 | 11 | 1 | EA | \$6,700.00 \$6,700 | | | | | | | | \$6,700 | | | | | | | | |
| 03030 Roof | 9318671 Chiller, Air-Cooled, Replace | 25 | 9 | 16 | 1 | EA | \$350,000.00 \$350,000 | | | | | | | | | | | | \$3 | 350,000 | + | | \$35 |
| D3030 Throughout Building | 9318812 Unit Ventilator, approx/nominal 2 Ton, Replace | 20 | 17 | 3 | 15 | EA | \$7,400.00 \$111,000 | | \$111,000 | | | | | | | | | | | | | | \$1 ⁻ |
| D3030 Courtyard | 9318819 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$3,500.00 \$3,500 | | | \$3,500 |) | | | | | | | | | | + | \$3,500 | |
| D3030 Building Exterior | 9318773 Heat Pump, Packaged & Wall-Mounted, Replace | 20 | 15 | 5 | 1 | EA | \$4,400.00 \$4,400 | | | \$4,400 | | | | | | | | | | | + | | |
| D3030 Courtyard | 9318680 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$3,500.00 \$3,500 | | | \$3,500 | | | | | | | | | | | + | \$3,500 | |
| 03030 Building Exterior | 9318725 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$3,500.00 \$3,500 | | | \$3,500 | | | | | | | | | | | + | \$3,500 | |
| D3030 Courtyard | 9318735 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$3,500.00 \$3,500 | | | \$3,500 | | | | | | | | | | | | \$3,500 | |
| 03030 Courtyard | 9318781 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$4,800.00 \$4,800 | | | \$4,800 | | | | | | | | | | | | \$4,800 | |
| | 9318797 Heat Pump, Packaged & Wall-Mounted, Replace | 20 | 15 | 5 | 1 | EA | \$4,400.00 \$4,400 | | | \$4,400 | | | | | | | | | | | | Ψ4,800 | |
| · · | | | | - 5 | ' ' | | \$3,500.00 \$3,500 | | | \$3,500 | | | | | | | | | | | | ¢2 500 | |
| | 9318795 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | | | | | | | | | | | | | | | | \$3,500 | |
| 3030 Roof | 9318657 Split System, Condensing Unit/Heat Pump, Replace | 15 | 10 | 5 | 1 | EA | \$2,300.00 \$2,300 | | | \$2,300 | | | | | | | | | | | | \$2,300 | |
| 3030 Roof | 9318811 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$4,800.00 \$4,800 | | | \$4,800 | | | | | | | | | | | | \$4,800 | |
| Courtyard | 9318661 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$4,800.00 \$4,800 | | | \$4,800 | | | | | | | | | | | \perp | \$4,800 | |
| 3030 Courtyard | 9318784 Split System, Condensing Unit/Heat Pump, Replace | 15 | 10 | 5 | 1 | EA | \$25,300.00 \$25,300 | | | \$25,300 | | | | | | | | | | | | \$25,300 | |
| 3030 Roof | 9318695 Heat Pump, Var Refrig Vol (VRV), Replace | 15 | 10 | 5 | 1 | EA | \$55,000.00 \$55,000 | | | \$55,000 |) | | | | | | | | | | | \$55,000 | \$1 |
| 3030 Building Exterior | 9318766 Split System Ductless, Single Zone, Replace | 15 | 10 | 5 | 1 | EA | \$4,800.00 \$4,800 | | | \$4,800 |) | | | | | | | | | | | \$4,800 |) |
| 3030 Hallways | 9318665 Unit Ventilator, approx/nominal 2 Ton, 300 to 750 CFM, Replace | 20 | 10 | 10 | 5 | EA | \$7,400.00 \$37,000 | | | | | | | \$37,000 | | | | | | | | | \$ |
| 8030 Entryways | 9318777 Unit Ventilator, approx/nominal 2 Ton, Replace | 20 | 10 | 10 | 3 | EA | \$7,400.00 \$22,200 | | | | | | | \$22,200 | | | | | | | | | \$ |
| 050 Boiler Room | 9318681 Pump, Distribution, HVAC Heating Water, Replace | 15 | 15 | 0 | 1 | EA | \$5,100.00 \$5,100 \$5,100 | | | | | | | | | | | \$5 | ,100 | | | | , |
| 8050 Boiler Room | 9318666 Pump, Distribution, HVAC Heating Water, Replace | 15 | 9 | 6 | 1 | EA | \$5,100.00 \$5,100 | | | | \$5,10 | 0 | | | | | | | | | | | |
| Boiler Room | 9318770 Pump, Distribution, HVAC Heating Water, Replace | 15 | 9 | 6 | 1 | EA | \$5,100.00 \$5,100 | | | | \$5,10 | 0 | | | | | | | | | | | |
| Boiler Room | 9318655 Pump, Distribution, HVAC Heating Water, Replace | 25 | 9 | 16 | 1 | EA | \$6,100.00 \$6,100 | | | | | | | | | | | | | \$6,100 | | | |
| Boiler Room | 9318809 Pump, Distribution, HVAC Chilled or Condenser Water, Replace | 25 | 9 | 16 | 1 | EA | \$7,600.00 \$7,600 | | | | | | | | | | | | | \$7,600 | | | |
| 3050 Boiler Room | 9318700 Pump, Distribution, HVAC Heating Water, Replace | 25 | 9 | 16 | 1 | EA | \$22,000.00 \$22,000 | | | | | | | | | | | | \$ | \$22,000 | | | \$ |
| 3050 Boiler Room | 9318772 Pump, Distribution, HVAC Heating Water, Replace | 25 | 9 | 16 | 1 | EA | \$6,100.00 \$6,100 | | | | | | | | | | | | | \$6,100 | | | |
| Boiler Room | 9318675 Pump, Distribution, HVAC Chilled or Condenser Water, Replace | 25 | 9 | 16 | 1 | EA | \$7,600.00 \$7,600 | | | | | | | | | | | | | \$7,600 | | | |
| 3050 Boiler Room | 9318736 Pump, Distribution, HVAC Heating Water, Replace | 25 | 9 | 16 | 1 | EA | \$22,000.00 \$22,000 | | | | | | | | | | | | 9 | \$22,000 | + | | |
| 3050 Throughout Building | 9318778 HVAC System, Ductwork, Medium Density, Replace | 30 | 20 | 10 | 78386 | SF | \$4.00 \$313,544 | | | | | | | \$313,544 | | | | | | | | | \$3 |
| 3050 Roof | 9318765 Air Handler, Exterior AHU, Replace | 20 | 9 | 11 | 1 | EA | \$37,200.00 \$37,200 | | | | | | | | \$37,200 | | | | | | + | | \$ |
| 3050 Roof | 9318744 Packaged Unit, RTU, Pad or Roof-Mounted, Replace | 20 | 9 | 11 | 1 | EA | \$40,000.00 \$40,000 | | | | | | | | \$40,000 | | | | | | + | | \$ |
| 3050 Roof | 9318816 Air Handler, Exterior AHU, 4001 to 6000 CFM, Replace | 20 | a | 11 | 1 | EA | \$37,200.00 \$37,200 | | | | | | | | \$37,200 | | | | | | + | | \$ |
| 3050 205A | 9318688 Air Handler, Interior AHU, Easy/Moderate Access, Replace | 25 | 9 | 16 | 1 | EA | \$15,000.00 \$15,000 | | | | | | | | ψ01,200 | | | | 9 | \$15,000 | | | |
| 3060 Roof | 9318815 Exhaust Fan, Roof or Wall-Mounted, 12" Damper, Replace | 20 | 11 | 0 | 1 | EA | \$1,400.00 \$1,400 | | | | | | \$1,400 | 1 | | | | | , | #10,000 | | | , |
| | 9318800 Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 10 | 10 | 1 | EA | | | | | | | \$1,400 | | | | | | | | | | |
| | | | | | ' ' | | \$2,400.00 \$2,400 | | | | | | | \$2,400 | | | | | | | | | |
| 8060 Roof | 9318716 Exhaust Fan, Roof or Wall-Mounted, 10" Damper, Replace | 20 | 10 | 10 | 1 | EA | \$1,200.00 \$1,200 | | | | | | | \$1,200 | | | | | | | | | |
| 3060 Roof | 9318679 Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 10 | 10 | 1 | EA | \$2,400.00 \$2,400 | | | | | | | \$2,400 | | | | | | | | | |
| 3060 Roof | 9318715 Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 10 | 10 | 1 | EA | \$2,400.00 \$2,400 | | | | | | | \$2,400 | | | | | | | | | |
| 3060 Roof | 9318747 Exhaust Fan, Roof or Wall-Mounted, 16" Damper, Replace | 20 | 10 | 10 | 1 | EA | \$2,400.00 \$2,400 | | | | | | | \$2,400 | | | | | | | | | |
| 3060 Roof | 9318706 Exhaust Fan, Roof or Wall-Mounted, 12" Damper, Replace | 20 | 10 | 10 | 1 | EA | \$1,400.00 \$1,400 | | | | | | | \$1,400 | | | | | | | \perp | | |
| 3060 Roof | 9318687 Air Handler, Outside Air Intake Energy Recovery Unit (ERU), Replace | 20 | 9 | 11 | 1 | EA | \$33,000.00 \$33,000 | | | | | | | | \$33,000 | | | | | | | | \$ |
| Throughout Building | 9318693 Fire Suppression System, Existing Sprinkler Heads, by SF, Replace | 25 | 10 | 15 | 78386 | SF | \$1.07 \$83,873 | | | | | | | | | | | \$83 | ,873 | | | | \$ |
| Building Exterior | 9318691 Generator, Gas or Gasoline, Replace | 25 | 8 | 17 | 1 | EA | \$66,000.00 \$66,000 | | | | | | | | | | | | | \$66,000 |) | | \$ |
| 5010 Elec 111 | 9318796 Automatic Transfer Switch, ATS, Replace | 25 | 5 | 20 | 1 | EA | \$20,000.00 \$20,000 | | | | | | | | | | | | | | | \$20,000 | \$ |
| 5010 Elec 111 | 9318658 Automatic Transfer Switch, ATS, Replace | 25 | 5 | 20 | 1 | EA | \$20,000.00 \$20,000 | | | | | | | | | | | | | | | \$20,000 | \$ |
| 5020 Electrical Shed | 9307001 Secondary Transformer, Dry, Stepdown, Replace | 30 | 28 | 2 | 1 | EA | \$25,000.00 \$25,000 | \$25,000 | | | | | | | | | | | | | | | : |
| 5020 Elec 111 | 9318761 Secondary Transformer, Dry, Stepdown, Replace | 30 | 27 | 3 | 1 | EA | \$10,000.00 \$10,000 | | \$10,000 | | | | | | | | | | | | | | \$ |
| 05020 Elec 111 | 9318763 Switchboard, 277/480 V, Replace | 40 | 36 | 4 | 1 | EA | \$75,000.00 \$75,000 | | \$75,000 | | | | | | | | | | | | | | \$ |
| 05020 232 | 9318746 Secondary Transformer, Dry, Stepdown, Replace | 30 | 26 | 4 | 1 | EA | \$10,000.00 \$10,000 | | \$10,000 | | | | | | | | | | | | | | \$ |

5/28/2025

| Uniformat Location Description Code | ID Cost Description | Lifespan (EUL) | EAge RI | JL | QuantityU | nit | Unit Cost* Subtotal 2025 | 2026 2027 | 2028 2029 | 2030 | 203 | 1 2032 203 | 33 2034 | 2035 2036 | 5 2037 | 7 2038 | 2039 | 2040 | 2041 20 | 42 204 | 3 2044 | 2045 | Deficie Re Estin |
|---|---|-------------------|---------|----|-----------|------|--------------------------|-----------|-----------|-----------|-----|------------|---------|-----------|--------|--------|------|----------|---------|--------|--------|----------|------------------------|
| D5020 Elec 113 | 9318740 Secondary Transformer, Dry, Stepdown, Replace | 30 | 26 | 4 | 1 | EA | \$16,000.00 \$16,000 | | \$16,000 | | | | | | | | | | | | | | \$16, |
| D5020 Elec 130 | 9318683 Secondary Transformer, Dry, Stepdown, Replace | 30 | 26 | 4 | 1 | EA | \$10,000.00 \$10,000 | | \$10,000 | | | | | | | | | | | | | | \$10, |
| D5020 Elec 111 | 9318713 Secondary Transformer, Dry, Stepdown, Replace | 30 | 15 | 15 | 1 | EA | \$6,700.00 \$6,700 | | | | | | | | | | | \$6,700 | | | | | \$6, |
| D5020 Elec 111 | 9318678 Secondary Transformer, Dry, Stepdown, Replace | 30 | 10 | 20 | 1 | EA | \$6,700.00 \$6,700 | | | | | | | | | | | | | | | \$6,700 | \$6, |
| 05020 Electrical Shed | 9307004 Distribution Panel, 120/208 V, Replace | 30 | 28 | 2 | 1 | EA | \$7,000.00 \$7,000 | \$7,000 | | | | | | | | | | | | | | | \$7, |
| 05020 Elec 113 | 9318684 Distribution Panel, 277/480 V, Replace | 30 | 26 | 4 | 1 | EA | \$10,000.00 \$10,000 | | \$10,000 | | | | | | | | | | | | | | \$10, |
| D5020 212 | 9318714 Distribution Panel, 277/480 V, Replace | 30 | 26 | 4 | 1 | EA | \$10,000.00 \$10,000 | | \$10,000 | | | | | | | | | | | | | | \$10, |
| D5020 Elec 130 | 9318659 Distribution Panel, 277/480 V, Replace | 30 | 26 | 4 | 1 | EA | \$7,000.00 \$7,000 | | \$7,000 | | | | | | | | | | | | | | \$7, |
| D5020 Elec 113 | 9318776 Distribution Panel, 120/208 V, Replace | 30 | 26 | 4 | 1 | EA | \$6,000.00 \$6,000 | | \$6,000 | | | | | | | | | | | | | | \$6 |
| D5030 Throughout Building | 9318667 Electrical System, Wiring & Switches, Average or Low Density/Complexity, Replace | 40 | 36 | 4 | 78386 | SF | \$2.50 \$195,965 | | \$195,965 | | | | | | | | | | | | | | \$195 |
| 05030 Boiler Room | 9318793 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 10 | 10 | 1 | EA | \$5,300.00 \$5,300 | | | | | | | \$5,300 | | | | | | | | | \$5 |
| 95030 Boiler Room | 9318685 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 10 | 10 | 1 | EA | \$5,300.00 \$5,300 | | | | | | | \$5,300 | | | | | | | | | \$5 |
| 5030 Boiler Room | 9318668 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 10 | 10 | 1 | EA | \$5,300.00 \$5,300 | | | | | | | \$5,300 | | | | | | | | - | \$5 |
| 5030 Boiler Room | 9318728 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 10 | 10 | 1 | EA | \$5,300.00 \$5,300 | | | | | | | \$5,300 | | | | | | | | | \$5 |
| 05030 | 9318705 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 10 | 10 | 1 | EA | \$7,000.00 \$7,000 | | | | | | | \$7,000 | | | | | | | | | \$7 |
| 05030 Boiler Room | | 20 | ۵ | 11 | 1 | EA | \$14,700.00 \$14,700 | | | | | | | \$14,700 | | | | | | | | | |
| | 9318780 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | | 9 | | 1 | | | | | | | | | | | | | | | | | | \$14 |
| 205A 205A Reiler Beem | 9318717 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 9 | 11 | 1 | EA | \$7,000.00 \$7,000 | | | | | | | \$7,000 | | | | | | | | | \$7 |
| 5030 Boiler Room | 9318756 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 9 | 11 | 1 | EA | \$7,000.00 \$7,000 | | | | | | | \$7,000 | | | | | | | | | \$7 |
| Boiler Room | 9318727 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 9 | 11 | 1 | EA | \$8,800.00 \$8,800 | | | | | | | \$8,800 | | | | | | | | | \$8 |
| Boiler Room | 9318804 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 9 | 11 | 1 | EA | \$14,700.00 \$14,700 | | | | | | | \$14,700 | | | | | | | | | \$14 |
| 5030 Boiler Room | 9318656 Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 9 | 11 | 1 | EA | \$8,800.00 \$8,800 | | | | | | | \$8,800 | | | | | | | | | \$8 |
| 5040 Auditorium | 9318788 Stage Lighting System, Full Upgrade, Specialty Fixtures, Replace | 20 | 15 | 5 | 1500 | SF | \$30.00 \$45,000 | | | \$45,000 | | | | | | | | | | | | | \$4 |
| 5040 Throughout Building | 9318721 Emergency & Exit Lighting System, Full Interior Upgrade, LED, Replace | 10 | 5 | 5 | 78386 | SF | \$0.65 \$50,951 | | | \$50,951 | | | | | | | | \$50,951 | | | | | \$10° |
| 5040 Throughout Building | 9318742 Interior Lighting System, Full Upgrade, High Density & Standard Fixtures, Replace | 20 | 10 | 10 | 78386 | SF | \$5.00 \$391,930 | | | | | | | \$391,930 | | | | | | | | | \$39 |
| 5040 Building Exterior | 9318730 Exterior Light, any type, w/ LED Replacement, Replace | 20 | 10 | 10 | 10 | EA | \$800.00 \$8,000 | | | | | | | \$8,000 | | | | | | | | | \$8 |
| 5040 Gymnasium | 9318775 High Intensity Discharge (HID) Fixtures, Metal Halide, Gymnasium Lighting, 400 W, Replace | 20 | 5 | 15 | 16 | EA | \$1,700.00 \$27,200 | | | | | | | | | | | \$27,200 | | | | | \$27 |
| 6060 Throughout Building | 9318802 Intercom/PA System, Public Address Upgrade, Facility-Wide, Replace | 20 | 5 | 15 | 78386 | SF | \$1.65 \$129,337 | | | | | | | | | | \$ | 129,337 | | | | | \$129 |
| 7030 Throughout Building | 9318704 Security/Surveillance System, Full System Upgrade, Average Density, Replace | 15 | 5 | 10 | 78386 | SF | \$2.00 \$156,772 | | | | | | | \$156,772 | | | | | | | | | \$150 |
| 7050 109 | 9318814 Fire Alarm Panel, Fully Addressable, Replace | 15 | 10 | 5 | 1 | EA | \$15,000.00 \$15,000 | | | \$15,000 | | | | | | | | | | | \$ | \$15,000 | \$30 |
| 7050 Throughout Building | 9318757 Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 20 | 15 | 5 | 78386 | SF | \$3.00 \$235,158 | | | \$235,158 | | | | | | | | | | | | | \$23 |
| 1030 Kitchen | 9318731 Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 16 | 4 | 8 | LF | \$1,000.00 \$8,000 | | \$8,000 | | | | | | | | | | | | | | \$8 |
| 1030 Kitchen | 9318813 Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 16 | 4 | 6 | LF | \$1,000.00 \$6,000 | | \$6,000 | | | | | | | | | | | | | | \$(|
| 1030 Kitchen | 9318694 Foodservice Equipment, Dairy Cooler/Wells, Replace | 15 | 10 | 5 | 1 | EA | \$3,600.00 \$3,600 | | | \$3,600 | | | | | | | | | | | | \$3,600 | \$7 |
| 1030 Kitchen | 9318674 Foodservice Equipment, Convection Oven, Single, Replace | 10 | 5 | 5 | 1 | EA | \$5,600.00 \$5,600 | | | \$5,600 | | | | | | | | \$5,600 | | | | | \$11 |
| 1030 Kitchen | 9318803 Foodservice Equipment, Walk-In, Evaporator for Refigerator/Freezer, Replace | 15 | 10 | 5 | 1 | EA | \$4,600.00 \$4,600 | | | \$4,600 | | | | | | | | | | | | \$4,600 | \$9 |
| 1030 Roof | 9318660 Foodservice Equipment, Walk-In, Condenser for Refigerator/Freezer, Replace | 15 | 10 | 5 | 1 | EA | \$6,300.00 \$6,300 | | | \$6,300 | | | | | | | | | | | | \$6,300 | \$12 |
| 1030 Kitchen | 9318755 Foodservice Equipment, Dairy Cooler/Wells, Replace | 15 | 10 | 5 | 1 | EA | \$3,600.00 \$3,600 | | | \$3,600 | | | | | | | | | | | | \$3,600 | \$ |
| 1030 Kitchen | 9318786 Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace | 15 | 10 | 5 | 1 | EA | \$1,700.00 \$1,700 | | | \$1,700 | | | | | | | | | | | | \$1,700 | \$3 |
| 1030 Kitchen | 9318703 Foodservice Equipment, Valk-In, Evaporator for Refigerator/Freezer, Replace | 15 | 10 | 5 | 1 | EA | \$4,600.00 \$4,600 | | | \$4,600 | | | | | | | | | | | | \$4,600 | \$9 |
| 1030 Kitchen | 9318718 Foodservice Equipment, Convection Oven, Double, Replace | 10 | 5 | 5 | 1 | EA | \$8,280.00 \$8,280 | | | \$8,280 | | | | | | | | \$8,280 | | | | \$4,000 | \$16 |
| | | | 45 | 5 | ' | | \$25,000.00 \$25,000 | | | | | | | | | | | \$0,200 | | | | | |
| 1030 Kitchen | 9318672 Foodservice Equipment, Walk-In, Freezer, Replace | 20 | 15 | 5 | 1 1 | EA | | | | \$25,000 | | | | | | | | | | | | | \$25 |
| 1030 Kitchen | 9318792 Foodservice Equipment, Walk-In, Refrigerator, Replace | 20 | 15 | 5 | 1 | EA . | \$15,000.00 \$15,000 | | | \$15,000 | | | | | | | | | | | | | \$15 |
| 1030 Kitchen | 9318748 Foodservice Equipment, Walk-In, Condenser for Refigerator/Freezer, Replace | 15 | 6 | 9 | 1 | EA | \$6,300.00 \$6,300 | | | * | | | \$6,300 | | | | | 04 =:: | | | | | \$6 |
| · · | as 9318787 Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted, Replace | 10 | 5 | 5 | 1 | EA | \$1,500.00 \$1,500 | | | \$1,500 | | | | | | | | \$1,500 | | | | | \$3 |
| 1070 Auditorium | 9318733 Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour, Replace | 15 | 10 | 5 | 2000 | SF | \$13.00 \$26,000 | | | \$26,000 | | | | | | | | | | | \$ | \$26,000 | \$52 |
| 1070 Gymnasium | 9318723 Basketball Backboard, Ceiling-Mounted, Operable | 30 | 20 | 10 | 4 | EA | \$7,830.00 \$31,320 | | | | | | | \$31,320 | | | | | | | | | \$31 |
| 1070 Gymnasium | 9318663 Basketball Backboard, Wall-Mounted, Fixed | 30 | 20 | 10 | 4 | EA | \$3,580.00 \$14,320 | | | | | | | \$14,320 | | | | | | | | | \$14 |
| 2010 Library | 9318791 Casework, Cabinetry, Standard, Replace | 20 | 15 | 5 | 20 | LF | \$300.00 \$6,000 | | | \$6,000 | | | | | | | | | | | | | \$6 |
| 2010 Library | 9318711 Library Shelving, Double-Faced, up to 90" Height, Replace | 20 | 10 | 10 | 75 | LF | \$480.00 \$36,000 | | | | | | | \$36,000 | | | | | | | | | \$36 |
| E2010 Library | 9318762 Library Shelving, Single-Faced, up to 90" Height, Replace | 20 | 10 | 10 | 150 | LF | \$330.00 \$49,500 | | | | | | | \$49,500 | | | | | | | | | \$49 |
| E2010 Throughout Building | 9318689 Casework, Cabinetry, Standard, Replace | 20 | 10 | 10 | 200 | LF | \$300.00 \$60,000 | | | | | | | \$60,000 | | | | | | | | | \$60, |

5/28/2025

| Uniforma Code | t Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | /Unit | Unit Cost* | Subtotal | 2025 2026 | 2027 | 2028 | 2029 | 2030 2 | 031 203 | 32 203 | 3 2034 | 203 | 5 2036 | 2037 | 2038 2 | 2039 2040 | 2041 | 2042 | 2043 2 | 044 204 | 45 | iciency Repair stimate |
|------------------|------------------------------|----------|--|-------------------|------|-----|----------|-------|-------------|----------|-------------------|----------|-----------|-----------|---------------------|---------|--------|------------|-------------|-----------|---------|--------------|----------------------|-------------|--------|--------|----------------|-----------|------------------------------|
| F1020 | Building Exterior | 930700 | Ancillary Building, Wood-Framed or CMU, Basic/Minimal, Replace | 35 | 34 | 1 | 200 | SF | \$60.00 | \$12,000 | \$12,000 | | | | | | | | | | | | | | | | | \$ | 12,000 |
| Y1090 | Throughout | 937702 | ADA Miscellaneous, Level III Study, Includes Measurements, Evaluate/Report | 0 | 0 | 0 | 1 | EA | \$7,500.00 | \$7,500 | \$7,500 | | | | | | | | | | | | | | | | | : | \$7,500 |
| Y1090 | Throughout | 937702 | ADA Miscellaneous, Lump Sum Budget, Allowance, Upgrade | 0 | 0 | 0 | 1 | EA | \$20,000.00 | \$20,000 | \$20,000 | | | | | | | | | | | | | | | | | \$ | 20,000 |
| Totals, U | nescalated | | | | | | | | | | \$32,600 \$12,000 | \$32,000 | \$123,400 | \$841,965 | \$1,268,009 \$402,1 | 130 \$ | 0 \$ | 0 \$7,700 | \$1,614,646 | \$218,300 | \$0 \$2 | 2,400 \$184, | ,600 \$1,606,051 \$4 | 136,400 \$ | 66,000 | \$0 | \$0 \$623,27 | 70 \$7,4 | 71,471 |
| Totals, E | scalated (3.0% inflation, co | ompounde | d annually) | | | | | | | | \$32,600 \$12,360 | \$33,949 | \$134,843 | \$947,639 | \$1,469,970 \$480,1 | 164 \$ | 0 \$ | 0 \$10,047 | \$2,169,949 | \$302,178 | \$0 \$: | 3,524 \$279, | ,224 \$2,502,175 \$7 | 700,294 \$1 | 09,088 | \$0 | \$0 \$1,125,69 | 95 \$10,3 | 13,699 |

| Uniformat Code | Location Description | ID Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | /Unit | Unit Co | st* Subtotal | 2025 | 2026 20 | 20 20 | 28 202 | 29 2030 | 2031 | 2032 | 2033 | 2034 | 2035 203 | 6 2037 | 2038 | 2039 | 2040 2 | 2041 2042 | 2 2043 204 | 4 2045 Def | ficiency Repa Estima |
|-------------------|----------------------------|--|-------------------|------|-----|----------|-------|----------|---------------|----------|------------|------------|--------|-------------|------|----------|----------|----------|----------|----------------|------------|------------|----------|--------------|--------------|------------|-------------------------|
| F1020 | Site General | 9306794 Covered Walkway, Metal-Framed, Light/Medium Gauge, Prep & Paint | 10 | 5 | 5 | 1900 | SF | \$2 | .74 \$5,206 | | | | | \$5,206 | | | | | | | | | \$5,206 | | | | \$10,41 |
| F1020 | Site | 9318758 Ancillary Building, Classroom/Office Module, Basic/Portable, Replace | 25 | 10 | 15 | 1600 | SF | \$100 | .00 \$160,000 | | | | | | | | | | | | | \$1 | 160,000 | | | | \$160,00 |
| F1020 | Site | 9318722 Ancillary Building, Classroom/Office Module, Standard/Permanent, Replace | 35 | 20 | 15 | 900 | SF | \$200 | .00 \$180,000 | | | | | | | | | | | | | \$1 | 180,000 | | | | \$180,00 |
| G2020 | Site Parking Areas | 9306783 Parking Lots, Pavement, Asphalt, Cut & Patch | 0 | 0 | 0 | 10000 | SF | \$5 | .50 \$55,000 | \$55,000 | | | | | | | | | | | | | | | | | \$55,00 |
| G2020 | Site Parking Areas | 9306792 Parking Lots, Pavement, Asphalt, Seal & Stripe | 5 | 3 | 2 | 28195 | SF | \$0 | .45 \$12,688 | | \$12,6 | 88 | | | | \$12,688 | | | | \$12,688 | | | | \$12,688 | | | \$50,7 |
| G2020 | Site Parking Areas | 9306785 Parking Lots, Pavement, Asphalt, Mill & Overlay | 25 | 23 | 2 | 18195 | SF | \$3 | .50 \$63,683 | | \$63,6 | 83 | | | | | | | | | | | | | | | \$63,6 |
| G2030 | Site Parking Areas | 9306768 Sidewalk, Concrete, Large Areas, Replace | 50 | 36 | 14 | 8871 | SF | \$9 | .00 \$79,839 | | | | | | | | | | | | \$7 | 79,839 | | | | | \$79,8 |
| G2050 | Site Sports Fields & Court | s 9306784 Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe | 5 | 3 | 2 | 7190 | SF | \$0 | .45 \$3,236 | | \$3,2 | 36 | | | | \$3,236 | | | | \$3,236 | | | | \$3,236 | | | \$12,94 |
| G2050 | Site Sports Fields & Court | s 9306779 Sports Apparatus, Baseball, Backstop Chain-Link, Replace | 20 | 17 | 3 | 1 | EA | \$5,000 | .00 \$5,000 | | | \$5,00 | 00 | | | | | | | | | | | | | | \$5,0 |
| G2050 | Site Sports Fields & Court | s 9306773 Sports Apparatus, Basketball, Backboard w/ Pole, Replace | 25 | 15 | 10 | 4 | EA | \$4,750 | .00 \$19,000 | | | | | | | | | \$19 | ,000 | | | | | | | | \$19,0 |
| G2050 | Play Area | 9306787 Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay | 25 | 10 | 15 | 7190 | SF | \$3 | .50 \$25,165 | | | | | | | | | | | | | \$ | \$25,165 | | | | \$25,1 |
| G2050 | Site Playground Areas | 9306778 Playground Surfaces, Engineered Wood Fiber Chips, 3" Depth, Replace | 5 | 2 | 3 | 9650 | SF | \$1 | .00 \$9,650 | | | \$9,6 | 50 | | | | \$9,650 | | | \$ | 9,650 | | | | \$9,650 | | \$38,6 |
| G2050 | Site Playground Areas | 9306775 Play Structure, Multipurpose, Small, Replace | 20 | 5 | 15 | 1 | EA | \$10,000 | .00 \$10,000 | | | | | | | | | | | | | \$ | \$10,000 | | | | \$10,0 |
| G2050 | Site Playground Areas | 9306776 Play Structure, Multipurpose, Large, Replace | 20 | 5 | 15 | 1 | EA | \$35,000 | .00 \$35,000 | | | | | | | | | | | | | \$ | \$35,000 | | | | \$35,0 |
| G2050 | Site Playground Areas | 9306791 Play Structure, Multipurpose, Medium, Replace | 20 | 5 | 15 | 1 | EA | \$20,000 | .00 \$20,000 | | | | | | | | | | | | | \$ | \$20,000 | | | | \$20,0 |
| G2050 | Site Playground Areas | 9306774 Play Structure, Multipurpose, Large, Replace | 20 | 5 | 15 | 1 | EA | \$35,000 | .00 \$35,000 | | | | | | | | | | | | | \$ | \$35,000 | | | | \$35,0 |
| G2060 | Site General | 9306793 Bike Rack, Fixed 1-5 Bikes, Replace | 20 | 2 | 18 | 2 | EA | \$600 | .00 \$1,200 | | | | | | | | | | | | | | | | \$1,200 | | \$1,2 |
| G2060 | Site General | 9306782 Fences & Gates, Fence, Chain Link 4', Replace | 40 | 20 | 20 | 173 | LF | \$18 | .00 \$3,114 | | | | | | | | | | | | | | | | | \$3,114 | \$3,1 |
| G2060 | Site General | 9306780 Signage, Property, Monument, Replace/Install | 20 | 18 | 2 | 1 | EA | \$3,000 | .00 \$3,000 | | \$3,0 | 00 | | | | | | | | | | | | | | | \$3,0 |
| G2060 | Exterior | 9306770 Signage, Property, Building-Mounted Individual Letters, Replace/Install | 20 | 15 | 5 | 32 | EA | \$150 | .00 \$4,800 | | | | | \$4,800 | | | | | | | | | | | | | \$4,8 |
| G2060 | Site | 9306771 Flagpole, Metal, Replace | 30 | 20 | 10 | 2 | EA | \$2,500 | .00 \$5,000 | | | | | | | | | \$5 | ,000 | | | | | | | | \$5,0 |
| G4050 | Site Parking Areas | 9306769 Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, 150 W, Replace/Install | 20 | 12 | 8 | 13 | EA | \$4,000 | .00 \$52,000 | | | | | | | | \$52,000 | | | | | | | | | | \$52,0 |
| G4050 | Site General | 9306789 Site Lighting, Wall Pack or Walkway Ceiling/Pole-Mounted, any type w/ LED, Higher-Lumen, Replace | e 20 | 18 | 2 | 11 | EA | \$800 | .00 \$8,800 | | \$8,8 | 00 | | | | | | | | | | | | | | | \$8,8 |
| G4050 | Site General | 9306786 Site Lighting, Wall Pack or Walkway Ceiling/Pole-Mounted, any type w/ LED, Higher-Lumen, Replace | e 20 | 10 | 10 | 15 | EA | \$800 | .00 \$12,000 | | | | | | | | | \$12 | ,000 | | | | | | | | \$12,0 |
| Y1010 | Parking Lot | 9377007 ADA Parking, Designated Stall, Pavement Markings & Signage, Install | 0 | 0 | 0 | 2 | EA | \$1,000 | .00 \$2,000 | \$2,000 | | | | | | | | | | | | | | | | | \$2,0 |
| Totals, Une | scalated | | | | | | | | | \$57,000 | \$0 \$91,4 | 06 \$14,6 | 50 \$ | \$10,006 | \$0 | \$15,923 | \$61,650 | \$0 \$36 | ,000 \$ | 0 \$15,923 \$ | 9,650 \$7 | 79,839 \$4 | 470,371 | \$0 \$15,923 | \$10,850 \$ | 0 \$3,114 | \$892,3 |
| Totals Fee | lated (3.0% inflation, com | nounded annually) | | | | | | | | \$57,000 | \$0 \$96 9 | 72 \$16,00 | 08 \$ | 50 \$11,600 | \$n | \$19,584 | \$79.006 | \$0 \$48 | 381 6 | 0 \$22,703 \$1 | A 171 \$12 | 20 764 \$* | 732 823 | \$0 \$26,319 | \$18 471 \$0 | 0 \$5,624 | \$1,268,51 |

^{*} Markup has been included in unit costs.

Appendix G:
Equipment Inventory List



| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|---------|---------|--------|-----------------------|---------------------|----------|---|-----------------|--------------|--------------|--------------|--------------|---------|-----|
| D10 Cor | nveying | | | | | | | | | | | | |
| 1 | 9318789 | D1010 | Elevator Controls | Automatic, 1 Car | | Capt. James E. Daly Jr. Elementary School / Main Building | 115 | Dover | No dataplate | No dataplate | 1989 | | |
| 2 | 9318799 | D1010 | Passenger Elevator | Hydraulic, 2 Floors | 2500 LB | Capt. James E. Daly Jr. Elementary School / Main Building | 115 | Dover | EP-150-30 | E-45834 | 1989 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------|---------|--------|----------------------------|--|----------|---|-----------------|---------------------------|------------------|--------------|--------------|---------|-----|
| D20 Plur | nbing | | | | | | | | | | | | |
| 1 | 9318719 | D2010 | Water Heater | Gas, Commercial (200 MBH) | 100 GAL | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | State Industries, Inc. | SBD100199NES 118 | 1026M001239 | 2010 | | |
| 2 | 9318808 | D2010 | Backflow Preventer | Domestic Water | 6 IN | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Watts Regulator | 709 | 24346 | | | |
| 3 | 9318737 | D2020 | Grease Trap/Interceptor | Grease Trap/Interceptor Underground | ., | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | No dataplate | No dataplate | No dataplate | | | |
| 4 | 9318750 | D2030 | Pump | Sump | 3 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|---------|---------|--------|--|-----------------------------|----------|---|-------------------|------------------|---|--------------|--------------|---------|-----|
| D30 HVA | C | | | | | | | | | | | | |
| 1 | 9318669 | D3020 | Boiler | Gas, HVAC | 1500 MBH | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Fulton | EDR-1500 | 121183 | 2016 | | |
| 2 | 9318817 | D3020 | Boiler | Gas, HVAC | 1500 MBH | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Fulton | EDR-1500 | 121179 | 2016 | | |
| 3 | 9318805 | D3020 | Boiler [B-1] | Gas, HVAC | 1500 MBH | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Fulton | EDR-1500 | 121188 | 2016 | | |
| 4 | 9318676 | D3020 | Unit Heater | Hydronic | 360 MBH | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | UHSB3601TAA1000000A | F16D31961 | 2016 | | |
| 5 | 9318677 | D3020 | Boiler Supplemental Components | Expansion Tank | 250 GAL | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | | | |
| 6 | 9318696 | D3020 | Boiler Supplemental Components [ET 1] | Expansion Tank | 250 GAL | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | | | |
| 7 | 9318671 | D3030 | Chiller | Air-Cooled | 275 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Trane | RTAE 275F UAF2 BALF N1X2 A140 0DE0 XC20 AAA1 0 | U16F9533 30 | 2016 | | |
| 8 | 9318773 | D3030 | Heat Pump | Packaged & Wall- Mounted | 3 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Building Exterior | General Electric | Inaccessible | Inaccessible | | | |
| 9 | 9318797 | D3030 | Heat Pump | Packaged & Wall- Mounted | 3 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Building Exterior | GE | Inaccessible | Inaccessible | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-------------------------------|------------------------------|----------|---|-------------------|------------------------|----------------|--------------|--------------|---------|-----|
| 10 | 9318695 | D3030 | Heat Pump | Var Refrig Vol (VRV) | 5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Ingersoll Rand | 4TVR0168B400NC | 153951035X | 2015 | | |
| 11 | 9318657 | D3030 | Split System | Condensing Unit/Heat Pump | 1 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | LG | LSU090HSV4 | 603KATM1FN93 | | | |
| 12 | 9318784 | D3030 | Split System [ACCU 6] | Condensing Unit/Heat Pump | 15 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | Trane | TTA 180H400AA | 16122XXKTA | | | |
| 13 | 9318680 | D3030 | Split System Ductless | Single Zone | .75 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | Mitsubishi Electric | MUZ-GS09NA | 2ZC00268 | | | |
| 14 | 9318725 | D3030 | Split System Ductless | Single Zone | 1 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Building Exterior | Mitsubishi Electric | MUY-GE12NA | 0000280 T | | | |
| 15 | 9318811 | D3030 | Split System Ductless | Single Zone | 1.5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | LG | LUU187HV | 602KCWC12253 | | | |
| 16 | 9318766 | D3030 | Split System Ductless | Single Zone | 1.5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Building Exterior | LG | LSU180HSV4 | 601KAMZ0YF91 | | | |
| 17 | 9318819 | D3030 | Split System Ductless [DSS 2] | Single Zone | .75 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | LG | LSU090HSV4 | 601KAMZ0SD35 | | | |
| 18 | 9318735 | D3030 | Split System Ductless [DSS 3] | Single Zone | .75 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | LG | LSU090HSV4 | 603KAGS1FN91 | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-------------------------------|---|----------|---|------------------------|--------------|-------------------------|----------------|--------------|---------|-----|
| 19 | 9318795 | D3030 | Split System Ductless [DSS 4] | Single Zone | 1 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | LG | LSU090HSV4. | Inaccessible | | | |
| 20 | 9318781 | D3030 | Split System Ductless [DSS 6] | Single Zone | 1.5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | LG | LUU187HV | Illegible | | | |
| 21 | 9318661 | D3030 | Split System Ductless [DSS 7] | Single Zone | 1.5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Courtyard | LG | LUU187HV | Illegible | | | |
| 22 | 9318777 | D3030 | Unit Ventilator | approx/nominal 2 Ton | 300 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Entryways | | | | | | 3 |
| 23 | 9318812 | D3030 | Unit Ventilator | approx/nominal 2 Ton | 500 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Throughout Building | | | | 2004 | | 15 |
| 24 | 9318665 | D3030 | Unit Ventilator | approx/nominal 2 Ton, 300 to 750 CFM | 300 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Hallways | | | | | | 5 |
| 25 | 9318655 | D3050 | Pump | Distribution, HVAC Heating Water | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |
| 26 | 9318681 | D3050 | Pump | Distribution, HVAC Heating Water | 1 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Paco | 16 20705-13/0 101-1442P | 1971119734-40B | | | |
| 27 | 9318675 | D3050 | P ump [P-1] | Distribution, HVAC Chilled or Condenser Water | 15 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-----------------------|---|----------|---|-----------------|--------------|-----------------------|-----------------|--------------|---------|-----|
| 28 | 9318809 | D3050 | Pump [P-2] | Distribution, HVAC Chilled or Condenser Water | 15 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |
| 29 | 9318736 | D3050 | Pump [P-3] | Distribution, HVAC Heating Water | 30 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |
| 30 | 9318772 | D3050 | P ump [P-4] | Distribution, HVAC Heating Water | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |
| 31 | 9318700 | D3050 | Pump [P-6] | Distribution, HVAC Heating Water | 30 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | No dataplate | No dataplate | No dataplate | 2016 | | |
| 32 | 9318666 | D3050 | P ump [P-7] | Distribution, HVAC Heating Water | 1 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Paco | 16-20705-130101-1442P | 19711197 34-40C | 2016 | | |
| 33 | 9318770 | D3050 | Pump [P-8] | Distribution, HVAC Heating Water | 1 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Paco | 16-20705-130101-1442P | 1971119734-40A | 2016 | | |
| 34 | 9318765 | D3050 | Air Handler | Exterior AHU | 6000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Trane | CSAA021UBL00 | K16E36422 | 2016 | | |
| 35 | 9318816 | D3050 | Air Handler | Exterior AHU, 4001 to 6000 CFM | 6000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Trane | CSAA012UBL00 | K16E35661 | 2016 | | |
| 36 | 9318771 | D3050 | Air Handler | Interior AHU, Easy/Moderate Access | 6000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | 220A | Trane | CSAA012UAL00 | K16E35670 | 2016 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|----------------------------|---------------------------------------|----------|---|-----------------|--------------|----------------------|--------------|--------------|---------|-----|
| 37 | 9318688 | D3050 | Air Handler [AHU 1] | Interior AHU, Easy/Moderate Access | 2400 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | 205A | Trane | CSAA010UAL00 | K16D33285 | 2016 | | |
| 38 | 9318744 | D3050 | Packaged Unit [RTU 1] | RTU, Pad or Roof- Mounted | 17.5 TON | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Valent | VPRX-210-16B-X-C-1DX | 14590362 | 2016 | | |
| 39 | 9318815 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 12" Damper | 1000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | Greenheck | GB-141-4-X | 14567667 | 2014 | | |
| 40 | 9318800 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | 2000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | No dataplate | No dataplate | No dataplate | | | |
| 41 | 9318747 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | 2000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | | | | | | |
| 42 | 9318679 | D3060 | Exhaust Fan [EF-25] | Roof or Wall-Mounted, 16" Damper | 2000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | No dataplate | No dataplate | No dataplate | | | |
| 43 | 9318715 | D3060 | Exhaust Fan [EF-27] | Roof or Wall-Mounted, 16" Damper | 2000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | No dataplate | No dataplate | No dataplate | | | |
| 44 | 9318706 | D3060 | Exhaust Fan [EF-3] | Roof or Wall-Mounted, 12" Damper | 1000 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | No dataplate | No dataplate | No dataplate | | | |
| 45 | 9318716 | D3060 | Exhaust Fan [FAN 2] | Roof or Wall-Mounted, 10" Damper | 500 CFM | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | No dataplate | No dataplate | No dataplate | | | |

| Secondary Seco | Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|--|----------|---------|--------|-----------------------|-----------------|----------|---|-------------------|------------------|--------------|--------------|--------------|---------|-----|
| 1 | D50 Elec | trical | | | | | | | | | | | | |
| Parameter Para | 1 | 9318691 | D5010 | Generator | Gas or Gasoline | 100 KW | Daly Jr. Elementary School / Main | Building Exterior | Kohler | 100REZGD | SGM32KJ4S | 2017 | | |
| Part | 2 | 9318796 | D5010 | | ATS | 400 AMP | Daly Jr. Elementary School / Main | Elec 111 | | | | | | |
| Parameter Para | 3 | 9318658 | D5010 | | ATS | 400 AMP | Daly Jr. Elementary School / Main | Elec 111 | | | | | | |
| Secondary Transformer Dry, Stepdown 25 KVA Electrical Shed Selectrical She | 4 | 9318713 | D5020 | - | Dry, Stepdown | 30 KVA | Daly Jr. Elementary School / Main | Elec 111 | Square D | Inaccessible | Inaccessible | | | |
| Parameter Prince | 5 | 9307001 | D5020 | - | Dry, Stepdown | 225 KVA | Daly Jr. Elementary School / Main | Electrical Shed | General Electric | 9T23B3877 | NA | | | |
| Parameter Policy | 6 | 9318783 | D5020 | - | Dry, Stepdown | 15 KVA | Daly Jr. Elementary School / Main | Boiler Room | LG | 9710C1001 | 1M0397513 | 2016 | | |
| 8 9318746 D5020 Secondary Transformer Dry, Stepdown 75 KVA Elementary School / Main Building Capt. James E. Daly Jr. Capt. James E. Daly Jr. Square D 75N No dataplate 1989 No dataplate 1989 No dataplate 1989 No dataplate 1989 Figure D 75N Secondary Transformer 1989 Secondary Transformer Dry, Stepdown 30 KVA Elementary School / Main School / Main Building 1989 Secondary Transformer Dry, Stepdown 30 KVA Elementary School / Main School / Main Building 1989 Square D 75N No dataplate 1989 No dataplate 1989 No dataplate 1989 Figure D 75N No dataplate 1989 Square D 75N No dataplate 1989 Figure D 75N No dataplate 1989 Figure D 75N No dataplate 1989 | 7 | 9318761 | D5020 | | Dry, Stepdown | 75 KVA | Daly Jr. Elementary School / Main | Elec 111 | Square D | 75T3HCU | No dataplate | 1989 | | |
| 9 9318678 D5020 Secondary Dry, Stepdown 30 KVA Elementary Elec 111 Square D EX30T3H 1063017079 School / Main | 8 | 9318746 | D5020 | - | Dry, Stepdown | 75 KVA | Daly Jr. Elementary School / Main | 232 | Square D | 75N | No dataplate | 1989 | | |
| | 9 | 9318678 | D5020 | | Dry, Stepdown | 30 KVA | Daly Jr. Elementary | Elec 111 | Square D | EX30T3H | 1063017079 | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|--------------------------------------|---------------------|-----------|---|-----------------|--------------|--------------|--------------|--------------|---------|-----|
| 10 | 9318740 | D5020 | Secondary Transformer | Dry, Stepdown | 112.5 KVA | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 113 | Square D | 112T3HCU | No dataplate | 1989 | | |
| 11 | 9318683 | D5020 | Secondary Transformer | Dry, Stepdown | 75 KVA | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 130 | Square D | 7513HGU | No dataplate | 1989 | | |
| 12 | 9318763 | D5020 | Switchboard | 277/480 V | 1600 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 111 | Square D | 44-02772-77 | No dataplate | 1989 | | |
| 13 | 9318684 | D5020 | Distribution Panel | 277/480 V | 800 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 113 | Square D | 5086-8 | No dataplate | 1989 | | |
| 14 | 9318714 | D5020 | Distribution Panel | 277/480 V | 800 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | 212 | Square D | 3273-81 | No dataplate | 1989 | | |
| 15 | 9318659 | D5020 | Distribution Panel | 277/480 V | 400 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 130 | Square D | 3274-6 | No dataplate | 1989 | | |
| 16 | 9307004 | D5020 | Distribution Panel [DALY] | 120/208 V | 700 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | Electrical Shed | GE | 069 X957599 | NA | | | |
| 17 | 9318776 | D5020 | Distribution Panel [RP #1] | 120/208 V | 400 AMP | Capt. James E. Daly Jr. Elementary School / Main Building | Elec 113 | Square D | 44-02772-77 | No dataplate | 1989 | | |
| 18 | 9318780 | D5030 | Variable Frequency Drive | VFD, by HP of Motor | 30 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 080904Y206 | 2016 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|--------------------------------------|---------------------|----------|---|-----------------|--------------|--------------|--------------|--------------|---------|-----|
| 19 | 9318656 | D5030 | Variable Frequency Drive | VFD, by HP of Motor | 15 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 080304Y206 | 2016 | | |
| 20 | 9318717 | D5030 | Variable Frequency Drive [VFD 12] | VFD, by HP of Motor | 10 HP | Capt. James E. Daly Jr. Elementary School / Main Building | 205A | Trane | No dataplate | 082304Y206 | 2016 | | |
| 21 | 9318705 | D5030 | Variable Frequency Drive [VFD 18] | VFD, by HP of Motor | 10 HP | Capt. James E. Daly Jr. Elementary School / Main Building | 220A | Trane | No dataplate | No dataplate | | | |
| 22 | 9318727 | D5030 | Variable Frequency Drive [VFD 2] | VFD, by HP of Motor | 15 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 080404Y206 | 2016 | | |
| 23 | 9318804 | D5030 | Variable Frequency Drive [VFD 3] | VFD, by HP of Motor | 30 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 081004Y206 | 2016 | | |
| 24 | 9318728 | D5030 | Variable Frequency Drive [VFD 4] | VFD, by HP of Motor | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 081304Y206 | | | |
| 25 | 9318685 | D5030 | Variable Frequency Drive [VFD 5] | VFD, by HP of Motor | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 081404Y206 | | | |
| 26 | 9318756 | D5030 | Variable Frequency Drive [VFD 7] | VFD, by HP of Motor | 10 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 081704Y206 | 2016 | | |
| 27 | 9318793 | D5030 | Variable Frequency Drive [VFD 8] | VFD, by HP of Motor | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 722304Y079 | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|---|---|----------|---|-----------------|--------------|--------------|------------|--------------|---------|-----|
| 28 | 9318668 | D5030 | Variable Frequency Drive [VFD 9] | VFD, by HP of Motor | 5 HP | Capt. James E. Daly Jr. Elementary School / Main Building | Boiler Room | Trane | No dataplate | 081604Y206 | | | |
| 29 | 9318775 | D5040 | High Intensity Discharge (HID) Fixtures | Metal Halide, Gymnasium Lighting, 400 W | | Capt. James E. Daly Jr. Elementary School / Main Building | Gymnasium | | | | | | 16 |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------------------------------|---------|--------|-----------------------|-------------------|----------|---|-----------------|--------------|-------------|--------------|--------------|---------|-----|
| D70 Electronic Safety & Security | | | | | | | | | | | | | |
| 1 | 9318814 | D7050 | Fire Alarm Panel | Fully Addressable | | Capt. James E. Daly Jr. Elementary School / Main Building | 109 | Honeywell | MS-9600UDLS | No dataplate | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|---------|---------|--------|--------------------------|--|----------|---|-----------------|-----------------------------|------------------|--------------|--------------|---------|-----|
| E10 Equ | ipment | | | | | | | | | | | | |
| 1 | 9318707 | E1030 | Foodservice Equipment | Commercial Kitchen, 3- Bowl | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | | | | | | |
| 2 | 9318718 | E1030 | Foodservice Equipment | Convection Oven, Double | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Blodgett | No dataplate | 071913ZA029T | | | |
| 3 | 9318674 | E1030 | Foodservice Equipment | Convection Oven, Singl | le | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Blodgett | No dataplate | 071913ZA030B | | | |
| 4 | 9318694 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | No dataplate | No dataplate | No dataplate | | | |
| 5 | 9318755 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Beverage-Air Corporation | SMF34 | No dataplate | | | |
| 6 | 9318786 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Metro | No dataplate | No dataplate | | | |
| 7 | 9318748 | E1030 | Foodservice Equipment | Walk-In, Condenser for Refigerator/Freezer | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Trenton | TEHA030L6-HT3C-F | 199102428 | 2019 | | |
| 8 | 9318660 | E1030 | Foodservice Equipment | Walk-In, Condenser for Refigerator/Freezer | | Capt. James E. Daly Jr. Elementary School / Main Building | Roof | | | | | | |
| 9 | 9318803 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refigerator/Freezer | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Bally | BA-75A-1 | 68669891 | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|--------------------------|--|----------|---|----------------------------|--------------|--------------|--------------|--------------|---------|-----|
| 10 | 9318703 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refigerator/Freezer | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | Bally | B150A-1 | 68680891 | | | |
| 11 | 9318672 | E1030 | Foodservice Equipment | Walk-In, Freezer | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | No dataplate | No dataplate | No dataplate | | | |
| 12 | 9318792 | E1030 | Foodservice Equipment | Walk-In, Refrigerator | | Capt. James E. Daly Jr. Elementary School / Main Building | Kitchen | No dataplate | No dataplate | No dataplate | | | |
| 13 | 9318787 | E1040 | Healthcare Equipment | Defibrillator (AED), Cabinet-Mounted | | Capt. James E. Daly Jr. Elementary School / Main Building | Hallways & Common Areas | | | | | | |