



**BUREAU
VERITAS**

FACILITY CONDITION ASSESSMENT

prepared for

Montgomery County Public Schools
45 West Gude Drive, Suite 4000
Rockville, MD 20850



Forest Oak Middle School
651 Saybrooke Oaks Boulevard
Gaithersburg, MD 20877

PREPARED BY:

Bureau Veritas
6021 University Boulevard, Suite 200
Ellicott City, MD 21043
800.733.0660
www.bvna.com

BV CONTACT:

Bill Champion
Senior Program Manager
443.622.5067
Bill.Champion@bureauveritas.com

BV PROJECT #:

172559.25R000-146.354

DATE OF REPORT:

May 8, 2026

ON SITE DATE:

February 23, 2026

Bureau Veritas

TABLE OF CONTENTS

1. Executive Summary	1
Property Overview and Assessment Details	1
Campus Findings and Deficiencies	2
Facility Characteristic Survey	3
Facility Condition Index (FCI) Depleted Value	4
Immediate Needs	5
Key Findings	6
Plan Types	8
2. Building Information	9
3. Site Summary	12
4. ADA Accessibility	14
5. Purpose and Scope	16
6. Opinions of Probable Costs	18
Methodology.....	18
Definitions	19
7. Certification	20
8. Appendices	21



1. Executive Summary

Property Overview and Assessment Details

General Information	
Property Type	Middle School
Number of Buildings	1
Main Address	651 Saybrooke Oaks Boulevard, Gaithersburg, MD 20877
Site Developed	1999
Outside Occupants / Leased Spaces	None
Date(s) of Visit	February 23, 2026
Management Point of Contact	Montgomery County Public Schools Greg Kellner Facilities Manager, Office of Facilities Management Direct 240.740.7746 Gregory_Kellner@mcpsmd.org
On-site Point of Contact (POC)	Elisio, Building Services Manager 240.474.6943
Assessment & Report Prepared By	William Hunt
Reviewed By	Daniel White, Technical Report Reviewer for, Bill Champion Program Manager 443.622.5067 Bill.Champion@bureauveritas.com
AssetCalc Link	Full dataset for this assessment can be found at: https://www.assetcalc.net/



Campus Findings and Deficiencies

Historical Summary

The building construction was completed in 1999 and there has not been a major renovation since that time. The most obvious improvement was roof replacement in 2023.

Architectural

The construction system appears to be a combination of steel columns and beams, and masonry load bearing walls supported by a concrete foundation. It appears structurally sound, with no significant areas of settlement or structural-related deficiencies reported or observed. The roof membranes could not be observed closely due to snow, although leaking was reported. The roof was only installed 2.5 years ago so it is under warranty. Overall, the exterior envelope systems and components were observed to be performing adequately. Some teachers have complained about mold, but there has been testing and the tests were unable to find any mold. Interior finishes have generally been replaced as needed and are anticipated for lifecycle replacement based on useful life and normal wear. Although, the paint in the building service area flooring had significantly deteriorated.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The central HVAC system is made up of boilers, chillers, and cooling tower feeding roof mounted and interior air handling units. The HVAC systems and BMS controls were reported to generally have issues. Several rooms are reported to be too hot or cold, although an exact cause was unknown. It is likely partially due to aged equipment. Most of the major equipment has exceeded their expected useful life and should be replaced in the near term.

The plumbing systems are also a mix of original and replacement, and plumbing appears adequate for the facility, with equipment and fixtures generally updated as needed. Two domestic gas water heaters are fairly new and provide hot water throughout. No significant leaks or pressure issues were reported with the plumbing system.

Electrical service equipment and systems appear generally adequate. Although exterior lighting was reportedly too dim, particularly in the rear. It is recommended to replace fixtures in the short term.

A fire alarm and sprinkler system are present.

Site

The facility's site includes asphalt paved parking and drive areas, as well as areas of concrete sidewalk. Pole lights are present throughout the site. Chain-link fencing surrounds a cooling tower and the tennis courts.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Characteristic Survey

The facility characteristics of school and associated buildings are shown below.

Indoor air quality including temperature and relative humidity level are monitored centrally. Most instructional spaces are equipped with IAQ sensors. Each general and specialty classroom has a heating, ventilation, and air conditioning (HVAC) system capable of maintaining a temperature between 68°F and 75°F and a relative humidity between 30% and 60% at full occupancy. Each general, science, and fine-arts classroom had an HVAC system that continuously moves air and is capable of maintaining a carbon dioxide level of not more than 1,200 parts per million. The temperature, relative humidity and air quality were measured at a work surface in the approximate center of the classroom.

The acoustics with the exception of physical-education spaces, each general and specialty classroom are maintainable at a sustained background sound level of less than 55 decibels. The sound levels were measured at a work surface in the approximate center of the classroom.

Each general and specialty classroom had a lighting system capable of maintaining at least 50 foot-candles of well-distributed light. The school has appropriate task lighting in specialty classrooms where enhanced visibility is required. The light levels measured at a work surface located in the approximate center of the classroom, between clean light fixtures. The school makes efficient use of natural light for students, teachers, and energy conservation.

Classroom spaces, including those for physical education, were sufficient for educational programs that are appropriate for the class-level needs. With the exception of physical-education spaces, each general and specialty classroom contained a work surface and seat for each student in the classroom. The work surface and seat were appropriate for the normal activity of the class conducted in the room.

Each general and specialty classroom had an erasable surface and a surface suitable for projection purposes, appropriate for group classroom instruction, and a display surface. Each general and specialty classroom had storage for classroom materials or access to conveniently located storage.

With the exception of physical-education spaces and music-education spaces, each general and specialty classroom shall had a work surface and seat for the teacher and for any aide assigned to the classroom. The classroom had secure storage for student records that is located in the classroom or is conveniently accessible to the classroom.

The school was constructed with sustainable design practices. The schools use durable, timeless, low-maintenance exterior materials. The school's materials (particularly shell) should withstand time as well as potential impacts related to structural, site and climate changes.

The school is functionally equitable. All students in this school have access to safe, well-maintained, and appropriately equipped learning environments as students in other MCPS schools. As part of the evaluation factor, the MDCl will be presented upon final of all assessments.

Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values. A School Facility with full estimated life of all systems (a brand new school) would have a 0 FCI. The FCIs cannot exceed 1.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

The FCI Depleted Value of this school is 0.50504.

Immediate Needs

There are no immediate needs to report.



Key Findings



Parking Lots in Poor Condition.

Pavement, Asphalt
Site Forest Oak Middle School Site

Uniformat Code: G2020
Recommendation: **Seal & Stripe in 2027**

Priority Score: **84.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$22,500

\$\$\$\$

Pavement displays excessive cracking throughout. - AssetCALC ID: 10399538



Athletic Surfaces & Courts in Poor Condition.

Tennis/Volleyball, 2-Color Surface
Site Forest Oak Middle School Site

Uniformat Code: G2050
Recommendation: **Seal & Stripe in 2027**

Priority Score: **82.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$30,000

\$\$\$\$

Play court displays excessive cracking and general surface deterioration. - AssetCALC ID: 10399534



Exterior Light in Poor Condition.

Any type, with LED Replacement
Main Building Forest Oak Middle School
Building Exterior

Uniformat Code: D5040
Recommendation: **Replace in 2026**

Priority Score: **81.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$16,000

\$\$\$\$

Site exterior lighting is aged and overall illumination is inadequate. - AssetCALC ID: 10399372



Foodservice Equipment in Poor Condition.

Walk-In, Freezer
Main Building Forest Oak Middle School
Kitchen

Uniformat Code: E1030
Recommendation: **Replace in 2027**

Priority Score: **81.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$25,000

\$\$\$\$

Freezer has exceeded EUL and has recurring issues according to staff. - AssetCALC ID: 10394540



Foodservice Equipment in Poor Condition.

Food Warmer, Proofing Cabinet on Wheels
Main Building Forest Oak Middle School
Kitchen

Uniformat Code: E1030
Recommendation: **Replace in 2027**

Priority Score: **81.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$1,700

\$\$\$\$

The units are not heating as originally designed. - AssetCALC ID: 10394561



Foodservice Equipment in Poor Condition.

Food Warmer, Proofing Cabinet on Wheels
Main Building Forest Oak Middle School
Kitchen

Uniformat Code: E1030
Recommendation: **Replace in 2027**

Priority Score: **81.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$1,700

\$\$\$\$

Unit is having intermittent operational issue. - AssetCALC ID: 10394567



Flooring in Poor Condition.

Any surface, with Paint or Sealant
Main Building Forest Oak Middle School
Building Service and Boiler Room

Uniformat Code: C2030
Recommendation: **Prep & Paint in 2027**

Priority Score: **81.7**

Plan Type:
Performance/Integrity

Cost Estimate: \$10,500

\$\$\$\$


Floor paint is significantly worn away. - AssetCALC ID: 10399382

Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.


Plan Type Descriptions & Distribution

Safety	■	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	■	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	■	Does not meet ADA, UFAS, and/or other accessibility requirements.
Environmental	■	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Retrofit/Adaptation	■	Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs.
Aged But Functional	■	Any component or system that has aged past its industry-average expected useful life (EUL) but is not currently deficient or problematic.
Lifecycle/Renewal	■	Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted.



10-YEAR TOTAL: \$6,033,100

2. Building Information



Main Building: Systems Summary

Address	651 Saybrooke Oaks Boulevard, Gaithersburg, MD 20877	
GPS Coordinates	39°09'14.97" N ; 77°11'06.50" W	
Constructed/Renovated	1999	
Building Area	132,259 SF	
Number of Stories	2 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
Structure	Steel columns, beams, and masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system	Good
Façade	Primary Wall Finish: Brick Windows: Aluminum	Fair
Roof	Primary: Flat construction with modified bituminous finish Secondary: Gable construction with asphalt shingles	Good
Interiors	Walls: Painted gypsum board, painted CMU Floors: Carpet, VCT, wood strips, painted concrete Ceilings: ACT, unfinished/exposed	Fair
Elevators	Passenger: 1 hydraulic cars serving 2 floors	Fair

Main Building: Systems Summary		
Plumbing	Distribution: Copper supply piping and waste & ventilation piping Hot Water: Gas water heater with integral tank Fixtures: Toilets, urinals, and sinks in restrooms	Fair
HVAC	Central System: Boilers, chillers feeding AHUs, hydronic cabinet terminal units, FCUs Non-Central System: Split systems	Fair
Fire Suppression	Sprinkler system and fire extinguishers	Fair
Electrical	Source & Distribution: Main switchboard with copper wiring Interior Lighting: LED, linear fluorescent Exterior Building-Mounted Lighting: LED, HPS, CFL Emergency Power: Diesel generator with automatic transfer switch	Fair
Fire Alarm	Alarm panel with smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
Equipment/Special	Commercial kitchen equipment	Fair
Accessibility	Presently it does not appear an accessibility study is needed for this building. See the appendix for associated photos and additional information.	
Additional Studies	No additional studies are currently recommended for the building.	
Areas Observed	Most of the interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the building, the exterior walls of the facility, and the roof.	
Key Spaces Not Observed	None	

The table below shows the anticipated costs by trade or building system over the next 20 years.

System Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
Structure	-	-	-	-	-	-
Facade	-	-	-	-	\$106,000	\$106,000
Roofing	-	-	-	-	\$2,337,800	\$2,337,800
Interiors	-	\$11,100	\$20,200	\$1,384,500	\$748,300	\$2,164,100
Conveying	-	-	\$100,000	-	\$15,800	\$115,800
Plumbing	-	-	-	\$132,700	\$1,177,300	\$1,310,000
HVAC	-	\$10,600	\$98,400	\$1,265,200	\$1,657,700	\$3,031,900
Fire Protection	-	-	\$11,800	\$179,300	-	\$191,100
Electrical	-	\$16,500	\$199,200	\$895,700	\$698,500	\$1,809,900
Fire Alarm & Electronic Systems	-	-	-	\$374,500	\$851,300	\$1,225,800
Equipment & Furnishings	-	\$30,100	\$68,800	\$126,900	\$154,400	\$380,200
TOTALS (3% inflation)	-	\$68,300	\$498,400	\$4,358,800	\$7,747,000	\$12,672,500

3. Site Summary



Site Information		
Site Area	41.2 acres	
Parking Spaces	Around 110 spaces in lot	
<i>System</i>	<i>Description</i>	<i>Condition</i>
Site Pavement	Asphalt parking lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalk	Fair
Site Development	Building-mounted signage; chain link fencing Playgrounds and sports fields Limited park benches, picnic tables, trash receptacles	Fair
Landscaping & Topography	Limited landscaping features including lawns, trees, and bushes Irrigation not present Low to moderate site slopes throughout	Good
Utilities	Municipal water and sewer Local utility-provided electric and natural gas	Good
Site Lighting	Pole-mounted: LED, HPS	Fair
Ancillary Structures	None	--
Site Accessibility	Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information.	

Site Information	
Site Additional Studies	No additional studies are currently recommended for the exterior site areas.
Site Areas Observed	Most of the exterior areas within the property boundaries were observed to gain a clear understanding of the site’s overall condition.
Site Key Spaces Not Observed	All key areas of the exterior site were accessible and observed.

The table below shows the anticipated costs by trade or site system over the next 20 years.

System Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
HVAC	-	-	\$28,500	-	\$216,700	\$245,300
Site Development	-	\$31,800	-	\$51,900	\$57,500	\$141,200
Site Pavement	-	\$23,900	-	\$27,700	\$311,500	\$363,100
Site Utilities	-	-	-	\$38,200	-	\$38,200
TOTALS (3% inflation)	-	\$55,700	\$28,500	\$117,800	\$585,700	\$787,700



4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The following table summarizes the accessibility conditions of the general site and each significant building or building group included in this report:

Accessibility Summary			
<i>Facility</i>	<i>Year Built/ Renovated</i>	<i>Prior Study Provided?</i>	<i>Major/Moderate Issues Observed?</i>
General Site	1999	No	No
Main Building	1999	No	No

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.



5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

6. Opinions of Probable Costs

Cost estimates are embedded throughout this report, including the detailed Replacement Reserves report in the appendix. The cost estimates are predominantly based on construction rehabilitation costs developed by the *RSMeans data from Gordian*. While the *RSMeans data from Gordian* is the primary reference source for the Bureau Veritas cost library, secondary and supporting sources include but are not limited to other industry experts work, such as *Marshall & Swift* and *CBRE Whitestone*. For improved accuracy, additional research integrated with Bureau Veritas's historical experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions also come into play when deemed necessary. Invoice or bid documents provided either by the owner or facility construction resources may be reviewed early in the process or for specific projects as warranted.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

To account for differences in prices between locations, the base costs are modified by geographical location factors to adjust for market conditions, transportation costs, or other local contributors. When requested by the client, the costs may be further adjusted by several additional factors including; labor rates (prevailing minimum wage), general contractor fees for profit and overhead, and insurance. If desired, costs for design and permits, and a contingency factor, may also be included in the calculations.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

7. Certification

Montgomery County Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Forest Oak Middle School, 651 Saybrooke Oaks Boulevard, Gaithersburg, MD 20877, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.


No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: William Hunt
Project Assessor

Reviewed by:



Daniel White
Technical Report Reviewer for,
Bill Champion
Program Manager
443.622.5067
Bill.Champion@bureauveritas.com

8. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan(s)
- Appendix C: Pre-Survey Questionnaire(s)
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List



Appendix A:

Photographic Record

Photographic Overview



1 - FRONT ELEVATION




2 - LEFT ELEVATION




3 - REAR ELEVATION



4 - RIGHT ELEVATION



5 - MAIN ENTRANCE



6 - CAFETERIA

Photographic Overview




7 - MEDIA CENTER




8 - GYMNASIUM



9 - COMMERCIAL KITCHEN



10 - TYPICAL HALLWAY



11 - RESTROOM



12 - ELEVATOR

Photographic Overview



13 - BOILER



14 - CHILLER




15 - TYPICAL PUMP



16 - WATER HEATER



17 - FIRE ALARM PANEL



18 - SWITCHBOARD


Photographic Overview



19 - DISTRIBUTION PANEL




20 - TRANSFORMER



21 - GENERATOR



22 - ROOFTOP PACKAGED UNIT



23 - AIR COMPRESSOR



24 - COOLING TOWER

Photographic Overview



25 - SPORTS FIELDS



26 - BASKETBALL COURT



27 - PARKING LOT



28 - SIDE PARKING LOT



29 - REAR SITE




30 - TENNIS COURTS



Appendix B:

Site Plan(s)



Site Plan



 BUREAU VERITAS	Project Number	Project Name	 N
	172559.25R000-146.354	Forest Oak Middle School	
	Source	On-Site Date	
	Google	February 23, 2026	

Appendix C:

Pre-Survey Questionnaire(s)

BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

Building / Facility Name: Forest Oak Middle School

Name of person completing form: Elisio

Title / Association w/ property: Building Services Manager

Length of time associated w/ property: 1.5 years

Date Completed: 2/24/2026

Phone Number: 2404746943

Method of Completion: INTERVIEW - verbally completed during interview

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.


Data Overview		Response		
1	Year(s) constructed	Constructed 1995	Renovated	
2	Building size in SF	SF		
3	Major Renovation/Rehabilitation		Year	Additional Detail
		Facade		
		Roof		
		Interiors		
		HVAC		
		Electrical		
		Site Pavement		
		Accessibility		
4	List other significant capital improvements (focus on recent years; provide approximate date).	Just did a water audit		
5	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?			
6	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.	HVAC is not good, some classrooms overheat some don't heat enough. Not sure what. Actuators get stuck, Motors burn out.		

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

Question		Response				Comments
		Yes	No	Unk	NA	
7	Are there any problems with foundations or structures, like excessive settlement?		X			
8	Are there any wall, window, basement or roof leaks?	X				Roof leaks, ongoing. New roof put in 2.5 years ago. They just retarred an area, still under warranty
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints?	X				Have had teachers complain about mold but people come out and test and they couldn't find any
10	Are your elevators unreliable, with frequent service calls?		X			
11	Are there any plumbing leaks, water pressure, or clogging/backup issues?		X			
12	Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service?		X			
13	Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas?	X				Some are too hot some are too cold
14	Is the electrical service outdated, undersized, or problematic?		X			
15	Are there any problems or inadequacies with exterior lighting?	X				Not very bright, especially in the back.
16	Is site/parking drainage inadequate, with excessive ponding or other problems?	X				Slight ponding issues, none big. By staff parking lot water will pool
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?				X	
18	ADA: Has an accessibility study been previously performed? If so, when?			X		
19	ADA: Have any ADA improvements been made to the property since original construction? Describe.		X			
20	ADA: Has building management reported any accessibility-based complaints or litigation?		X			
21	Are any areas of the property leased to outside occupants?		X			



Signature of Assessor



Signature of POC

Appendix D: Accessibility Review and Photos

Visual Checklist - 2010 ADA Standards for Accessible Design

Property Name: Forest Oak Middle School

BV Project Number: 172559.25R000-146.354

Abbreviated Accessibility Checklist

Facility History & Interview

Question		Yes	No	Unk	Comments
1	Has an accessibility study been previously performed? If so, when?			X	
2	Have any ADA improvements been made to the property since original construction? Describe.		X		
3	Has building management reported any accessibility-based complaints or litigation?		X		

Abbreviated Accessibility Checklist

Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



2ND AREA OF ACCESSIBLE PARKING

Question		Yes	No	NA	Comments
1	Does the required number of standard ADA designated spaces appear to be provided ?	✘			
2	Does the required number of van-accessible designated spaces appear to be provided ?	✘			
3	Are accessible spaces on the shortest accessible route to an accessible building entrance ?	✘			
4	Does parking signage include the International Symbol of Accessibility ?	✘			
5	Does each accessible space have an adjacent access aisle ?	✘			
6	Do parking spaces and access aisles appear to be relatively level and without obstruction ?	✘			

Abbreviated Accessibility Checklist

Exterior Accessible Route



ACCESSIBLE PATH



ACCESSIBLE PATH

Question		Yes	No	NA	Comments
1	Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ?	✗			
2	Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ?	✗			
3	Are curb ramps present at transitions through raised curbs on all accessible routes?	✗			
4	Do curb ramps appear to have compliant slopes for all components ?	✗			
5	Do ramp runs on an accessible route appear to have compliant slopes ?			✗	
6	Do ramp runs on an accessible route appear to have a compliant rise and width ?			✗	

7	Do ramps on an accessible route appear to have compliant end and intermediate landings ?			X	
8	Do ramps and stairs on an accessible route appear to have compliant handrails?			X	
9	For stairways that are open underneath, are permanent barriers present that prevent or discourage access?			X	

Abbreviated Accessibility Checklist

Building Entrances



ACCESSIBLE ENTRANCE



DOOR HARDWARE

Question		Yes	No	NA	Comments
1	Do a sufficient number of accessible entrances appear to be provided ?	✗			
2	If the main entrance is not accessible, is an alternate accessible entrance provided?			✗	
3	Is signage provided indicating the location of alternate accessible entrances ?			✗	
4	Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ?	✗			
5	Do doors at accessible entrances appear to have compliant hardware ?	✗			
6	Do doors at accessible entrances appear to have a compliant clear opening width ?	✗			

7	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ?	X			
8	Do thresholds at accessible entrances appear to have a compliant height ?	X			

Abbreviated Accessibility Checklist

Interior Accessible Route



ACCESSIBLE INTERIOR PATH



DOOR HARDWARE

Question		Yes	No	NA	Comments
1	Does an accessible route appear to connect all public areas inside the building ?	✗			
2	Do accessible routes appear free of obstructions and/or protruding objects ?	✗			
3	Do ramps on accessible routes appear to have compliant slopes ?			✗	
4	Do ramp runs on an accessible route appear to have a compliant rise and width ?			✗	
5	Do ramps on accessible routes appear to have compliant end and intermediate landings ?			✗	
6	Do ramps on accessible routes appear to have compliant handrails ?			✗	

7	Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ?			X	
8	Do public transaction areas have an accessible, lowered service counter section ?			X	
9	Do public telephones appear mounted with an accessible height and location ?			X	
10	Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ?	X			
11	Do doors at interior accessible routes appear to have compliant hardware ?	X			
12	Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ?	X			
13	Do doors on interior accessible routes appear to have a compliant clear opening width ?	X			

Abbreviated Accessibility Checklist

Elevators



LOBBY LOOKING AT CABS (WITH DOORS OPEN)



IN-CAB CONTROLS

Question		Yes	No	NA	Comments
1	Are hallway call buttons configured with the "UP" button above the "DOWN" button?	✗			
2	Is accessible floor identification signage present on the hoistway sidewalls on each level ?	✗			
3	Do the elevators have audible and visual arrival indicators at the lobby and hallway entrances?	✗			
4	Do the elevator hoistway and car interior appear to have a minimum compliant clear floor area ?	✗			
5	Do the elevator car doors have automatic re-opening devices to prevent closure on obstructions?	✗			
6	Do elevator car control buttons appear to be mounted at a compliant height ?	✗			

7	Are tactile and Braille characters mounted to the left of each elevator car control button ?	X			
8	Are audible and visual floor position indicators provided in the elevator car?	X			
9	Is the emergency call system on or adjacent to the control panel and does it not require voice communication ?	X			

Abbreviated Accessibility Checklist

Public Restrooms



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

Question		Yes	No	NA	Comments
1	Do publicly accessible toilet rooms appear to have a minimum compliant floor area ?	✗			
2	Does the lavatory appear to be mounted at a compliant height and with compliant knee area ?	✗			
3	Does the lavatory faucet have compliant handles ?	✗			
4	Is the plumbing piping under lavatories configured to protect against contact ?	✗			
5	Are grab bars provided at compliant locations around the toilet ?	✗			
6	Do toilet stall doors appear to provide the minimum compliant clear width ?	✗			

7	Do toilet stalls appear to provide the minimum compliant clear floor area ?	X			
8	Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ?	X			
9	Do accessories and mirrors appear to be mounted at a compliant height ?	X			

Abbreviated Accessibility Checklist

Playgrounds & Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

Question		Yes	No	NA	Comments
1	Is there an accessible route to the play area / s?	✗			
2	Has the play area been reviewed for accessibility ?			✗	Unknown
3	Are publicly accessible swimming pools equipped with an entrance lift ?			✗	

Appendix E:

Component Condition Report

Component Condition Report | Forest Oak Middle School / Main Building

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
Structure						
A4010	Throughout Building	Good	Foundation, Concrete, Standard w/ Integral Perimeter Footings, w/ Integral Perimeter Footings	132,259 SF	49	10399381
B1010	Throughout Building	Good	Structural Framing, Masonry (CMU) Bearing Walls, 1-2 Story Building, 1-2 Story Building	132,259 SF	49	10399379
Facade						
B2010	Building Exterior	Fair	Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain	30,000 SF	11	10399380
B2050	Building Exterior	Fair	Exterior Door, Aluminum-Framed & Glazed, Standard Swing	16	11	10399378
Roofing						
B3010	Roof	Fair	Roofing, Asphalt Shingle, 30-Year Premium	5,000 SF	19	10399377
B3010	Roof	Fair	Roofing, Built-Up	96,000 SF	18	10394554
B3060	Roof	Good	Roof Hatch, Metal	3	29	10394596
Interiors						
C1030	Throughout Building	Fair	Interior Door, Wood, Solid-Core	150	16	10394548
C1070	Throughout Building	Fair	Suspended Ceilings, Acoustical Tile (ACT)	92,580 SF	7	10394514
C2010	Throughout Building	Fair	Wall Finishes, any surface, Prep & Paint	198,390 SF	6	10394569
C2030	Gymnasium	Fair	Flooring, Wood, Sports, Refinish	5,000 SF	5	10394580
C2030	Building Service and Boiler Room	Poor	Flooring, any surface, w/ Paint or Sealant, Prep & Paint	7,000 SF	2	10399382
C2030	Media Center	Fair	Flooring, Carpet, Commercial Standard	5,000 SF	6	10394564
C2030	Throughout Building	Fair	Flooring, Vinyl Tile (VCT)	95,280 SF	7	10394553
Conveying						
D1010	Elevator Shafts/Utility	Fair	Passenger Elevator, Hydraulic, 3 Floors, 3500 LB, Renovate	1	4	10394591
D1010	Elevator Shafts/Utility	Fair	Elevator Controls, Automatic, 1 Car	1	3	10394525
D1010	Elevator Shafts/Utility	Fair	Elevator Cab Finishes, Standard	1	4	10394542
Plumbing						
D2010	Restrooms	Fair	Toilet, Commercial Water Closet	50	11	10394520

Component Condition Report | Forest Oak Middle School / Main Building

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
D2010	Restrooms	Fair	Urinal, Standard	20	16	10394590
D2010	Throughout Building	Fair	Drinking Fountain, Wall-Mounted, Bi-Level	8	9	10394587
D2010	Boiler Room	Good	Water Heater, Gas, Commercial (200 MBH), 193 GAL	1	15	10394529
D2010	Throughout Building	Fair	Plumbing System, Supply & Sanitary, Low Density (excludes fixtures)	132,259 SF	14	10394601
D2010	Restrooms	Fair	Sink/Lavatory, Wall-Hung, Enameled Steel	50	9	10394505
D2010	Boiler Room	Good	Water Heater, Gas, Commercial (200 MBH), 193 GAL	1	15	10394532
D2060	Boiler Room	Fair	Air Compressor, Tank-Style, 0.75 HP	1	6	10394538
HVAC						
D3020	Boiler Room	Fair	Boiler, Gas, HVAC, 3769 MBH	1	6	10394557
D3020	Boiler Room	Fair	Boiler, Gas, HVAC, 3769 MBH	1	6	10394543
D3030	Throughout Building	Fair	Fan Coil Unit, Split System DX, Interior Unit, 2 to 2.5 TON, Inaccessible	8	1	10394559
D3030	Throughout Building	Fair	Fan Coil Unit, Split System DX, Interior Unit, 3 to 3.5 TON, Inaccessible	15	4	10399374
D3030	Roof	Fair	Split System, Condensing Unit/Heat Pump, 5 TON	1	8	10394555
D3030	Roof	Fair	Split System Ductless, Single Zone, Inaccessible	1	8	10394539
D3030	Boiler Room	Fair	Chiller, Water-Cooled, 151 to 200 TON, 180 TON [CHILLER-1]	1	6	10394598
D3050	Throughout Building	Fair	HVAC System, Hydronic Piping, 4-Pipe	132,259 SF	14	10394571
D3050	Throughout Building	Fair	HVAC System, Ductwork, Medium Density	132,259 SF	8	10394511
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 2 HP	1	6	10394584
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 5 HP	1	5	10394521
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 7.5 HP	1	6	10394545
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Heating Water, 30 HP	1	6	10394589
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 30 HP	1	5	10394508
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 30 HP	1	5	10394594
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 5 HP	1	5	10394531
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 7.5 HP	1	3	10394526

Component Condition Report | Forest Oak Middle School / Main Building

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Chilled or Condenser Water, 2 HP	1	6	10394558
D3050	Boiler Room	Fair	Pump, Distribution, HVAC Heating Water, 30 HP	1	6	10394562
Fire Protection						
D4010	Boiler Room	Fair	Backflow Preventer, Fire Suppression, 6 IN	1	4	10394586
D4010	Throughout Building	Fair	Fire Suppression System, Existing Sprinkler Heads, by SF	132,259 SF	8	10394597
Electrical						
D5010	Boiler Room	Fair	Generator, Diesel, 60 KW	1	4	10394573
D5010	Boiler Room	Fair	Automatic Transfer Switch, ATS, 400 AMP	1	4	10394519
D5020	E121	Fair	Distribution Panel, 277/480 V, 600 AMP	1	4	10394549
D5020	Boiler Room	Fair	Distribution Panel, 277/480 V, 800 AMP	1	4	10394547
D5020	Boiler Room	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	9	10394533
D5020	E221	Fair	Distribution Panel, 277/480 V, 400 AMP	1	7	10399373
D5020	Boiler Room	Fair	Distribution Panel, 277/480 V, 800 AMP [MDP1]	1	4	10394600
D5020	Boiler Room	Fair	Switchboard, 277/480 V, 2500 AMP	1	14	10394546
D5020	E121	Fair	Secondary Transformer, Dry, Stepdown, 45 KVA	1	4	10394536
D5020	E221	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	9	10399384
D5020	D104	Fair	Distribution Panel, 277/480 V, 800 AMP [MDP-5]	1	4	10394551
D5020	B108	Fair	Secondary Transformer, Dry, Stepdown, 45 KVA	1	6	10394570
D5020	Boiler Room	Fair	Secondary Transformer, Dry, Stepdown, 75 KVA	1	4	10394550
D5020	D104	Fair	Secondary Transformer, Dry, Stepdown, 225 KVA	1	4	10394566
D5020	D222	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	16	10399375
D5020	D104	Fair	Distribution Panel, 277/480 V, 800 AMP [MDP4]	1	4	10394560
D5020	E221	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	7	10399383
D5020	D222	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	16	10399376
D5020	E121	Fair	Secondary Transformer, Dry, Stepdown, 30 KVA	1	4	10394501

Component Condition Report | Forest Oak Middle School / Main Building

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
D5020	Boiler Room	Fair	Secondary Transformer, Dry, Stepdown, 15 KVA	1	4	10394512
D5030	Throughout Building	Fair	Electrical System, Wiring & Switches, Average or Low Density/Complexity	132,259 SF	14	10394522
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, 10 HP, Replace/Install [RTU #5]	1	6	10394527
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, 30 HP, Replace/Install [PUMP-3]	1	4	10394577
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, 30 HP, Replace/Install	1	11	10394575
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, 30 HP, Replace/Install	1	11	10394502
D5030	Boiler Room	Fair	Variable Frequency Drive, VFD, by HP of Motor, 10 HP, Replace/Install [RTU #5]	1	6	10394585
D5040	Throughout Building	Fair	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	132,259 SF	8	10394509
D5040	Building Exterior	Poor	Exterior Light, any type, w/ LED Replacement, 100 WATT	20	1	10399372
Fire Alarm & Electronic Systems						
D6060	Throughout Building	Fair	Intercom/PA System, Public Address Upgrade, Facility-Wide	132,259 SF	11	10394574
D7030	Throughout Building	Good	Security/Surveillance System, Full System Upgrade, Average Density	132,259 SF	10	10394506
D7050	B121	Fair	Fire Alarm Panel, Fully Addressable	1	8	10394556
D7050	Throughout Building	Fair	Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install	132,259 SF	11	10394535
Equipment & Furnishings						
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	3	10394581
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	8	10394515
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Single	1	3	10394507
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	3	10394518
E1030	Kitchen	Poor	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	2	10394567
E1030	Kitchen	Poor	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	2	10394561
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	4	10394524
E1030	Kitchen	Fair	Foodservice Equipment, Commercial Kitchen, 2-Bowl	1	16	10394576
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	8	10394523
E1030	Kitchen	Fair	Foodservice Equipment, Steamer, Freestanding	1	4	10394498

Component Condition Report | Forest Oak Middle School / Main Building

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
E1030	Kitchen	Poor	Foodservice Equipment, Walk-In, Freezer	1	2	10394540
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Single	1	6	10394592
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	4	10394544
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	4	10394588
E1030	Kitchen	Fair	Foodservice Equipment, Exhaust Hood, 8 to 10 LF	1	8	10394513
E1030	Kitchen	Fair	Foodservice Equipment, Commercial Kitchen, 1-Bowl	1	8	10394528
E1030	Kitchen	Fair	Foodservice Equipment, Steamer, Freestanding	1	4	10394537
E1030	Kitchen	Fair	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer	1	8	10394578
E1030	Kitchen	Fair	Foodservice Equipment, Range/Oven, 4-Burner w/ Griddle	1	8	10394541
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	3	10394595
E1030	Kitchen	Fair	Foodservice Equipment, Deep Fryer	1	8	10394572
E1030	Kitchen	Fair	Foodservice Equipment, Commercial Kitchen, 3-Bowl	1	16	10394579
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	4	10394504
E1030	Kitchen	Fair	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer	1	8	10394534
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	4	10394499
E1030	Kitchen	Fair	Foodservice Equipment, Walk-In, Refrigerator	1	11	10394500
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Double	1	6	10394565
E1030	Kitchen	Fair	Foodservice Equipment, Icemaker, Freestanding	1	6	10394510
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	4	10394530
E1030	Kitchen	Fair	Foodservice Equipment, Steamer, Freestanding	1	3	10394503
E1070	Site	Fair	Basketball Backboard, Ceiling-Mounted, Operable, Operable	6	9	10394582

Component Condition Report | Forest Oak Middle School

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
Roofing						

Component Condition Report | Forest Oak Middle School

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
B3060	Roof	Good	Roof Hatch, Metal	1	29	10909785
B3060	Roof	Good	Roof Hatch, Metal	1	29	10909811
B3060	Roof	Good	Roof Hatch, Metal	1	29	10909808
B3060	Roof	Good	Roof Hatch, Metal	1	29	10909789
HVAC						
D3030	Roof	Fair	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, 5 TON [CU 2]	1	2	10909813
D3030	Roof	Fair	Ductless Mini-Split, Multi Zone, Condenser w/ Two Evaporators of 1 TON each, 1 TON	1	11	10909815
D3030	Roof	Fair	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 1.5 to 2 TON, 1.5 TON [SS HEAT PUMP]	1	2	10909817
D3030	Roof	Fair	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, 5 TON [CU 2]	1	2	10909790
D3030	Roof	Fair	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, 5 TON [CU 2]	1	2	10909791
D3030	Roof	Fair	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 1.5 to 2 TON, 1.5 TON [SS HEAT PUMP]	1	2	10909784
D3030	Roof	Fair	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 0.75 to 1 TON, 0.75 TON	1	6	10909804
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-8]	1	3	10909786
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-10]	1	3	10909832
D3050	Roof	Fair	Make-Up Air Unit, MUA or MAU, 2000 to 6000 CFM, 4000 CFM [RTU-13]	1	2	10909805
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-5]	1	2	10909833
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-6]	1	2	10909825
D3050	roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-9]	1	2	10909823
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 6000 CFM [RTU-3]	1	2	10909827
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-12]	1	2	10909803
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-7]	1	2	10909800
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 6000 CFM [RTU-1]	1	2	10909787
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 6000 CFM [RTU-2]	1	2	10909788
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 6000 CFM [RTU-4]	1	2	10909816
D3050	Roof	Fair	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, 8000 CFM [RTU-11]	1	2	10909792

Component Condition Report | Forest Oak Middle School

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 8]	1	3	10909799
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 9]	1	2	10909796
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 10]	1	2	10909836
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 2]	1	2	10909830
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 1]	1	2	10909828
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 15]	1	2	10909795
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 16]	1	2	10909807
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 11]	1	2	10909822
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 13]	1	2	10909798
D3060	Roof	Fair	Exhaust Fan, Exterior, 24" Diameter, 2001 to 5000 CFM, 2000 CFM	1	2	10909809
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 7]	1	2	10909837
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 4]	1	2	10909806
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 21]	1	2	10909783
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 3]	1	2	10909819
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 18]	1	2	10909802
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 20]	1	2	10909818
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 14]	1	2	10909820
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 26]	1	2	10909831
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 24]	1	2	10909793
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 27]	1	2	10909797
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 23]	1	2	10909829
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 19]	1	2	10909835
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 17]	1	2	10909801
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 6]	1	2	10909810
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [PRV 12]	1	2	10909794

Component Condition Report | Forest Oak Middle School

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM	1	2	10909826
D3060	Roof	Fair	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, 500 CFM [FUME HOOD]	1	2	10909821
Equipment & Furnishings						
E1030	Roof	Good	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer	1	15	10909824
E1030	Roof	Fair	Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer	1	2	10909834

Component Condition Report | Forest Oak Middle School / Site

UF L3 Code	Location	Condition	Component/Attributes/Capacity	Quantity	RUL	ID
HVAC						
D3030	Building Exterior	Fair	Cooling Tower, (Typical) Open Circuit, 51 - 75 TON	1	5	10399531
D3030	Building Exterior	Good	Chiller, Air-Cooled, 100 TON	1	20	10399533
Pedestrian Plazas & Walkways						
G2020	Site	Fair	Parking Lots, Pavement, Asphalt, Mill & Overlay	50,000 SF	11	10399536
G2020	Site	Poor	Parking Lots, Pavement, Asphalt, Seal & Stripe	50,000 SF	2	10399538
Athletic, Recreational & Playfield Areas						
G2050	Site	Poor	Athletic Surfaces & Courts, Tennis/Volleyball, 2-Color Surface, Seal & Stripe	20,000 SF	2	10399534
G2050	Site	Fair	Sports Apparatus, Basketball, Backboard/Rim/Pole	8	8	10399535
Sitework						
G2060	Site	Fair	Park Bench, Wood/Composite/Fiberglass	5	8	10399532
G2060	Site	Fair	Flagpole, Metal	2	11	10399537
G2060	Site	Fair	Fences & Gates, Fence, Chain Link 8'	200 LF	15	10515417
G4050	Site	Fair	Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, 1000 WATT, Replace/Install	8	6	10399539

Appendix F: Replacement Reserves

Replacement Reserves Report



4/21/2026

Location	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Total Escalated Estimate
Forest Oak Middle School	\$0	\$0	\$762,973	\$140,470	\$0	\$0	\$2,048	\$0	\$0	\$0	\$0	\$4,900	\$0	\$0	\$0	\$7,837	\$0	\$38,858	\$0	\$0	\$0	\$957,086
Forest Oak Middle School / Main Building	\$0	\$27,077	\$41,269	\$41,961	\$371,137	\$85,323	\$1,036,575	\$999,186	\$1,762,265	\$205,345	\$355,490	\$1,108,777	\$14,970	\$23,643	\$3,268,728	\$78,833	\$809,178	\$5,620	\$2,306,456	\$130,812	\$0	\$12,672,645
Forest Oak Middle School / Site	\$0	\$0	\$55,697	\$0	\$0	\$28,518	\$38,210	\$27,672	\$51,938	\$0	\$0	\$249,162	\$74,852	\$0	\$0	\$7,790	\$0	\$37,189	\$0	\$0	\$216,733	\$787,762
Grand Total	\$0	\$27,077	\$859,939	\$182,431	\$371,137	\$113,841	\$1,076,832	\$1,026,859	\$1,814,202	\$205,345	\$355,490	\$1,362,840	\$89,823	\$23,643	\$3,268,728	\$94,460	\$809,178	\$81,667	\$2,306,456	\$130,812	\$216,733	\$14,417,492

Forest Oak Middle School

Uniform Code	Location	Description	ID	Cost Description	Lifespan (EUL)	Age	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate	
D3030	Roof	10909813	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, Replace		15	13	2	1	EA	\$4,550.00	\$4,550			\$4,550																		\$4,550	\$9,100	
D3030	Roof	10909817	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 1.5 to 2 TON, Replace		15	13	2	1	EA	\$2,415.00	\$2,415			\$2,415																			\$2,415	\$4,830
D3030	Roof	10909790	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, Replace		15	13	2	1	EA	\$4,550.00	\$4,550			\$4,550																			\$4,550	\$9,100
D3030	Roof	10909791	Condensing Unit/Heat Pump, Split System, Exterior, 5 TON, Replace		15	13	2	1	EA	\$4,550.00	\$4,550			\$4,550																			\$4,550	\$9,100
D3030	Roof	10909784	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 1.5 to 2 TON, Replace		15	13	2	1	EA	\$2,415.00	\$2,415			\$2,415																			\$2,415	\$4,830
D3030	Roof	10909804	Ductless Mini-Split, Single Zone, Condenser & Evaporator, 0.75 to 1 TON, Replace		15	9	6	1	EA	\$1,715.00	\$1,715								\$1,715															\$1,715
D3030	Roof	10909815	Ductless Mini-Split, Multi Zone, Condenser w/ Two Evaporators of 1 TON each, Replace		15	4	11	1	EA	\$3,540.00	\$3,540												\$3,540											\$3,540
D3050	Roof	10909805	Make-Up Air Unit, MUA or MAU, 2000 to 6000 CFM, Replace		20	18	2	1	EA	\$27,040.00	\$27,040			\$27,040																				\$27,040
D3050	Roof	10909833	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909825	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	roof	10909823	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909827	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909803	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909800	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909787	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909788	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909816	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909792	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	18	2	1	EA	\$63,700.00	\$63,700			\$63,700																				\$63,700
D3050	Roof	10909786	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	17	3	1	EA	\$63,700.00	\$63,700											\$63,700												\$63,700
D3050	Roof	10909832	Air Handler, Exterior AHU, Packaged, 6001 to 8000 CFM, Replace		20	17	3	1	EA	\$63,700.00	\$63,700											\$63,700												\$63,700
D3060	Roof	10909796	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909836	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909830	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909828	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909795	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909807	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909822	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909798	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909809	Exhaust Fan, Exterior, 24" Diameter, 2001 to 5000 CFM, Replace		20	18	2	1	EA	\$2,875.00	\$2,875			\$2,875																				\$2,875
D3060	Roof	10909837	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909806	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909783	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909819	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909802	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909818	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909820	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909831	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909793	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909797	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2	1	EA	\$1,150.00	\$1,150			\$1,150																				\$1,150
D3060	Roof	10909829	Exhaust Fan, Exterior, 10" Diameter, 50 to 500 CFM, Replace		20	18	2																											

Replacement Reserves Report



4/21/2026

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate
D4010	Throughout Building	10394597	Fire Suppression System, Existing Sprinkler Heads, by SF, Replace	25	17	8	132259	SF	\$1.07	\$141,517									\$141,517												\$141,517	
D5010	Boiler Room	10394573	Generator, Diesel, Replace	25	21	4	1	EA	\$40,000.00	\$40,000					\$40,000																\$40,000	
D5010	Boiler Room	10394519	Automatic Transfer Switch, ATS, Replace	25	21	4	1	EA	\$20,000.00	\$20,000					\$20,000																\$20,000	
D5020	E121	10394536	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$7,600.00	\$7,600					\$7,600																\$7,600	
D5020	Boiler Room	10394550	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$10,000.00	\$10,000					\$10,000																\$10,000	
D5020	D104	10394566	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$25,000.00	\$25,000					\$25,000																\$25,000	
D5020	E121	10394501	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$6,700.00	\$6,700					\$6,700																\$6,700	
D5020	Boiler Room	10394512	Secondary Transformer, Dry, Stepdown, Replace	30	26	4	1	EA	\$6,000.00	\$6,000					\$6,000																\$6,000	
D5020	B108	10394570	Secondary Transformer, Dry, Stepdown, Replace	30	24	6	1	EA	\$7,600.00	\$7,600							\$7,600														\$7,600	
D5020	E221	10399383	Secondary Transformer, Dry, Stepdown, Replace	30	23	7	1	EA	\$6,700.00	\$6,700								\$6,700													\$6,700	
D5020	Boiler Room	10394533	Secondary Transformer, Dry, Stepdown, Replace	30	21	9	1	EA	\$6,700.00	\$6,700										\$6,700											\$6,700	
D5020	E221	10399384	Secondary Transformer, Dry, Stepdown, Replace	30	21	9	1	EA	\$6,700.00	\$6,700										\$6,700											\$6,700	
D5020	Boiler Room	10394546	Switchboard, 277/480 V, Replace	40	26	14	1	EA	\$90,000.00	\$90,000															\$90,000						\$90,000	
D5020	D222	10399375	Secondary Transformer, Dry, Stepdown, Replace	30	14	16	1	EA	\$6,700.00	\$6,700																			\$6,700		\$6,700	
D5020	D222	10399376	Secondary Transformer, Dry, Stepdown, Replace	30	14	16	1	EA	\$6,700.00	\$6,700																			\$6,700		\$6,700	
D5020	E121	10394549	Distribution Panel, 277/480 V, Replace	30	26	4	1	EA	\$7,000.00	\$7,000					\$7,000																\$7,000	
D5020	Boiler Room	10394547	Distribution Panel, 277/480 V, Replace	30	26	4	1	EA	\$10,000.00	\$10,000					\$10,000																\$10,000	
D5020	Boiler Room	10394600	Distribution Panel, 277/480 V, Replace	30	26	4	1	EA	\$10,000.00	\$10,000					\$10,000																\$10,000	
D5020	D104	10394551	Distribution Panel, 277/480 V, Replace	30	26	4	1	EA	\$10,000.00	\$10,000					\$10,000																\$10,000	
D5020	D104	10394560	Distribution Panel, 277/480 V, Replace	30	26	4	1	EA	\$10,000.00	\$10,000					\$10,000																\$10,000	
D5020	E221	10399373	Distribution Panel, 277/480 V, Replace	30	23	7	1	EA	\$5,300.00	\$5,300								\$5,300													\$5,300	
D5030	Throughout Building	10394522	Electrical System, Wiring & Switches, Average or Low Density/Complexity, Replace	40	26	14	132259	SF	\$2.50	\$330,648															\$330,648						\$330,648	
D5030	Boiler Room	10394577	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	16	4	1	EA	\$14,700.00	\$14,700					\$14,700																\$14,700	
D5030	Boiler Room	10394527	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	14	6	1	EA	\$7,000.00	\$7,000							\$7,000														\$7,000	
D5030	Boiler Room	10394585	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	14	6	1	EA	\$7,000.00	\$7,000							\$7,000														\$7,000	
D5030	Boiler Room	10394575	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	9	11	1	EA	\$14,700.00	\$14,700												\$14,700									\$14,700	
D5030	Boiler Room	10394502	Variable Frequency Drive, VFD, by HP of Motor, Replace/Install	20	9	11	1	EA	\$14,700.00	\$14,700												\$14,700									\$14,700	
D5040	Building Exterior	10399372	Exterior Light, any type, w/ LED Replacement, Replace	20	19	1	20	EA	\$800.00	\$16,000	\$16,000																				\$16,000	
D5040	Throughout Building	10394509	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures, Replace	20	12	8	132259	SF	\$5.00	\$661,295									\$661,295												\$661,295	
D6060	Throughout Building	10394574	Intercom/PA System, Public Address Upgrade, Facility-Wide, Replace	20	9	11	132259	SF	\$1.65	\$218,227												\$218,227									\$218,227	
D7030	Throughout Building	10394506	Security/Surveillance System, Full System Upgrade, Average Density, Replace	15	5	10	132259	SF	\$2.00	\$264,518											\$264,518										\$264,518	
D7050	B121	10394556	Fire Alarm Panel, Fully Addressable, Replace	15	7	8	1	EA	\$15,000.00	\$15,000									\$15,000												\$15,000	
D7050	Throughout Building	10394535	Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install	20	9	11	132259	SF	\$3.00	\$396,777												\$396,777									\$396,777	
E1030	Kitchen	10394567	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	13	2	1	EA	\$1,700.00	\$1,700			\$1,700														\$1,700				\$3,400	
E1030	Kitchen	10394561	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	13	2	1	EA	\$1,700.00	\$1,700			\$1,700														\$1,700				\$3,400	
E1030	Kitchen	10394540	Foodservice Equipment, Walk-In, Freezer, Replace	20	18	2	1	EA	\$25,000.00	\$25,000			\$25,000																		\$25,000	
E1030	Kitchen	10394581	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	12	3	1	EA	\$3,600.00	\$3,600				\$3,600													\$3,600				\$7,200	
E1030	Kitchen	10394507	Foodservice Equipment, Convection Oven, Single, Replace	10	7	3	1	EA	\$5,600.00	\$5,600				\$5,600									\$5,600								\$11,200	
E1030	Kitchen	10394518	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	12	3	1	EA	\$3,600.00	\$3,600				\$3,600												\$3,600					\$7,200	
E1030	Kitchen	10394595	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	12	3	1	EA	\$3,600.00	\$3,600				\$3,600												\$3,600					\$7,200	
E1030	Kitchen	10394503	Foodservice Equipment, Steamer, Freestanding, Replace	10	7	3	1	EA	\$10,500.00	\$10,500				\$10,500									\$10,500								\$21,000	
E1030	Kitchen	10394524	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	11	4	1	EA	\$3,600.00	\$3,600					\$3,600														\$3,600		\$7,200	
E1030	Kitchen	10394498	Foodservice Equipment, Steamer, Freestanding, Replace	10	6	4	1	EA	\$10,500.00	\$10,500					\$10,500									\$10,500							\$21,000	
E1030	Kitchen	10394544	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	11	4	1	EA	\$1,700.00	\$1,700					\$1,700														\$1,700		\$3,400	
E1030	Kitchen	10394588	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	11	4	1	EA	\$1,700.00	\$1,700					\$1,700														\$1,700		\$3,400	
E1030	Kitchen	10394537	Foodservice Equipment, Steamer, Freestanding, Replace	10	6	4	1	EA	\$10,500.00	\$10,500					\$10,500										\$10,500						\$21,000	
E1030	Kitchen	10394504	Foodservice Equipment, Dairy Cooler/Wells, Replace	15	11	4	1	EA	\$3,600.00	\$3,600					\$3,600														\$3,600		\$7,200	
E1030	Kitchen	10394499	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	11	4	1	EA	\$1,700.00	\$1,700					\$1,700														\$1,700		\$3,400	
E1030	Kitchen	10394530	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	11	4	1	EA	\$1,700.00	\$1,700					\$1,700														\$1,700		\$3,400	
E1030	Kitchen	10394592	Foodservice Equipment, Convection Oven, Single, Replace	10	4	6	1	EA	\$5,600.00																							

Replacement Reserves Report



4/21/2026

Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate									
E1030	Kitchen	10394510	Foodservice Equipment, Icemaker, Freestanding, Replace	15	9	6	1	EA	\$6,700.00	\$6,700							\$6,700														\$6,700										
E1030	Kitchen	10394515	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	7	8	1	EA	\$1,700.00	\$1,700									\$1,700												\$1,700										
E1030	Kitchen	10394523	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace	15	7	8	1	EA	\$1,700.00	\$1,700									\$1,700												\$1,700										
E1030	Kitchen	10394513	Foodservice Equipment, Exhaust Hood, 8 to 10 LF, Replace	15	7	8	1	EA	\$4,500.00	\$4,500									\$4,500												\$4,500										
E1030	Kitchen	10394528	Foodservice Equipment, Commercial Kitchen, 1-Bowl, Replace	30	22	8	1	EA	\$1,600.00	\$1,600									\$1,600												\$1,600										
E1030	Kitchen	10394578	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace	15	7	8	1	EA	\$4,600.00	\$4,600									\$4,600												\$4,600										
E1030	Kitchen	10394541	Foodservice Equipment, Range/Oven, 4-Burner w/ Griddle, Replace	15	7	8	1	EA	\$6,700.00	\$6,700									\$6,700												\$6,700										
E1030	Kitchen	10394572	Foodservice Equipment, Deep Fryer, Replace	15	7	8	1	EA	\$7,000.00	\$7,000									\$7,000												\$7,000										
E1030	Kitchen	10394534	Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace	15	7	8	1	EA	\$4,600.00	\$4,600									\$4,600												\$4,600										
E1030	Kitchen	10394500	Foodservice Equipment, Walk-In, Refrigerator, Replace	20	9	11	1	EA	\$15,000.00	\$15,000											\$15,000										\$15,000										
E1030	Kitchen	10394576	Foodservice Equipment, Commercial Kitchen, 2-Bowl, Replace	30	14	16	1	EA	\$2,100.00	\$2,100																				\$2,100	\$2,100										
E1030	Kitchen	10394579	Foodservice Equipment, Commercial Kitchen, 3-Bowl, Replace	30	14	16	1	EA	\$2,500.00	\$2,500																				\$2,500	\$2,500										
E1070	Site	10394582	Basketball Backboard, Ceiling-Mounted, Operable, Operable	30	21	9	6	EA	\$7,830.00	\$46,980										\$46,980											\$46,980										
Totals, Unescalated																																									
Totals, Escalated (3.0% inflation, compounded annually)																																									
											\$0	\$26,288	\$38,900	\$38,400	\$329,750	\$73,600	\$868,115	\$812,430	\$1,391,148	\$157,380	\$264,518	\$801,004	\$10,500	\$16,100	\$2,161,015	\$50,600	\$504,253	\$3,400	\$1,354,800	\$74,600	\$0	\$8,976,801									
											\$0	\$27,077	\$41,269	\$41,961	\$371,137	\$85,323	\$1,036,575	\$999,186	\$1,762,265	\$205,345	\$355,490	\$1,108,777	\$14,970	\$23,643	\$3,268,728	\$78,833	\$809,178	\$5,620	\$2,306,456	\$130,812	\$0	\$12,672,645									

Forest Oak Middle School / Site																																										
Uniformat Code	Location Description	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost*	Subtotal	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	Deficiency Repair Estimate										
D3030	Building Exterior	10399531	Cooling Tower, (Typical) Open Circuit, Replace	25	20	5	1	EA	\$24,600.00	\$24,600						\$24,600																\$24,600										
D3030	Building Exterior	10399533	Chiller, Air-Cooled, Replace	25	5	20	1	EA	\$120,000.00	\$120,000																				\$120,000	\$120,000											
G2020	Site	10399538	Parking Lots, Pavement, Asphalt, Seal & Stripe	5	3	2	50000	SF	\$0.45	\$22,500			\$22,500										\$22,500							\$22,500	\$90,000											
G2020	Site	10399536	Parking Lots, Pavement, Asphalt, Mill & Overlay	25	14	11	50000	SF	\$3.50	\$175,000											\$175,000										\$175,000											
G2050	Site	10399534	Athletic Surfaces & Courts, Tennis/Volleyball, 2-Color Surface, Seal & Stripe	10	8	2	20000	SF	\$1.50	\$30,000			\$30,000									\$30,000									\$60,000											
G2050	Site	10399535	Sports Apparatus, Basketball, Backboard/Rim/Pole, Replace	25	17	8	8	EA	\$4,750.00	\$38,000								\$38,000													\$38,000											
G2060	Site	10399532	Park Bench, Wood/Composite/Fiberglass, Replace	20	12	8	5	EA	\$600.00	\$3,000								\$3,000													\$3,000											
G2060	Site	10515417	Fences & Gates, Fence, Chain Link 8', Replace	40	25	15	200	LF	\$25.00	\$5,000																\$5,000					\$5,000											
G2060	Site	10399537	Flagpole, Metal, Replace	30	19	11	2	EA	\$2,500.00	\$5,000											\$5,000										\$5,000											
G4050	Site	10399539	Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install	20	14	6	8	EA	\$4,000.00	\$32,000							\$32,000															\$32,000										
Totals, Unescalated																																										
Totals, Escalated (3.0% inflation, compounded annually)																																										
											\$0	\$0	\$52,500	\$0	\$0	\$24,600	\$32,000	\$22,500	\$41,000	\$0	\$0	\$180,000	\$52,500	\$0	\$0	\$5,000	\$0	\$22,500	\$0	\$0	\$120,000										\$552,600	
											\$0	\$0	\$55,697	\$0	\$0	\$28,518	\$38,210	\$27,672	\$51,938	\$0	\$0	\$249,162	\$74,852	\$0	\$0	\$7,790	\$0	\$37,189	\$0	\$0	\$216,733										\$787,762	

* Markup has been included in unit costs.

Appendix G: Equipment Inventory List

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D10 Conveying													
1	10394525	D1010	Elevator Controls	Automatic, 1 Car		Forest Oak Middle School / Main Building	Elevator Shafts/Utility	Dover	EP06020	EJ7604	1999		
2	10394591	D1010	Passenger Elevator	Hydraulic, 3 Floors	3500 LB	Forest Oak Middle School / Main Building	Elevator Shafts/Utility	Dover	NA	NA	1999		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D20 Plumbing													
1	10394529	D2010	Water Heater	Gas, Commercial (200 MBH)	193 GAL	Forest Oak Middle School / Main Building	Boiler Room	State Industries, Inc.	SBD-81-199NE 118	2001117648358	2020		
2	10394532	D2010	Water Heater	Gas, Commercial (200 MBH)	193 GAL	Forest Oak Middle School / Main Building	Boiler Room	State Industries, Inc.	SBD-81-199NE 118	2001117648357	2020		
3	10394538	D2060	Air Compressor	Tank-Style	0.75 HP	Forest Oak Middle School / Main Building	Boiler Room	Furnas	6DA3ED	NA			

Index	ID	UFCODE	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D30 HVAC													
1	10394557	D3020	Boiler	Gas, HVAC	3769 MBH	Forest Oak Middle School / Main Building	Boiler Room	Burnham	4FW-450A-50-G-GP	25388	1999		
2	10394543	D3020	Boiler	Gas, HVAC	3769 MBH	Forest Oak Middle School / Main Building	Boiler Room	Burnham	4FW-450A-50-G-GP	25389	1999		
3	10399533	D3030	Chiller	Air-Cooled	100 TON	Forest Oak Middle School / Site	Building Exterior	Daikin Industries	AGZ100ED SEMNN00	STNU180500078	2019		
4	10394598	D3030	Chiller [CHILLER-1]	Water-Cooled, 151 to 200 TON	180 TON	Forest Oak Middle School / Main Building	Boiler Room	Trane	RTHB180FLF00EWP000UNA3LF2LFV00D0	U98L04072	1999		
5	10399531	D3030	Cooling Tower	(Typical) Open Circuit	51 - 75 TON	Forest Oak Middle School / Site	Building Exterior	Evapco	SST 8-59B	982646	1999		
6	10909813	D3030	Condensing Unit/Heat Pump [CU 2]	Split System, Exterior, 5 TON	5 TON	Forest Oak Middle School	Roof	Trane	TTA060C300A1	N2855XAFF	1999		
7	10909790	D3030	Condensing Unit/Heat Pump [CU 2]	Split System, Exterior, 5 TON	5 TON	Forest Oak Middle School	Roof	Trane	TTA060C300A1	N2855RJFF	1999		
8	10909791	D3030	Condensing Unit/Heat Pump [CU 2]	Split System, Exterior, 5 TON	5 TON	Forest Oak Middle School	Roof	Trane	TTA060C300A	N262D39FF	1999		
9	10909815	D3030	Ductless Mini-Split	Multi Zone, Condenser w/ Two Evaporators of 1 TON each	1 TON	Forest Oak Middle School	Roof	Mitsubishi	MUYGL12NA	0XC08470	2020		
10	10909804	D3030	Ductless Mini-Split	Single Zone, Condenser & Evaporator, 0.75 to 1 TON	0.75 TON	Forest Oak Middle School	Roof	Mitsubishi	MUZJP09WA	9ZC02820			
11	10909817	D3030	Ductless Mini-Split [SS HEAT PUMP]	Single Zone, Condenser & Evaporator, 1.5 to 2 TON	1.5 TON	Forest Oak Middle School	Roof	Mitsubishi	PUH18EK	Illegible			
12	10909784	D3030	Ductless Mini-Split [SS HEAT PUMP]	Single Zone, Condenser & Evaporator, 1.5 to 2 TON	1.5 TON	Forest Oak Middle School	Roof	Mitsubishi	PUH18EK	Illegible	1999		

Index	ID	UFCODE	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
13	10394559	D3030	Fan Coil Unit	Split System DX, Interior Unit, 2 to 2.5 TON	Inaccessible	Forest Oak Middle School / Main Building	Throughout Building						8
14	10399374	D3030	Fan Coil Unit	Split System DX, Interior Unit, 3 to 3.5 TON	Inaccessible	Forest Oak Middle School / Main Building	Throughout Building						15
15	10394555	D3030	Split System	Condensing Unit/Heat Pump	5 TON	Forest Oak Middle School / Main Building	Roof	NA	NA	NA			
16	10394539	D3030	Split System Ductless	Single Zone	Inaccessible	Forest Oak Middle School / Main Building	Roof	Inaccessible	Inaccessible	Inaccessible			
17	10394584	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	2 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor	NA	W398	1999		
18	10394521	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	5 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor Reliance	NA	NA	1999		
19	10394545	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	7.5 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor	NA	F598	1999		
20	10394508	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Super-E	NA	0980512	1999		
21	10394594	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Super-E	NA	0980512	1999		

Index	ID	UFCODE	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
22	10394531	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	5 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor Reliance	NA	NA	1999		
23	10394526	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	7.5 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor	NA	F598	1999		
24	10394558	D3050	Pump	Distribution, HVAC Chilled or Condenser Water	2 HP	Forest Oak Middle School / Main Building	Boiler Room	Baldor	NA	W398	1999		
25	10394589	D3050	Pump	Distribution, HVAC Heating Water	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Super-E	NA	0980512	1999		
26	10394562	D3050	Pump	Distribution, HVAC Heating Water	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Super-E	NA	0980512	1999		
27	10909787	D3050	Air Handler [RTU-1]	Exterior AHU, Packaged, 6001 to 8000 CFM	6000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
28	10909832	D3050	Air Handler [RTU-10]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
29	10909792	D3050	Air Handler [RTU-11]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
30	10909803	D3050	Air Handler [RTU-12]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
31	10909788	D3050	Air Handler [RTU-2]	Exterior AHU, Packaged, 6001 to 8000 CFM	6000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
32	10909827	D3050	Air Handler [RTU-3]	Exterior AHU, Packaged, 6001 to 8000 CFM	6000 CFM	Forest Oak Middle School	Roof	Trane	No dataplate	No dataplate	1999		
33	10909816	D3050	Air Handler [RTU-4]	Exterior AHU, Packaged, 6001 to 8000 CFM	6000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		

Index	ID	UFCCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
34	10909833	D3050	Air Handler [RTU-5]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	No dataplate	No dataplate	1999		
35	10909825	D3050	Air Handler [RTU-6]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	No dataplate	No dataplate	1999		
36	10909800	D3050	Air Handler [RTU-7]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
37	10909786	D3050	Air Handler [RTU-8]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	Roof	Trane	Illegible	Illegible	1999		
38	10909823	D3050	Air Handler [RTU-9]	Exterior AHU, Packaged, 6001 to 8000 CFM	8000 CFM	Forest Oak Middle School	roof	Trane	Illegible	Illegible	1999		
39	10909805	D3050	Make-Up Air Unit [RTU-13]	MUA or MAU, 2000 to 6000 CFM	4000 CFM	Forest Oak Middle School	Roof	Trane	No dataplate	No dataplate	1999		
40	10909826	D3060	Exhaust Fan	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	No dataplate	No dataplate	1999		
41	10909809	D3060	Exhaust Fan	Exterior, 24" Diameter, 2001 to 5000 CFM	2000 CFM	Forest Oak Middle School	Roof	Loren Cook	No dataplate	No dataplate	1998		
42	10909821	D3060	Exhaust Fan [FUME HOOD]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	100C3B	011298	1999		
43	10909828	D3060	Exhaust Fan [PRV 1]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	180C5B	0011298	1999		
44	10909836	D3060	Exhaust Fan [PRV 10]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	0011298	1999		
45	10909822	D3060	Exhaust Fan [PRV 11]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	011298	1999		
46	10909794	D3060	Exhaust Fan [PRV 12]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	011298	1999		
47	10909798	D3060	Exhaust Fan [PRV 13]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	21298	1999		
48	10909820	D3060	Exhaust Fan [PRV 14]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	031298	1999		

Index	ID	UFCODE	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
49	10909795	D3060	Exhaust Fan [PRV 15]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	041298	1999		
50	10909807	D3060	Exhaust Fan [PRV 16]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	0011298	1999		
51	10909801	D3060	Exhaust Fan [PRV 17]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	021298	1999		
52	10909802	D3060	Exhaust Fan [PRV 18]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	031298	1999		
53	10909835	D3060	Exhaust Fan [PRV 19]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	135C3B	011298	1999		
54	10909830	D3060	Exhaust Fan [PRV 2]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	135C3B	0011298	1999		
55	10909818	D3060	Exhaust Fan [PRV 20]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	041298	1999		
56	10909783	D3060	Exhaust Fan [PRV 21]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	9011298	1999		
57	10909829	D3060	Exhaust Fan [PRV 23]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	100R3B	0011298	1999		
58	10909793	D3060	Exhaust Fan [PRV 24]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	100R3B	21298	1999		
59	10909831	D3060	Exhaust Fan [PRV 26]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	135C3B	0011298	1999		
60	10909797	D3060	Exhaust Fan [PRV 27]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	120R3B	0011298	1999		
61	10909819	D3060	Exhaust Fan [PRV 3]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	135C3B	0011298	1999		
62	10909806	D3060	Exhaust Fan [PRV 4]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	135C3B	0011298	1999		
63	10909810	D3060	Exhaust Fan [PRV 6]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	120C3B	01129H	1999		

Index	ID	UFCODE	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
64	10909837	D3060	Exhaust Fan [PRV 7]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	100C3B	0011298	1999		
65	10909799	D3060	Exhaust Fan [PRV 8]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	00112	1999		
66	10909796	D3060	Exhaust Fan [PRV 9]	Exterior, 10" Diameter, 50 to 500 CFM	500 CFM	Forest Oak Middle School	Roof	Loren Cook	80C3B	001129	1999		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D40 Fire Protection													
1	10394586	D4010	Backflow Preventer	Fire Suppression	6 IN	Forest Oak Middle School / Main Building	Boiler Room	Watts	709	252566	1999		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D50 Electrical													
1	10394573	D5010	Generator	Diesel	60 KW	Forest Oak Middle School / Main Building	Boiler Room	Generac	98A03633-S	2042590	1999		
2	10394519	D5010	Automatic Transfer Switch	ATS	400 AMP	Forest Oak Middle School / Main Building	Boiler Room	Generac	NA	NA	1999		
3	10394533	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	Boiler Room	GE	NA	NA			
4	10394536	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Forest Oak Middle School / Main Building	E121	GE	NA	NA	1999		
5	10399384	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	E221	GE	NA	NA			
6	10394570	D5020	Secondary Transformer	Dry, Stepdown	45 KVA	Forest Oak Middle School / Main Building	B108	GE	NA	NA			
7	10394550	D5020	Secondary Transformer	Dry, Stepdown	75 KVA	Forest Oak Middle School / Main Building	Boiler Room	GE	No dataplate	No dataplate	1999		
8	10394566	D5020	Secondary Transformer	Dry, Stepdown	225 KVA	Forest Oak Middle School / Main Building	D104	GE	NA	NA	1999		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
9	10399375	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	D222	GE	NA	NA			
10	10399383	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	E221	GE	NA	NA	1999		
11	10399376	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	D222	GE	NA	NA			
12	10394501	D5020	Secondary Transformer	Dry, Stepdown	30 KVA	Forest Oak Middle School / Main Building	E121	GE	NA	NA	1999		
13	10394512	D5020	Secondary Transformer	Dry, Stepdown	15 KVA	Forest Oak Middle School / Main Building	Boiler Room	GE	NA	NA	1999		
14	10394546	D5020	Switchboard	277/480 V	2500 AMP	Forest Oak Middle School / Main Building	Boiler Room	GE	NA	NA	1999		
15	10394549	D5020	Distribution Panel	277/480 V	600 AMP	Forest Oak Middle School / Main Building	E121	GE	NA	NA	1999		
16	10394547	D5020	Distribution Panel	277/480 V	800 AMP	Forest Oak Middle School / Main Building	Boiler Room	GE	NA	NA	1999		
17	10399373	D5020	Distribution Panel	277/480 V	400 AMP	Forest Oak Middle School / Main Building	E221	GE	NA	NA	1999		

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
18	10394600	D5020	Distribution Panel [MDP1]	277/480 V	800 AMP	Forest Oak Middle School / Main Building	Boiler Room	GE	NA	NA	1999		
19	10394560	D5020	Distribution Panel [MDP4]	277/480 V	800 AMP	Forest Oak Middle School / Main Building	D104	GE	NA	NA	1999		
20	10394551	D5020	Distribution Panel [MDP-5]	277/480 V	800 AMP	Forest Oak Middle School / Main Building	D104	GE	NA	NA	1999		
21	10394575	D5030	Variable Frequency Drive	VFD, by HP of Motor	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Trane	No dataplate	875504Y075			
22	10394502	D5030	Variable Frequency Drive	VFD, by HP of Motor	30 HP	Forest Oak Middle School / Main Building	Boiler Room	Trane	No dataplate	875604Y075			
23	10394577	D5030	Variable Frequency Drive [PUMP-3]	VFD, by HP of Motor	30 HP	Forest Oak Middle School / Main Building	Boiler Room	MagneTek	GPD505	NA			
24	10394527	D5030	Variable Frequency Drive [RTU #5]	VFD, by HP of Motor	10 HP	Forest Oak Middle School / Main Building	Boiler Room	Yaskawa	NA	NA			
25	10394585	D5030	Variable Frequency Drive [RTU #5]	VFD, by HP of Motor	10 HP	Forest Oak Middle School / Main Building	Boiler Room	Yaskawa	NA	NA			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
D70 Electronic Safety & Security													
1	10394556	D7050	Fire Alarm Panel	Fully Addressable		Forest Oak Middle School / Main Building	B121	Honeywell	MS-9600UDLS	NA			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
E10 Equipment													
1	10394528	E1030	Foodservice Equipment	Commercial Kitchen, 1-Bowl		Forest Oak Middle School / Main Building	Kitchen						
2	10394576	E1030	Foodservice Equipment	Commercial Kitchen, 2-Bowl		Forest Oak Middle School / Main Building	Kitchen						
3	10394579	E1030	Foodservice Equipment	Commercial Kitchen, 3-Bowl		Forest Oak Middle School / Main Building	Kitchen						
4	10394565	E1030	Foodservice Equipment	Convection Oven, Double		Forest Oak Middle School / Main Building	Kitchen	Blodgett	NA	NA			
5	10394507	E1030	Foodservice Equipment	Convection Oven, Single		Forest Oak Middle School / Main Building	Kitchen	Blodgett	NA	NA			
6	10394592	E1030	Foodservice Equipment	Convection Oven, Single		Forest Oak Middle School / Main Building	Kitchen	Blodgett	G0S-86/AB	04279911102S			
7	10394581	E1030	Foodservice Equipment	Dairy Cooler/Wells		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
8	10394518	E1030	Foodservice Equipment	Dairy Cooler/Wells		Forest Oak Middle School / Main Building	Kitchen	Beverage-Air Corporation	No dataplate	No dataplate			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
9	10394524	E1030	Foodservice Equipment	Dairy Cooler/Wells		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
10	10394595	E1030	Foodservice Equipment	Dairy Cooler/Wells		Forest Oak Middle School / Main Building	Kitchen	Beverage-Air Corporation	No dataplate	No dataplate			
11	10394504	E1030	Foodservice Equipment	Dairy Cooler/Wells		Forest Oak Middle School / Main Building	Kitchen	Beverage-Air Corporation	SMF34	NA			
12	10394572	E1030	Foodservice Equipment	Deep Fryer		Forest Oak Middle School / Main Building	Kitchen	Frymaster	NA	NA			
13	10394513	E1030	Foodservice Equipment	Exhaust Hood, 8 to 10 LF		Forest Oak Middle School / Main Building	Kitchen	Illegible	Illegible	Illegible			
14	10394515	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
15	10394567	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
16	10394561	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	SLRPT29-SHSH	AIV506004-T			
17	10394523	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	Inaccessible	Inaccessible			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
18	10394544	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
19	10394588	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
20	10394499	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	No dataplate	HM2000	NA			
21	10394530	E1030	Foodservice Equipment	Food Warmer, Proofing Cabinet on Wheels		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
22	10394510	E1030	Foodservice Equipment	Icemaker, Freestanding		Forest Oak Middle School / Main Building	Kitchen	Scotsman	NA	NA			
23	10394541	E1030	Foodservice Equipment	Range/Oven, 4-Burner w/ Griddle		Forest Oak Middle School / Main Building	Kitchen	Garland	NA	NA			
24	10394498	E1030	Foodservice Equipment	Steamer, Freestanding		Forest Oak Middle School / Main Building	Kitchen	NA	NA	NA			
25	10394537	E1030	Foodservice Equipment	Steamer, Freestanding		Forest Oak Middle School / Main Building	Kitchen	Delfield	NA	NA			
26	10394503	E1030	Foodservice Equipment	Steamer, Freestanding		Forest Oak Middle School / Main Building	Kitchen	Colorpoint	5E5-CPA	C06B13742C			

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
27	10909824	E1030	Foodservice Equipment	Walk-In, Condenser for Refrigerator/Freezer		Forest Oak Middle School	Roof	Trenton Refrigeration	TEZA010H8	249239535	2024		
28	10909834	E1030	Foodservice Equipment	Walk-In, Condenser for Refrigerator/Freezer		Forest Oak Middle School	Roof	ColdZone	No dataplate	No dataplate			
29	10394578	E1030	Foodservice Equipment	Walk-In, Evaporator for Refrigerator/Freezer		Forest Oak Middle School / Main Building	Kitchen	Trenton	Inaccessible	Inaccessible			
30	10394534	E1030	Foodservice Equipment	Walk-In, Evaporator for Refrigerator/Freezer		Forest Oak Middle School / Main Building	Kitchen	ColdZone	NA	NA			
31	10394540	E1030	Foodservice Equipment	Walk-In, Freezer		Forest Oak Middle School / Main Building	Kitchen	Bally	NA	NA	1999		
32	10394500	E1030	Foodservice Equipment	Walk-In, Refrigerator		Forest Oak Middle School / Main Building	Kitchen	Bally	NA	NA			