



**BUREAU
VERITAS**

FACILITY CONDITION ASSESSMENT

prepared for

Montgomery County Public Schools
45 West Gude Drive, Suite 4000
Rockville, MD 20850



Francis Scott Key Middle School
910 Schindler Drive
Silver Spring, MD 20903

PREPARED BY:

Bureau Veritas
6021 University Boulevard, Suite 200
Ellicott City, MD 21043
800.733.0660
www.bvna.com

BV CONTACT:

Bill Champion
Senior Program Manager
443.622.5067
Bill.Champion@bureauveritas.com

BV PROJECT #:

172559.25R000-150.354

DATE OF REPORT:

May 26, 2026

ON SITE DATE:

February 24, 2026

Bureau Veritas

TABLE OF CONTENTS

| | |
|---|-----------|
| 1. Executive Summary | 1 |
| Property Overview and Assessment Details | 1 |
| Campus Findings and Deficiencies | 2 |
| Facility Characteristic Survey | 3 |
| Facility Condition Index (FCI) Depleted Value | 4 |
| Immediate Needs | 5 |
| Key Findings | 6 |
| Plan Types | 7 |
| 2. Building Information | 8 |
| 3. Site Summary | 11 |
| 4. ADA Accessibility | 13 |
| 5. Purpose and Scope | 15 |
| 6. Opinions of Probable Costs | 17 |
| Methodology..... | 17 |
| Definitions | 18 |
| 7. Certification | 19 |
| 8. Appendices | 20 |



1. Executive Summary

Property Overview and Assessment Details

| General Information | |
|--|--|
| Property Type | Middle school campus |
| Number of Buildings | 1 |
| Main Address | 910 Schindler Drive, Silver Spring, MD 20903 |
| Site Developed | Built 1966 Renovated 2009 |
| Outside Occupants / Leased Spaces | None |
| Date(s) of Visit | February 24, 2026 |
| Management Point of Contact | Montgomery County Public Schools Greg Kellner Facilities Manager, Office of Facilities Management Direct 240.740.7746 Gregory_Kellner@mcpsmd.org |
| On-site Point of Contact (POC) | Mr. Riggs, Building Service Manager 301.422.5700 |
| Assessment & Report Prepared By | Sonal George Issac |
| Reviewed By | Daniel White, Technical Report Reviewer for, Bill Champion Program Manager 443.622.5067 Bill.Champion@bureauveritas.com |
| AssetCalc Link | Full dataset for this assessment can be found at: https://www.assetcalc.net/ |

Campus Findings and Deficiencies

Historical Summary

Francis Scott Key Middle School was originally constructed in 1966 and underwent a major renovation in 2008/2009 that included demolition of the former structure and construction of the current two-story building. The school became the first middle school to attain Leed Gold certification in Maryland and opened for student year 2009/2010.

Architectural

The masonry clad structure is primarily supported by steels columns and beams and appears structurally sound with no obvious evidence of movement or settlement. Building envelope consists primarily of masonry exterior walls with glazed windows and doors, which were observed to be in generally fair condition. The built-up roof system is at half-life and should perform well for the next 6-10 years. Interior finishes include rubber tile, quarry tile, wood flooring, carpet, ceramic tile, and vinyl tiles (VCT), which appear to be typical for educational facilities and are overall in fair condition. Ceilings throughout the building consist mainly of acoustical ceiling tiles (ACT). Some ceiling tiles were observed to be missing, stained, or slightly sagging, particularly in localized areas such as the cafeteria, which may be associated with past moisture intrusion.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The facility is served by a variety of mechanical, electrical, and plumbing systems, many of which appear to have been upgraded during the 2008 renovation. Mechanical systems include heat pumps, air handling units (AHUs), split systems, ductless split systems, makeup air units, and exhaust fans that provide heating, cooling, and ventilation to the building. Heating is supported by boilers, which distribute heated water to cabinet units serving classrooms and other interior spaces. Electrical infrastructure includes a main distribution panel, secondary transformer, and automatic transfer switch (ATS) that distributes power throughout the facility. A diesel-powered generator is installed to provide backup power during outages. The building also contains one hydraulic elevator for vertical accessibility and domestic water heaters for hot water supply. In addition, solar panels are installed to supplement the building's electrical generation.

Site

The campus includes parking areas, outdoor athletic facilities, and landscaped open spaces. The parking lot pavement was observed to be in poor condition, with visible deterioration that may require resurfacing or repair. Recreational areas include basketball courts, a baseball field, and a soccer field. The basketball courts show surface cracking and deterioration, which should be addressed for safety purposes. The baseball and soccer fields appear to be in generally fair condition and remain suitable for use.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Characteristic Survey

The facility characteristics of school and associated buildings are shown below.

Indoor air quality including temperature and relative humidity level are monitored centrally. Most instructional spaces are equipped with IAQ sensors. Each general and specialty classroom has a heating, ventilation, and air conditioning (HVAC) system capable of maintaining a temperature between 68°F and 75°F and a relative humidity between 30% and 60% at full occupancy. Each general, science, and fine-arts classroom had an HVAC system that continuously moves air and is capable of maintaining a carbon dioxide level of not more than 1,200 parts per million. The temperature, relative humidity and air quality were measured at a work surface in the approximate center of the classroom.

The acoustics with the exception of physical-education spaces, each general and specialty classroom are maintainable at a sustained background sound level of less than 55 decibels. The sound levels were measured at a work surface in the approximate center of the classroom.

Each general and specialty classroom had a lighting system capable of maintaining at least 50 foot-candles of well-distributed light. The school has appropriate task lighting in specialty classrooms where enhanced visibility is required. The light levels measured at a work surface located in the approximate center of the classroom, between clean light fixtures. The school makes efficient use of natural light for students, teachers, and energy conservation.

Classroom spaces, including those for physical education, were sufficient for educational programs that are appropriate for the class-level needs. With the exception of physical-education spaces, each general and specialty classroom contained a work surface and seat for each student in the classroom. The work surface and seat were appropriate for the normal activity of the class conducted in the room.

Each general and specialty classroom had an erasable surface and a surface suitable for projection purposes, appropriate for group classroom instruction, and a display surface. Each general and specialty classroom had storage for classroom materials or access to conveniently located storage.

With the exception of physical-education spaces and music-education spaces, each general and specialty classroom shall had a work surface and seat for the teacher and for any aide assigned to the classroom. The classroom had secure storage for student records that is located in the classroom or is conveniently accessible to the classroom.

The school was constructed with sustainable design practices. The schools use durable, timeless, low-maintenance exterior materials. The school's materials (particularly shell) should withstand time as well as potential impacts related to structural, site and climate changes.

The school is functionally equitable. All students in this school have access to safe, well-maintained, and appropriately equipped learning environments as students in other MCPS schools. As part of the evaluation factor, the MDCl will be presented upon final of all assessments.

Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values. A School Facility with full estimated life of all systems (a brand new school) would have a 0 FCI. The FCIs cannot exceed 1.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

The FCI Depleted Value of this school is 0.549129.

Immediate Needs

There are no immediate needs to report.

Key Findings



Parking Lots in Failed Condition.

Pavement, Asphalt
Site Francis Scott Key Middle School Site

Uniformat Code: G2020
Recommendation: **Cut & Patch in 2027**

Priority Score: **84.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$77,000

\$\$\$\$

Needs to be repaved throughout the parking lot for better lifespan. - AssetCALC ID: 10594693



Sports Apparatus in Poor Condition.

Tennis/Volleyball, Net w/ Posts & Anchors
Site Francis Scott Key Middle School Site

Uniformat Code: G2050
Recommendation: **Replace in 2027**

Priority Score: **82.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$5,600

\$\$\$\$

The tennis netting needs to be replaced. - AssetCALC ID: 10594700



Athletic Surfaces & Courts in Poor Condition.

Basketball/General, Asphalt Pavement
Site Francis Scott Key Middle School Site

Uniformat Code: G2050
Recommendation: **Replace in 2027**


Priority Score: **82.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$94,300

\$\$\$\$

The basketball court needs to be repaved throughout for kids safety and the safety. - AssetCALC ID: 10594686



Foodservice Equipment in Poor Condition.

Convection Oven, Single
Main Building Francis Scott Key Middle School
Kitchen

Uniformat Code: E1030
Recommendation: **Replace in 2026**

Priority Score: **81.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$5,600

\$\$\$\$


The oven reportedly does not function - AssetCALC ID: 10592889

Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.

Plan Type Descriptions & Distribution

| | | |
|------------------------------|---|---|
| Safety | ■ | An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. |
| Performance/Integrity | ■ | Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability. |
| Accessibility | ■ | Does not meet ADA, UFAS, and/or other accessibility requirements. |
| Environmental | ■ | Improvements to air or water quality, including removal of hazardous materials from the building or site. |
| Retrofit/Adaptation | ■ | Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs. |
| Aged But Functional | ■ | Any component or system that has aged past its industry-average expected useful life (EUL) but is not currently deficient or problematic. |
| Lifecycle/Renewal | ■ | Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted. |



10-YEAR TOTAL: \$10,364,900

2. Building Information



Main Building: Systems Summary

| | | |
|------------------------------|---|------------------|
| Address | 910 Schindler Drive, Silver Spring, MD 20903 | |
| GPS Coordinates | 39.027761, -76.9924125 | |
| Constructed/Renovated | 1966 / 2009 | |
| Building Area | 147424 SF | |
| Number of Stories | 2 above grade | |
| <i>System</i> | <i>Description</i> | <i>Condition</i> |
| Structure | Steel columns and beams construction with masonry walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system | Good |
| Façade | Primary Wall Finish: Brick Windows: Aluminum | Fair |
| Roof | Primary: Flat construction with built-up finish roofing | Fair |
| Interiors | Walls: Glazed CMU, ceramic tile Floors: Carpet, VCT, faux ceramic tile, quarry tile, wood strip, rubber tile Ceilings: ACT | Fair |
| Elevators | Passenger: 1 hydraulic car serving all AA floors | Fair |

| Main Building: Systems Summary | | |
|---------------------------------------|--|------|
| Plumbing | Distribution: Copper supply and cast-iron waste & venting Hot Water: Gas water heaters with integral tanks Fixtures: Toilets, urinals, and sinks in all restrooms | Fair |
| HVAC | Central System: Boilers and air handlers, feeding VAV, fan coil, and cabinet terminal units Non-Central System: Packaged units, Split-system heat pumps and Ductless split-systems Supplemental components: Make-up air units | Fair |
| Fire Suppression | Wet-pipe sprinkler system, fire extinguishers, and kitchen hood system | Fair |
| Electrical | Source & Distribution: Main switchboard panel with copper wiring Interior Lighting: LED, linear fluorescent, CFL, halogen Exterior Building-Mounted Lighting: LED Emergency Power: Diesel generator with automatic transfer switch | Fair |
| Fire Alarm | Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs | Fair |
| Equipment/Special | Commercial kitchen equipment | Fair |
| Accessibility | Presently it does not appear an accessibility study is needed for this building. See the appendix for associated photos and additional information. | |
| Additional Studies | No additional studies are currently recommended for the building. | |
| Areas Observed | The interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the buildings, the exterior walls of the facility, and the roofs. | |
| Key Spaces Not Observed | All key areas of the facility were accessible and observed. | |

The table below shows the anticipated costs by trade or building system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|------------------------------------|------------------|-------------------|--------------------|--------------------|--------------------|---------------------|
| System | Immediate | Short Term | Near Term | Med Term | Long Term | TOTAL |
| | | (1-2 yr) | (3-5 yr) | (6-10 yr) | (11-20 yr) | |
| Structure | - | - | - | - | - | - |
| Facade | - | - | - | \$99,800 | \$1,297,600 | \$1,397,500 |
| Roofing | - | - | - | \$1,992,600 | - | \$1,992,600 |
| Interiors | - | - | \$1,999,000 | \$50,700 | \$1,751,400 | \$3,801,100 |
| Conveying | - | - | \$15,600 | - | \$96,600 | \$112,100 |
| Plumbing | - | - | \$24,500 | \$19,800 | \$176,600 | \$221,000 |
| HVAC | - | \$3,600 | \$834,700 | \$219,800 | \$2,382,900 | \$3,441,000 |
| Fire Protection | - | - | \$5,000 | \$212,000 | \$24,900 | \$241,900 |
| Electrical | - | - | \$2,223,300 | \$145,000 | \$507,000 | \$2,875,400 |
| Fire Alarm & Electronic Systems | - | - | \$698,600 | \$899,200 | \$649,100 | \$2,246,900 |
| Equipment & Furnishings | - | \$5,800 | \$353,100 | \$30,200 | \$284,400 | \$673,500 |
| Site Development | - | - | - | \$5,700 | - | \$5,700 |
| TOTALS (3% inflation) | - | \$9,400 | \$6,153,900 | \$3,674,800 | \$7,170,600 | \$17,008,700 |

3. Site Summary



| Site Information | | |
|-------------------------------------|--|------------------|
| Site Area | 17.85 acres | |
| Parking Spaces | 86 total spaces all in open lots; 4 of which are accessible | |
| <i>System</i> | <i>Description</i> | <i>Condition</i> |
| Site Pavement | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs | Poor |
| Site Development | Property entrance signage; chain link fencing Playgrounds, sports fields and courts with bleachers, dugouts, fencing, and site lights Limited park benches, picnic tables, trash receptacles | Fair |
| Landscaping & Topography | Limited landscaping features including lawns, trees, bushes, and planters Irrigation not present Low to moderate site slopes throughout | Fair |
| Utilities | Municipal water and sewer Local utility-provided electric and natural gas | Fair |
| Site Lighting | Pole-mounted: LED | Fair |
| Ancillary Structures | Storage shed | Fair |

| Site Information | |
|-------------------------------------|---|
| Site Accessibility | Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information. |
| Site Additional Studies | No additional studies are currently recommended for the exterior site areas. |
| Site Areas Observed | The exterior areas within the property boundaries were observed to gain a clear understanding of the site's overall condition. |
| Site Key Spaces Not Observed | All key areas of the exterior site were accessible and observed. |

The table below shows the anticipated costs by trade or site system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|------------------------------|-----------|------------------------|-----------------------|-----------------------|-------------------------|------------------|
| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
| Special Construction & Demo | - | - | - | - | \$126,400 | \$126,400 |
| Site Development | - | \$105,900 | \$40,400 | \$95,100 | \$56,800 | \$298,300 |
| Site Utilities | - | - | - | \$73,800 | - | \$73,800 |
| Site Pavement | - | \$81,700 | \$129,800 | - | - | \$211,500 |
| TOTALS (3% inflation) | - | \$187,600 | \$170,300 | \$168,900 | \$183,300 | \$710,100 |

4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The following table summarizes the accessibility conditions of the general site and each significant building or building group included in this report:

| Accessibility Summary | | | |
|------------------------------|----------------------------------|----------------------------------|--|
| <i>Facility</i> | <i>Year Built/ Renovated</i> | <i>Prior Study Provided?</i> | <i>Major/Moderate Issues Observed?</i> |
| General Site | 1966 / 2009 | No | Yes |
| Main Building | 1966 / 2009 | No | No |

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.

5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

| Condition Ratings | |
|-----------------------|---|
| Excellent | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Good | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Fair | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life. |
| Poor | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| Failed | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required. |
| Not Applicable | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present. |

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

6. Opinions of Probable Costs

Cost estimates are embedded throughout this report, including the detailed Replacement Reserves report in the appendix. The cost estimates are predominantly based on construction rehabilitation costs developed by the *RSMeans data from Gordian*. While the *RSMeans data from Gordian* is the primary reference source for the Bureau Veritas cost library, secondary and supporting sources include but are not limited to other industry experts work, such as *Marshall & Swift* and *CBRE Whitestone*. For improved accuracy, additional research integrated with Bureau Veritas's historical experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions also come into play when deemed necessary. Invoice or bid documents provided either by the owner or facility construction resources may be reviewed early in the process or for specific projects as warranted.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

To account for differences in prices between locations, the base costs are modified by geographical location factors to adjust for market conditions, transportation costs, or other local contributors. When requested by the client, the costs may be further adjusted by several additional factors including; labor rates (prevailing minimum wage), general contractor fees for profit and overhead, and insurance. If desired, costs for design and permits, and a contingency factor, may also be included in the calculations.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

7. Certification

Montgomery County Public School (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Francis Scott Key Middle School, 910 Schindler Drive, Silver Spring, MD 20903, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: Sonal George Issac
Project Assessor

Reviewed by:

Daniel White

Daniel White
Technical Report Reviewer
for
Bill Champion
Program Manager
443.622.5067
Bill.Champion@bureauveritas.com

8. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan(s)
- Appendix C: Pre-Survey Questionnaire(s)
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

Appendix A:

Photographic Record

Photographic Overview



1 - FRONT ELEVATION




2 - RIGHT ELEVATION



3 - LEFT ELEVATION



4 - REAR ELEVATION



5 - STRUCTURAL OVERVIEW



6 - BUILDING FACADE

Photographic Overview




7 - FRONT OFFICE



8 - HEALTHCARE ROOM




9 - INTERIOR OVERVIEW



10 - STAIRWAYS



11 - COMMERCIAL KITCHEN



12 - CAFETERIA

Photographic Overview



13 - SCIENCE CLASSROOM




14 - LIBRARY




15 - HALLWAY



16 - CLASSROOM



17 - CONFERENCE ROOM



18 - MUSIC CLASSROOM



Photographic Overview



19 - STAGE



20 - GYMNASIUM




21 - MAIN MECHANICAL ROOM



22 - MAIN ELECTRICAL ROOM



23 - DOMESTIC WATER HEATERS



24 - DOMESTIC WATER PIPING

Photographic Overview



25 - FIRE ALARM PANEL



26 - FIRE SPRINKLER RISERS




27 - ELEVATOR



28 - ELEVATOR CONTROL ROOM



29 - MAIN SWITCHBOARD



30 - EMERGENCY GENERATOR

Photographic Overview



31 - PROPERTY SIGNAGE



32 - MAIN PARKING AREA



33 - SPORTS COURTS



34 - SIDEWALKS AND LANDSCAPING



35 - SPORTS FIELDS




36 - SITE FURNISHINGS



Appendix B:

Site Plan(s)



Site Plan



| | | | |
|--|-----------------------|---------------------------------|---|
|  BUREAU VERITAS | Project Number | Project Name |  N |
| | 172559.25R000-150.354 | Francis Scott Key Middle School | |
| | Source | On-Site Date | |
| | Google Earth | February 24, 2026 | |

Appendix C: Pre-Survey Questionnaire(s)

BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

Building / Facility Name: Francis Scott Key Middle School

Name of person completing form: Mr. Riggs

Title / Association w/ property: Building Service Manager

Length of time associated w/ property: 10 years

Date Completed: 2/25/2026

Phone Number: 301-422-5700

Method of Completion: DURING - verbally completed during assessment

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.


| Data Overview | | Response | | |
|---------------|--|---------------------|-------------------|--|
| 1 | Year(s) constructed | Constructed 1966 | Renovated 2010 | Building was fully demolished and reconstructed in 2009 and opened by 2010 |
| 2 | Building size in SF | 147,424 SF | | |
| 3 | Major Renovation/Rehabilitation | | Year | Additional Detail |
| | | Facade | | |
| | | Roof | | |
| | | Interiors | | |
| | | HVAC | | |
| | | Electrical | | |
| | | Site Pavement | | |
| | | Accessibility | | |
| 4 | List other significant capital improvements (focus on recent years; provide approximate date). | No | | |
| 5 | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? | No | | |
| 6 | Describe any on-going extremely problematic, historically chronic, or immediate facility needs. | No | | |

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

| Question | | Response | | | | Comments |
|----------|--|----------|----|-----|----|--|
| | | Yes | No | Unk | NA | |
| 7 | Are there any problems with foundations or structures, like excessive settlement? | X | | | | There are some cracks in floor in different parts of building. |
| 8 | Are there any wall, window, basement or roof leaks? | X | | | | Mostly roof leaks |
| 9 | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints? | X | | | | Classroom and closet |
| 10 | Are your elevators unreliable, with frequent service calls? | X | | | | Out of order |
| 11 | Are there any plumbing leaks, water pressure, or clogging/backup issues? | | X | | | |
| 12 | Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service? | | X | | | |
| 13 | Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas? | X | | | | Hallways are the areas least heated |
| 14 | Is the electrical service outdated, undersized, or problematic? | | X | | | |
| 15 | Are there any problems or inadequacies with exterior lighting? | | X | | | |
| 16 | Is site/parking drainage inadequate, with excessive ponding or other problems? | | X | | | |
| 17 | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? | | X | | | |
| 18 | ADA: Has an accessibility study been previously performed? If so, when? | | | X | | |
| 19 | ADA: Have any ADA improvements been made to the property since original construction? Describe. | | | | X | |
| 20 | ADA: Has building management reported any accessibility-based complaints or litigation? | | X | | | |
| 21 | Are any areas of the property leased to outside occupants? | | | X | | |



Signature of Assessor



Signature of POC

Appendix D: Accessibility Review and Photos

Visual Checklist - 2010 ADA Standards for Accessible Design

Property Name: Francis Scott Key Middle School

BV Project Number: 172559.25R000-150.354

| Abbreviated Accessibility Checklist | | | | | |
|-------------------------------------|--|-----|----|-----|----------|
| Facility History & Interview | | | | | |
| Question | | Yes | No | Unk | Comments |
| 1 | Has an accessibility study been previously performed? If so, when? | | X | | |
| 2 | Have any ADA improvements been made to the property since original construction? Describe. | | | X | |
| 3 | Has building management reported any accessibility-based complaints or litigation? | | X | | |

Abbreviated Accessibility Checklist

Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



CLOSE-UP OF STALL

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Does the required number of standard ADA designated spaces appear to be provided ? | ✗ | | | |
| 2 | Does the required number of van-accessible designated spaces appear to be provided ? | ✗ | | | |
| 3 | Are accessible spaces on the shortest accessible route to an accessible building entrance ? | ✗ | | | |
| 4 | Does parking signage include the International Symbol of Accessibility ? | ✗ | | | |
| 5 | Does each accessible space have an adjacent access aisle ? | ✗ | | | |
| 6 | Do parking spaces and access aisles appear to be relatively level and without obstruction ? | ✗ | | | |

Abbreviated Accessibility Checklist

Exterior Accessible Route



CURB CUT



ACCESSIBLE PATH

| Question | | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1 | Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ? | ✗ | | | |
| 2 | Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ? | ✗ | | | |
| 3 | Are curb ramps present at transitions through raised curbs on all accessible routes? | ✗ | | | |
| 4 | Do curb ramps appear to have compliant slopes for all components ? | ✗ | | | |
| 5 | Do ramp runs on an accessible route appear to have compliant slopes ? | ✗ | | | |
| 6 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | ✗ | | | |

| | | | | | |
|---|---|---|--|--|--|
| 7 | Do ramps on an accessible route appear to have compliant end and intermediate landings ? | X | | | |
| 8 | Do ramps and stairs on an accessible route appear to have compliant handrails? | X | | | |
| 9 | For stairways that are open underneath, are permanent barriers present that prevent or discourage access? | X | | | |

Abbreviated Accessibility Checklist

Building Entrances



MAIN ENTRANCE



ADDITIONAL ENTRANCE

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Do a sufficient number of accessible entrances appear to be provided ? | X | | | |
| 2 | If the main entrance is not accessible, is an alternate accessible entrance provided? | X | | | |
| 3 | Is signage provided indicating the location of alternate accessible entrances ? | X | | | |
| 4 | Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ? | X | | | |
| 5 | Do doors at accessible entrances appear to have compliant hardware ? | X | | | |
| 6 | Do doors at accessible entrances appear to have a compliant clear opening width ? | X | | | |

| | | | | | |
|---|---|---|--|--|--|
| 7 | Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ? | X | | | |
| 8 | Do thresholds at accessible entrances appear to have a compliant height ? | X | | | |

Abbreviated Accessibility Checklist

Interior Accessible Route



ACCESSIBLE INTERIOR RAMP



DOOR HARDWARE

| Question | | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1 | Does an accessible route appear to connect all public areas inside the building ? | ✗ | | | |
| 2 | Do accessible routes appear free of obstructions and/or protruding objects ? | ✗ | | | |
| 3 | Do ramps on accessible routes appear to have compliant slopes ? | ✗ | | | |
| 4 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | ✗ | | | |
| 5 | Do ramps on accessible routes appear to have compliant end and intermediate landings ? | ✗ | | | |
| 6 | Do ramps on accessible routes appear to have compliant handrails ? | ✗ | | | |

| | | | | | |
|----|---|---|--|--|--|
| 7 | Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ? | X | | | |
| 8 | Do public transaction areas have an accessible, lowered service counter section ? | X | | | |
| 9 | Do public telephones appear mounted with an accessible height and location ? | X | | | |
| 10 | Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ? | X | | | |
| 11 | Do doors at interior accessible routes appear to have compliant hardware ? | X | | | |
| 12 | Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ? | X | | | |
| 13 | Do doors on interior accessible routes appear to have a compliant clear opening width ? | X | | | |

Abbreviated Accessibility Checklist

Elevators



ELEVATOR



ELEVATOR CONTROL ROOM

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Are hallway call buttons configured with the "UP" button above the "DOWN" button? | ✗ | | | |
| 2 | Is accessible floor identification signage present on the hoistway sidewalls on each level ? | ✗ | | | |
| 3 | Do the elevators have audible and visual arrival indicators at the lobby and hallway entrances? | ✗ | | | |
| 4 | Do the elevator hoistway and car interior appear to have a minimum compliant clear floor area ? | ✗ | | | |
| 5 | Do the elevator car doors have automatic re-opening devices to prevent closure on obstructions? | ✗ | | | |
| 6 | Do elevator car control buttons appear to be mounted at a compliant height ? | ✗ | | | |

| | | | | | |
|---|--|---|--|--|--|
| 7 | Are tactile and Braille characters mounted to the left of each elevator car control button ? | X | | | |
| 8 | Are audible and visual floor position indicators provided in the elevator car? | X | | | |
| 9 | Is the emergency call system on or adjacent to the control panel and does it not require voice communication ? | X | | | |

Abbreviated Accessibility Checklist

Public Restrooms



TOILET STALL OVERVIEW




SINK, FAUCET HANDLES AND ACCESSORIES

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Do publicly accessible toilet rooms appear to have a minimum compliant floor area ? | ✗ | | | |
| 2 | Does the lavatory appear to be mounted at a compliant height and with compliant knee area ? | ✗ | | | |
| 3 | Does the lavatory faucet have compliant handles ? | ✗ | | | |
| 4 | Is the plumbing piping under lavatories configured to protect against contact ? | ✗ | | | |
| 5 | Are grab bars provided at compliant locations around the toilet ? | ✗ | | | |
| 6 | Do toilet stall doors appear to provide the minimum compliant clear width ? | ✗ | | | |

| | | | | | |
|---|--|---|--|--|--|
| 7 | Do toilet stalls appear to provide the minimum compliant clear floor area ? | X | | | |
| 8 | Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ? | X | | | |
| 9 | Do accessories and mirrors appear to be mounted at a compliant height ? | X | | | |

Abbreviated Accessibility Checklist

Kitchens/Kitchenettes



BREAKROOM OVERVIEW



SINK CLEARANCE

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Do kitchens/kitchenettes appear to have a minimum compliant path of travel or area of maneuverability ? | ✗ | | | |
| 2 | Are the appliances centered for a parallel or forward approach with adequate clear floor space ? | ✗ | | | |
| 3 | Is there an accessible countertop/preparation space of proper width and height ? | ✗ | | | |
| 4 | Is there an accessible sink space of proper width and height ? | ✗ | | | |
| 5 | Does the sink faucet have compliant handles ? | ✗ | | | |
| 6 | Is the plumbing piping under the sink configured to protect against contact ? | ✗ | | | |

| | | | | | |
|---|---|---|--|--|--|
| 7 | Are the cooktop/range controls front-mounted (or in a location that does not require reaching across the burners) ? | ✘ | | | |
|---|---|---|--|--|--|

Abbreviated Accessibility Checklist

Playgrounds & Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Is there an accessible route to the play area / s? | ✗ | | | |
| 2 | Has the play area been reviewed for accessibility ? | ✗ | | | |
| 3 | Are publicly accessible swimming pools equipped with an entrance lift ? | ✗ | | | |

Appendix E: Component Condition Report

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------------|------------------------|-----------|---|------------|-----|----------|
| Structure | | | | | | |
| A4010 | 130 | Good | Foundation, Concrete Slab-on-Grade | 78,000 SF | 60 | 10592814 |
| B1010 | Throughout Building | Good | Structural Framing, Masonry (CMU) Bearing Walls, 1-2 Story Building, 1-2 Story Building | 10,000 SF | 60 | 10592866 |
| Facade | | | | | | |
| B2010 | Building Exterior | Fair | Exterior Walls, Brick/Masonry/Stone, Clean & Seal, Maintain | 41,000 SF | 8 | 10592816 |
| B2020 | Entrance Hallway | Fair | Screens & Shutters, Rolling Security Shutter, 55 to 100 SF | 1 | 6 | 10592977 |
| B2020 | Building Exterior | Fair | Glazing, any type by SF | 14,350 SF | 15 | 10592910 |
| B2050 | Building Exterior | Fair | Exterior Door, Steel, Standard | 7 | 14 | 10592848 |
| B2050 | Building Exterior | Fair | Exterior Door, Aluminum-Framed & Glazed, Standard Swing | 19 | 14 | 10593002 |
| B2050 | Building Exterior | Fair | Exterior Door, Aluminum-Framed & Glazed, Standard Swing | 12 | 15 | 10592837 |
| Roofing | | | | | | |
| B3010 | Roof | Fair | Roofing, Built-Up | 105,905 SF | 10 | 10595773 |
| Interiors | | | | | | |
| C1010 | Gymnasium | Fair | Movable Partition, Gym Divider, Deluxe/Operable | 1,200 SF | 9 | 10593001 |
| C1030 | Throughout Building | Fair | Interior Door, Steel, w/ Extensive Glazing | 14 | 24 | 10592937 |
| C1030 | Hallways | Fair | Interior Door, Steel, Fire-Rated at 90 Minutes or Over | 8 | 24 | 10592833 |
| C1030 | Throughout Building | Fair | Interior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 22 | 25 | 10592947 |
| C1030 | Throughout Building | Fair | Interior Door, Wood, Solid-Core | 92 | 25 | 10592905 |
| C1030 | Throughout Building | Fair | Interior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 9 | 24 | 10592997 |
| C1030 | Hallways | Fair | Interior Door, Steel, Fire-Rated at 90 Minutes or Over | 18 | 25 | 10592888 |
| C1070 | Throughout Building | Fair | Suspended Ceilings, Acoustical Tile (ACT) | 147,424 SF | 5 | 10592991 |
| C1090 | Restrooms | Fair | Toilet Partitions, Plastic/Laminate | 29 | 5 | 10592890 |
| C1090 | Hallways & Locker room | Fair | Lockers, Steel-Baked Enamel, 12" W x 15" D x 72" H | 350 LF | 5 | 10592818 |
| C2010 | Restrooms | Fair | Wall Finishes, Ceramic Tile | 4,500 SF | 24 | 10592838 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------------|-----------------------|-----------|---|------------|-----|----------|
| C2010 | Throughout Building | Fair | Wall Finishes, any surface, Prep & Paint | 236,800 SF | 3 | 10592956 |
| C2030 | Restrooms | Fair | Flooring, Ceramic Tile | 4,250 SF | 23 | 10592856 |
| C2030 | Gymnasium | Fair | Flooring, Wood, Sports, Refinish | 5,300 SF | 4 | 10592767 |
| C2030 | Throughout Building | Fair | Flooring, Vinyl Tile (VCT) | 130,164 SF | 3 | 10593003 |
| C2030 | Commercial Kitchen | Good | Flooring, Quarry Tile | 1,210 SF | 34 | 10592821 |
| C2030 | Stage | Fair | Flooring, Wood, Strip, Refinish | 800 SF | 4 | 10592839 |
| C2030 | Library | Fair | Flooring, Carpet, Commercial Standard | 4,850 SF | 4 | 10592834 |
| C2030 | Health Gymroom | Fair | Flooring, Rubber Tile | 850 SF | 4 | 10592916 |
| C2050 | Gymnasium | Fair | Ceiling Finishes, exposed irregular elements, Prep & Paint | 5,300 SF | 6 | 10592996 |
| Conveying | | | | | | |
| D1010 | Elevator Control room | Fair | Passenger Elevator, Hydraulic, 2 Floors, 2500 LB, Renovate | 1 | 13 | 10592853 |
| D1010 | Elevator Control room | Fair | Elevator Controls, Automatic, 1 Car | 1 | 3 | 10592968 |
| D1010 | Elevator | Fair | Elevator Cab Finishes, Standard | 1 | 4 | 10593005 |
| Plumbing | | | | | | |
| D2010 | Kitchen | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 1 | 13 | 10592936 |
| D2010 | Commercial Kitchen | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 1 | 13 | 10592872 |
| D2010 | Locker Rooms | Fair | Shower, Valve & Showerhead | 8 | 13 | 10592840 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Service Sink, Wall-Hung | 21 | 18 | 10592886 |
| D2010 | Throughout Building | Fair | Plumbing System, Supply & Sanitary, Low Density (excludes fixtures) | 147,424 SF | 25 | 10592873 |
| D2010 | Restrooms | Fair | Urinal, Waterless | 13 | 13 | 10592823 |
| D2010 | Janitor closet | Fair | Water Heater, Gas, Commercial (125 MBH), 80 GAL | 1 | 5 | 10592915 |
| D2010 | Restrooms | Fair | Toilet, Commercial Water Closet | 28 | 13 | 10592869 |
| D2010 | 134 | Fair | Water Heater, Gas, Commercial (200 MBH), 199 GAL | 1 | 6 | 10592774 |
| D2010 | 134 | Fair | Water Heater, Gas, Commercial (200 MBH), 199 GAL | 1 | 12 | 10592958 |
| D2010 | Janitor closet | Fair | Sink/Lavatory, Service Sink, Floor | 4 | 20 | 10592770 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|-------------|--------------|-----------|---|----------|-----|----------|
| D2010 | Kitchen | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 1 | 13 | 10592999 |
| D2010 | Hallways | Fair | Drinking Fountain, Wall-Mounted, Bi-Level | 6 | 4 | 10592769 |
| D2010 | Kitchen | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 1 | 13 | 10592855 |
| HVAC | | | | | | |
| D3020 | Storage room | Fair | Unit Heater, Electric, 5 kW | 1 | 9 | 10592836 |
| D3020 | 134 | Fair | Boiler Supplemental Components, Expansion Tank, 75 GAL [ET-1] | 1 | 23 | 10592846 |
| D3020 | 130 | Fair | Unit Heater, Electric, 5 kW [EUH-2] | 1 | 3 | 10592980 |
| D3020 | 134 | Fair | Unit Heater, Electric, 7.5 kW [EUH-3] | 1 | 9 | 10592862 |
| D3020 | 134 | Fair | Boiler Supplemental Components, Shot Feed Tank, 5 GAL | 1 | 15 | 10592806 |
| D3020 | 134 | Fair | Boiler Supplemental Components, Expansion Tank, 5 GAL | 1 | 25 | 10592847 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 2 TON [HP-1] | 1 | 4 | 10592871 |
| D3030 | 229 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 8-4] | 1 | 5 | 10592944 |
| D3030 | 154 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-3] | 1 | 5 | 10592841 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 1 TON [HP-3] | 1 | 4 | 10592824 |
| D3030 | 165 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 7-9] | 1 | 5 | 10593009 |
| D3030 | 172 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 7-2] | 1 | 5 | 10592932 |
| D3030 | 123 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-16] | 1 | 5 | 10592954 |
| D3030 | 131 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-13] | 1 | 5 | 10592962 |
| D3030 | 184 | Fair | Heat Pump, Water Source, 7.5 TON, 5.5 TON [HP 7-7] | 1 | 5 | 10592925 |
| D3030 | 123 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-15] | 1 | 5 | 10592832 |
| D3030 | 208 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-2] | 1 | 5 | 10592951 |
| D3030 | 110H | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 1-13] | 1 | 5 | 10592929 |
| D3030 | 236 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-3] | 1 | 5 | 10592781 |
| D3030 | 253 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-8] | 1 | 5 | 10592949 |
| D3030 | 159 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 7-5] | 1 | 5 | 10592859 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|----------|-----------|---|----------|-----|----------|
| D3030 | 159 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-12] | 1 | 5 | 10592819 |
| D3030 | 218 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-3] | 1 | 5 | 10592829 |
| D3030 | 183 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 7-10] | 1 | 5 | 10592801 |
| D3030 | 230 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-1] | 1 | 5 | 10592759 |
| D3030 | 190 | Fair | Heat Pump, Water Source, 10 TON, 9 TON [HP 1-16] | 1 | 5 | 10592796 |
| D3030 | 172 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 7-1] | 1 | 5 | 10592822 |
| D3030 | 215 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-11] | 1 | 5 | 10592789 |
| D3030 | 226 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-6] | 1 | 5 | 10592861 |
| D3030 | 205 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-13] | 1 | 5 | 10592957 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 2 TON [HP-1] | 1 | 4 | 10592983 |
| D3030 | 236 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-2] | 1 | 5 | 10592827 |
| D3030 | 127 | Fair | Heat Pump, Water Source, 5 TON, 1.5 TON [HP 6-18] | 1 | 5 | 10592899 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2 TON | 1 | 4 | 10592952 |
| D3030 | 165 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 7-8] | 1 | 5 | 10592942 |
| D3030 | 226 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-6] | 1 | 5 | 10592946 |
| D3030 | 229 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 9-8] | 1 | 5 | 10592843 |
| D3030 | 166 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-6] | 1 | 5 | 10592831 |
| D3030 | 184 | Fair | Heat Pump, Water Source, 5 TON, 3.5 TON [HP 7-6] | 1 | 5 | 10592970 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 1 TON | 1 | 3 | 10592892 |
| D3030 | 223 | Fair | Heat Pump, Water Source, 5 TON, 1 TON [HP 9-18] | 1 | 5 | 10592807 |
| D3030 | 131 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-14] | 1 | 5 | 10592987 |
| D3030 | 183 | Fair | Heat Pump, Water Source, 7.5 TON, 7 TON [HP 7-11] | 1 | 5 | 10592870 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 2 TON [HP-2] | 1 | 2 | 10592897 |
| D3030 | 119 | Fair | Heat Pump, Water Source, 5 TON, 1.5 TON [HP 6-17] | 1 | 5 | 10592924 |
| D3030 | 215 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-10] | 1 | 5 | 10592850 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|---------------------|-----------|--|------------|-----|----------|
| D3030 | 208 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-1] | 1 | 5 | 10592799 |
| D3030 | 256 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-14] | 1 | 5 | 10592926 |
| D3030 | 146 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-2] | 1 | 5 | 10592761 |
| D3030 | 155 | Fair | Heat Pump, Water Source, 5 TON, 5 TON [HP 7-3] | 1 | 5 | 10592884 |
| D3030 | 146 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-1] | 1 | 5 | 10592982 |
| D3030 | 261 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-12] | 1 | 5 | 10592931 |
| D3030 | 205 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-12] | 1 | 5 | 10592995 |
| D3030 | 127 | Fair | Heat Pump, Water Source, 5 TON, 1.5 TON [HP 6-19] | 1 | 5 | 10592989 |
| D3030 | 253 | Fair | Heat Pump, Water Source, 5 TON, 1.5 TON [HP 8-7] | 1 | 5 | 10592858 |
| D3030 | Roof | Fair | Split System Ductless, Multi Zone, Condenser & 2 Evaporators of 1 TON each | 1 | 3 | 10592922 |
| D3030 | 261 | Fair | Heat Pump, Water Source, 5 TON, 4 TON [HP 8-11] | 1 | 5 | 10593007 |
| D3030 | 250 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-9] | 1 | 3 | 10592920 |
| D3030 | 218 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 9-4] | 1 | 5 | 10592934 |
| D3030 | 256 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-13] | 1 | 5 | 10592878 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump, 2 TON [HP-2] | 1 | 4 | 10592933 |
| D3030 | 154 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-4] | 1 | 5 | 10592879 |
| D3030 | 190 | Fair | Heat Pump, Water Source, 5 TON, 4 TON [HP 1-15] | 1 | 5 | 10592908 |
| D3030 | 155 | Fair | Heat Pump, Water Source, 5 TON, 2.5 TON [HP 7-4] | 1 | 5 | 10592860 |
| D3030 | 166 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 6-5] | 1 | 5 | 10592930 |
| D3030 | 250 | Fair | Heat Pump, Water Source, 5 TON, 3 TON [HP 8-10] | 1 | 5 | 10592959 |
| D3050 | 134 | Fair | Pump, Distribution, HVAC Heating Water, 150 HP [P-2] | 1 | 10 | 10592772 |
| D3050 | Throughout Building | Fair | HVAC System, Ductwork, Medium Density | 147,424 SF | 15 | 10592913 |
| D3050 | Roof | Fair | Make-Up Air Unit, MUA or MAU, 4000 CFM [SAF-A] | 1 | 3 | 10592927 |
| D3050 | Throughout Building | Fair | HVAC System, Hydronic Piping, 4-Pipe | 147,424 SF | 25 | 10592935 |
| D3050 | Roof | Fair | Make-Up Air Unit, MUA or MAU, 3000 CFM [HV-1] | 1 | 3 | 10592778 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|---------------------|-----------|--|------------|-----|----------|
| D3050 | 134 | Fair | Pump, Distribution, HVAC Heating Water, 150 HP [P-1] | 1 | 10 | 10592825 |
| D3050 | 134 | Fair | Supplemental Components, Air Separator, HVAC, 4 IN [AS-1] | 1 | 4 | 10592898 |
| D3050 | Throughout Building | Fair | HVAC System, Ductwork w/ VAV/FCU, Medium Density | 147,424 SF | 15 | 10592791 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 12" Damper, 500 CFM [EF-G2] | 1 | 14 | 10592877 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-G1] | 1 | 17 | 10592784 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-P] | 1 | 17 | 10592797 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-E6] | 1 | 19 | 10592785 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 500 CFM [EF-N] | 1 | 18 | 10592917 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 28" Damper, 8500 CFM [EF-B1] | 1 | 8 | 10593004 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 7200 CFM [ERU-8] | 1 | 5 | 10592914 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-E2] | 1 | 17 | 10592783 |
| D3060 | Commercial Kitchen | Fair | Supplemental Components, Air Curtain, 8' Wide Heated, 9.5 | 1 | 5 | 10592768 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 12" Damper, 600 CFM [EF-F2] | 1 | 8 | 10592852 |
| D3060 | Commercial Kitchen | Fair | Supplemental Components, Air Curtain, 5' Wide Non-Heated, 2.4 | 1 | 3 | 10592758 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 9600 CFM [ERU-4] | 1 | 5 | 10592984 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 9600 CFM [ERU-2] | 1 | 5 | 10592777 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 16" Damper, 1100 CFM [WPRC] | 1 | 8 | 10592800 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 9800 CFM [ERU-5] | 1 | 5 | 10592907 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 550 CFM [EF-E4] | 1 | 20 | 10592973 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-E1] | 1 | 8 | 10592960 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 12800 [ERU-6] | 1 | 5 | 10592883 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 600 CFM [EF-E5] | 1 | 20 | 10592795 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 200 CFM [EF-G3] | 1 | 21 | 10592900 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 800 CFM [EF-J] | 1 | 18 | 10592812 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 9600 CFM [ERU-1] | 1 | 5 | 10592967 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------------------|------------------------------|-----------|--|------------|-----|----------|
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 16" Damper, 1500 CFM [EF-E3] | 1 | 8 | 10592828 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 7200 CFM [ERU-7] | 1 | 5 | 10592844 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 250 CFM [EF-G4] | 1 | 18 | 10592985 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 200 CFM [EF-G6] | 1 | 19 | 10592851 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 12" Damper, 200 CFM [EF-G5] | 1 | 19 | 10592802 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 9600 CFM [ERU-3] | 1 | 5 | 10593000 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-F3] | 1 | 9 | 10592854 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 28" Damper, 8500 CFM [EF-B2] | 1 | 8 | 10592835 |
| D3060 | Roof | Good | Exhaust Fan, Centrifugal, 28" Damper, 7500 CFM [EF-X] | 1 | 21 | 10592810 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 16" Damper, 1200 CFM [EF-4] | 1 | 8 | 10592938 |
| D3060 | Roof | n/a | Exhaust Fan, Centrifugal, 12" Damper, 700 CFM [EF-F1] | 1 | 8 | 10592863 |
| D3060 | Roof | Fair | Air Handler, Outside Air Intake Energy Recovery Unit (ERU), 3000 CFM [ERU-9] | 1 | 5 | 10592993 |
| Fire Protection | | | | | | |
| D4010 | 134 | Fair | Backflow Preventer, Fire Suppression, 3 INCH | 1 | 15 | 10592813 |
| D4010 | Commercial Kitchen | Fair | Fire Suppression System, Commercial Kitchen, per LF of Hood | 10 LF | 5 | 10593006 |
| D4010 | Throughout Building | Fair | Fire Suppression System, Existing Sprinkler Heads, by SF | 147,424 SF | 10 | 10592830 |
| D4010 | 134 | Fair | Backflow Preventer, Fire Suppression, 6 IN | 1 | 15 | 10592780 |
| D4010 | Throughout Building | Fair | Fire Suppression System, Full System Install/Retrofit, Medium Density/Complexity, Renovate | 147,424 SF | 25 | 10593010 |
| D4030 | Commercial Kitchen | Fair | Fire Extinguisher, Wet Chemical/CO2 | 1 | 5 | 10592891 |
| Electrical | | | | | | |
| D5010 | 130 | Fair | Automatic Transfer Switch, ATS, 100 AMP [TRANSFER SWITCH PANEL] | 1 | 8 | 10592911 |
| D5010 | Right Side Building Exterior | Fair | Generator, Diesel, 250 KW | 1 | 8 | 10592804 |
| D5010 | Right Side Building Exterior | Fair | Solar Power, Inverter, 7500 WATTS | 1 | 3 | 10592940 |
| D5010 | 130 | Fair | Automatic Transfer Switch, ATS, 400 AMP [TRANSFER SWITCH PANEL] | 1 | 8 | 10592902 |
| D5010 | Roof | Fair | Solar Power, Photovoltaic (PV) Panel, 24 SF | 552 | 5 | 10592815 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|----------|-----------|---|----------|-----|----------|
| D5020 | 130 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL EH] | 1 | 13 | 10592998 |
| D5020 | 130 | Fair | Secondary Transformer, Dry, Stepdown, 45 KVA [TRANSFORMER EL] | 1 | 13 | 10592972 |
| D5020 | 237 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H2A-2] | 1 | 13 | 10592792 |
| D5020 | 130 | Fair | Secondary Transformer, Dry, Stepdown, 150 KVA [TRANSFORMER MDPK] | 1 | 13 | 10592918 |
| D5020 | 120 | Fair | Distribution Panel, 120/208 V, 400 AMP [PANEL L1C-1] | 1 | 13 | 10593008 |
| D5020 | 120 | Fair | Secondary Transformer, Dry, Stepdown, 112.5 KVA [TRANSFORMER L1C] | 1 | 13 | 10592950 |
| D5020 | 130 | Fair | Switchboard, 277/480 V, 4000 AMP [MAIN SWITCHBOARD] | 2 | 23 | 10592885 |
| D5020 | 130 | Fair | Distribution Panel, 277/480 V, 1200 AMP [PANEL MDPA] | 1 | 13 | 10592880 |
| D5020 | 151 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1A-1] | 1 | 13 | 10592964 |
| D5020 | 130 | Fair | Distribution Panel, 120/208 V, 400 AMP [PANEL MDPK] | 1 | 13 | 10592765 |
| D5020 | 151 | Fair | Secondary Transformer, Dry, Stepdown, 75 KVA [TRANSFORMER L1 A] | 1 | 13 | 10592793 |
| D5020 | 130 | Fair | Secondary Transformer, Dry, Stepdown, 15 KVA [TRANSFORMER E] | 1 | 13 | 10592776 |
| D5020 | 120 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1C-2] | 1 | 13 | 10592948 |
| D5020 | 151 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1B-2] | 1 | 13 | 10592766 |
| D5020 | 130 | Fair | Secondary Transformer, Dry, Stepdown, 225 KVA [TRANSFORMER MD] | 1 | 13 | 10592963 |
| D5020 | 120 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL L1C-3] | 1 | 13 | 10592882 |
| D5020 | 130 | Fair | Distribution Panel, 120/208 V, 600 AMP [PANEL MD] | 1 | 13 | 10592811 |
| D5020 | 151 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1B-1] | 1 | 13 | 10592794 |
| D5020 | 151 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1A-1] | 1 | 13 | 10592992 |
| D5020 | 237 | Fair | Secondary Transformer, Dry, Stepdown, 75 KVA [TRANSFORMER L2A] | 1 | 13 | 10592912 |
| D5020 | 151 | Fair | Distribution Panel, 120/208 V, 400 AMP [PANEL L1B-2] | 1 | 13 | 10592881 |
| D5020 | 130 | Fair | Distribution Panel, 277/480 V, 600 AMP [PANEL MP] | 1 | 13 | 10592975 |
| D5020 | 151 | Fair | Distribution Panel, 120/208 V, 400 AMP [PANEL L1B1] | 1 | 13 | 10592875 |
| D5020 | 130 | Fair | Distribution Panel, 277/480 V, 1200 AMP [PANEL MDPB] | 1 | 13 | 10592979 |
| D5020 | 120 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL L1C-2] | 1 | 13 | 10592887 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|--|---------------------|-----------|--|----------|-------|----------|
| D5020 | 130 | Fair | Secondary Transformer, Dry, Stepdown, 45 KVA [TRANSFORMER ML] | 1 | 13 | 10592762 |
| D5020 | 237 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H2A-1] | 1 | 13 | 10592994 |
| D5020 | 151 | Fair | Secondary Transformer, Dry, Stepdown, 112.5 KVA [TRANSFORMER L1B] | 1 | 13 | 10592782 |
| D5020 | 120 | Fair | Distribution Panel, 277/480 V, 400 AMP [PANEL H1C-1] | 1 | 13 | 10592939 |
| D5030 | 134 | Fair | Variable Frequency Drive, VFD, by HP of Motor, 75 HP, Replace/Install [PUMP 2] | 1 | 5 | 10592809 |
| D5030 | Throughout Building | Fair | Electrical System, Wiring & Switches, Average or Low Density/Complexity | 147,424 | SF 25 | 10592790 |
| D5030 | 134 | Fair | Variable Frequency Drive, VFD, by HP of Motor, 75 HP, Replace/Install [PUMP 1] | 1 | 5 | 10592906 |
| D5040 | Building Exterior | Fair | Exterior Light, any type, w/ LED Replacement, 100 WATT | 19 | 3 | 10592876 |
| D5040 | Stage | Fair | Stage Lighting System, Full Upgrade, Specialty Fixtures | 800 | SF 5 | 10592865 |
| D5040 | Throughout Building | Fair | Interior Lighting System, Full Upgrade, High Density & Standard Fixtures | 147,424 | SF 5 | 10592974 |
| D5040 | Throughout Building | Fair | Emergency & Exit Lighting System, Full Interior Upgrade, LED | 147,424 | SF 3 | 10592771 |
| Fire Alarm & Electronic Systems | | | | | | |
| D6060 | Throughout Building | Fair | Intercom/PA System, Public Address Upgrade, Facility-Wide | 147,424 | SF 5 | 10592955 |
| D7030 | Throughout Building | Fair | Security/Surveillance System, Full System Upgrade, Average Density | 147,424 | SF 6 | 10592760 |
| D7050 | Throughout Building | Fair | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 147,424 | SF 6 | 10592817 |
| D7050 | Front Entrance | Fair | Fire Alarm Panel, Annunciator | 1 | 5 | 10592874 |
| D7050 | 130 | Fair | Fire Alarm Panel, Fully Addressable | 1 | 8 | 10592864 |
| D8010 | Throughout Building | Fair | BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install | 147,424 | SF 4 | 10592978 |
| Equipment & Furnishings | | | | | | |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4) | 1 | 4 | 10593011 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Commercial Kitchen, 3-Bowl | 1 | 13 | 10592969 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Double | 1 | 3 | 10592779 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In | 1 | 5 | 10592788 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 3 | 10592953 |
| E1030 | Kitchen | Good | Foodservice Equipment, Convection Oven, Single | 1 | 8 | 10592904 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|--------------------|-----------|--|----------|-----|----------|
| E1030 | Kitchen | Good | Foodservice Equipment, Convection Oven, Single | 1 | 8 | 10592763 |
| E1030 | Commercial Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, 115 VOLTS | 1 | 3 | 10592826 |
| E1030 | Kitchen | Poor | Foodservice Equipment, Convection Oven, Single | 1 | 1 | 10592889 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 1 LF | 3 | 10592919 |
| E1030 | Commercial Kitchen | Fair | Foodservice Equipment, Commercial Kitchen, 3-Bowl | 1 | 13 | 10592943 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4) | 1 | 4 | 10592868 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 6 | 10592786 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 1 LF | 3 | 10592895 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Griddle | 1 | 4 | 10592981 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 4 | 10592787 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Exhaust Hood, 3 to 6 LF | 1 | 3 | 10592903 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 5 | 10592986 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 3 | 10592976 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 3 | 10592923 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 10 | 10592928 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 4 | 10592909 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 3 | 10592842 |
| E1030 | Commercial Kitchen | Fair | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer | 1 | 4 | 10592820 |
| E1030 | Laundry Room | Fair | Laundry Equipment, Dryer, Commercial, 50 LB | 1 | 5 | 10592961 |
| E1030 | Commercial Kitchen | Fair | Foodservice Equipment, Walk-In, Freezer | 1 | 3 | 10592764 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 3 | 10592808 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Icemaker, Freestanding | 1 | 5 | 10592901 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Exhaust Hood, 3 to 6 LF | 1 | 4 | 10592867 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4) | 1 | 4 | 10592775 |
| E1030 | Commercial Kitchen | Fair | Foodservice Equipment, Walk-In, Refrigerator | 1 | 3 | 10592966 |

Component Condition Report | Francis Scott Key Middle School / Main Building

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|------------|---------------------------------|-----------|---|----------|-----|----------|
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In | 1 | 4 | 10592798 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 1 LF | 3 | 10592805 |
| E1030 | Kitchen | Fair | Commercial Kitchen Line, Serving/Warming Equipment | 2 LF | 3 | 10592849 |
| E1040 | Hallways | Fair | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted | 2 | 7 | 10592971 |
| E1060 | Healthroom | Fair | Residential Appliances, Refrigerator, 14 to 18 CF | 1 | 3 | 10592896 |
| E1060 | Building service manager office | Fair | Residential Appliances, Refrigerator, 14 to 18 CF | 1 | 3 | 10592921 |
| E1060 | Workroom | Fair | Residential Appliances, Refrigerator, 14 to 18 CF | 1 | 3 | 10592965 |
| E1060 | Workroom | Fair | Residential Appliances, Refrigerator, 14 to 18 CF | 1 | 4 | 10592988 |
| E1060 | Workroom | Fair | Residential Appliances, Refrigerator, 14 to 18 CF | 1 | 3 | 10592893 |
| E1070 | Stage | Fair | Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour | 800 SF | 4 | 10592941 |
| E1070 | Gymnasium | Fair | Basketball Backboard, Ceiling-Mounted, Operable, Operable | 6 | 13 | 10593012 |
| E1070 | Gymnasium | Fair | Gym Scoreboard, Electronic Standard | 1 | 15 | 10592857 |
| E2010 | Classrooms | Fair | Casework, Cabinetry, Standard | 550 LF | 5 | 10592773 |
| E2010 | Hallways | Fair | Fixed Seating, Courtroom/Church, Wood Benches/Pews | 14 LF | 15 | 10592803 |
| E2010 | Gymnasium | Fair | Bleachers, Telescoping Manual, up to 15 Tier (per Seat) | 16 | 6 | 10592945 |

Sitework

| | | | | | | |
|-------|--------------|------|---------------------------------------|---|---|----------|
| G2060 | Locker Rooms | Fair | Park Bench, Wood/Composite/Fiberglass | 8 | 6 | 10592845 |
|-------|--------------|------|---------------------------------------|---|---|----------|

Component Condition Report | Francis Scott Key Middle School / Site

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|---|----------|-----------|---|-----------|-----|----------|
| Special Construction & Demo | | | | | | |
| F1020 | Site | Fair | Ancillary Building, Classroom/Office Module, Standard/Permanent | 350 SF | 20 | 10594697 |
| Pedestrian Plazas & Walkways | | | | | | |
| G2020 | Site | Failed | Parking Lots, Pavement, Asphalt, Cut & Patch | 14,000 SF | 2 | 10594693 |
| G2020 | Site | Fair | Parking Lots, Pavement, Asphalt, Mill & Overlay | 32,000 SF | 5 | 10594683 |

Component Condition Report | Francis Scott Key Middle School / Site

| UF L3 Code | Location | Condition | Component/Attributes/Capacity | Quantity | RUL | ID |
|---|----------|-----------|---|-----------|-----|----------|
| G2030 | Site | Good | Sidewalk, Concrete, Large Areas | 18,220 SF | 35 | 10594689 |
| Athletic, Recreational & Playfield Areas | | | | | | |
| G2050 | Site | Fair | Sports Apparatus, Player/Dugout Benches, 12' Length | 4 | 4 | 10594696 |
| G2050 | Site | Fair | Outdoor Spectator Seating, Bleachers, Aluminum Benches (per Seat) | 10 | 10 | 10594681 |
| G2050 | Site | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay | 5,750 SF | 10 | 10594688 |
| G2050 | Site | Fair | Sports Apparatus, Soccer, Regulation Goal | 2 | 5 | 10594694 |
| G2050 | Site | Fair | Sports Apparatus, Basketball, Backboard/Rim/Pole | 6 | 10 | 10594691 |
| G2050 | Site | Fair | Sports Apparatus, Baseball, Backstop Chain-Link | 4 | 6 | 10594692 |
| G2050 | Site | Fair | Athletic Surfaces & Courts, Tennis/Volleyball, Rubber-Acrylic w/ Integral Color, Resurface | 5,750 SF | 4 | 10594684 |
| G2050 | Site | Poor | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement | 14,500 SF | 2 | 10594686 |
| G2050 | Site | Poor | Sports Apparatus, Tennis/Volleyball, Net w/ Posts & Anchors | 4 | 2 | 10594700 |
| Sitework | | | | | | |
| G2060 | Site | Fair | Bike Rack, Fixed 1-5 Bikes | 6 | 6 | 10594699 |
| G2060 | Site | Fair | Park Bench, Wood/Composite/Fiberglass | 8 | 11 | 10594695 |
| G2060 | Site | Fair | Trash Receptacle, Medium-Duty Metal or Precast | 4 | 12 | 10594690 |
| G2060 | Site | Fair | Fences & Gates, Fence, Chain Link 8' | 102 LF | 25 | 10594685 |
| G2060 | Site | Fair | Flagpole, Metal | 1 | 15 | 10594682 |
| G2060 | Site | Fair | Signage, Property, Monument, Replace/Install | 1 | 5 | 10594698 |
| G4050 | Site | Fair | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, 400 WATT, Replace/Install | 15 | 7 | 10594687 |

Appendix F: Replacement Reserves

Replacement Reserves Report



5/15/2026

| Uniformat Code | Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost* | Subtotal | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | Deficiency Repair Estimate |
|----------------|------------------------------|----------|---|----------------|------|-----|----------|------|-------------|-----------|------|---------|------|-----------|------|-----------|------|------|----------|------|------|---------|------|----------|------|------|---------|------|-----------|---------|---------|----------------------------|
| D5010 | Right Side Building Exterior | 10592940 | Solar Power, Inverter, Replace | 15 | 12 | 3 | 1 | EA | \$6,000.00 | \$6,000 | | | | \$6,000 | | | | | | | | | | | | | | | | | \$6,000 | \$12,000 |
| D5010 | Roof | 10592815 | Solar Power, Photovoltaic (PV) Panel, 24 SF, Replace | 20 | 15 | 5 | 552 | EA | \$1,800.00 | \$993,600 | | | | | | \$993,600 | | | | | | | | | | | | | | | | \$993,600 |
| D5010 | 130 | 10592911 | Automatic Transfer Switch, ATS, Replace | 25 | 17 | 8 | 1 | EA | \$8,500.00 | \$8,500 | | | | | | | | | \$8,500 | | | | | | | | | | | | | \$8,500 |
| D5010 | 130 | 10592902 | Automatic Transfer Switch, ATS, Replace | 25 | 17 | 8 | 1 | EA | \$20,000.00 | \$20,000 | | | | | | | | | \$20,000 | | | | | | | | | | | | | \$20,000 |
| D5020 | 130 | 10592972 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$7,600.00 | \$7,600 | | | | | | | | | | | | | | \$7,600 | | | | | | | | \$7,600 |
| D5020 | 130 | 10592918 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$20,000.00 | \$20,000 | | | | | | | | | | | | | | \$20,000 | | | | | | | | \$20,000 |
| D5020 | 120 | 10592950 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$16,000.00 | \$16,000 | | | | | | | | | | | | | | \$16,000 | | | | | | | | \$16,000 |
| D5020 | 151 | 10592793 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | \$10,000 | | | | | | | | \$10,000 |
| D5020 | 130 | 10592776 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | \$6,000 | | | | | | | | \$6,000 |
| D5020 | 130 | 10592963 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$25,000.00 | \$25,000 | | | | | | | | | | | | | | \$25,000 | | | | | | | | \$25,000 |
| D5020 | 237 | 10592912 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$10,000.00 | \$10,000 | | | | | | | | | | | | | | \$10,000 | | | | | | | | \$10,000 |
| D5020 | 130 | 10592762 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$7,600.00 | \$7,600 | | | | | | | | | | | | | | \$7,600 | | | | | | | | \$7,600 |
| D5020 | 151 | 10592782 | Secondary Transformer, Dry, Stepdown, Replace | 30 | 17 | 13 | 1 | EA | \$16,000.00 | \$16,000 | | | | | | | | | | | | | | \$16,000 | | | | | | | | \$16,000 |
| D5020 | 130 | 10592998 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 237 | 10592792 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 120 | 10593008 | Distribution Panel, 120/208 V, Replace | 30 | 17 | 13 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | \$6,000 | | | | | | | | \$6,000 |
| D5020 | 130 | 10592880 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$14,000.00 | \$14,000 | | | | | | | | | | | | | | \$14,000 | | | | | | | | \$14,000 |
| D5020 | 151 | 10592964 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 130 | 10592765 | Distribution Panel, 120/208 V, Replace | 30 | 17 | 13 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | \$6,000 | | | | | | | | \$6,000 |
| D5020 | 120 | 10592948 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 151 | 10592766 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 120 | 10592882 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 130 | 10592811 | Distribution Panel, 120/208 V, Replace | 30 | 17 | 13 | 1 | EA | \$7,000.00 | \$7,000 | | | | | | | | | | | | | | \$7,000 | | | | | | | | \$7,000 |
| D5020 | 151 | 10592794 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 151 | 10592992 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 151 | 10592881 | Distribution Panel, 120/208 V, Replace | 30 | 17 | 13 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | \$6,000 | | | | | | | | \$6,000 |
| D5020 | 130 | 10592975 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$7,000.00 | \$7,000 | | | | | | | | | | | | | | \$7,000 | | | | | | | | \$7,000 |
| D5020 | 151 | 10592875 | Distribution Panel, 120/208 V, Replace | 30 | 17 | 13 | 1 | EA | \$6,000.00 | \$6,000 | | | | | | | | | | | | | | \$6,000 | | | | | | | | \$6,000 |
| D5020 | 130 | 10592979 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$14,000.00 | \$14,000 | | | | | | | | | | | | | | \$14,000 | | | | | | | | \$14,000 |
| D5020 | 120 | 10592887 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 237 | 10592994 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5020 | 120 | 10592939 | Distribution Panel, 277/480 V, Replace | 30 | 17 | 13 | 1 | EA | \$5,300.00 | \$5,300 | | | | | | | | | | | | | | \$5,300 | | | | | | | | \$5,300 |
| D5030 | 134 | 10592809 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 15 | 5 | 1 | EA | \$30,000.00 | \$30,000 | | | | | | \$30,000 | | | | | | | | | | | | | | | | \$30,000 |
| D5030 | 134 | 10592906 | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 20 | 15 | 5 | 1 | EA | \$30,000.00 | \$30,000 | | | | | | \$30,000 | | | | | | | | | | | | | | | | \$30,000 |
| D5040 | Building Exterior | 10592876 | Exterior Light, any type, w/ LED Replacement, Replace | 20 | 17 | 3 | 19 | EA | \$400.00 | \$7,600 | | | | \$7,600 | | | | | | | | | | | | | | | | | | \$7,600 |
| D5040 | Throughout Building | 10592771 | Emergency & Exit Lighting System, Full Interior Upgrade, LED, Replace | 10 | 7 | 3 | 147424 | SF | \$0.65 | \$95,826 | | | | \$95,826 | | | | | | | | | | \$95,826 | | | | | | | | \$191,651 |
| D5040 | Stage | 10592865 | Stage Lighting System, Full Upgrade, Specialty Fixtures, Replace | 20 | 15 | 5 | 800 | SF | \$30.00 | \$24,000 | | | | | | \$24,000 | | | | | | | | | | | | | | | | \$24,000 |
| D5040 | Throughout Building | 10592974 | Interior Lighting System, Full Upgrade, High Density & Standard Fixtures, Replace | 20 | 15 | 5 | 147424 | SF | \$5.00 | \$737,120 | | | | | | \$737,120 | | | | | | | | | | | | | | | | \$737,120 |
| D6060 | Throughout Building | 10592955 | Intercom/PA System, Public Address Upgrade, Facility-Wide, Replace | 20 | 15 | 5 | 147424 | SF | \$1.65 | \$243,250 | | | | | | \$243,250 | | | | | | | | | | | | | | | | \$243,250 |
| D7030 | Throughout Building | 10592760 | Security/Surveillance System, Full System Upgrade, Average Density, Replace | 15 | 9 | 6 | 147424 | SF | \$2.00 | \$294,848 | | | | | | \$294,848 | | | | | | | | | | | | | | | | \$294,848 |
| D7050 | Front Entrance | 10592874 | Fire Alarm Panel, Annunciator, Replace | 15 | 10 | 5 | 1 | EA | \$1,580.00 | \$1,580 | | | | | | \$1,580 | | | | | | | | | | | | | | \$1,580 | \$3,160 | |
| D7050 | Throughout Building | 10592817 | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 20 | 14 | 6 | 147424 | SF | \$3.00 | \$442,272 | | | | | | \$442,272 | | | | | | | | | | | | | | | | \$442,272 |
| D7050 | 130 | 10592864 | Fire Alarm Panel, Fully Addressable, Replace | 15 | 7 | 8 | 1 | EA | \$15,000.00 | \$15,000 | | | | | | | | | \$15,000 | | | | | | | | | | | | | \$15,000 |
| D8010 | Throughout Building | 10592978 | BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install | 15 | 11 | 4 | 147424 | SF | \$2.50 | \$368,560 | | | | \$368,560 | | | | | | | | | | | | | | | \$368,560 | | | \$737,120 |
| E1030 | Laundry Room | 10592961 | Laundry Equipment, Dryer, Commercial, Replace | 15 | 10 | 5 | 1 | EA | \$4,000.00 | \$4,000 | | | | | | \$4,000 | | | | | | | | | | | | | \$4,000 | \$8,000 | | |
| E1030 | Kitchen | 10592889 | Foodservice Equipment, Convection Oven, Single, Replace | 10 | 9 | 1 | 1 | EA | \$5,600.00 | \$5,600 | | \$5,600 | | | | | | | | | | \$5,600 | | | | | | | | | | \$11,200 |
| E1030 | Kitchen | 10592779 | Foodservice Equipment, Convection Oven, Double, Replace | 10 | 7 | 3 | 1 | EA | \$8,280.00 | \$8,280 | | | | \$8,280 | | | | | | | | | | \$8,280 | | | | | | | | \$16,560 |
| E1030 | Kitchen | 10592953 | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace | 15 | 12 | 3 | 1 | EA | \$1,700.00 | \$1,700 | | | | \$1,700 | | | | | | | | | | | | | \$1,700 | | | | | \$3,400 |
| E1030 | Commercial Kitchen | 10592826 | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace | 15 | 12 | 3 | 1 | EA | \$4,600.00 | \$4,60 | | | | | | | | | | | | | | | | | | | | | | |

Replacement Reserves Report



5/15/2026

| Uniformat Code | Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost* | Subtotal | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | Deficiency Repair Estimate |
|--|---------------------------------|----------|--|----------------|------|-----|----------|------|-------------|-----------|------|---------|---------|-------------|-----------|-------------|-----------|---------|-----------|----------|-------------|---------|----------|-------------|-----------|-------------|----------|----------|-------------|-----------|-----------|----------------------------|
| E1030 | Kitchen | 10592903 | Foodservice Equipment, Exhaust Hood, 3 to 6 LF, Replace | 15 | 12 | 3 | 1 | EA | \$3,300.00 | \$3,300 | | | | \$3,300 | | | | | | | | | | | | | | | | | \$3,300 | \$6,600 |
| E1030 | Kitchen | 10592976 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Kitchen | 10592923 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Kitchen | 10592842 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Commercial Kitchen | 10592764 | Foodservice Equipment, Walk-In, Freezer, Replace | 20 | 17 | 3 | 1 | EA | \$25,000.00 | \$25,000 | | | | \$25,000 | | | | | | | | | | | | | | | | | | \$25,000 |
| E1030 | Kitchen | 10592808 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Commercial Kitchen | 10592966 | Foodservice Equipment, Walk-In, Refrigerator, Replace | 20 | 17 | 3 | 1 | EA | \$15,000.00 | \$15,000 | | | | \$15,000 | | | | | | | | | | | | | | | | | | \$15,000 |
| E1030 | Kitchen | 10592805 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 1 | LF | \$1,000.00 | \$1,000 | | | | \$1,000 | | | | | | | | | | | | | | | | | | \$1,000 |
| E1030 | Kitchen | 10592849 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 17 | 3 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Kitchen | 10593011 | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4), Replace | 15 | 11 | 4 | 1 | EA | \$5,700.00 | \$5,700 | | | | | \$5,700 | | | | | | | | | | | | | | | \$5,700 | \$11,400 | |
| E1030 | Kitchen | 10592868 | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4), Replace | 15 | 11 | 4 | 1 | EA | \$5,700.00 | \$5,700 | | | | | \$5,700 | | | | | | | | | | | | | | | \$5,700 | \$11,400 | |
| E1030 | Kitchen | 10592981 | Foodservice Equipment, Griddle, Replace | 15 | 11 | 4 | 1 | EA | \$7,000.00 | \$7,000 | | | | \$7,000 | | | | | | | | | | | | | | | | | \$7,000 | \$14,000 |
| E1030 | Kitchen | 10592787 | Foodservice Equipment, Dairy Cooler/Wells, Replace | 15 | 11 | 4 | 1 | EA | \$3,600.00 | \$3,600 | | | | \$3,600 | | | | | | | | | | | | | | | | | \$3,600 | \$7,200 |
| E1030 | Kitchen | 10592909 | Commercial Kitchen Line, Serving/Warming Equipment, Replace | 20 | 16 | 4 | 2 | LF | \$1,000.00 | \$2,000 | | | | \$2,000 | | | | | | | | | | | | | | | | | | \$2,000 |
| E1030 | Commercial Kitchen | 10592820 | Foodservice Equipment, Walk-In, Evaporator for Refrigerator/Freezer, Replace | 15 | 11 | 4 | 1 | EA | \$4,600.00 | \$4,600 | | | | \$4,600 | | | | | | | | | | | | | | | | \$4,600 | \$9,200 | |
| E1030 | Kitchen | 10592867 | Foodservice Equipment, Exhaust Hood, 3 to 6 LF, Replace | 15 | 11 | 4 | 1 | EA | \$3,300.00 | \$3,300 | | | | \$3,300 | | | | | | | | | | | | | | | | \$3,300 | \$6,600 | |
| E1030 | Kitchen | 10592775 | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4), Replace | 15 | 11 | 4 | 1 | EA | \$5,700.00 | \$5,700 | | | | \$5,700 | | | | | | | | | | | | | | | | \$5,700 | \$11,400 | |
| E1030 | Kitchen | 10592798 | Foodservice Equipment, Refrigerator, 2-Door Reach-In, Replace | 15 | 11 | 4 | 1 | EA | \$4,600.00 | \$4,600 | | | | \$4,600 | | | | | | | | | | | | | | | | \$4,600 | \$9,200 | |
| E1030 | Kitchen | 10592788 | Foodservice Equipment, Refrigerator, 2-Door Reach-In, Replace | 15 | 10 | 5 | 1 | EA | \$4,600.00 | \$4,600 | | | | | \$4,600 | | | | | | | | | | | | | | | \$4,600 | \$9,200 | |
| E1030 | Kitchen | 10592986 | Foodservice Equipment, Dairy Cooler/Wells, Replace | 15 | 10 | 5 | 1 | EA | \$3,600.00 | \$3,600 | | | | | \$3,600 | | | | | | | | | | | | | | | \$3,600 | \$7,200 | |
| E1030 | Kitchen | 10592901 | Foodservice Equipment, IceMaker, Freestanding, Replace | 15 | 10 | 5 | 1 | EA | \$6,700.00 | \$6,700 | | | | | \$6,700 | | | | | | | | | | | | | | | \$6,700 | \$13,400 | |
| E1030 | Kitchen | 10592786 | Foodservice Equipment, Dairy Cooler/Wells, Replace | 15 | 9 | 6 | 1 | EA | \$3,600.00 | \$3,600 | | | | | | \$3,600 | | | | | | | | | | | | | | | | \$3,600 |
| E1030 | Kitchen | 10592904 | Foodservice Equipment, Convection Oven, Single, Replace | 10 | 2 | 8 | 1 | EA | \$5,600.00 | \$5,600 | | | | | | | | | \$5,600 | | | | | | | | | | \$5,600 | \$11,200 | | |
| E1030 | Kitchen | 10592763 | Foodservice Equipment, Convection Oven, Single, Replace | 10 | 2 | 8 | 1 | EA | \$5,600.00 | \$5,600 | | | | | | | | | \$5,600 | | | | | | | | | | \$5,600 | \$11,200 | | |
| E1030 | Kitchen | 10592928 | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels, Replace | 15 | 5 | 10 | 1 | EA | \$1,700.00 | \$1,700 | | | | | | | | | | | \$1,700 | | | | | | | | | | \$1,700 | |
| E1030 | Kitchen | 10592969 | Foodservice Equipment, Commercial Kitchen, 3-Bowl, Replace | 30 | 17 | 13 | 1 | EA | \$2,500.00 | \$2,500 | | | | | | | | | | | | | | \$2,500 | | | | | | | \$2,500 | |
| E1030 | Commercial Kitchen | 10592943 | Foodservice Equipment, Commercial Kitchen, 3-Bowl, Replace | 30 | 17 | 13 | 1 | EA | \$2,500.00 | \$2,500 | | | | | | | | | | | | | | \$2,500 | | | | | | | \$2,500 | |
| E1040 | Hallways | 10592971 | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted, Replace | 10 | 3 | 7 | 2 | EA | \$1,500.00 | \$3,000 | | | | | | | | \$3,000 | | | | | | | | | | \$3,000 | | \$6,000 | | |
| E1060 | Healthroom | 10592896 | Residential Appliances, Refrigerator, 14 to 18 CF, Replace | 15 | 12 | 3 | 1 | EA | \$600.00 | \$600 | | | | \$600 | | | | | | | | | | | | | | | \$600 | \$1,200 | | |
| E1060 | Building service manager office | 10592921 | Residential Appliances, Refrigerator, 14 to 18 CF, Replace | 15 | 12 | 3 | 1 | EA | \$600.00 | \$600 | | | | \$600 | | | | | | | | | | | | | | | \$600 | \$1,200 | | |
| E1060 | Workroom | 10592965 | Residential Appliances, Refrigerator, 14 to 18 CF, Replace | 15 | 12 | 3 | 1 | EA | \$600.00 | \$600 | | | | \$600 | | | | | | | | | | | | | | | \$600 | \$1,200 | | |
| E1060 | Workroom | 10592893 | Residential Appliances, Refrigerator, 14 to 18 CF, Replace | 15 | 12 | 3 | 1 | EA | \$600.00 | \$600 | | | | \$600 | | | | | | | | | | | | | | | \$600 | \$1,200 | | |
| E1060 | Workroom | 10592988 | Residential Appliances, Refrigerator, 14 to 18 CF, Replace | 15 | 11 | 4 | 1 | EA | \$600.00 | \$600 | | | | | \$600 | | | | | | | | | | | | | | \$600 | \$1,200 | | |
| E1070 | Stage | 10592941 | Theater & Stage Equipment, Flameproof Curtain, Medium Weight Velour, Replace | 15 | 11 | 4 | 800 | SF | \$13.00 | \$10,400 | | | | \$10,400 | | | | | | | | | | | | | | \$10,400 | \$20,800 | | | |
| E1070 | Gymnasium | 10593012 | Basketball Backboard, Ceiling-Mounted, Operable, Operable | 30 | 17 | 13 | 6 | EA | \$7,830.00 | \$46,980 | | | | | | | | | | | | | \$46,980 | | | | | | | | \$46,980 | |
| E1070 | Gymnasium | 10592857 | Gym Scoreboard, Electronic Standard, Replace | 30 | 15 | 15 | 1 | EA | \$8,500.00 | \$8,500 | | | | | | | | | | | | | | | | \$8,500 | | | | \$8,500 | | |
| E2010 | Classrooms | 10592773 | Casework, Cabinetry, Standard, Replace | 20 | 15 | 5 | 550 | LF | \$300.00 | \$165,000 | | | | | \$165,000 | | | | | | | | | | | | | | | | \$165,000 | |
| E2010 | Gymnasium | 10592945 | Bleachers, Telescoping Manual, up to 15 Tier (per Seat), Replace | 20 | 14 | 6 | 16 | EA | \$300.00 | \$4,800 | | | | | | \$4,800 | | | | | | | | | | | | | | | \$4,800 | |
| E2010 | Hallways | 10592803 | Fixed Seating, Courtroom/Church, Wood Benches/Pews, Replace | 30 | 15 | 15 | 14 | LF | \$300.00 | \$4,200 | | | | | | | | | | | | | | | \$4,200 | | | | | \$4,200 | | |
| G2060 | Locker Rooms | 10592845 | Park Bench, Wood/Composite/Fiberglass, Replace | 20 | 14 | 6 | 8 | EA | \$600.00 | \$4,800 | | | | | | \$4,800 | | | | | | | | | | | | | | | \$4,800 | |
| Totals, Unescalated | | | | | | | | | | | \$0 | \$5,600 | \$3,400 | \$1,280,156 | \$526,213 | \$3,590,884 | \$782,860 | \$3,000 | \$236,360 | \$32,160 | \$1,782,114 | \$5,600 | \$16,600 | \$864,186 | \$87,903 | \$2,309,310 | \$13,250 | \$10,600 | \$720,850 | \$470,810 | \$26,480 | \$12,768,334 |
| Totals, Escalated (3.0% inflation, compounded annually) | | | | | | | | | | | \$0 | \$5,768 | \$3,607 | \$1,398,861 | \$592,257 | \$4,162,818 | \$934,776 | \$3,690 | \$299,414 | \$41,962 | \$2,395,012 | \$7,752 | \$23,668 | \$1,269,086 | \$132,961 | \$3,597,830 | \$21,262 | \$17,520 | \$1,227,199 | \$825,568 | \$47,826 | \$17,008,835 |

Francis Scott Key Middle School / Site

| Uniformat Code | Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost* | Subtotal | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | Deficiency Repair Estimate |
|----------------|----------------------|----------|---|----------------|------|-----|----------|------|------------|-----------|------|------|----------|------|-----------|------|------|------|------|------|------|------|------|------|------|------|------|------|----------|----------|----------|----------------------------|
| F1020 | Site | 10594697 | Ancillary Building, Classroom/Office Module, Standard/Permanent, Replace | 35 | 15 | 20 | 350 | SF | \$200.00 | \$70,000 | | | | | | | | | | | | | | | | | | | \$70,000 | \$70,000 | | |
| G2020 | Site | 10594693 | Parking Lots, Pavement, Asphalt, Cut & Patch | 0 | -2 | 2 | 14000 | SF | \$5.50 | \$77,000 | | | \$77,000 | | | | | | | | | | | | | | | | | | | \$77,000 |
| G2020 | Site | 10594683 | Parking Lots, Pavement, Asphalt, Mill & Overlay | 25 | 20 | 5 | 32000 | SF | \$3.50 | \$112,000 | | | | | \$112,000 | | | | | | | | | | | | | | | | | \$112,000 |
| G2050 | Site | 10594686 | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Replace | 25 | 23 | 2 | 14500 | SF | \$6.50 | \$94,250 | | | \$94,250 | | | | | | | | | | | | | | | | | | \$94,250 | |
| G2050 | Site | 10594700 | Sports Apparatus, Tennis/Volleyball, Net w/ Posts & Anchors, Replace | 20 | 18 | 2 | 4 | EA | \$1,400.00 | \$5,600 | | | \$5,600 | | | | | | | | | | | | | | | | | | \$5,600 | |
| G2050 | Site | 10594696 | Sports Apparatus, Player/Dugout Benches, 12' Length, Replace | 15 | | | | | | | | | | | | | | | | | | | | | | | | | | | | |

Replacement Reserves Report



5/15/2026

| Uniformat Code | Location | Description | ID | Cost Description | Lifespan (EUL) | EA | RUL | Quantity | Unit | Unit Cost* | Subtotal | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045 | Deficiency Repair Estimate | |
|--|----------|-------------|--|------------------|----------------|----|-----|----------|------|------------|----------|------|------|-----------|------|----------|-----------|----------|----------|------|------|----------|---------|---------|------|----------|---------|------|------|------|---------|-----------|----------------------------|----------|
| G2050 | Site | 10594684 | Athletic Surfaces & Courts, Tennis/Volleyball, Rubber-Acrylic w/ Integral Color, Resurface | | 10 | 6 | 4 | 5750 | SF | \$4.50 | \$25,875 | | | | | \$25,875 | | | | | | | | | | | | | | | | | | \$51,750 |
| G2050 | Site | 10594694 | Sports Apparatus, Soccer, Regulation Goal, Replace | | 20 | 15 | 5 | 2 | EA | \$2,500.00 | \$5,000 | | | | | \$5,000 | | | | | | | | | | | | | | | | | | \$5,000 |
| G2050 | Site | 10594692 | Sports Apparatus, Baseball, Backstop Chain-Link, Replace | | 20 | 14 | 6 | 4 | EA | \$5,000.00 | \$20,000 | | | | | | \$20,000 | | | | | | | | | | | | | | | | | \$20,000 |
| G2050 | Site | 10594681 | Outdoor Spectator Seating, Bleachers, Aluminum Benches (per Seat), Replace | | 25 | 15 | 10 | 10 | EA | \$120.00 | \$1,200 | | | | | | | | | | | \$1,200 | | | | | | | | | | | | \$1,200 |
| G2050 | Site | 10594688 | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay | | 25 | 15 | 10 | 5750 | SF | \$3.50 | \$20,125 | | | | | | | | | | | \$20,125 | | | | | | | | | | | | \$20,125 |
| G2050 | Site | 10594691 | Sports Apparatus, Basketball, Backboard/Rim/Pole, Replace | | 25 | 15 | 10 | 6 | EA | \$4,750.00 | \$28,500 | | | | | | | | | | | \$28,500 | | | | | | | | | | | | \$28,500 |
| G2060 | Site | 10594699 | Bike Rack, Fixed 1-5 Bikes, Replace | | 20 | 14 | 6 | 6 | EA | \$600.00 | \$3,600 | | | | | | \$3,600 | | | | | | | | | | | | | | | | | \$3,600 |
| G2060 | Site | 10594695 | Park Bench, Wood/Composite/Fiberglass, Replace | | 20 | 9 | 11 | 8 | EA | \$600.00 | \$4,800 | | | | | | | | | | | \$4,800 | | | | | | | | | | | | \$4,800 |
| G2060 | Site | 10594690 | Trash Receptacle, Medium-Duty Metal or Precast, Replace | | 20 | 8 | 12 | 4 | EA | \$700.00 | \$2,800 | | | | | | | | | | | | \$2,800 | | | | | | | | | | | \$2,800 |
| G2060 | Site | 10594698 | Signage, Property, Monument, Replace/Install | | 20 | 15 | 5 | 1 | EA | \$3,000.00 | \$3,000 | | | | | \$3,000 | | | | | | | | | | | | | | | | | | \$3,000 |
| G2060 | Site | 10594682 | Flagpole, Metal, Replace | | 30 | 15 | 15 | 1 | EA | \$2,500.00 | \$2,500 | | | | | | | | | | | | | | | | | | | | | | | \$2,500 |
| G4050 | Site | 10594687 | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install | | 20 | 13 | 7 | 15 | EA | \$4,000.00 | \$60,000 | | | | | | | \$60,000 | | | | | | | | | | | | | | | | \$60,000 |
| Totals, Unescalated | | | | | | | | | | | | \$0 | \$0 | \$176,850 | \$0 | \$27,675 | \$120,000 | \$23,600 | \$60,000 | \$0 | \$0 | \$49,825 | \$4,800 | \$2,800 | \$0 | \$25,875 | \$2,500 | \$0 | \$0 | \$0 | \$1,800 | \$70,000 | \$565,725 | |
| Totals, Escalated (3.0% inflation, compounded annually) | | | | | | | | | | | | \$0 | \$0 | \$187,620 | \$0 | \$31,148 | \$139,113 | \$28,180 | \$73,792 | \$0 | \$0 | \$66,961 | \$6,644 | \$3,992 | \$0 | \$39,138 | \$3,895 | \$0 | \$0 | \$0 | \$3,156 | \$126,428 | \$710,068 | |

* Markup has been included in unit costs.

Appendix G: Equipment Inventory List

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------------------|----------|--------|---------------------------|---------------------|----------|---|-----------------------|--------------------------------|--------------|--------------|--------------|---------|-----|
| D10 Conveying | | | | | | | | | | | | | |
| 1 | 10592968 | D1010 | Elevator Controls | Automatic, 1 Car | | Francis Scott Key Middle School / Main Building | Elevator Control room | Schneider Electric | No dataplate | No dataplate | 2008 | | |
| 2 | 10592853 | D1010 | Passenger Elevator | Hydraulic, 2 Floors | 2500 LB | Francis Scott Key Middle School / Main Building | Elevator Control room | Schindler Elevator Corporation | No dataplate | No dataplate | 2009 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|---------------------|----------|--------|-----------------------|---------------------------|----------|---|-----------------|------------------------|-------------------|---------------|--------------|---------|-----|
| D20 Plumbing | | | | | | | | | | | | | |
| 1 | 10592915 | D2010 | Water Heater | Gas, Commercial (125 MBH) | 80 GAL | Francis Scott Key Middle School / Main Building | Janitor closet | Inaccessible | Inaccessible | Inaccessible | 2010 | | |
| 2 | 10592774 | D2010 | Water Heater | Gas, Commercial (200 MBH) | 199 GAL | Francis Scott Key Middle School / Main Building | 134 | State Industries, Inc. | BTH 199A 100 | 1106M002118 | 2011 | | |
| 3 | 10592958 | D2010 | Water Heater | Gas, Commercial (200 MBH) | 199 GAL | Francis Scott Key Middle School / Main Building | 134 | State Industries, Inc. | SUF-100-199NE 200 | 1706104954878 | 2017 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-----------------|----------|--------|--|---------------------|----------|---|-----------------|--------------|------------------------------|--------------|--------------|---------|-----|
| D30 HVAC | | | | | | | | | | | | | |
| 1 | 10592836 | D3020 | Unit Heater | Electric | 5 kW | Francis Scott Key Middle School / Main Building | Storage room | Taskmaster | Inaccessible | Inaccessible | | | |
| 2 | 10592980 | D3020 | Unit Heater [EUH-2] | Electric | 5 kW | Francis Scott Key Middle School / Main Building | 130 | Taskmaster | P3PS106CA1N | NA | 2008 | | |
| 3 | 10592862 | D3020 | Unit Heater [EUH-3] | Electric | 7.5 kW | Francis Scott Key Middle School / Main Building | 134 | Taskmaster | P3P5107CA1N | NA | | | |
| 4 | 10592847 | D3020 | Boiler Supplemental Components | Expansion Tank | 5 GAL | Francis Scott Key Middle School / Main Building | 134 | | | | 2010 | | |
| 5 | 10592846 | D3020 | Boiler Supplemental Components [ET-1] | Expansion Tank | 75 GAL | Francis Scott Key Middle School / Main Building | 134 | Taco | 800-1 | X06034 | 2010 | | |
| 6 | 10592929 | D3030 | Heat Pump [HP 1-13] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 110H | McQuay | W. FCW. 1.060. E.K. Y.R.T.01 | NA | 2009 | | |
| 7 | 10592908 | D3030 | Heat Pump [HP 1-15] | Water Source, 5 TON | 4 TON | Francis Scott Key Middle School / Main Building | 190 | McQuay | W.FCW.1.048. E.K. Y.L.T.01 | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|----------------------|----------|---|-----------------|--------------|-------------------------------------|-----------|--------------|---------|-----|
| 8 | 10592796 | D3030 | Heat Pump [HP 1-16] | Water Source, 10 TON | 9 TON | Francis Scott Key Middle School / Main Building | 190 | McQuay | W.LLG.2.108.K.T.O.U.O.AF.13.2.2.C.2 | NA | 2009 | | |
| 9 | 10592982 | D3030 | Heat Pump [HP 6-1] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 146 | McQuay | W.FCW.1.036.E.K.Y.L.T.01 | NA | 2009 | | |
| 10 | 10592819 | D3030 | Heat Pump [HP 6-12] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 159 | McQuay | W.FCW.1.036.E.K.Y.R.T.01 | NA | 2009 | | |
| 11 | 10592962 | D3030 | Heat Pump [HP 6-13] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 131 | McQuay | W.FCW. 1.036.E.K. Y.L.T.01 | NA | 2009 | | |
| 12 | 10592987 | D3030 | Heat Pump [HP 6-14] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 131 | McQuay | W.FCW 1.036.E.K.Y.R.T.01 | Illegible | 2009 | | |
| 13 | 10592832 | D3030 | Heat Pump [HP 6-15] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 123 | McQuay | W.FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 14 | 10592954 | D3030 | Heat Pump [HP 6-16] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 123 | McQuay | W.FCW.1.036.E.K.Y.R.T.01 | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|---------------------|----------|---|-----------------|--------------|---------------------------------|--------|--------------|---------|-----|
| 15 | 10592924 | D3030 | Heat Pump [HP 6-17] | Water Source, 5 TON | 1.5 TON | Francis Scott Key Middle School / Main Building | 119 | McQuay | W.FCW. 1.019. E. J. Y. R. T. 01 | NA | 2009 | | |
| 16 | 10592899 | D3030 | Heat Pump [HP 6-18] | Water Source, 5 TON | 1.5 TON | Francis Scott Key Middle School / Main Building | 127 | McQuay | W.FCW.1.019. E. J. Y.L.T.01 | NA | 2009 | | |
| 17 | 10592989 | D3030 | Heat Pump [HP 6-19] | Water Source, 5 TON | 1.5 TON | Francis Scott Key Middle School / Main Building | 127 | McQuay | W.FCW. 1.019. E. J. Y.R.T.01 | NA | 2009 | | |
| 18 | 10592761 | D3030 | Heat Pump [HP 6-2] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 146 | McQuay | W.FCW 036.EK. R.T.01 | NA | 2009 | | |
| 19 | 10592841 | D3030 | Heat Pump [HP 6-3] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 154 | McQuay | W.FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 20 | 10592879 | D3030 | Heat Pump [HP 6-4] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 154 | McQuay | W.FCW. 1.036. E.K. Y. R. T. 01 | NA | 2009 | | |
| 21 | 10592930 | D3030 | Heat Pump [HP 6-5] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 166 | McQuay | W.FCW. 1.036. E.K. Y. L. T. 01. | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|-----------------------|----------|---|-----------------|--------------|---------------------------------------|------------|--------------|---------|-----|
| 22 | 10592831 | D3030 | Heat Pump [HP 6-6] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 166 | McQuay | W.FCW. 1.036.E.K. Y.R. T. 01 | NA | 2009 | | |
| 23 | 10592822 | D3030 | Heat Pump [HP 7-1] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 172 | McQuay | W. FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 24 | 10592801 | D3030 | Heat Pump [HP 7-10] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 183 | McQuay | W.FCW. 1.060.E.K.Y.L.T.01 | NA | 2009 | | |
| 25 | 10592870 | D3030 | Heat Pump [HP 7-11] | Water Source, 7.5 TON | 7 TON | Francis Scott Key Middle School / Main Building | 183 | Mcquay | W.LLG.1.070.K.1.00.V.00.AF.13.Z.Z.C.2 | AUBU082200 | 2009 | | |
| 26 | 10592932 | D3030 | Heat Pump [HP 7-2] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 172 | McQuay | W.FCW.1.060.E.K.Y.R.T.01 | NA | 2009 | | |
| 27 | 10592884 | D3030 | Heat Pump [HP 7-3] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 155 | McQuay | W.FCW.1.060. E.K. Y.L.T.01 | NA | 2009 | | |
| 28 | 10592860 | D3030 | Heat Pump [HP 7-4] | Water Source, 5 TON | 2.5 TON | Francis Scott Key Middle School / Main Building | 155 | McQuay | W.FCW.1.030. E.K.Y.L.T. 01 | NA | 2009 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|-----------------------|----------|---|-----------------|--------------|--------------------------------------|---------------|--------------|---------|-----|
| 29 | 10592859 | D3030 | Heat Pump [HP 7-5] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 159 | McQuay | W.FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 30 | 10592970 | D3030 | Heat Pump [HP 7-6] | Water Source, 5 TON | 3.5 TON | Francis Scott Key Middle School / Main Building | 184 | McQuay | W.FCW. 1.042. E.K. Y.R.T.01 | NA | 2009 | | |
| 31 | 10592925 | D3030 | Heat Pump [HP 7-7] | Water Source, 7.5 TON | 5.5 TON | Francis Scott Key Middle School / Main Building | 184 | McQuay | W.LLG.1.070.K.T.O.U.00.AF.13.Z.Z.C.2 | AUBU082200380 | 2009 | | |
| 32 | 10592942 | D3030 | Heat Pump [HP 7-8] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 165 | McQuay | W.FCW. 1.060. E.K. Y.L. T. 01. | NA | 2009 | | |
| 33 | 10593009 | D3030 | Heat Pump [HP 7-9] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 165 | McQuay | W.FCW.1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 34 | 10592759 | D3030 | Heat Pump [HP 8-1] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 230 | McQuay | W. FCW. 1.036. E.K. Y.R.T.01 | NA | 2009 | | |
| 35 | 10592959 | D3030 | Heat Pump [HP 8-10] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 250 | McQuay | W.FCW. 1.036. E.K. Y. R. T. 01. | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|---------------------|----------|---|-----------------|--------------|-----------------------------|--------|--------------|---------|-----|
| 36 | 10593007 | D3030 | Heat Pump [HP 8-11] | Water Source, 5 TON | 4 TON | Francis Scott Key Middle School / Main Building | 261 | McQuay | W.FCW.1.042. E.K. Y.R.T.01 | NA | 2009 | | |
| 37 | 10592931 | D3030 | Heat Pump [HP 8-12] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 261 | McQuay | W.FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 38 | 10592878 | D3030 | Heat Pump [HP 8-13] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 256 | McQuay | W.FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 39 | 10592926 | D3030 | Heat Pump [HP 8-14] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 256 | McQuay | W.FCW.1.036.E.K. Y.R.T.01 | NA | 2009 | | |
| 40 | 10592827 | D3030 | Heat Pump [HP 8-2] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 236 | McQuay | W.FCW.1.036.E.K. Y.L.T.01 | NA | 2009 | | |
| 41 | 10592781 | D3030 | Heat Pump [HP 8-3] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 236 | McQuay | W.FCW.1.036.E.K.Y.R.T.01 | NA | 2009 | | |
| 42 | 10592944 | D3030 | Heat Pump [HP 8-4] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 229 | McQuay | W.FCW.1.060. E.K. Y.L.T.01 | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|---------------------|----------|---|-----------------|--------------|--------------------------------|-----------|--------------|---------|-----|
| 43 | 10592858 | D3030 | Heat Pump [HP 8-7] | Water Source, 5 TON | 1.5 TON | Francis Scott Key Middle School / Main Building | 253 | McQuay | W.FCW. 1.019. E. J. Y.R.T.01 | NA | 2009 | | |
| 44 | 10592949 | D3030 | Heat Pump [HP 8-8] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 253 | McQuay | W.FCW.1.036.E.K.Y.L.T.01 | NA | 2009 | | |
| 45 | 10592920 | D3030 | Heat Pump [HP 8-9] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 250 | McQuay | W.FCW. 1.036. E.K. Y. L. T. 01 | Illegible | 2008 | | |
| 46 | 10592799 | D3030 | Heat Pump [HP 9-1] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 208 | McQuay | W.FCW.1.036.E.K.Y.L.T.01 | NA | 2009 | | |
| 47 | 10592850 | D3030 | Heat Pump [HP 9-10] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 215 | McQuay | W.FCW 036. E.K. Y.L.T.01 | NA | 2009 | | |
| 48 | 10592789 | D3030 | Heat Pump [HP 9-11] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 215 | McQuay | W.FCW. 1.036. E.K. Y. R. T.01 | NA | 2009 | | |
| 49 | 10592995 | D3030 | Heat Pump [HP 9-12] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 205 | McQuay | W.FCW.1.036.E.K. Y.L.T.01 | NA | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|---------------------|----------|---|-----------------|--------------|------------------------------|--------|--------------|---------|-----|
| 50 | 10592957 | D3030 | Heat Pump [HP 9-13] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 205 | McQuay | W.FCW.1.036. E.K. Y.R.T.01 | NA | 2009 | | |
| 51 | 10592807 | D3030 | Heat Pump [HP 9-18] | Water Source, 5 TON | 1 TON | Francis Scott Key Middle School / Main Building | 223 | McQuay | W.FCW. 1.012. E. J. Y.L.T.01 | NA | 2009 | | |
| 52 | 10592951 | D3030 | Heat Pump [HP 9-2] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 208 | McQuay | W.FCW.1.036.E.K.Y.R.T.01 | NA | 2009 | | |
| 53 | 10592829 | D3030 | Heat Pump [HP 9-3] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 218 | McQuay | W.FCW.1.036. E.K. Y.L.T. 01. | NA | 2009 | | |
| 54 | 10592934 | D3030 | Heat Pump [HP 9-4] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 218 | McQuay | W.FCW.1.036. E.K. Y.R.T.01 | NA | 2009 | | |
| 55 | 10592861 | D3030 | Heat Pump [HP 9-6] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 226 | McQuay | W. FCW. 1.036. E.K. Y.L.T.01 | NA | 2009 | | |
| 56 | 10592946 | D3030 | Heat Pump [HP 9-6] | Water Source, 5 TON | 3 TON | Francis Scott Key Middle School / Main Building | 226 | McQuay | W.FCW.1.036.E.K.Y R.T.01 | NA | 2009 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|---------------------------|----------|---|-----------------|---------------------|---------------------------|--------------|--------------|---------|-----|
| 57 | 10592843 | D3030 | Heat Pump [HP 9-8] | Water Source, 5 TON | 5 TON | Francis Scott Key Middle School / Main Building | 229 | McQuay | W.FCW.1.060.E.K. Y.R.T.01 | NA | 2009 | | |
| 58 | 10592892 | D3030 | Split System | Condensing Unit/Heat Pump | 1 TON | Francis Scott Key Middle School / Main Building | Roof | Inaccessible | Inaccessible | Inaccessible | 2008 | | |
| 59 | 10592871 | D3030 | Split System [HP-1] | Condensing Unit/Heat Pump | 2 TON | Francis Scott Key Middle School / Main Building | Roof | Mitsubishi Electric | MUZ-A24NA | Illegible | 2009 | | |
| 60 | 10592983 | D3030 | Split System [HP-1] | Condensing Unit/Heat Pump | 2 TON | Francis Scott Key Middle School / Main Building | Roof | Mitsubishi Electric | MUZ-A24NA | 7004555 | 2008 | | |
| 61 | 10592897 | D3030 | Split System [HP-2] | Condensing Unit/Heat Pump | 2 TON | Francis Scott Key Middle School / Main Building | Roof | Mitsubishi Electric | MUZ-A24NA | Illegible | 2008 | | |
| 62 | 10592933 | D3030 | Split System [HP-2] | Condensing Unit/Heat Pump | 2 TON | Francis Scott Key Middle School / Main Building | Roof | Mitsubishi Electric | MUZ-A24NA | 7003829 | 2008 | | |
| 63 | 10592824 | D3030 | Split System [HP-3] | Condensing Unit/Heat Pump | 1 TON | Francis Scott Key Middle School / Main Building | Roof | Mitsubishi Electric | MU2A09NA | 7003983 | 2009 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|---------------------------------|---|----------|---|-----------------|---------------------|--------------|----------------|--------------|---------|-----|
| 64 | 10592922 | D3030 | Split System Ductless | Multi Zone, Condenser & 2 Evaporators of 1 TON each | | Francis Scott Key Middle School / Main Building | Roof | Illegible | Illegible | Illegible | 2008 | | |
| 65 | 10592952 | D3030 | Split System Ductless | Single Zone | 2 TON | Francis Scott Key Middle School / Main Building | Roof | BOHN | Illegible | Illegible | 2008 | | |
| 66 | 10592825 | D3050 | Pump [P-1] | Distribution, HVAC Heating Water | 150 HP | Francis Scott Key Middle School / Main Building | 134 | Baldor Reliance | EM2558T-4 | C0802050070 | 2010 | | |
| 67 | 10592772 | D3050 | Pump [P-2] | Distribution, HVAC Heating Water | 150 HP | Francis Scott Key Middle School / Main Building | 134 | Baldor Reliance | EM2558T-4 | C0802040065 | 2010 | | |
| 68 | 10592778 | D3050 | Make-Up Air Unit [HV-1] | MUA or MAU | 3000 CFM | Francis Scott Key Middle School / Main Building | Roof | Preeva | Illegible | Illegible | 2008 | | |
| 69 | 10592927 | D3050 | Make-Up Air Unit [SAF-A] | MUA or MAU | 4000 CFM | Francis Scott Key Middle School / Main Building | Roof | CaptiveAire Systems | A2-D.500-G15 | 457697 | 2008 | | |
| 70 | 10592938 | D3060 | Exhaust Fan [EF-4] | Centrifugal, 16" Damper | 1200 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | GB-121-4-X | 11290050 08.04 | 2008 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|-------------------------|----------|---|-----------------|--------------|----------------|---------------|--------------|---------|-----|
| 71 | 10593004 | D3060 | Exhaust Fan [EF-B1] | Centrifugal, 28" Damper | 8500 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | GB-360-20-X | 11290012 0804 | 2008 | | |
| 72 | 10592835 | D3060 | Exhaust Fan [EF-B2] | Centrifugal, 28" Damper | 8500 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | GB-350-20-X | 11790020 0804 | 2008 | | |
| 73 | 10592960 | D3060 | Exhaust Fan [EF-E1] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE-101HP-4-X | 11290041 0604 | 2008 | | |
| 74 | 10592783 | D3060 | Exhaust Fan [EF-E2] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HP-4-X | 11290039 0804 | | | |
| 75 | 10592828 | D3060 | Exhaust Fan [EF-E3] | Centrifugal, 16" Damper | 1500 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE-101HP-4-X | 11290022 0804 | 2008 | | |
| 76 | 10592973 | D3060 | Exhaust Fan [EF-E4] | Centrifugal, 12" Damper | 550 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HP-4-X | 030 2200611 | | | |
| 77 | 10592795 | D3060 | Exhaust Fan [EF-E5] | Centrifugal, 12" Damper | 600 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HPA-X | 11290020 0804 | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|-------------------------|----------|---|-----------------|---------------|-------------------|----------------|--------------|---------|-----|
| 78 | 10592785 | D3060 | Exhaust Fan [EF-E6] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HP-4-X | 11290029 0804 | | | |
| 79 | 10592863 | D3060 | Exhaust Fan [EF-F1] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HP-4-X | 7030 070063115 | 2008 | | |
| 80 | 10592852 | D3060 | Exhaust Fan [EF-F2] | Centrifugal, 12" Damper | 600 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE-101HP-4-X | 11290021 0804 | 2008 | | |
| 81 | 10592854 | D3060 | Exhaust Fan [EF-F3] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Grease Master | CUBE 10 1HP-4 - X | 11290023 0604 | 2008 | | |
| 82 | 10592784 | D3060 | Exhaust Fan [EF-G1] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUE-095-6-X | 11290046 0804 | | | |
| 83 | 10592877 | D3060 | Exhaust Fan [EF-G2] | Centrifugal, 12" Damper | 500 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUE 095-6-X | 11290047 0804 | | | |
| 84 | 10592900 | D3060 | Exhaust Fan [EF-G3] | Centrifugal, 12" Damper | 200 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUE-095-6-X | 11290044 0804 | | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|----------------------------|-------------------------|----------|---|-----------------|---------------------|----------------|----------------|--------------|---------|-----|
| 85 | 10592985 | D3060 | Exhaust Fan [EF-G4] | Centrifugal, 12" Damper | 250 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUE 095-6-X | 11290043 0804 | | | |
| 86 | 10592802 | D3060 | Exhaust Fan [EF-G5] | Centrifugal, 12" Damper | 200 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUE 095-6-X | 11290046 0804 | | | |
| 87 | 10592851 | D3060 | Exhaust Fan [EF-G6] | Centrifugal, 12" Damper | 200 CFM | Francis Scott Key Middle School / Main Building | Roof | ANNEXAIR | Illegible | Illegible | | | |
| 88 | 10592812 | D3060 | Exhaust Fan [EF-J] | Centrifugal, 12" Damper | 800 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101HP-4-X | 11290053 0804 | | | |
| 89 | 10592917 | D3060 | Exhaust Fan [EF-N] | Centrifugal, 12" Damper | 500 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 101KP-4-X | 11290090 0804 | | | |
| 90 | 10592797 | D3060 | Exhaust Fan [EF-P] | Centrifugal, 12" Damper | 700 CFM | Francis Scott Key Middle School / Main Building | Roof | Greenheck | CUBE 121-4-X | 2060 36 393911 | | | |
| 91 | 10592810 | D3060 | Exhaust Fan [EF-X] | Centrifugal, 28" Damper | 7500 CFM | Francis Scott Key Middle School / Main Building | Roof | CaptiveAire Systems | Illegible | Illegible | | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|--------------------------------|---------------------------------|----------|---|--------------------|--------------|--------------|--------------------|--------------|---------|-----|
| 92 | 10592800 | D3060 | Exhaust Fan [WPRC] | Centrifugal, 16" Damper | 1100 CFM | Francis Scott Key Middle School / Main Building | Roof | No dataplate | No dataplate | No dataplate | 2008 | | |
| 93 | 10592758 | D3060 | Supplemental Components | Air Curtain, 5' Wide Non-Heated | 2.4 | Francis Scott Key Middle School / Main Building | Commercial Kitchen | Mars | WA36 | 0905PWA36-L 125338 | 2008 | | |
| 94 | 10592768 | D3060 | Supplemental Components | Air Curtain, 8' Wide Heated | 9.5 | Francis Scott Key Middle School / Main Building | Commercial Kitchen | Mars | NHV48 | 0803FNHV48-L | 2010 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------------------------|----------|--------|--------------------------------|------------------------------------|----------|---|--------------------|-----------------|-----------|---------|--------------|---------|-----|
| D40 Fire Protection | | | | | | | | | | | | | |
| 1 | 10592813 | D4010 | Backflow Preventer | Fire Suppression | 3 INCH | Francis Scott Key Middle School / Main Building | 134 | Watts Regulator | Illegible | 186683 | 2010 | | |
| 2 | 10592780 | D4010 | Backflow Preventer | Fire Suppression | 6 IN | Francis Scott Key Middle School / Main Building | 134 | Watts Regulator | Illegible | 11-0015 | 2010 | | |
| 3 | 10593006 | D4010 | Fire Suppression System | Commercial Kitchen, per LF of Hood | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | | | | 2008 | | 10 |
| 4 | 10592891 | D4030 | Fire Extinguisher | Wet Chemical/CO2 | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | | | | | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-----------------------|----------|--------|--|--------------------------------|------------|---|------------------------------|------------------------------|------------|-----------|--------------|---------|-----|
| D50 Electrical | | | | | | | | | | | | | |
| 1 | 10592804 | D5010 | Generator | Diesel | 250 KW | Francis Scott Key Middle School / Main Building | Right Side Building Exterior | Generac | 9722300400 | 2098679 | 2008 | | |
| 2 | 10592940 | D5010 | Solar Power | Inverter | 7500 WATTS | Francis Scott Key Middle School / Main Building | Right Side Building Exterior | Utility Interactive Inverter | PUS-75 | 9818BA | 2009 | | |
| 3 | 10592815 | D5010 | Solar Power | Photovoltaic (PV) Panel, 24 SF | | Francis Scott Key Middle School / Main Building | Roof | | | | 2010 | | 552 |
| 4 | 10592911 | D5010 | Automatic Transfer Switch [TRANSFER SWITCH PANEL] | ATS | 100 AMP | Francis Scott Key Middle School / Main Building | 130 | Generac | 9722300100 | 96732 | 2008 | | |
| 5 | 10592902 | D5010 | Automatic Transfer Switch [TRANSFER SWITCH PANEL] | ATS | 400 AMP | Francis Scott Key Middle School / Main Building | 130 | Generac | 9722300300 | 96733 | 2008 | | |
| 6 | 10592776 | D5020 | Secondary Transformer [TRANSFORMER E] | Dry, Stepdown | 15 KVA | Francis Scott Key Middle School / Main Building | 130 | Siemens | 3F3Y015TP1 | 1M0111423 | 2008 | | |
| 7 | 10592972 | D5020 | Secondary Transformer [TRANSFORMER EL] | Dry, Stepdown | 45 KVA | Francis Scott Key Middle School / Main Building | 130 | Siemens | 3F3Y045TP1 | 1M0104908 | 2008 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|---|---------------|-----------|---|-----------------|--------------|---------------|---------------|--------------|---------|-----|
| 8 | 10592793 | D5020 | Secondary Transformer [TRANSFORMER L1A] | Dry, Stepdown | 75 KVA | Francis Scott Key Middle School / Main Building | 151 | Siemens | 3F3Y075TP1 | 1M0112064 | 2008 | | |
| 9 | 10592782 | D5020 | Secondary Transformer [TRANSFORMER L1B] | Dry, Stepdown | 112.5 KVA | Francis Scott Key Middle School / Main Building | 151 | Siemens | 3F3Y112TP1 | 1M0102471 | 2008 | | |
| 10 | 10592950 | D5020 | Secondary Transformer [TRANSFORMER L1C] | Dry, Stepdown | 112.5 KVA | Francis Scott Key Middle School / Main Building | 120 | Siemens | 3F3Y112TP1 | 1M0102470 | 2008 | | |
| 11 | 10592912 | D5020 | Secondary Transformer [TRANSFORMER L2A] | Dry, Stepdown | 75 KVA | Francis Scott Key Middle School / Main Building | 237 | Siemens | 3F3Y075TP1 | 1M0110793 | 2008 | | |
| 12 | 10592963 | D5020 | Secondary Transformer [TRANSFORMER MD] | Dry, Stepdown | 225 KVA | Francis Scott Key Middle School / Main Building | 130 | Siemens | 3F3Y225K13TP1 | 3F3Y225K13TP1 | 2008 | | |
| 13 | 10592918 | D5020 | Secondary Transformer [TRANSFORMER MDPK] | Dry, Stepdown | 150 KVA | Francis Scott Key Middle School / Main Building | 130 | Siemens | 3F3Y150K13TP1 | 3F3Y150K13TP1 | 2008 | | |
| 14 | 10592762 | D5020 | Secondary Transformer [TRANSFORMER ML] | Dry, Stepdown | 45 KVA | Francis Scott Key Middle School / Main Building | 130 | Siemens | 3F3Y045TP1 | 1M0086989 | 2008 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|---|------------|----------|---|-----------------|--------------|---------------|----------------------|--------------|---------|-----|
| 15 | 10592885 | D5020 | Switchboard [MAIN SWITCHBOARD] | 277/480 V | 4000 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | SB3 REV. A | 3001622613-010600-01 | 2008 | | 2 |
| 16 | 10592998 | D5020 | Distribution Panel [PANEL EH] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | P1E42ML400CTS | 3001622613 | 2008 | | |
| 17 | 10592964 | D5020 | Distribution Panel [PANEL H1A-1] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1E42ML400CTS | 001622613 | 2008 | | |
| 18 | 10592992 | D5020 | Distribution Panel [PANEL H1A-1] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1E42ML400CBS | 3001622613 | 2008 | | |
| 19 | 10592794 | D5020 | Distribution Panel [PANEL H1B-1] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1E42ML400CBS | 3001622613 | 2008 | | |
| 20 | 10592766 | D5020 | Distribution Panel [PANEL H1B-2] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1E42ML400CTS | 3001622613 | 2008 | | |
| 21 | 10592939 | D5020 | Distribution Panel [PANEL H1C-1] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 120 | Siemens | P1E42ML400CBS | 3001622613 | 2008 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|--|------------|----------|--|-----------------|--------------|---------------|------------|--------------|---------|-----|
| 22 | 10592948 | D5020 | Distribution Panel [PANEL H1C-2] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 120 | Siemens | P1E42ML400CTS | 3001622613 | 2008 | | |
| 23 | 10592994 | D5020 | Distribution Panel [PANEL H2A-1] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 237 | Siemens | P1E42ML400CBS | 3001622613 | 2008 | | |
| 24 | 10592792 | D5020 | Distribution Panel [PANEL H2A-2] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 237 | Siemens | P1E42ML400CTS | 3001622613 | 2008 | | |
| 25 | 10592875 | D5020 | Distribution Panel [PANEL L1B1] | 120/208 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1C42JX400CBS | 3001622613 | 2008 | | |
| 26 | 10592881 | D5020 | Distribution Panel [PANEL L1B-2] | 120/208 V | 400 AMP | Francis Scott Key Middle School / Main Building | 151 | Siemens | P1C42ML400CTS | 3001622613 | 2008 | | |
| 27 | 10593008 | D5020 | Distribution Panel [PANEL L1C-1] | 120/208 V | 400 AMP | Francis Scott Key Middle School / Main Building | 120 | Siemens | P1C42JX400CBS | 3001622613 | 2008 | | |
| 28 | 10592887 | D5020 | Distribution Panel [PANEL L1C-2] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 120 | Siemens | P1C42ML400CTS | 3001622613 | 2008 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|--|---------------------|----------|--|-----------------|--------------|---------------|--------------|--------------|---------|-----|
| 29 | 10592882 | D5020 | Distribution Panel [PANEL L1C-3] | 277/480 V | 400 AMP | Francis Scott Key Middle School / Main Building | 120 | Siemens | P1C42ML400CBS | 3001622613 | 2008 | | |
| 30 | 10592811 | D5020 | Distribution Panel [PANEL MD] | 120/208 V | 600 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | P4C75LX600FBS | 3001622613 : | 2008 | | |
| 31 | 10592880 | D5020 | Distribution Panel [PANEL MDPA] | 277/480 V | 1200 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | P4E75ML120FBS | 3001622613 | 2008 | | |
| 32 | 10592979 | D5020 | Distribution Panel [PANEL MDPB] | 277/480 V | 1200 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | P4E60ML120FBS | 3001622613 | 2008 | | |
| 33 | 10592765 | D5020 | Distribution Panel [PANEL MDPK] | 120/208 V | 400 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | P4C60JX400FBS | 3002012571 | 2008 | | |
| 34 | 10592975 | D5020 | Distribution Panel [PANEL MP] | 277/480 V | 600 AMP | Francis Scott Key Middle School / Main Building | 130 | Siemens | Illegible | Illegible | 2008 | | |
| 35 | 10592906 | D5030 | Variable Frequency Drive [PUMP 1] | VFD, by HP of Motor | 75 HP | Francis Scott Key Middle School / Main Building | 134 | ABB | Illegible | 2081600134 | 2010 | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|--|---------------------|----------|---|-----------------|--------------|------------|------------|--------------|---------|-----|
| 36 | 10592809 | D5030 | Variable Frequency Drive [PUMP 2] | VFD, by HP of Motor | 75 HP | Francis Scott Key Middle School / Main Building | 134 | ABB | ACH BC18-4 | 2081600013 | 2010 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|---|----------|--------|-------------------------|-------------------|----------|----------|--|--------------|------------------------|--------------|--------------|---------|-----|
| D70 Electronic Safety & Security | | | | | | | | | | | | | |
| 1 | 10592864 | D7050 | Fire Alarm Panel | Fully Addressable | | | Francis Scott Key Middle School / Main Building | 130 | Vsc fire & security | No dataplate | No dataplate | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------------------|----------|--------|------------------------------|----------------------------|----------|---|--------------------|------------------|----------------|------------------|--------------|---------|-----|
| E10 Equipment | | | | | | | | | | | | | |
| 1 | 10592961 | E1030 | Laundry Equipment | Dryer, Commercial | 50 LB | Francis Scott Key Middle School / Main Building | Laundry Room | Alliance Laundry | HC60MN20U60001 | 0811004203 | | | |
| 2 | 10592969 | E1030 | Foodservice Equipment | Commercial Kitchen, 3-Bowl | | Francis Scott Key Middle School / Main Building | Kitchen | | | | 2008 | | |
| 3 | 10592943 | E1030 | Foodservice Equipment | Commercial Kitchen, 3-Bowl | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | | | | 2008 | | |
| 4 | 10592779 | E1030 | Foodservice Equipment | Convection Oven, Double | | Francis Scott Key Middle School / Main Building | Kitchen | Blodgett | NA | 120105R4055T | 2008 | | |
| 5 | 10592904 | E1030 | Foodservice Equipment | Convection Oven, Single | | Francis Scott Key Middle School / Main Building | Kitchen | Rational | LM100CG.AXXXXX | 062SJ22103006529 | 2023 | | |
| 6 | 10592763 | E1030 | Foodservice Equipment | Convection Oven, Single | | Francis Scott Key Middle School / Main Building | Kitchen | Rational | LM100CG.AXXXXX | Q62SJ23033042714 | 2023 | | |
| 7 | 10592889 | E1030 | Foodservice Equipment | Convection Oven, Single | | Francis Scott Key Middle School / Main Building | Kitchen | Rational | SCC 102G | G12SE08032133749 | 2009 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|------------------------------|---|----------|---|-----------------|--------------------------|-----------|-------------|--------------|---------|-----|
| 8 | 10592786 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Francis Scott Key Middle School / Main Building | Kitchen | Carrier | SMF 49 | 29307.26003 | | | |
| 9 | 10592787 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Francis Scott Key Middle School / Main Building | Kitchen | Beverage-Air Corporation | SMF49 | 29307.26003 | 2008 | | |
| 10 | 10592986 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Francis Scott Key Middle School / Main Building | Kitchen | Beverage-Air Corporation | SMF 49 | 29307.26003 | | | |
| 11 | 10592903 | E1030 | Foodservice Equipment | Exhaust Hood, 3 to 6 LF | | Francis Scott Key Middle School / Main Building | Kitchen | CaptiveAire Systems | 6630 ND-2 | 697373 | 2008 | | |
| 12 | 10592867 | E1030 | Foodservice Equipment | Exhaust Hood, 3 to 6 LF | | Francis Scott Key Middle School / Main Building | Kitchen | CaptiveAire Systems | 6630 ND-2 | 697373 | 2009 | | |
| 13 | 10592953 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Francis Scott Key Middle School / Main Building | Kitchen | Victory | Illegible | Illegible | 2008 | | |
| 14 | 10592928 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Francis Scott Key Middle School / Main Building | Kitchen | Victory | Illegible | Illegible | | | |

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|------------------------------|--|----------|---|-----------------|--------------|-------------|---------------|--------------|---------|-----|
| 15 | 10593011 | E1030 | Foodservice Equipment | Food Warmer, Tabletop Drawers (Set of 4) | | Francis Scott Key Middle School / Main Building | Kitchen | Delfield | SH-4-NU-29A | 0807150001963 | 2008 | | |
| 16 | 10592868 | E1030 | Foodservice Equipment | Food Warmer, Tabletop Drawers (Set of 4) | | Francis Scott Key Middle School / Main Building | Kitchen | Delfield | KH-4-NU-29A | 0807150001949 | 2008 | | |
| 17 | 10592775 | E1030 | Foodservice Equipment | Food Warmer, Tabletop Drawers (Set of 4) | | Francis Scott Key Middle School / Main Building | Kitchen | Delfield | KH-4-NU-29A | 0807150001950 | 2008 | | |
| 18 | 10592981 | E1030 | Foodservice Equipment | Griddle | | Francis Scott Key Middle School / Main Building | Kitchen | Garland | MST44SE | 0802100101862 | 2008 | | |
| 19 | 10592901 | E1030 | Foodservice Equipment | Icemaker, Freestanding | | Francis Scott Key Middle School / Main Building | Kitchen | Ice-O-Matic | B570 | 140719971 | | | |
| 20 | 10592788 | E1030 | Foodservice Equipment | Refrigerator, 2-Door Reach-In | | Francis Scott Key Middle School / Main Building | Kitchen | Victory | RS-2D-S7-PT | C0862014 | 2008 | | |
| 21 | 10592798 | E1030 | Foodservice Equipment | Refrigerator, 2-Door Reach-In | | Francis Scott Key Middle School / Main Building | Kitchen | Victory | RS-2D-87-PT | C0862015 | 2008 | | |

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|----------|--------|------------------------------|--|-----------|---|--------------------|--------------|--------------|--------------|--------------|---------|-----|
| 22 | 10592826 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refrigerator/Freezer | 115 VOLTS | Francis Scott Key Middle School / Main Building | Commercial Kitchen | Heatcraft | ADT130AK | D08F00684 | 2008 | | |
| 23 | 10592820 | E1030 | Foodservice Equipment | Walk-In, Evaporator for Refrigerator/Freezer | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | BOHN | No dataplate | No dataplate | 2008 | | |
| 24 | 10592764 | E1030 | Foodservice Equipment | Walk-In, Freezer | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | Hartford | 18600S | 0W438F-2 | 2008 | | |
| 25 | 10592966 | E1030 | Foodservice Equipment | Walk-In, Refrigerator | | Francis Scott Key Middle School / Main Building | Commercial Kitchen | Hartford | 18600S | 0W438F-1 | 2008 | | |
| 26 | 10592971 | E1040 | Healthcare Equipment | Defibrillator (AED), Cabinet-Mounted | | Francis Scott Key Middle School / Main Building | Hallways | | | | | | 2 |