



# FACILITY CONDITION ASSESSMENT

*prepared for*

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4000  
Rockville, MD 20850



Lynnbrook Center  
8001 Lynbrook Drive  
Bethesda, MD 20814

**PREPARED BY:**

*Bureau Veritas*  
6021 University Boulevard, Suite 200  
Ellicott City, MD 21043  
800.733.0660  
[www.bvna.com](http://www.bvna.com)

**BV CONTACT:**

*Bill Champion*  
Senior Program Manager  
443.622.5067  
[Bill.Champion@bureauveritas.com](mailto:Bill.Champion@bureauveritas.com)

**BV PROJECT #:**

172559.25R000-223.354

**DATE OF REPORT:**

*August 11, 2025*

**ON SITE DATE:**

*July 15, 2025*

**Bureau Veritas**

6021 University Boulevard, Suite 200 | Ellicott City, MD 21043 | [www.bvna.com](http://www.bvna.com) | p 800.733.0660

## TABLE OF CONTENTS

|   |           |
|---|-----------|
| <b>1. Executive Summary .....</b>                   | <b>1</b>  |
| Property Overview and Assessment Details .....      | 1         |
| Campus Findings and Deficiencies .....              | 2         |
| Facility Characteristic Survey .....                | 3         |
| Facility Condition Index (FCI) Depleted Value ..... | 4         |
| Immediate Needs.....                                | 5         |
| Key Findings .....                                  | 6         |
| Plan Types.....                                     | 7         |
| <b>2. Elementary School Building.....</b>           | <b>8</b>  |
| <b>3. Site Summary.....</b>                         | <b>11</b> |
| <b>4. ADA Accessibility .....</b>                   | <b>13</b> |
| <b>5. Purpose and Scope .....</b>                   | <b>15</b> |
| <b>6. Opinions of Probable Costs .....</b>          | <b>17</b> |
| Methodology .....                                   | 17        |
| Definitions .....                                   | 18        |
| <b>7. Certification.....</b>                        | <b>19</b> |
| <b>8. Appendices .....</b>                          | <b>20</b> |

## 1. Executive Summary

### Property Overview and Assessment Details

| General Information                      |  |
|--|--|
| <b>Property Type</b>                     | Elementary school campus   |
| <b>Number of Buildings</b>               | One  |
| <b>Main Address</b>                      | 8001 Lynbrook Drive, Bethesda, MD 20814  |
| <b>Site Developed</b>                    | 1942<br>Renovated 1995   |
| <b>Outside Occupants / Leased Spaces</b> | None   |
| <b>Date(s) of Visit</b>                  | July 15, 2025  |
| <b>Management Point of Contact</b>       | Montgomery County Public Schools<br>Mr. Greg Kellner<br>Facilities Manager, Office of Facilities Management<br>Direct 240.740.7746<br><a href="mailto:Gregory_Kellner@mcpssmd.org">Gregory_Kellner@mcpssmd.org</a> |
| <b>On-site Point of Contact (POC)</b>    | same as above  |
| <b>Assessment and Report Prepared By</b> | Chris Ledbetter  |
| <b>Reviewed By</b>                       | Daniel White, <i>Technical Report Reviewer for</i> ,<br>Bill Champion<br>Program Manager<br>443.622.5067<br><a href="mailto:Bill.Champion@bureauveritas.com">Bill.Champion@bureauveritas.com</a>                   |
| <b>AssetCalc Link</b>                    | Full dataset for this assessment can be found at:<br><a href="https://www.assetcalc.net/">https://www.assetcalc.net/</a>   |

## Campus Findings and Deficiencies

### Historical Summary

Lynbrook Center was originally constructed in 1942. The school building latest renovation was in 1995.

### Architectural

In general, the structure appears to be sound, with no significant areas of settlement or structural-related deficiencies observed. The roof is outdated with a history of roof leaks reported. The roof is recommended for short-term replacement. The interior finishes are in fair condition. Typical lifecycle-based interior and exterior finish replacements are budgeted and anticipated.

### Mechanical, Electrical, Plumbing and Fire (MEPF)

The MEPF systems and infrastructure vary significantly in age; while the majority of components were replaced and upgraded during the 1995 renovation. Heating and cooling are provided by a central system with boilers feeding fan coil units, unit heaters and radiators. Although the boilers were recently replaced, Individual split systems and package units are outdated and inefficient. The facility HVAC is controlled using an outdated pneumatic system supplied by an air compressor. For improved reliability and increased control, full conversion to a web-based direct digital control (DDC) platform is highly recommended.

Most of the domestic water lines are galvanized iron original to the 1942 construction. To date there has been no history of chronic leaks or water pressure problems. However, it is quite common for galvanized iron piping to develop problems due to long-term corrosion with thinning walls and/or interior mineral deposit accumulation, especially once it has aged 40 or 50 years. As such, Bureau Veritas recommends replacing all the plumbing supply lines with copper.

The electrical system in the building was replaced, as evidenced by manufacture dates on the electrical panels, and the building electrical system appeared to be overall in fair condition.

The central alarm panel appears to be more than 15 years old. Based on its age and because replacement parts and components for this type of equipment may be obsolete, the alarm panel requires replacement.

The vast majority of the building is not protected by fire suppression. Due to its construction date, the facility is most likely “grandfathered” by code and the installation of fire sprinklers not required until major renovations are performed. Regardless of when or if installation of facility-wide fire suppression is required by the governing municipality, Bureau Veritas recommends a retrofit be performed.

### Site

In general, the site has been well maintained. Sidewalks have minor cracks, and asphalt pavement has been regularly maintained with seal coating and striping, with only a few areas of significant cracking in the main parking lot. The majority of the site lighting consists of energy inefficient metal halide and high-pressure sodium fixtures and lamps.

## Facility Characteristic Survey

The facility characteristics of school and associated buildings are shown below.

Indoor air quality including temperature and relative humidity level are monitored centrally. Most instructional spaces are equipped with IAQ sensors. Each general and specialty classroom has a heating, ventilation, and air conditioning (HVAC) system capable of maintaining a temperature between 68°F and 75°F and a relative humidity between 30% and 60% at full occupancy. Each general, science, and fine-arts classroom had an HVAC system that continuously moves air and is capable of maintaining a carbon dioxide level of not more than 1,200 parts per million. The temperature, relative humidity and air quality were measured at a work surface in the approximate center of the classroom.

The acoustics with the exception of physical-education spaces, each general and specialty classroom are maintainable at a sustained background sound level of less than 55 decibels. The sound levels were measured at a work surface in the approximate center of the classroom.

Each general and specialty classroom had a lighting system capable of maintaining at least 50 foot-candles of well-distributed light. The school has appropriate task lighting in specialty classrooms where enhanced visibility is required. The light levels measured at a work surface located in the approximate center of the classroom, between clean light fixtures. The school makes efficient use of natural light for students, teachers, and energy conversation.

Classroom spaces, including those for physical education, were sufficient for educational programs that are appropriate for the class-level needs. With the exception of physical-education spaces, each general and specialty classroom contained a work surface and seat for each student in the classroom. The work surface and seat were appropriate for the normal activity of the class conducted in the room.

Each general and specialty classroom had an erasable surface and a surface suitable for projection purposes, appropriate for group classroom instruction, and a display surface.

Each general and specialty classroom had storage for classroom materials or access to conveniently located storage.

With the exception of physical-education spaces and music-education spaces, each general and specialty classroom shall had a work surface and seat for the teacher and for any aide assigned to the classroom. The classroom had secure storage for student records that is located in the classroom or is conveniently accessible to the classroom.

The school was constructed with sustainable design practices. The schools use durable, timeless, low-maintenance exterior materials. The school's materials (particularly shell) should withstand time as well as potential impacts related to structural, site and climate changes.

The school is functionally equitable. All students in this school have access to safe, well-maintained, and appropriately equipped learning environments as students in other MCPS schools.

## Facility Condition Index (FCI) Depleted Value

A School Facility's total FCI Depleted Value (below) and FCI Replacement Value (above) are the sum of all of its building assets and systems values. A School Facility with full estimated life of all systems (a brand new school) would have a 0 FCI. The FCIs cannot exceed 1.

The Facility Condition Index (FCI) Depleted Value quantifies the depleted life and value of a facility's primary building assets, systems and components such as roofs, windows, walls, and HVAC systems. FCI Depleted Value metrics are useful for estimating the levels of spending necessary to achieve and maintain a specific level of physical condition. Lower scores are better, as facilities with lower FCI scores have fewer building-system deficiencies, are more reliable, and will require less maintenance spending on systems replacement and mission-critical emergencies.

The FCI Depleted Value of this school is 0.636007.

## Immediate Needs

There are no immediate needs to report.

## Key Findings



### **Flooring in Poor condition.**

Vinyl Tile (VCT), w/ Asbestos Abatement  
Lynnbrook Center Throughout Building

Uniformat Code: C2030  
Recommendation: **Replace in 2026**

Priority Score: **81.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$1,600

**\$\$\$\$**


Stained floor - AssetCALC ID: 9554035

## Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.

### Plan Type Descriptions and Distribution

|                              |   |
|------------------------------|---|
| <b>Safety</b>                | ■ An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. |
| <b>Performance/Integrity</b> | ■ Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.    |
| <b>Accessibility</b>         | ■ Does not meet ADA, UFAS, and/or other accessibility requirements.   |
| <b>Environmental</b>         | ■ Improvements to air or water quality, including removal of hazardous materials from the building or site.   |
| <b>Retrofit/Adaptation</b>   | ■ Components, systems, or spaces recommended for upgrades in order to meet current standards, facility usage, or client/occupant needs.                   |
| <b>Aged But Functional</b>   | ■ Any component or system that has aged past its industry-average expected useful life (EUL) but is not currently deficient or problematic.               |
| <b>Lifecycle/Renewal</b>     | ■ Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted.             |



## 2. Elementary School Building



### Elementary School Building: Systems Summary

|                              |  |                  |
|------------------------------|--|------------------|
| <b>Address</b>               | 8001 Lynbrook Drive, Bethesda, MD 20814  |                  |
| <b>Constructed/Renovated</b> | 1942/1995  |                  |
| <b>Building Area</b>         | 35,000 SF  |                  |
| <b>Number of Stories</b>     | 2 above grade  |                  |
| <b>System</b>                | <i>Description</i>   | <i>Condition</i> |
| <b>Structure</b>             | Masonry load bearing structures over concrete pad column footings  | Fair             |
| <b>Facade</b>                | Primary Wall Finish: Brick<br>Windows: Vinyl   | Fair             |
| <b>Roof</b>                  | Primary: Flat construction with built-up finish  | Fair             |
| <b>Interiors</b>             | Walls: Painted gypsum board, ceramic tile<br>Floors: VCT, ceramic tile, Unfinished<br>Ceilings: ACT  | Good             |
| <b>Elevators</b>             | None   | --               |
| <b>Plumbing</b>              | Distribution: Galvanized supply and cast-iron<br>Hot Water: Electric water heaters with integral tanks<br>Fixtures: Toilets, urinals, and sinks in all restrooms | Poor             |

## Elementary School Building: Systems Summary

|                                |  |      |
|--------------------------------|--|------|
| <b>HVAC</b>                    | Central System: Boilers feeding baseboard radiators and ventilators<br>Non-Central System: Packaged units<br>Supplemental components: Ductless split system  | Fair |
| <b>Fire Suppression</b>        | Fire extinguishers only  | Fair |
| <b>Electrical</b>              | Source and Distribution: Main panel with copper<br>Interior Lighting: linear fluorescent<br>Exterior Building-Mounted Lighting: metal halide<br>Emergency Power: None  | Fair |
| <b>Fire Alarm</b>              | Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs   | Fair |
| <b>Equipment/Special</b>       | None   | --   |
| <b>Accessibility</b>           | Presently it does not appear an accessibility study is needed for this building. See the appendix for associated photos and additional information.  |      |
| <b>Additional Studies</b>      | No additional studies are currently recommended for the building.  |      |
| <b>Areas Observed</b>          | The interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the buildings, the exterior walls of the facility, and the roofs. |      |
| <b>Key Spaces Not Observed</b> | All key areas of the facility were accessible and observed.  |      |

The table below shows the anticipated costs by trade or building system over the next 20 years.

| System Expenditure Forecast     |           |                        |                       |                       |                         |                    |
|---------------------------------|-----------|------------------------|-----------------------|-----------------------|-------------------------|--------------------|
| System                          | Immediate | Short Term<br>(1-2 yr) | Near Term<br>(3-5 yr) | Med Term<br>(6-10 yr) | Long Term<br>(11-20 yr) | TOTAL              |
| Structure                       | -         | -                      | -                     | -                     | \$61,800                | \$61,800           |
| Facade                          | -         | -                      | -                     | \$77,500              | \$232,400               | \$309,900          |
| Roofing                         | -         | -                      | \$367,900             | \$1,800               | -                       | \$369,700          |
| Interiors                       | -         | \$1,600                | -                     | \$281,200             | \$536,600               | \$819,500          |
| Plumbing                        | -         | \$24,400               | \$93,900              | \$590,400             | \$57,200                | \$765,900          |
| HVAC                            | -         | \$140,700              | \$278,900             | \$435,000             | \$301,600               | \$1,156,200        |
| Fire Protection                 | -         | -                      | \$3,500               | -                     | \$4,700                 | \$8,100            |
| Electrical                      | -         | -                      | \$21,400              | \$401,200             | -                       | \$422,600          |
| Fire Alarm & Electronic Systems | -         | \$92,800               | \$247,000             | \$169,100             | \$197,200               | \$706,100          |
| Equipment & Furnishings         | -         | -                      | -                     | \$56,400              | \$51,100                | \$107,500          |
| Special Construction & Demo     | -         | -                      | \$2,300               | -                     | -                       | \$2,300            |
| Site Development                | -         | \$2,600                | \$34,000              | \$22,800              | \$52,000                | \$111,500          |
| Site Pavement                   | -         | -                      | \$29,500              | \$34,200              | \$385,000               | \$448,700          |
| Site Utilities                  | -         | -                      | \$4,500               | \$10,800              | -                       | \$15,300           |
| <b>TOTALS (3% inflation)</b>    | <b>-</b>  | <b>\$262,200</b>       | <b>\$1,082,800</b>    | <b>\$2,080,500</b>    | <b>\$1,879,600</b>      | <b>\$5,305,100</b> |

### 3. Site Summary



#### Site Information

| Site Area                         | 5 acres (estimated)   |           |
|-----------------------------------|---|-----------|
| Parking Spaces                    | 180 total spaces all in open lots; 4 of which are accessible  |           |
| System                            | Description   | Condition |
| <b>Site Pavement</b>              | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs                     | Fair      |
| <b>Site Development</b>           | Property entrance signage<br>Playgrounds and sports courts with fencing<br>Limited park benches, picnic tables, trash receptacles             | Fair      |
| <b>Landscaping and Topography</b> | Limited landscaping features including lawns, trees, bushes, and planters<br>Irrigation not present<br>Low to moderate site slopes throughout | Good      |
| <b>Utilities</b>                  | Municipal water and sewer<br>Local utility-provided electric and natural gas  | Fair      |
| <b>Site Lighting</b>              | Pole-mounted: HPS   | Fair      |
| <b>Ancillary Structures</b>       | Shed  | Good      |

## Site Information

|                                     |   |
|-------------------------------------|---|
| <b>Site Accessibility</b>           | Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information. |
| <b>Site Additional Studies</b>      | No additional studies are currently recommended for the exterior site areas.  |
| <b>Site Areas Observed</b>          | The exterior areas within the property boundaries were observed to gain a clear understanding of the site's overall condition.                                |
| <b>Site Key Spaces Not Observed</b> | All key areas of the exterior site were accessible and observed.  |

The table below shows the anticipated costs by trade or site system over the next 20 years.

| <b>System</b>                | <b>Immediate</b> | <b>Short Term</b> | <b>Near Term</b> | <b>Med Term</b> | <b>Long Term</b> | <b>TOTAL</b>     |
|------------------------------|------------------|-------------------|------------------|-----------------|------------------|------------------|
|                              |                  | (1-2 yr)          | (3-5 yr)         | (6-10 yr)       | (11-20 yr)       |                  |
| Structure                    | -                | -                 | -                | -               | \$11,900         | \$11,900         |
| Special Construction & Demo  | -                | -                 | \$2,300          | -               | -                | \$2,300          |
| Site Development             | -                | \$2,600           | \$34,000         | \$22,800        | \$52,000         | \$111,500        |
| Site Pavement                | -                | -                 | \$29,500         | \$34,200        | \$385,000        | \$448,700        |
| Site Utilities               | -                | -                 | \$4,500          | \$10,800        | -                | \$15,300         |
| <b>TOTALS (3% inflation)</b> | <b>-</b>         | <b>\$2,600</b>    | <b>\$70,300</b>  | <b>\$67,800</b> | <b>\$449,000</b> | <b>\$589,700</b> |

## 4. ADA Accessibility

---

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The following table summarizes the accessibility conditions of the general site and each significant building or building group included in this report:

| <b>Accessibility Summary</b> |                                  |                                  |  |
|------------------------------|----------------------------------|----------------------------------|--|
| <i>Facility</i>              | <i>Year Built/<br/>Renovated</i> | <i>Prior Study<br/>Provided?</i> | <i>Major/Moderate<br/>Issues Observed?</i> |
| General Site                 | 1942                             | No                               | No   |
| Building                     | 1942/1995                        | No                               | No   |

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.

## 5. Purpose and Scope

### Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

### Condition Ratings

|                       |   |
|-----------------------|---|
| <b>Excellent</b>      | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.   |
| <b>Good</b>           | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.   |
| <b>Fair</b>           | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.  |
| <b>Poor</b>           | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| <b>Failed</b>         | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.   |
| <b>Not Applicable</b> | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.  |

## Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

## 6. Opinions of Probable Costs

---

Cost estimates are embedded throughout this report, including the detailed Replacement Reserves report in the appendix. The cost estimates are predominantly based on construction rehabilitation costs developed by the *RSMeans data from Gordian*. While the *RSMeans data from Gordian* is the primary reference source for the Bureau Veritas cost library, secondary and supporting sources include but are not limited to other industry experts work, such as *Marshall & Swift* and *CBRE Whitestone*. For improved accuracy, additional research integrated with Bureau Veritas's historical experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions also come into play when deemed necessary. Invoice or bid documents provided either by the owner or facility construction resources may be reviewed early in the process or for specific projects as warranted.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

### Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

To account for differences in prices between locations, the base costs are modified by geographical location factors to adjust for market conditions, transportation costs, or other local contributors. When requested by the client, the costs may be further adjusted by several additional factors including; labor rates (prevailing minimum wage), general contractor fees for profit and overhead, and insurance. If desired, costs for design and permits, and a contingency factor, may also be included in the calculations.

## Definitions

### Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

### Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

### Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

## 7. Certification

Montgomery County Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Lynnbrook Center, 8001 Lynbrook Drive, Bethesda, MD 20814 the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.


The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

**Prepared by:** Chris Ledbetter  
Project Assessor

**Reviewed by:**   
\_\_\_\_\_  
Daniel White  
Technical Report Reviewer  
for  
Bill Champion  
Senior Program Manager  
443.622.5067  
[Bill.Champion@bureauveritas.com](mailto:Bill.Champion@bureauveritas.com)

## 8. Appendices

---

- Appendix A: Photographic Record
- Appendix B: Site Plan(s)
- Appendix C: Pre-Survey Questionnaire(s)
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

## **Appendix A:** *Photographic Record*

---

## Photographic Overview



1 - FRONT ELEVATION



2 - LEFT ELEVATION



3 - REAR ELEVATION



4 - ANNEX BUILDING -7921



5 - MAIN ROOF



6 - PARKING LOT

**Photographic Overview**

7 - PLAY STRUCTURE



8 - SITE DUMPSTERS



9 - INTERIOR HALLWAY



10 - CLASSROOM



11 - RESTROOM



12 - ANNEX BUILDING

## Photographic Overview



13 - MULTIPURPOSE ROOM



14 - STAIRWELL



15 - BOILERS



16 - CHILLER



17 - AHU



18 - PACKAGE UNIT

**Photographic Overview**

19 - DUCTLESS SPLIT SYSTEM



20 - EXHAUST FAN



21 - PUMPS



22 - RADIATOR



23 - WATER HEATER



24 - EXTERIOR LIGHTING

## **Appendix B:** Site Plan(s)

---

## Site Plan



| <br>BUREAU<br>VERITAS | Project Number        | Project Name     |  |
|--|-----------------------|------------------|---|
|  | 172559.25R000-223.354 | Lynnbrook Center |   |
| Source   | On-Site Date          |                  |   |
| Google   | July 15, 2025         |                  |   |

## **Appendix C:** Pre-Survey Questionnaire(s)

---

# BV FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

**Building / Facility Name:** Lynnbrook Center

**Name of person completing form:** \_\_\_\_\_

**Title / Association w/ property:** \_\_\_\_\_

**Length of time associated w/ property:** \_\_\_\_\_

**Date Completed:** 7/14/2025

**Phone Number:** \_\_\_\_\_

**Method of Completion:** DURING - verbally completed during assessment

**Directions:** Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

| Data Overview |  | Response            |                   |                   |
|---------------|--|---------------------|-------------------|-------------------|
| 1             | Year(s) constructed  | Constructed<br>1942 | Renovated<br>1995 |                   |
| 2             | Building size in SF  | 35,000              | SF                |                   |
| 3             | Major Renovation/Rehabilitation  |                     | Year              | Additional Detail |
|               |  | Facade              |                   |                   |
|               |  | Roof                | 1995              |                   |
|               |  | Interiors           |                   |                   |
|               |  | HVAC                | 1995              |                   |
|               |  | Electrical          |                   |                   |
|               |  | Site Pavement       |                   |                   |
|               |  | Accessibility       |                   |                   |
| 4             | List other significant capital improvements (focus on recent years; provide approximate date).         |                     |                   |                   |
| 5             | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? |                     |                   |                   |
| 6             | Describe any on-going extremely problematic, historically chronic, or immediate facility needs.        |                     |                   |                   |

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

| Question |  | Response |    |     |    | Comments   |
|----------|--|----------|----|-----|----|--|
|          |  | Yes      | No | Unk | NA |  |
| 7        | Are there any problems with foundations or structures, like excessive settlement?  |          | X  |     |    |  |
| 8        | Are there any wall, window, basement or roof leaks?  | X        |    |     |    | No active leaks, but a history of roof leaks reported        |
| 9        | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality complaints?             |          | X  |     |    |  |
| 10       | Are your elevators unreliable, with frequent service calls?  |          |    |     | X  |  |
| 11       | Are there any plumbing leaks, water pressure, or clogging/backup issues?   | X        |    |     |    | Galvanized piping  |
| 12       | Have there been any leaks or pressure problems with natural gas, HVAC piping, or steam service?  |          | X  |     |    |  |
| 13       | Are any areas of the facility inadequately heated, cooled or ventilated? Poorly insulated areas?   | X        |    |     |    | Throughout building, poor ventilation and outdated equipment |
| 14       | Is the electrical service outdated, undersized, or problematic?  |          | X  |     |    |  |
| 15       | Are there any problems or inadequacies with exterior lighting?   |          | X  |     |    |  |
| 16       | Is site/parking drainage inadequate, with excessive ponding or other problems?   |          | X  |     |    |  |
| 17       | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? |          | X  |     |    |  |
| 18       | ADA: Has an accessibility study been previously performed? If so, when?  |          |    |     | X  |  |
| 19       | ADA: Have any ADA improvements been made to the property since original construction? Describe.  |          |    |     | X  |  |
| 20       | ADA: Has building management reported any accessibility-based complaints or litigation?  |          | X  |     |    |  |
| 21       | Are any areas of the property leased to outside occupants?   | X        |    |     |    | Classrooms   |

Signature of Assessor

Signature of POC

## **Appendix D:** Accessibility Review and Photos

---

## Visual Checklist - 2010 ADA Standards for Accessible Design

Property Name: Lynnbrook Center

BV Project Number: 172559.25R000-223.354

| Abbreviated Accessibility Checklist |  |     |    |     |          |
|-------------------------------------|--|-----|----|-----|----------|
| Facility History & Interview        |  |     |    |     |          |
|                                     | Question   | Yes | No | Unk | Comments |
| 1                                   | Has an accessibility study been previously performed? If so, when?                         |     |    | X   |          |
| 2                                   | Have any ADA improvements been made to the property since original construction? Describe. |     |    | X   |          |
| 3                                   | Has building management reported any accessibility-based complaints or litigation?         |     | X  |     |          |

## Abbreviated Accessibility Checklist

### Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



CLOSE-UP OF STALL

| Question |   | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1        | Does the required number of standard ADA designated spaces appear to be provided ?          | ✗   |    |    |          |
| 2        | Does the required number of van-accessible designated spaces appear to be provided ?        | ✗   |    |    |          |
| 3        | Are accessible spaces on the shortest accessible route to an accessible building entrance ? | ✗   |    |    |          |
| 4        | Does parking signage include the International Symbol of Accessibility ?                    | ✗   |    |    |          |
| 5        | Does each accessible space have an adjacent access aisle ?                                  | ✗   |    |    |          |
| 6        | Do parking spaces and access aisles appear to be relatively level and without obstruction ? | ✗   |    |    |          |

## Abbreviated Accessibility Checklist

### Exterior Accessible Route



ACCESSIBLE PATH



CURB CUT

| Question |  | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1        | Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ?                                       | ✗   |    |    |          |
| 2        | Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ? | ✗   |    |    |          |
| 3        | Are curb ramps present at transitions through raised curbs on all accessible routes?   | ✗   |    |    |          |
| 4        | Do curb ramps appear to have compliant slopes for all components ?   | ✗   |    |    |          |
| 5        | Do ramp runs on an accessible route appear to have compliant slopes ?  | ✗   |    |    |          |
| 6        | Do ramp runs on an accessible route appear to have a compliant rise and width ?  | ✗   |    |    |          |

|          |   |          |  |  |  |
|----------|---|----------|--|--|--|
| <b>7</b> | Do ramps on an accessible route appear to have compliant end and intermediate landings ?                  | <b>X</b> |  |  |  |
| <b>8</b> | Do ramps and stairs on an accessible route appear to have compliant handrails?                            | <b>X</b> |  |  |  |
| <b>9</b> | For stairways that are open underneath, are permanent barriers present that prevent or discourage access? | <b>X</b> |  |  |  |

## Abbreviated Accessibility Checklist

### Building Entrances



ACCESSIBLE ENTRANCE



DOOR HARDWARE

| Question |   | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1        | Do a sufficient number of accessible entrances appear to be provided ?                              | ✗   |    |    |          |
| 2        | If the main entrance is not accessible, is an alternate accessible entrance provided?               | ✗   |    |    |          |
| 3        | Is signage provided indicating the location of alternate accessible entrances ?                     | ✗   |    |    |          |
| 4        | Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ? | ✗   |    |    |          |
| 5        | Do doors at accessible entrances appear to have compliant hardware ?                                | ✗   |    |    |          |
| 6        | Do doors at accessible entrances appear to have a compliant clear opening width ?                   | ✗   |    |    |          |

|   |   |   |  |  |  |
|---|---|---|--|--|--|
| 7 | Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ? | X |  |  |  |
| 8 | Do thresholds at accessible entrances appear to have a compliant height ?                             | X |  |  |  |

## Abbreviated Accessibility Checklist

### Interior Accessible Route



ACCESSIBLE INTERIOR PATH



SELF-SERVICE AREA

| Question |  | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1        | Does an accessible route appear to connect all public areas inside the building ?      | ✗   |    |    |          |
| 2        | Do accessible routes appear free of obstructions and/or protruding objects ?           | ✗   |    |    |          |
| 3        | Do ramps on accessible routes appear to have compliant slopes ?                        | ✗   |    |    |          |
| 4        | Do ramp runs on an accessible route appear to have a compliant rise and width ?        | ✗   |    |    |          |
| 5        | Do ramps on accessible routes appear to have compliant end and intermediate landings ? | ✗   |    |    |          |
| 6        | Do ramps on accessible routes appear to have compliant handrails ?                     | ✗   |    |    |          |

|           |   |          |  |  |  |
|-----------|---|----------|--|--|--|
| <b>7</b>  | Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ? | <b>X</b> |  |  |  |
| <b>8</b>  | Do public transaction areas have an accessible, lowered service counter section ?                                     | <b>X</b> |  |  |  |
| <b>9</b>  | Do public telephones appear mounted with an accessible height and location ?  | <b>X</b> |  |  |  |
| <b>10</b> | Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ?             | <b>X</b> |  |  |  |
| <b>11</b> | Do doors at interior accessible routes appear to have compliant hardware ?  | <b>X</b> |  |  |  |
| <b>12</b> | Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ?  | <b>X</b> |  |  |  |
| <b>13</b> | Do doors on interior accessible routes appear to have a compliant clear opening width ?                               | <b>X</b> |  |  |  |

## Abbreviated Accessibility Checklist

### Public Restrooms



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

| Question |   | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1        | Do publicly accessible toilet rooms appear to have a minimum compliant floor area ?         | ✗   |    |    |          |
| 2        | Does the lavatory appear to be mounted at a compliant height and with compliant knee area ? | ✗   |    |    |          |
| 3        | Does the lavatory faucet have compliant handles ?   | ✗   |    |    |          |
| 4        | Is the plumbing piping under lavatories configured to protect against contact ?             | ✗   |    |    |          |
| 5        | Are grab bars provided at compliant locations around the toilet ?                           | ✗   |    |    |          |
| 6        | Do toilet stall doors appear to provide the minimum compliant clear width ?                 | ✗   |    |    |          |

|          |  |          |  |  |  |
|----------|--|----------|--|--|--|
| <b>7</b> | Do toilet stalls appear to provide the minimum compliant clear floor area ?  | <b>X</b> |  |  |  |
| <b>8</b> | Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ? | <b>X</b> |  |  |  |
| <b>9</b> | Do accessories and mirrors appear to be mounted at a compliant height ?  | <b>X</b> |  |  |  |

## Abbreviated Accessibility Checklist

### Playgrounds & Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

| Question |   | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1        | Is there an accessible route to the play area / s?                      | ✗   |    |    |          |
| 2        | Has the play area been reviewed for accessibility ?                     | ✗   |    |    |          |
| 3        | Are publicly accessible swimming pools equipped with an entrance lift ? |     |    | ✗  |          |

## **Appendix E:** Component Condition Report

## Component Condition Report | Lynnbrook Center / Lynnbrook Center

| UF L3 Code                 | Location            | Condition | Asset/Component/Repair   | Quantity | RUL | ID |
|----------------------------|---------------------|-----------|--|----------|-----|----|
| <strong>Structure</strong> |                     |           |  |          |     |    |
| A1010                      | Substructure        | Fair      | Foundation System, Concrete Strip/Pad Footings w/ Slab, 1-2 Story Building, 1-2 Story Building | 35,000   | SF  | 25 |
| A1010                      | Annex Building      | Fair      | Foundation System, Concrete Strip/Pad Footings w/ Slab, 1-2 Story Building, 1-2 Story Building | 5,850    | SF  | 25 |
| B1010                      | Superstructure      | Fair      | Structural Framing, Masonry (CMU) Bearing Walls, 1-2 Story Building, 1-2 Story Building        | 35,000   | SF  | 25 |
| B1010                      | Annex building      | Fair      | Structural Framing, Masonry (CMU) Bearing Walls, 1-2 Story Building, 1-2 Story Building        | 5,850    | SF  | 25 |
| B1080                      | Stairwells          | Fair      | Stairs, Wood, Interior   | 800      | SF  | 15 |
| <strong>Facade</strong>    |                     |           |  |          |     |    |
| B2010                      | Building Exterior   | Fair      | Exterior Walls, any painted surface, 1-2 Story Building, Prep & Paint                          | 21,000   | SF  | 7  |
| B2020                      | Building Exterior   | Fair      | Window, Vinyl-Clad Double-Glazed, 16-25 SF   | 56       |     | 15 |
| B2020                      | Building Exterior   | Fair      | Window, Aluminum Double-Glazed, 16-25 SF   | 8        |     | 15 |
| B2050                      | Building Exterior   | Fair      | Exterior Door, Steel, Commercial   | 6        |     | 15 |
| <strong>Roofing</strong>   |                     |           |  |          |     |    |
| B3010                      | Main building       | Fair      | Roofing, Built-Up  | 18,200   | SF  | 3  |
| B3010                      | Annex building      | Fair      | Roofing, Built-Up  | 5,850    | SF  | 3  |
| B3020                      | Roof                | Fair      | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings                                 | 150      | LF  | 10 |
| <strong>Interiors</strong> |                     |           |  |          |     |    |
| C1030                      | Throughout Building | Fair      | Interior Door, Wood, Solid-Core  | 40       |     | 20 |
| C1030                      | Annex building      | Fair      | Interior Door, Wood, Solid-Core  | 25       |     | 20 |
| C1030                      | Throughout Building | Fair      | Interior Door, Steel, Standard   | 25       |     | 15 |
| C1070                      | Annex building      | Fair      | Suspended Ceilings, Acoustical Tile (ACT)  | 5,850    | SF  | 12 |
| C1070                      | Throughout Building | Fair      | Suspended Ceilings, Acoustical Tile (ACT)  | 30,000   | SF  | 12 |
| C1090                      | Annex building      | Fair      | Toilet Partitions, Wood  | 10       |     | 10 |
| C1090                      | Throughout Building | Fair      | Toilet Partitions, Plastic/Laminate  | 7        |     | 10 |
| C2010                      | Throughout Building | Good      | Wall Finishes, any surface, Prep & Paint   | 35,000   | SF  | 8  |

## Component Condition Report | Lynnbrook Center / Lynnbrook Center

| UF L3 Code      | Location            | Condition | Asset/Component/Repair   | Quantity | RUL | ID |
|-----------------|---------------------|-----------|--|----------|-----|----|
| C2010           | Restrooms           | Fair      | Wall Finishes, Ceramic Tile  | 1,500    | SF  | 20 |
| C2030           | Throughout Building | Fair      | Flooring, Vinyl Tile (VCT)   | 25,000   | SF  | 8  |
| C2030           | Annex building      | Fair      | Flooring, Vinyl Tile (VCT)   | 5,850    | SF  | 8  |
| C2030           | Throughout Building | Poor      | Flooring, Vinyl Tile (VCT), w/ Asbestos Abatement                      | 200      | SF  | 1  |
| C2030           | Restrooms           | Fair      | Flooring, Ceramic Tile   | 3,000    | SF  | 20 |
| C2030           | Annex building      | Fair      | Flooring, Ceramic Tile   | 200      | SF  | 20 |
| C2030           | Annex building      | Fair      | Flooring, Carpet, Commercial Standard                                  | 600      | SF  | 7  |
| <b>Plumbing</b> |                     |           |  |          |     |    |
| D2010           | Annex building      | Fair      | Plumbing System, Supply & Sanitary, Medium Density (excludes fixtures) | 5,850    | SF  | 4  |
| D2010           | Annex building      | Fair      | Urinal, Standard   | 1        |     | 10 |
| D2010           | Boiler Room         | Fair      | Storage Tank, Domestic Water   | 1        |     | 10 |
| D2010           | Restrooms           | Fair      | Sink/Lavatory, Wall-Hung, Enameled Steel                               | 22       |     | 10 |
| D2010           | Throughout Building | Fair      | Drinking Fountain, Wall-Mounted, Single-Level                          | 1        |     | 3  |
| D2010           | Throughout Building | Good      | Sink/Lavatory, Service Sink, Wall-Hung                                 | 1        |     | 18 |
| D2010           | Throughout Building | Fair      | Plumbing System, Supply & Sanitary, Medium Density (excludes fixtures) | 35,000   | SF  | 10 |
| D2010           | Annex building      | Fair      | Sink/Lavatory, Service Sink, Floor                                     | 1        |     | 10 |
| D2010           | Throughout Building | Fair      | Sink/Lavatory, Vanity Top, Stainless Steel                             | 3        |     | 15 |
| D2010           | Throughout Building | Good      | Drinking Fountain, Wall-Mounted, Single-Level                          | 1        |     | 13 |
| D2010           | Boiler Room         | Fair      | Water Heater, Gas, Commercial (125 MBH)                                | 1        |     | 5  |
| D2010           | Throughout Building | Fair      | Sink/Lavatory, Vanity Top, Stainless Steel                             | 6        |     | 15 |
| D2010           | Annex building      | Fair      | Storage Tank, Domestic Water   | 1        |     | 5  |
| D2010           | Throughout Building | Fair      | Urinal, Standard   | 6        |     | 10 |
| D2010           | Throughout Building | Fair      | Sink/Lavatory, Service Sink, Wall-Hung                                 | 1        |     | 18 |
| D2010           | Annex building      | Fair      | Water Heater, Electric, Commercial ( 12 kW)                            | 1        |     | 2  |
| D2010           | Annex building      | Fair      | Sink/Lavatory, Wall-Hung, Enameled Steel                               | 2        |     | 10 |

## Component Condition Report | Lynnbrook Center / Lynnbrook Center

| UF L3 Code  | Location            | Condition | Asset/Component/Repair   | Quantity | RUL | ID      |
|-------------|---------------------|-----------|--|----------|-----|---------|
| D2010       | Restrooms           | Fair      | Toilet, Residential Water Closet   | 22       | 15  | 9553978 |
| D2010       | Annex building      | Fair      | Toilet, Commercial Water Closet  | 3        | 15  | 9554034 |
| D2010       | Annex building      | Fair      | Drinking Fountain, Wall-Mounted, Single-Level                                  | 1        | 12  | 9553973 |
| D2060       | Boiler Room         | Fair      | Air Compressor, Tank-Style   | 1        | 2   | 9553994 |
| <b>HVAC</b> |                     |           |  |          |     |         |
| D3020       | Boiler Room         | Good      | Unit Heater, Hydronic [PUH-1]  | 1        | 18  | 9553968 |
| D3020       | Throughout Building | Fair      | Radiator, Hydronic, Baseboard (per LF)   | 100      | LF  | 4       |
| D3020       | Boiler Room         | Good      | Boiler, Gas, HVAC [B-2]  | 1        | 28  | 9554049 |
| D3020       | Boiler Room         | Good      | Boiler, Gas, HVAC [B-1]  | 1        | 28  | 9553960 |
| D3020       | Throughout Building | Fair      | Unit Heater, Hydronic  | 1        | 2   | 9553955 |
| D3020       | Boiler Room         | Fair      | Boiler Supplemental Components, Shot Feed Tank                                 | 1        | 5   | 9554000 |
| D3020       | Annex building      | Fair      | Boiler, Gas, HVAC, 1001 to 2000 MBH  | 1        | 3   | 9554004 |
| D3030       | Roof                | Fair      | Computer Room AC Unit, Air-Cooled, CRAC Drycooler/Condenser                    | 1        | 2   | 9554039 |
| D3030       | Boiler Room         | Fair      | Chiller, Water-Cooled  | 1        | 2   | 9554024 |
| D3030       | Roof                | Fair      | Split System Ductless, Single Zone, Condenser & Evaporator                     | 1        | 3   | 9553949 |
| D3030       | Throughout Building | Fair      | Air Conditioner, Window/Thru-Wall, Residential                                 | 12       | 3   | 9554046 |
| D3030       | Throughout Building | Fair      | Unit Ventilator, approx/nominal 2 Ton, 300 to 750 CFM                          | 21       | 3   | 9554054 |
| D3030       | Annex building      | Fair      | Split System Ductless, Single Zone   | 1        | 2   | 9553970 |
| D3030       | Throughout Building | Fair      | Fan Coil Cassette, Variable Refrigerant Volume (VRV) Interior Unit, 1 to 2 TON | 2        | 8   | 9553962 |
| D3050       | Basement            | Fair      | Air Handler, Interior AHU, Easy/Moderate Access                                | 1        | 2   | 9554048 |
| D3050       | Lynnbrook center    | Fair      | HVAC System, Ductwork, Medium Density  | 35,000   | SF  | 15      |
| D3050       | Annex building      | Fair      | Packaged Unit, RTU, Pad or Roof-Mounted  | 1        | 2   | 9553986 |
| D3050       | Boiler Room         | Fair      | Pump, Distribution, HVAC Chilled or Condenser Water [P-4]                      | 1        | 2   | 9553946 |
| D3050       | Annex building      | Fair      | Packaged Unit, RTU, Pad or Roof-Mounted  | 1        | 2   | 9554030 |
| D3050       | Boiler Room         | Good      | Pump, Distribution, HVAC Heating Water [P-3]                                   | 1        | 13  | 9553963 |

## Component Condition Report | Lynnbrook Center / Lynnbrook Center

| UF L3 Code             | Location            | Condition | Asset/Component/Repair   | Quantity | RUL | ID      |
|------------------------|---------------------|-----------|--|----------|-----|---------|
| D3050                  | Annex building      | Fair      | HVAC System, Ductwork, Medium Density                                      | 5,850    | SF  | 15      |
| D3050                  | Boiler Room         | Fair      | Supplemental Components, Air Separator, HVAC                               | 1        |     | 9553956 |
| D3050                  | Boiler Room         | Fair      | Pump, Distribution, HVAC Chilled or Condenser Water [P-5]                  | 1        |     | 9554047 |
| D3050                  | Annex building      | Fair      | Packaged Unit, RTU, Pad or Roof-Mounted                                    | 1        |     | 9554044 |
| D3050                  | Boiler Room         | Good      | Pump, Distribution, HVAC Heating Water [P-4]                               | 1        | 13  | 9553984 |
| D3050                  | Annex building      | Fair      | HVAC System, Hydronic Piping, 2-Pipe                                       | 5,850    | SF  | 10      |
| D3050                  | Lynnbrook center    | Fair      | HVAC System, Hydronic Piping, 4-Pipe                                       | 35,000   | SF  | 10      |
| D3050                  | Annex building      | Fair      | HVAC Steam Components, Condensate Return Station                           | 1        |     | 9554011 |
| D3060                  | Annex building      | Fair      | Exhaust Fan, Roof or Wall-Mounted, 10" Damper                              | 3        |     | 9553974 |
| D3060                  | Roof                | Fair      | Exhaust Fan, Roof or Wall-Mounted, 10" Damper                              | 5        |     | 9554022 |
| D3060                  | Roof                | Fair      | Exhaust Fan, Roof or Wall-Mounted, 16" Damper                              | 2        |     | 9554019 |
| D3060                  | Boiler Room         | Fair      | Exhaust Fan, Propeller, 5 HP Motor   | 1        |     | 9553953 |
| <b>Fire Protection</b> |                     |           |  |          |     |         |
| D4030                  | Throughout Building | Fair      | Fire Extinguisher, Type ABC, up to 20 LB                                   | 10       |     | 9553991 |
| D4030                  | Annex building      | Fair      | Fire Extinguisher, Type ABC, up to 20 LB                                   | 10       |     | 9554003 |
| <b>Electrical</b>      |                     |           |  |          |     |         |
| D5020                  | Electrical Room     | Fair      | Distribution Panel, 120/208 V  | 1        |     | 9554037 |
| D5020                  | Electrical Room     | Fair      | Distribution Panel, 120/208 V  | 1        |     | 9554006 |
| D5020                  | Boiler Room         | Fair      | Distribution Panel, 120/208 V  | 1        |     | 9553987 |
| D5020                  | Throughout Building | Fair      | Distribution Panel, 120/208 V  | 1        | 10  | 9553950 |
| D5030                  | Boiler Room         | Fair      | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD-4]     | 1        | 10  | 9553975 |
| D5030                  | Annex building      | Fair      | Electrical System, Wiring & Switches, Average or Low Density/Complexity    | 5,850    | SF  | 10      |
| D5030                  | Boiler Room         | Fair      | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install [VFD-3]     | 1        | 10  | 9554005 |
| D5030                  | Lynnbrook center    | Fair      | Electrical System, Wiring & Switches, Average or Low Density/Complexity    | 35,000   | SF  | 10      |
| D5040                  | Throughout Building | Fair      | Interior Lighting System, Full Upgrade, Medium Density & Standard Fixtures | 35,000   | SF  | 10      |

## Component Condition Report | Lynnbrook Center / Lynnbrook Center

| UF L3 Code                                 | Location            | Condition | Asset/Component/Repair  | Quantity | RUL | ID      |
|--|---------------------|-----------|---|----------|-----|---------|
| D5040                                      | Annex building      | Fair      | Interior Lighting System, Full Upgrade, Medium Density & Standard Fixtures    | 5,850    | SF  | 10      |
| <b>Fire Alarm &amp; Electronic Systems</b> |                     |           |   |          |     |         |
| D6020                                      | Annex building      | Fair      | Low Voltage System, Phone or Data Lines                                       | 5,850    | SF  | 10      |
| D6020                                      | Throughout Building | Fair      | Low Voltage System, Phone & Data Lines  | 35,000   | SF  | 10      |
| D6060                                      | Throughout Building | Fair      | Intercom/PA System, Public Address Upgrade, Facility-Wide                     | 35,000   | SF  | 5       |
| D6060                                      | Annex building      | Fair      | Intercom/PA System, Public Address Upgrade, Facility-Wide                     | 5,850    | SF  | 5       |
| D7030                                      | Throughout Building | Fair      | Security/Surveillance System, Full System Upgrade, Average Density            | 35,000   | SF  | 8       |
| D7050                                      | Throughout Building | Fair      | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 35,000   | SF  | 3       |
| D7050                                      | Electrical Room     | Fair      | Fire Alarm Panel, Fully Addressable   | 1        |     | 9553948 |
| D7050                                      | Throughout Building | Fair      | Fire Alarm Panel, Annunciator   | 1        |     | 9553943 |
| D7050                                      | Annex building      | Fair      | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 5,850    | SF  | 5       |
| D7050                                      | Annex building      | Fair      | Fire Alarm Panel, Fully Addressable   | 1        |     | 9554031 |
| D8010                                      | Boiler Room         | Fair      | BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install           | 35,000   | SF  | 2       |
| <b>Equipment &amp; Furnishings</b>         |                     |           |   |          |     |         |
| E2010                                      | Annex building      | Good      | Casework, Cabinetry, Standard   | 100      | LF  | 18      |
| E2010                                      | Throughout Building | Fair      | Casework, Cabinetry, Standard   | 140      | LF  | 10      |

## Component Condition Report | Lynnbrook Center / Site

| UF L3 Code                              | Location | Condition | Asset/Component/Repair   | Quantity | RUL | ID |
|---|----------|-----------|--|----------|-----|----|
| <b>Structure</b>                        |          |           |  |          |     |    |
| B1080                                   | Site     | Fair      | Stairs, Concrete, Exterior                                       | 120      | SF  | 20 |
| <b>Special Construction &amp; Demo</b>  |          |           |  |          |     |    |
| F1020                                   | Site     | Fair      | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal | 80       | SF  | 5  |
| <b>Pedestrian Plazas &amp; Walkways</b> |          |           |  |          |     |    |
| G2020                                   | Site     | Fair      | Parking Lots, Pavement, Asphalt, Mill & Overlay                  | 60,000   | SF  | 12 |

## Component Condition Report | Lynnbrook Center / Site

| UF L3 Code  | Location          | Condition | Asset/Component/Repair  | Quantity | RUL | ID |
|---|-------------------|-----------|---|----------|-----|----|
| G2020   | Site              | Fair      | Parking Lots, Pavement, Asphalt, Seal & Stripe                                      | 60,000   | SF  | 3  |
| <b>Athletic, Recreational &amp; Playfield Areas</b> |                   |           |   |          |     |    |
| G2050   | Site              | Fair      | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay    | 5,550    | SF  | 3  |
| G2050   | Site              | Fair      | Playground Surfaces, Chips Wood, 6" Depth   | 2,500    | SF  | 3  |
| G2050   | Site              | Fair      | Sports Apparatus, Basketball Backboard, Building-Mounted                            | 2        |     | 4  |
| G2050   | Site              | Fair      | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe     | 5,550    | SF  | 2  |
| G2050   | Site              | Fair      | Play Structure, Multipurpose, Small   | 1        |     | 10 |
| <b>Sitework</b>                                     |                   |           |   |          |     |    |
| G2060   | Site              | Fair      | Park Bench, Wood/Composite/Fiberglass   | 3        |     | 15 |
| G2060   | Site              | Fair      | Fences & Gates, Fence, Chain Link 6'  | 80       | LF  | 5  |
| G2060   | Site              | Fair      | Fences & Gates, Fence, Chain Link 4'  | 1,000    | LF  | 12 |
| G4050   | Site              | Fair      | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install | 2        |     | 10 |
| G4050   | Building Exterior | Fair      | Site Lighting, Wall Pack or Walkway Pole-Mounted, any type w/ LED                   | 5        |     | 4  |

## **Appendix F:** Replacement Reserves

---



7/31/2025

| Location                            | 2025       | 2026           | 2027             | 2028             | 2029             | 2030             | 2031       | 2032            | 2033             | 2034       | 2035               | 2036       | 2037             | 2038            | 2039       | 2040             | 2041           | 2042             | 2043             | 2044            | 2045             | Total Escalated Estimate |
|-------------------------------------|------------|----------------|------------------|------------------|------------------|------------------|------------|-----------------|------------------|------------|--------------------|------------|------------------|-----------------|------------|------------------|----------------|------------------|------------------|-----------------|------------------|--------------------------|
| Lynnbrook Center                    | \$0        | \$0            | \$0              | \$0              | \$0              | \$0              | \$0        | \$0             | \$0              | \$0        | \$0                | \$0        | \$0              | \$0             | \$0        | \$0              | \$0            | \$0              | \$0              | \$0             | \$0              | \$0                      |
| Lynnbrook Center / Lynnbrook Center | \$0        | \$1,648        | \$257,905        | \$727,756        | \$160,891        | \$123,895        | \$0        | \$83,016        | \$372,012        | \$0        | \$1,557,666        | \$0        | \$180,608        | \$25,552        | \$0        | \$507,679        | \$2,568        | \$264,125        | \$162,582        | \$52,605        | \$234,975        | \$4,715,485              |
| Lynnbrook Center / Site             | \$0        | \$0            | \$2,650          | \$56,193         | \$9,837          | \$4,266          | \$0        | \$3,072         | \$40,537         | \$0        | \$24,190           | \$0        | \$328,634        | \$46,993        | \$0        | \$2,804          | \$0            | \$4,128          | \$54,478         | \$0             | \$11,920         | \$589,703                |
| <b>Grand Total</b>                  | <b>\$0</b> | <b>\$1,648</b> | <b>\$260,554</b> | <b>\$783,950</b> | <b>\$170,728</b> | <b>\$128,161</b> | <b>\$0</b> | <b>\$86,088</b> | <b>\$412,549</b> | <b>\$0</b> | <b>\$1,581,857</b> | <b>\$0</b> | <b>\$509,243</b> | <b>\$72,546</b> | <b>\$0</b> | <b>\$510,484</b> | <b>\$2,568</b> | <b>\$268,253</b> | <b>\$217,060</b> | <b>\$52,605</b> | <b>\$246,895</b> | <b>\$5,305,188</b>       |

Lynnbrook Center

Lynnbrook Center / Lynnbrook Center

| Uniformat Location Code | Description         | ID        | Cost Description  | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost*  | Subtotal  | 2025    | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044 | 2045      | Deficiency Repair Estimate |
|-------------------------|---------------------|-----------|---|----------------|------|-----|----------|------|-------------|-----------|---------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|-----------|----------------------------|
| B1080                   | Stairwells          | 9554053   | Stairs, Wood, Interior, Replace   | 30             | 15   | 15  | 800      | SF   | \$40.00     | \$32,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$32,000  |                            |
| B2010                   | Building Exterior   | 9566474   | Exterior Walls, any painted surface, 1-2 Story Building, Prep & Paint   | 10             | 3    | 7   | 21000    | SF   | \$3.00      | \$63,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$63,000  | \$126,000                  |
| B2020                   | Building Exterior   | 9554036   | Window, Vinyl-Clad Double-Glazed, 16-25 SF, Replace                     | 30             | 15   | 15  | 56       | EA   | \$900.00    | \$50,400  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$50,400  |                            |
| B2020                   | Building Exterior   | 9553942   | Window, Aluminum Double-Glazed, 16-25 SF, Replace                       | 30             | 15   | 15  | 8        | EA   | \$950.00    | \$7,600   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$7,600   |                            |
| B2050                   | Building Exterior   | 9554033   | Exterior Door, Steel, Commercial, Replace                               | 40             | 25   | 15  | 6        | EA   | \$4,060.00  | \$24,360  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$24,360  |                            |
| B3010                   | Main building       | 9554043   | Roofing, Built-Up, Replace  | 25             | 22   | 3   | 18200    | SF   | \$14.00     | \$254,800 |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$254,800 |                            |
| B3010                   | Annex building      | 9553971   | Roofing, Built-Up, Replace  | 25             | 22   | 3   | 5850     | SF   | \$14.00     | \$81,900  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$81,900  |                            |
| B3020                   | Roof                | 9553959   | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings, Replace | 20             | 10   | 10  | 150      | LF   | \$9.00      | \$1,350   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$1,350   |                            |
| C1030                   | Throughout Building | 9554052   | Interior Door, Steel, Standard, Replace                                 | 40             | 25   | 15  | 25       | EA   | \$600.00    | \$15,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$15,000  |                            |
| C1030                   | Throughout Building | 9553945   | Interior Door, Wood, Solid-Core, Replace                                | 40             | 20   | 20  | 40       | EA   | \$700.00    | \$28,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$28,000  | \$28,000                   |
| C1030                   | Annex building      | 9553979   | Interior Door, Wood, Solid-Core, Replace                                | 40             | 20   | 20  | 25       | EA   | \$700.00    | \$17,500  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$17,500  |                            |
| C1070                   | Annex building      | 9553993   | Suspended Ceilings, Acoustical Tile (ACT), Replace                      | 25             | 13   | 12  | 5850     | SF   | \$3.50      | \$20,475  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$20,475  |                            |
| C1070                   | Throughout Building | 9553989   | Suspended Ceilings, Acoustical Tile (ACT), Replace                      | 25             | 13   | 12  | 30000    | SF   | \$3.50      | \$105,000 |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$105,000 |                            |
| C1090                   | Annex building      | 9554040   | Toilet Partitions, Wood, Replace  | 20             | 10   | 10  | 10       | EA   | \$500.00    | \$5,000   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$5,000   |                            |
| C1090                   | Throughout Building | 9553996   | Toilet Partitions, Plastic/Laminate, Replace                            | 20             | 10   | 10  | 7        | EA   | \$750.00    | \$5,250   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$5,250   |                            |
| C2010                   | Restrooms           | 9553981   | Wall Finishes, Ceramic Tile, Replace                                    | 40             | 20   | 20  | 1500     | SF   | \$18.00     | \$27,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$27,000  |                            |
| C2010                   | Throughout Building | 9554057   | Wall Finishes, any surface, Prep & Paint                                | 10             | 2    | 8   | 35000    | SF   | \$1.50      | \$52,500  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$52,500  | \$105,000                  |
| C2030                   | Restrooms           | 9553958   | Flooring, Ceramic Tile, Replace   | 40             | 20   | 20  | 3000     | SF   | \$18.00     | \$54,000  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$54,000  | \$54,000                   |
| C2030                   | Annex building      | 9553983   | Flooring, Ceramic Tile, Replace   | 40             | 20   | 20  | 200      | SF   | \$18.00     | \$3,600   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$3,600   | \$3,600                    |
| C2030                   | Throughout Building | 9554035   | Flooring, Vinyl Tile (VCT), w/ Asbestos Abatement, Replace              | 15             | 14   | 1   | 200      | SF   | \$8.00      | \$1,600   | \$1,600 |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$1,600   | \$3,200                    |
| C2030                   | Throughout Building | 9554018   | Flooring, Vinyl Tile (VCT), Replace                                     | 15             | 7    | 8   | 25000    | SF   | \$5.00      | \$125,000 |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$125,000                  |
| C2030                   | Annex building      | 9553990   | Flooring, Vinyl Tile (VCT), Replace                                     | 15             | 7    | 8   | 5850     | SF   | \$5.00      | \$29,250  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$29,250                   |
| C2030                   | Annex building      | 9553982   | Flooring, Carpet, Commercial Standard, Replace                          | 10             | 3    | 7   | 600      | SF   | \$7.50      | \$4,500   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$4,500                    |
| D2010                   | Annex building      | 9553961   | Storage Tank, Domestic Water, Replace                                   | 30             | 25   | 5   | 1        | EA   | \$5,000.00  | \$5,000   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$5,000                    |
| D2010                   | Boiler Room         | 9553985   | Storage Tank, Domestic Water, Replace                                   | 30             | 20   | 10  | 1        | EA   | \$5,000.00  | \$5,000   |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$5,000                    |
| D2010                   | Annex building      | 9554027   | Water Heater, Electric, Commercial ( 12 kW), Replace                    | 20             | 18   | 2   | 1        | EA   | \$12,400.00 | \$12,400  |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           | \$12,400                   |
| D2010                   | Boiler Room         | 9553976</ |   |                |      |     |          |      |             |           |         |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |           |                            |

7/31/2025

| Uniformat Code | Location Description | ID      | Cost Description  | Lifespan (EUL) | EAge | RUL | Quantity | Unit  | Unit Cost* | Subtotal    | 2025      | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044     | 2045 | Deficiency Repair Estimate |  |          |           |           |
|----------------|----------------------|---------|---|----------------|------|-----|----------|-------|------------|-------------|-----------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|----------|------|----------------------------|--|----------|-----------|-----------|
|                |                      |         |   |                |      |     |          |       |            |             | 2025      | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | 2042 | 2043 | 2044     | 2045 |                            |  |          |           |           |
| D2010          | Restrooms            | 9553978 | Toilet, Residential Water Closet, Replace   |                | 30   | 15  | 15       | 22    | EA         | \$700.00    | \$15,400  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$15,400 |      |                            |  | \$15,400 |           |           |
| D2010          | Annex building       | 9554034 | Toilet, Commercial Water Closet, Replace  |                | 30   | 15  | 15       | 3     | EA         | \$1,300.00  | \$3,900   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      | \$3,900  |      |                            |  | \$3,900  |           |           |
| D2010          | Throughout Building  | 9554001 | Sink/Lavatory, Service Sink, Wall-Hung, Replace   |                | 35   | 17  | 18       | 1     | EA         | \$1,400.00  | \$1,400   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      | \$1,400                    |  |          | \$1,400   |           |
| D2010          | Throughout Building  | 9554050 | Sink/Lavatory, Service Sink, Wall-Hung, Replace   |                | 35   | 17  | 18       | 1     | EA         | \$1,400.00  | \$1,400   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      | \$1,400                    |  |          | \$1,400   |           |
| D2060          | Boiler Room          | 9553994 | Air Compressor, Tank-Style, Replace   |                | 20   | 18  | 2        | 1     | EA         | \$10,600.00 | \$10,600  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$10,600  |           |
| D3020          | Annex building       | 9554004 | Boiler, Gas, HVAC, 1001 to 2000 MBH, Replace  |                | 30   | 27  | 3        | 1     | EA         | \$50,800.00 | \$50,800  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$50,800  |           |
| D3020          | Throughout Building  | 9553955 | Unit Heater, Hydronic, Replace  |                | 20   | 18  | 2        | 1     | EA         | \$4,600.00  | \$4,600   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$4,600   |           |
| D3020          | Throughout Building  | 9554056 | Radiator, Hydronic, Baseboard (per LF), Replace   |                | 30   | 26  | 4        | 100   | LF         | \$150.00    | \$15,000  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$15,000  |           |
| D3020          | Boiler Room          | 9553968 | Unit Heater, Hydronic, Replace  |                | 20   | 2   | 18       | 1     | EA         | \$2,900.00  | \$2,900   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$2,900   |           |
| D3020          | Boiler Room          | 9554000 | Boiler Supplemental Components, Shot Feed Tank, Replace                                 |                | 30   | 25  | 5        | 1     | EA         | \$1,520.00  | \$1,520   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$1,520   |           |
| D3030          | Boiler Room          | 9554024 | Chiller, Water-Cooled, Replace  |                | 25   | 23  | 2        | 1     | EA         | \$33,200.00 | \$33,200  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$33,200  |           |
| D3030          | Roof                 | 9554039 | Computer Room AC Unit, Air-Cooled, CRAC Drycooler/Condenser, Replace                    |                | 20   | 18  | 2        | 1     | EA         | \$15,500.00 | \$15,500  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$15,500  |           |
| D3030          | Annex building       | 9553970 | Split System Ductless, Single Zone, Replace   |                | 15   | 13  | 2        | 1     | EA         | \$4,800.00  | \$4,800   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$4,800   |           |
| D3030          | Roof                 | 9553949 | Split System Ductless, Single Zone, Condenser & Evaporator, Replace                     |                | 15   | 12  | 3        | 1     | EA         | \$6,100.00  | \$6,100   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$6,100   |           |
| D3030          | Throughout Building  | 9554046 | Air Conditioner, Window/Thru-Wall, Residential, Replace                                 |                | 10   | 7   | 3        | 12    | EA         | \$500.00    | \$6,000   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$12,000  |           |
| D3030          | Throughout Building  | 9554054 | Unit Ventilator, approx/nominal 2 Ton, 300 to 750 CFM, Replace                          |                | 20   | 17  | 3        | 21    | EA         | \$7,400.00  | \$155,400 |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$155,400 |           |
| D3030          | Throughout Building  | 9553962 | Fan Coil Cassette, Variable Refrigerant Volume (VRV) Interior Unit, 1 to 2 TON, Replace |                | 15   | 7   | 8        | 2     | EA         | \$4,020.00  | \$8,040   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$8,040   |           |
| D3050          | Boiler Room          | 9553946 | Pump, Distribution, HVAC Chilled or Condenser Water, Replace                            |                | 25   | 23  | 2        | 1     | EA         | \$6,100.00  | \$6,100   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$6,100   |           |
| D3050          | Boiler Room          | 9554047 | Pump, Distribution, HVAC Chilled or Condenser Water, Replace                            |                | 25   | 23  | 2        | 1     | EA         | \$6,100.00  | \$6,100   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$6,100   |           |
| D3050          | Boiler Room          | 9553956 | Supplemental Components, Air Separator, HVAC, Replace                                   |                | 15   | 7   | 8        | 1     | EA         | \$7,300.00  | \$7,300   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$7,300   |           |
| D3050          | Annex building       | 9554032 | HVAC System, Hydronic Piping, 2-Pipe, Replace   |                | 40   | 30  | 10       | 5850  | SF         | \$5.00      | \$29,250  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$29,250  |           |
| D3050          | Lynnbrook center     | 9554015 | HVAC System, Hydronic Piping, 4-Pipe, Replace   |                | 40   | 30  | 10       | 35000 | SF         | \$8.00      | \$280,000 |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          |           | \$280,000 |
| D3050          | Boiler Room          | 9553963 | Pump, Distribution, HVAC Heating Water, Replace   |                | 15   | 2   | 13       | 1     | EA         | \$5,100.00  | \$5,100   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$5,100   |           |
| D3050          | Boiler Room          | 9553984 | Pump, Distribution, HVAC Heating Water, Replace   |                | 15   | 2   | 13       | 1     | EA         | \$5,100.00  | \$5,100   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$5,100   |           |
| D3050          | Annex building       | 9554011 | HVAC Steam Components, Condensate Return Station, Replace                               |                | 25   | 21  | 4        | 1     | EA         | \$8,600.00  | \$8,600   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$8,600   |           |
| D3050          | Basement             | 9554048 | Air Handler, Interior AHU, Easy/Moderate Access, Replace                                |                | 25   | 23  | 2        | 1     | EA         | \$22,000.00 | \$22,000  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$22,000  |           |
| D3050          | Annex building       | 9553986 | Packaged Unit, RTU, Pad or Roof-Mounted, Replace  |                | 20   | 18  | 2        | 1     | EA         | \$11,000.00 | \$11,000  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$11,000  |           |
| D3050          | Annex building       | 9554030 | Packaged Unit, RTU, Pad or Roof-Mounted, Replace  |                | 20   | 18  | 2        | 1     | EA         | \$11,000.00 | \$11,000  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$11,000  |           |
| D3050          | Annex building       | 9554044 | Packaged Unit, RTU, Pad or Roof-Mounted, Replace  |                | 20   | 18  | 2        | 1     | EA         | \$11,000.00 | \$11,000  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$11,000  |           |
| D3050          | Lynnbrook center     | 9554009 | HVAC System, Ductwork, Medium Density, Replace  |                | 30   | 15  | 15       | 35000 | SF         | \$4.00      | \$140,000 |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$140,000 |           |
| D3050          | Annex building       | 9553997 | HVAC System, Ductwork, Medium Density, Replace  |                | 30   | 15  | 15       | 5850  | SF         | \$4.00      | \$23,400  |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$23,400  |           |
| D3060          | Annex building       | 9553974 | Exhaust Fan, Roof or Wall-Mounted, 10" Damper, Replace                                  |                | 20   | 18  | 2        | 3     | EA         | \$1,200.00  | \$3,600   |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          | \$3,600   |           |
| D3060          | Boiler Room          | 9553953 | Exhaust Fan, Propeller, 5 HP Motor, Replace   |                | 20   | 18  | 2        | 1     | EA</       |             |           |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |      |          |      |                            |  |          |           |           |

7/31/2025

## Lynnbrook Center / Site

| Uniform<br>Code  | Location<br>Description | ID      | Cost Description  | Lifespan<br>(EUL) |  | EAge | RUL | Quantity | Unit | Unit Cost*  | Subtotal  | 2025 | 2026 | 2027    | 2028     | 2029    | 2030    | 2031 | 2032     | 2033     | 2034 | 2035     | 2036     | 2037      | 2038     | 2039 | 2040     | 2041 | 2042      | 2043      | 2044      | 2045     | Deficiency Repair<br>Estimate |
|--|-------------------------|---------|---|-------------------|--|------|-----|----------|------|-------------|-----------|------|------|---------|----------|---------|---------|------|----------|----------|------|----------|----------|-----------|----------|------|----------|------|-----------|-----------|-----------|----------|-------------------------------|
| B1080  | Site                    | 9553977 | Stairs, Concrete, Exterior, Replace   | 50                |  | 30   | 20  | 120      | SF   | \$55.00     | \$6,600   |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           | \$6,600   | \$6,600   |          |                               |
| F1020  | Site                    | 9554045 | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal, Replace           | 30                |  | 25   | 5   | 80       | SF   | \$25.00     | \$2,000   |      |      |         |          |         | \$2,000 |      |          |          |      |          |          |           |          |      |          |      |           | \$2,000   | \$2,000   |          |                               |
| G2020  | Site                    | 9553944 | Parking Lots, Pavement, Asphalt, Seal & Stripe                                      | 5                 |  | 2    | 3   | 60000    | SF   | \$0.45      | \$27,000  |      |      |         | \$27,000 |         |         |      | \$27,000 |          |      |          | \$27,000 |           |          |      | \$27,000 |      | \$108,000 |           |           |          |                               |
| G2020  | Site                    | 9553969 | Parking Lots, Pavement, Asphalt, Mill & Overlay                                     | 25                |  | 13   | 12  | 60000    | SF   | \$3.50      | \$210,000 |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           | \$210,000 | \$210,000 |          |                               |
| G2050  | Site                    | 9554041 | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Seal & Stripe     | 5                 |  | 3    | 2   | 5550     | SF   | \$0.45      | \$2,498   |      |      |         | \$2,498  |         |         |      | \$2,498  |          |      |          | \$2,498  |           |          |      |          |      | \$2,498   | \$9,990   |           |          |                               |
| G2050  | Site                    | 9553957 | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay    | 25                |  | 22   | 3   | 5550     | SF   | \$3.50      | \$19,425  |      |      |         | \$19,425 |         |         |      |          |          |      |          |          |           |          |      |          |      |           |           | \$19,425  |          |                               |
| G2050  | Site                    | 9554059 | Sports Apparatus, Basketball Backboard, Building-Mounted, Replace                   | 25                |  | 21   | 4   | 2        | EA   | \$2,370.00  | \$4,740   |      |      |         |          |         | \$4,740 |      |          |          |      |          |          |           |          |      |          |      |           |           |           | \$4,740  |                               |
| G2050  | Site                    | 9553967 | Playground Surfaces, Chips Wood, 6" Depth, Replace                                  | 5                 |  | 2    | 3   | 2500     | SF   | \$2.00      | \$5,000   |      |      |         | \$5,000  |         |         |      | \$5,000  |          |      |          | \$5,000  |           |          |      |          |      | \$5,000   | \$20,000  |           |          |                               |
| G2050  | Site                    | 9554013 | Play Structure, Multipurpose, Small, Replace  | 20                |  | 10   | 10  | 1        | EA   | \$10,000.00 | \$10,000  |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           |           | \$10,000  |          |                               |
| G2060  | Site                    | 9554042 | Fences & Gates, Fence, Chain Link 6', Replace                                       | 40                |  | 35   | 5   | 80       | LF   | \$21.00     | \$1,680   |      |      |         |          |         | \$1,680 |      |          |          |      |          |          |           |          |      |          |      |           |           | \$1,680   |          |                               |
| G2060  | Site                    | 9553947 | Fences & Gates, Fence, Chain Link 4', Replace                                       | 40                |  | 28   | 12  | 1000     | LF   | \$18.00     | \$18,000  |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           | \$18,000  |           |          |                               |
| G2060  | Site                    | 9553988 | Park Bench, Wood/Composite/Fiberglass, Replace                                      | 20                |  | 5    | 15  | 3        | EA   | \$600.00    | \$1,800   |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           | \$1,800   |           |          |                               |
| G4050  | Site                    | 9554008 | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install | 20                |  | 10   | 10  | 2        | EA   | \$4,000.00  | \$8,000   |      |      |         |          |         |         |      |          |          |      |          |          |           |          |      |          |      |           |           | \$8,000   |          |                               |
| G4050  | Building Exterior       | 9554029 | Site Lighting, Wall Pack or Walkway Pole-Mounted, any type w/ LED, Replace          | 20                |  | 16   | 4   | 5        | EA   | \$800.00    | \$4,000   |      |      |         | \$4,000  |         |         |      |          |          |      |          |          |           |          |      |          |      |           |           | \$4,000   |          |                               |
| <b>Totals, Unescalated</b>                                     |                         |         |   |                   |  |      |     |          |      |             |           | \$0  | \$0  | \$2,498 | \$51,425 | \$8,740 | \$3,680 | \$0  | \$2,498  | \$32,000 | \$0  | \$18,000 | \$0      | \$230,498 | \$32,000 | \$0  | \$1,800  | \$0  | \$2,498   | \$32,000  | \$0       | \$6,600  | \$424,235                     |
| <b>Totals, Escalated (3.0% inflation, compounded annually)</b> |                         |         |   |                   |  |      |     |          |      |             |           | \$0  | \$0  | \$2,650 | \$56,193 | \$9,837 | \$4,266 | \$0  | \$3,072  | \$40,537 | \$0  | \$24,190 | \$0      | \$328,634 | \$46,993 | \$0  | \$2,804  | \$0  | \$4,128   | \$54,478  | \$0       | \$11,920 | \$589,703                     |

\* Markup has been included in unit costs

## **Appendix G:** Equipment Inventory List

---

| Index               | ID      | UFCode | Component Description | Attributes                    | Capacity | Building                            | Location Detail | Manufacturer      | Model              | Serial           | Datplate Yr | Barcode | Qty |
|---------------------|---------|--------|-----------------------|-------------------------------|----------|-------------------------------------|-----------------|-------------------|--------------------|------------------|-------------|---------|-----|
| <b>D20 Plumbing</b> |         |        |                       |                               |          |                                     |                 |                   |                    |                  |             |         |     |
| 1                   | 9553985 | D2010  | <b>Storage Tank</b>   | Domestic Water                | 500 GAL  | Lynnbrook Center / Lynnbrook Center | Boiler Room     |                   |                    |                  |             |         |     |
| 2                   | 9553961 | D2010  | <b>Storage Tank</b>   | Domestic Water                | 500 GAL  | Lynnbrook Center / Lynnbrook Center | Annex building  | Inaccessible      | Inaccessible       | Inaccessible     |             |         |     |
| 3                   | 9554027 | D2010  | <b>Water Heater</b>   | Electric, Commercial ( 12 kW) | 66 GAL   | Lynnbrook Center / Lynnbrook Center | Annex building  | A. O. Smith       | EES--66-J202172543 | MA99-0035666-543 |             |         |     |
| 4                   | 9553976 | D2010  | <b>Water Heater</b>   | Gas, Commercial (125 MBH)     | 75 GAL   | Lynnbrook Center / Lynnbrook Center | Boiler Room     | A. O. Smith       | GPS75200           | 1033M002070      | 2010        |         |     |
| 5                   | 9553994 | D2060  | <b>Air Compressor</b> | Tank-Style                    | 5 HP     | Lynnbrook Center / Lynnbrook Center | Boiler Room     | Quincy Compressor | 2100RB             | 200504180-0099   |             |         |     |

| Index           | ID      | UFCode | Component Description        | Attributes                           | Capacity | Building                            | Location Detail     | Manufacturer        | Model        | Serial                | Dataplate Yr | Barcode | Qty |
|-----------------|---------|--------|------------------------------|--------------------------------------|----------|-------------------------------------|---------------------|---------------------|--------------|-----------------------|--------------|---------|-----|
| <b>D30 HVAC</b> |         |        |                              |                                      |          |                                     |                     |                     |              |                       |              |         |     |
| 1               | 9554004 | D3020  | <b>Boiler</b>                | Gas, HVAC, 1001 to 2000 MBH          | 1170 MBH | Lynnbrook Center / Lynnbrook Center | Annex building      | Weil-McLain         | LGB-10       | NA                    |              |         |     |
| 2               | 9553960 | D3020  | <b>Boiler [B-1]</b>          | Gas, HVAC                            | 3000 MBH | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Fulton              | EDR+3000     | 23225                 | 2023         |         |     |
| 3               | 9554049 | D3020  | <b>Boiler [B-2]</b>          | Gas, HVAC                            | 3000 MBH | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Fulton              | EDR+3000     | 23226                 | 2023         |         |     |
| 4               | 9554056 | D3020  | <b>Radiator</b>              | Hydronic, Baseboard (per LF)         |          | Lynnbrook Center / Lynnbrook Center | Throughout Building |                     |              |                       |              |         | 100 |
| 5               | 9553955 | D3020  | <b>Unit Heater</b>           | Hydronic                             | 186 MBH  | Lynnbrook Center / Lynnbrook Center | Throughout Building | Trane               | Illegible    | Illegible             |              |         |     |
| 6               | 9553968 | D3020  | <b>Unit Heater [PUH-1]</b>   | Hydronic                             | 108 MBH  | Lynnbrook Center / Lynnbrook Center | Boiler Room         | AIRTHERM            | HA-108       | J230194567<br>4001001 | 2023         |         |     |
| 7               | 9554024 | D3030  | <b>Chiller</b>               | Water-Cooled                         | 30 TON   | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Trane               | Illegible    | Illegible             |              |         |     |
| 8               | 9554046 | D3030  | <b>Air Conditioner</b>       | Window/Thru-Wall, Residential        |          | Lynnbrook Center / Lynnbrook Center | Throughout Building |                     |              |                       |              |         | 12  |
| 9               | 9554039 | D3030  | <b>Computer Room AC Unit</b> | Air-Cooled, CRAC Drycooler/Condenser | 25 TON   | Lynnbrook Center / Lynnbrook Center | Roof                | Inaccessible        | Inaccessible | Inaccessible          |              |         |     |
| 10              | 9553970 | D3030  | <b>Split System Ductless</b> | Single Zone                          | 1.5 TON  | Lynnbrook Center / Lynnbrook Center | Annex building      | Mitsubishi Electric | MUY-A17NA    | 8001206T              |              |         |     |
| 11              | 9553949 | D3030  | <b>Split System Ductless</b> | Single Zone, Condenser & Evaporator  | 3 TON    | Lynnbrook Center / Lynnbrook Center | Roof                | Mitsubishi Electric | MXZ-3B30NA   | Illegible             |              |         |     |

| Index | ID      | UFCode | Component Description        | Attributes                                    | Capacity  | Building                            | Location Detail     | Manufacturer   | Model                  | Serial     | Datplate Yr | Barcode        | Qty |
|-------|---------|--------|------------------------------|---|-----------|-------------------------------------|---------------------|----------------|------------------------|------------|-------------|----------------|-----|
| 12    | 9554054 | D3030  | <b>Unit Ventilator</b>       | approx/nominal 2 Ton, 300 to 750 CFM          |           | Lynnbrook Center / Lynnbrook Center | Throughout Building |                |                        |            |             |                | 21  |
| 13    | 9553963 | D3050  | <b>Pump [P-3]</b>            | Distribution, HVAC Heating Water              | 3 HP      | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Taco           | FI1507E4DCH1L3DXB1939D | 625391/1   | 2023        |                |     |
| 14    | 9553946 | D3050  | <b>Pump [P-4]</b>            | Distribution, HVAC Chilled or Condenser Water | 5 HP      | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Bell & Gossett | Illegible              |            |             | Illegible      |     |
| 15    | 9553984 | D3050  | <b>Pump [P-4]</b>            | Distribution, HVAC Heating Water              | 3 HP      | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Taco           | FI1507E4DCH1L3DXB1939D | 6253911    | 2023        |                |     |
| 16    | 9554047 | D3050  | <b>Pump [P-5]</b>            | Distribution, HVAC Chilled or Condenser Water | 5 HP      | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Bell & Gossett | 1510                   |            |             | C014564-01 B60 |     |
| 17    | 9554011 | D3050  | <b>HVAC Steam Components</b> | Condensate Return Station                     | 15 GAL    | Lynnbrook Center / Lynnbrook Center | Annex building      |                |                        |            |             |                |     |
| 18    | 9554048 | D3050  | <b>Air Handler</b>           | Interior AHU, Easy/Moderate Access            | 3200 CFM  | Lynnbrook Center / Lynnbrook Center | Basement            | Trane          | L-8                    |            |             | K146387        |     |
| 19    | 9553986 | D3050  | <b>Packaged Unit</b>         | RTU, Pad or Roof-Mounted                      | 5 TON     | Lynnbrook Center / Lynnbrook Center | Annex building      | York           | D2NA060N06525D         | NGMM084031 | 2003        |                |     |
| 20    | 9554030 | D3050  | <b>Packaged Unit</b>         | RTU, Pad or Roof-Mounted                      | 5 TON     | Lynnbrook Center / Lynnbrook Center | Annex building      | York           | Illegible              |            |             | Illegible      |     |
| 21    | 9554044 | D3050  | <b>Packaged Unit</b>         | RTU, Pad or Roof-Mounted                      | 5 TON     | Lynnbrook Center / Lynnbrook Center | Annex building      | York           | D2NA060N06525D         | NGMM084035 |             |                |     |
| 22    | 9553953 | D3060  | <b>Exhaust Fan</b>           | Propeller, 5 HP Motor                         | 35000 CFM | Lynnbrook Center / Lynnbrook Center | Boiler Room         | Inaccessible   | Inaccessible           |            |             | Inaccessible   |     |

| Index | ID      | UFCode | Component Description | Attributes                       | Capacity | Building                            | Location Detail | Manufacturer | Model        | Serial       | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-----------------------|----------------------------------|----------|-------------------------------------|-----------------|--------------|--------------|--------------|--------------|---------|-----|
| 23    | 9553974 | D3060  | Exhaust Fan           | Roof or Wall-Mounted, 10" Damper | 400 CFM  | Lynnbrook Center / Lynnbrook Center | Annex building  |              |              |              |              |         | 3   |
| 24    | 9554022 | D3060  | Exhaust Fan           | Roof or Wall-Mounted, 10" Damper | 500 CFM  | Lynnbrook Center / Lynnbrook Center | Roof            | Greenheck    | No dataplate | No dataplate |              |         | 5   |
| 25    | 9554019 | D3060  | Exhaust Fan           | Roof or Wall-Mounted, 16" Damper | 1800 CFM | Lynnbrook Center / Lynnbrook Center | Roof            | Greenheck    | Illegible    | Illegible    |              |         | 2   |

| Index                      | ID      | UFCode | Component Description    | Attributes            | Capacity | Building                            | Location Detail     | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|----------------------------|---------|--------|--------------------------|-----------------------|----------|-------------------------------------|---------------------|--------------|-------|--------|--------------|---------|-----|
| <b>D40 Fire Protection</b> |         |        |                          |                       |          |                                     |                     |              |       |        |              |         |     |
| 1                          | 9553991 | D4030  | <b>Fire Extinguisher</b> | Type ABC, up to 20 LB |          | Lynnbrook Center / Lynnbrook Center | Throughout Building |              |       |        |              |         | 10  |
| 2                          | 9554003 | D4030  | <b>Fire Extinguisher</b> | Type ABC, up to 20 LB |          | Lynnbrook Center / Lynnbrook Center | Annex building      |              |       |        |              |         | 10  |

| Index                 | ID      | UFCode | Component Description                                       | Attributes | Capacity | Building                            | Location Detail     | Manufacturer     | Model        | Serial       | Datplate Yr  | Barcode      | Qty |
|-----------------------|---------|--------|---|------------|----------|-------------------------------------|---------------------|------------------|--------------|--------------|--------------|--------------|-----|
| <b>D50 Electrical</b> |         |        |   |            |          |                                     |                     |                  |              |              |              |              |     |
| 1                     | 9554037 | D5020  | <b>Distribution Panel</b> 120/208 V                         |            | 600 AMP  | Lynnbrook Center / Lynnbrook Center | Electrical Room     | General Electric | NAB          |              |              |              |     |
| 2                     | 9554006 | D5020  | <b>Distribution Panel</b> 120/208 V                         |            | 400 AMP  | Lynnbrook Center / Lynnbrook Center | Electrical Room     | General Electric | No dataplate |              | No dataplate |              |     |
| 3                     | 9553987 | D5020  | <b>Distribution Panel</b> 120/208 V                         |            | 400 AMP  | Lynnbrook Center / Lynnbrook Center | Boiler Room         | General Electric |              |              |              |              |     |
| 4                     | 9553950 | D5020  | <b>Distribution Panel</b> 120/208 V                         |            |          | Lynnbrook Center / Lynnbrook Center | Throughout Building |                  |              |              |              |              |     |
| 5                     | 9554005 | D5030  | <b>Variable Frequency Drive</b> VFD, by HP of Motor [VFD-3] |            | 5 HP     | Lynnbrook Center / Lynnbrook Center | Boiler Room         | ABB              |              | No dataplate |              | No dataplate |     |
| 6                     | 9553975 | D5030  | <b>Variable Frequency Drive</b> VFD, by HP of Motor [VFD-4] |            | 5 HP     | Lynnbrook Center / Lynnbrook Center | Boiler Room         | ABB              |              | No dataplate |              | No dataplate |     |

| Index                                       | ID      | UFCode | Component Description   | Attributes        | Capacity | Building                            | Location Detail | Manufacturer | Model        | Serial       | Dataplate Yr | Barcode | Qty |
|---|---------|--------|-------------------------|-------------------|----------|-------------------------------------|-----------------|--------------|--------------|--------------|--------------|---------|-----|
| <b>D70 Electronic Safety &amp; Security</b> |         |        |                         |                   |          |                                     |                 |              |              |              |              |         |     |
| 1   | 9553948 | D7050  | <b>Fire Alarm Panel</b> | Fully Addressable |          | Lynnbrook Center / Lynnbrook Center | Electrical Room | Honeywell    | No dataplate | No dataplate |              |         |     |
| 2   | 9554031 | D7050  | <b>Fire Alarm Panel</b> | Fully Addressable |          | Lynnbrook Center / Lynnbrook Center | Annex building  | Honeywell    |              |              |              |         |     |