### **Montgomery County Public Schools**

#### 2018 School Facilities Assessment

School Number 207 School Name Beall

School Type Elementary School

 Year Built\*
 1954

 Year of Last Renovation\*
 1991

 GSF\*
 79,477



# **Building Level - Key Facility Indicators**



### Infrastructure - Facility Condition

A10 Foundations
n/a A20 Basement
B10 Superstructure

B20 Exterior Enclosure
B30 Roofing

C10 Interior Construction

C20 Stairs

C30 Interior Finishes

D10 Conveying Systems

D20 Plumbing
D30 HVAC

D40 Fire Protection

D50 Electrical

E10 Equipment
E20 Furnishings

F10 Special Construction

# **Building Characteristics**

#### **Building Quality**

Classroom Shape\*

IMC Size\*Cafeteria Size\*

Corridor\*

Indoor Environment

Temperature Control

Humidity Control

Natural Light

Acoustic Features

Building-Level Power Delivery

Ī	*indicates that underlying data was provided by MCPS not collected by FEA.	
	Information Sources:	(References)

5/1/2019 Version 4.0