## **Montgomery County Public Schools**

#### 2018 School Facilities Assessment


School Number 246

School Name Northwest

School Type High School
Year Built\* 1998
Year of Last Renovation\* Unknown
GSF\* 340,867



# **Building Level - Key Facility Indicators**



## Infrastructure - Facility Condition

A10 Foundations
A20 Basement

B10 Superstructure

B20 Exterior Enclosure
B30 Roofing

C10 Interior Construction

C20 Stairs

C30 Interior Finishes

D10 Conveying Systems

D20 Plumbing
D30 HVAC

D40 Fire Protection

D50 Electrical

E10 Equipment E20 Furnishings

F10 Special Construction

# **Building Characteristics**

#### **Building Quality**

Classroom Shape\*

IMC Size\*

Cafeteria Size\*

Corridor\*

# Indoor Environment

Temperature Control

Humidity Control

Natural Light

Acoustic Features

Building-Level Power Delivery

*indicates that underlying data was provided by MCPS not collected by FEA.	
Information Sources:	(References)

5/1/2019 Version 4.0