
Montgomery County Public Schools

2018 School Facilities AssessmentSchool Number410School NameBradley HillsSchool TypeElementary SchoolYear Built*1951Year of Last Renovation*1984GSF*76,745





Infrastructure - Facility Condition

	A10	Foundations	C20	Stairs		D50	Electrical
n/a	A20	Basement	C30	Interior Finishes	\bigcirc	E10	Equipment
	B10	Superstructure	D10	Conveying Systems	\bigcirc	E20	Furnishings
	B20	Exterior Enclosure	D20	Plumbing		F10	Special Construction
	B30	Roofing	D30	HVAC			
\bigcirc	C10	Interior Construction	D40	Fire Protection			

Building Characteristics

Building Quality	Indoor Environment
Classroom Shape*	Temperature Control
IMC Size*	Humidity Control
Cafeteria Size*	Natural Light
Corridor*	Acoustic Features
	Building-Level Power Delivery

*indicates that underlying data was provided by MCPS not collected by FEA.							
Information Sources:	(References)						
5/1/2019		Version 4.0					