Montgomery County Public Schools

2018 School Facilities AssessmentSchool Number790School NameArcolaSchool TypeElementary SchoolYear Built*1956Year of Last Renovation*2007GSF*95,421



Building Level - Key Fa	cility Indicators
Infrastructure (FCI)	
Building Quality	
Indoor Environment	

Infrastructure - Facility Condition

A10	Foundations		C20	Stairs		D50	Electrical
A20	Basement		C30	Interior Finishes	\bigcirc	E10	Equipment
B10	Superstructure		D10	Conveying Systems	\bigcirc	E20	Furnishings
B20	Exterior Enclosure	\bigcirc	D20	Plumbing		F10	Special Construction
B30	Roofing	\bigcirc	D30	HVAC			
C10	Interior Construction		D40	Fire Protection			

Building Characteristics

Building Quality	Indoor Environment
Classroom Shape*	Temperature Control
IMC Size*	Humidity Control
Cafeteria Size*	Natural Light
Corridor*	Acoustic Features
	Building-Level Power Delivery

*indicates that underlying data w	vas provided by MCPS not collected by FEA.	
Information Sources:	(References)	
5/1/2019	Vers	ion 4.0