### **Montgomery County Public Schools**

### 2018 School Facilities Assessment

School Number 812
School Name Parkland

School Type Middle School

 Year Built\*
 1963

 Year of Last Renovation\*
 2007

 GSF\*
 151,169



# **Building Level - Key Facility Indicators**



## Infrastructure - Facility Condition

A10 Foundations
A20 Basement

B10 Superstructure
B20 Exterior Enclosure

B30 Roofing

C10 Interior Construction

C20 Stairs

C30 Interior Finishes

D10 Conveying Systems

D20 Plumbing
D30 HVAC

D40 Fire Protection

D50 Electrical

E10 Equipment

E20 Furnishings
F10 Special Construction

# **Building Characteristics**

### **Building Quality**

Classroom Shape\*

IMC Size\*

Cafeteria Size\*

Corridor\*

### **Indoor Environment**

Temperature Control

Humidity Control

Natural Light

Acoustic Features

Building-Level Power Delivery

Ī	findicates that underlying data was provided by MCPS not collected by FEA.	
Ī	Information Sources:	(References)

5/1/2019 Version 4.0