## Montgomery County Public Schools

## 2018 School Facilities Assessment

School	Number
School	Name

School Type Year Built\* Year of Last Renovation\* GSF\* Elementary School 1974 Unknown

568 Stedwick

109,677



Building Level - Key Facility Indicators								
Infrastructure (FCI)								
Building Quality								
Indoor Environment								

## Infrastructure - Facility Condition

A10	Foundations		C20	Stairs	$\bigcirc$	D50	Electrical
A20	Basement		C30	Interior Finishes		E10	Equipment
B10	Superstructure		D10	Conveying Systems	$\bigcirc$	E20	Furnishings
B20	Exterior Enclosure	$\bigcirc$	D20	Plumbing		F10	Special Construction
B30	Roofing		D30	HVAC			
C10	Interior Construction		D40	Fire Protection			

## **Building Characteristics**

Building Quality	Indoor Environment	
Classroom Shape*	Temperature Control	
IMC Size*	Humidity Control	
Cafeteria Size*	Natural Light	
Corridor*	Acoustic Features	
	Building-Level Power Delivery	

*indicates that underlying data v	was provided by MCPS not collected by FEA.	
Information Sources:	(References)	
5/1/2019		Version 4.0