



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Sargent Shriver Elementary School
12518 Greenly Street
Silver Spring, Maryland 20906

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number: 123821.17R000-083.303
Date of Report: October 30, 2019
On Site Date: September 13-14, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Sargent Shriver Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Sargent Shriver Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Sargent Shriver Elementary School	56	19	35	7		117
Grand Total	56	19	35	7		117

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
70830	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Row 1 (access aisle 1)	ADA
70960	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk from public ROW (Greenly Street) on west side of bus drop-off	ADA
70964	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route from Building 1 to Portables 4-9	ADA
70968	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 5 (Exterior)	ADA
70971	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk adjacent to Playground 1	ADA
70979	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Flagpole	ADA
70981	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	South elevation of building parallel bus drop off area	ADA
70982	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-1 along bus drop off near Exterior Door 2 CR-2 at student drop off East side of building	ADA
70989	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Building 1 courtyard	ADA
70999	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	ST-5, 6, 7, 8, 9 (Adjacent to Portables)	ADA
71003	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	ST-5	ADA
71007	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	ST-5, 6, 7, 8, 9 (Exterior wood stairs at Portable classrooms)	ADA
71008	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Door 2	ADA
71011	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	ST-8 (Portable 1)	ADA
71014	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Asphalt walkway east of Portable 4	ADA
71016	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Public ROW at Greenly near main entrance (Door 1 and Door 2)	ADA
71018	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	East side of building adjacent to student drop off, and east of gym along paved drive aisle	ADA
71019	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete walk on north side of Building 1	ADA
71020	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	North side of building near basement level entry (Door 10)	ADA
71021	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	North of Building 1 above concrete walkway	ADA
71023	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible route from ADA parking to Building 1 main entry	ADA
71024	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 2 adjacent to Daycare (Rm 1300)	ADA
71025	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 3 between Portables 5 and 6	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71026	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp 4 and Ramp 5 (adjacent to Portables 1 and 3)	ADA
71027	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Row 1	ADA
71028	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Row 1 (access aisle 2)	ADA
71029	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Row 1	State of Maryland
71030	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1, Row 1	ADA
71032	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1, Row 1	State of Maryland
71033	Sargent Shriver Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1, Row 1	State of Maryland
71049	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball field	ADA
71052	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Parking lot 1, Student drop off	ADA
71053	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The operable part is not within an allowable reach range.	Main Entry - Door 1	ADA
71055	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Portable Classrooms 1, 2, 3	ADA
71059	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 5 (Exterior)	ADA
71472	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Exterior play area south of Portable #3	ADA
71475	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Bench adjacent to Student drop off lane	ADA
71486	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Main entry door call button	ADA
71497	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrail height is not compliant.	Ramp 3 between Portables 5 and 6	ADA
71061	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 1	ADA
71063	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 1	ADA
71064	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 3	ADA
71066	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2	ADA
71067	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	Rooms 1201,1510, 1512,1604, 1608, 2010, 2014	ADA
71069	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	R-1- Interior ramp at all-purpose room	ADA
71070	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrails are not provided.	R-1 All-purpose Room	ADA
71079	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	2010, 2014, 1608, 1604, 1512, 1510, 1201, 1115, 1113, 1000, 1000F, 1002	ADA
71081	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	1000 Main Office Door	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71083	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	Stage - All Purpose Room	State of Massachusetts
71086	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Media Center	ADA
71088	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Main Office	ADA
71090	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width.	1102 (Staff), 1106 (Staff)	ADA
71091	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	1102 (Staff), 1106 (Staff)	ADA
71092	Sargent Shriver Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gym	ADA
71121	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Vertical Level Change	1	Vertical level changes between 1/4" and 1/2" high are not beveled or vertical level changes greater than 1/2" high are not ramped.	Girls/Boys Restroom 1203,1207, 2014	ADA
71127	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The space between two doors in a series is less than 48" clear with doors open 90 degrees.	Girls/Boys Restroom 1203, 1207	ADA
70995	Sargent Shriver Elementary School	BUILDING EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Building 1 courtyard	ADA
70996	Sargent Shriver Elementary School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 1	ADA
71012	Sargent Shriver Elementary School	BUILDING EXTERIOR	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Asphalt play area south of Portable 2 and 3	ADA
71034	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 1	ADA
71035	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 1	ADA
71036	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 2	ADA
71037	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 2	ADA
71040	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Exterior Accessible Route	2	An accessible route within the play area has not been provided.	Playground 2	ADA
71045	Sargent Shriver Elementary School	BUILDING EXTERIOR	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball field team benches (2)	ADA
71057	Sargent Shriver Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Portables 1-6	ADA
71467	Sargent Shriver Elementary School	BUILDING EXTERIOR	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	Asphalt play / picnic area south of Portable 2 and 3	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71491	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Playground 2	ADA
71503	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Protruding Object	2	The vertical clearance is less than 80" minimum. The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Staff restroom 1126A	ADA
71076	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	Means of egress exit signs do not have tactile lettering.	Exterior egress doors	ADA
71093	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Portables 1-3	ADA
71094	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Portables 4-9	ADA
71095	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Typical classroom	ADA
71096	Sargent Shriver Elementary School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
71098	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Multiple classrooms- restrooms throughout	ADA
71134	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff restrooms 1117A, 1122B, 1510, 1201, 1000F, 1002C, 2002B, 1214B	ADA
71136	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Staff restrooms 1000F, 1126A, 1510, 1201, 2002B, 1214B	ADA
71137	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff restrooms 1510, 1117A	ADA
71138	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff restrooms 1201, 1122B	ADA
71140	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff restrooms 1000F, 1002C, 1201, 1126A, 1122B, 2002B	ADA
71142	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff restroom 1201, 1000A1 (Principal)	ADA
71145	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Staff restroom 1117A	ADA
71146	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Staff restroom 1126A	ADA
71147	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall in a multi-stall restroom used primarily by children (ages 3-12) does not have the required dimensions.	Girls/Boys Restroom 1203, 1207	ADA
71068	Sargent Shriver Elementary School	BUILDING INTERIOR	Exterior Access Route	Elevator	3	The illumination at car controls, car platform, car threshold and car landing sill is less than 5 foot candles (54 lux).	EL-1	ADA
71084	Sargent Shriver Elementary School	BUILDING INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	All Purpose Room	ADA
71099	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Floor Space	3	The required turning space within the restroom is not provided.	Staff Restroom 1008A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71100	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Floor Space	3	The required turning space within the restroom is not provided.	Student Restrooms 1019A, 1023A	ADA
71102	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restrooms 1102, 2010	ADA
71103	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	1203 Boys	ADA
71106	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Student Restrooms 2010,2014,1203,1207,1115,1113,1106	ADA
71107	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys/Girls Restroom 1113,2014,1608,1010A,1300C, 1206A	ADA
71109	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Classrooms 1004A, 1204A	ADA
71110	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Boys/Girls Restrooms 1010A, 1608, 2010, 1206A, 1604	ADA
71111	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Boys/Girls Restrooms 1102, 2014, 2010, 1115, 1113, 1106	ADA
71112	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Student Restrooms 2014, 1113, 2010	ADA
71113	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys/Girls Restrooms 1106, 1102, 1206A, 1207, 1010A, 1300C, 1004A, 1204A	ADA
71114	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys/Girls Restrooms 1102, 1106, 1010A, 1204A, 1115, 1113	ADA
71115	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Student Restrooms 1207, 1115, 1113	ADA
71116	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Girls Restroom 1106	ADA
71117	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Classrooms 1010A, 1300C	ADA
71118	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys/Girls Restroom 1106, 1102	ADA
71119	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Boys/Girls Restrooms 1010A, 1300C, 1206A, 1204A	ADA
71120	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Student restrooms1300C, 1203, 1207, 2014, 2010	ADA
71123	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys/Girls Restrooms 1102, 1106, 1203, 1207	ADA
71126	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Girls/Boys Restroom 1203, 1207	ADA
71129	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff restrooms 1126A, 1512, 1201, 1000F, 1002C, 1117A, 1122B, 2002B, 1214B	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71131	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff restrooms 1512, 1510, 1000F, 1122B, 2002B, 1214B	ADA
71132	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Staff restrooms 1512, 1122	ADA
71133	Sargent Shriver Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Staff restrooms 1214B, 1117A, 1122B, 1201, 1000A1, 1000F, 1126A, 2002B	ADA
71039	Sargent Shriver Elementary School	BUILDING EXTERIOR	Playground	Play Component	4	The play component which has manipulative or interactive features that require reaching is not within the child's reach range.	Playground 2	ADA
71071	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	Classrooms 1004, 1010, 1014, 1300, 1023, 1019, 1200, 1209, 1204, 1206	ADA
71072	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Classrooms - Grade 1 through Grade 5	ADA
71073	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	DF-2, DF-5	ADA
71074	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	DF-1, DF-3	ADA
71075	Sargent Shriver Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	DF-4	ADA
71097	Sargent Shriver Elementary School	BUILDING INTERIOR	Kitchen	Storage	4	The storage does not have at least 50% of cabinet shelf space within reach ranges (15"-48"; 46" max when shelving is 10" deep) AND/OR with handles that cannot be operated with one hand, and require tight grasping, pinching, or twisting of the wrist, or require more than 5 pounds force to operate, AND/OR without clear floor space.	Staff Lounge	ADA