



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

James Hubert Blake High School
300 Norwood Road
Silver Spring, Maryland 20905

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-114.303

Date of Report:

October 28, 2019

On Site Date:

October 11th-13th, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at James Hubert Blake High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at James Hubert Blake High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
James Hubert Blake High School	71	15	14			100
Grand Total	71	15	14			100

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88671	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisle between P1 and P2	ADA
88672	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisles between Stalls P4 and P3	ADA
88673	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisle between Stalls P6 and P5	ADA
88674	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 1: Parking Stalls P6 - P2	ADA
88675	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Parking Stall P1	ADA
88676	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: Parking Stall's P1-P6	State of Maryland
88678	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisle between P9 and P10	ADA
88679	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisle between stalls P7 and P8	ADA
88681	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Parking Stall P10	ADA
88682	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: Access Aisle between stalls P9 and P10	ADA
88683	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: Stalls P1 to P6 and P7 to P14	State of Maryland
88685	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1: Access Aisles between Stalls P11 and P12	ADA
88686	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 1: Access Aisle between Stalls P13 and P14	State of Maryland
88688	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	The van parking space is less than 132" wide, where the van aisle is less than 96" wide.	Parking Lot 1: Van Stalls P13 and P14	ADA
88690	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Stall's P11 and P12	ADA
88691	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: Stalls P13 and P14	ADA
88692	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: Access Aisles between Stalls P11 and P12	ADA
88693	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: Access Aisles between Stalls P13 and P14	State of Maryland
88719	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2: Stall P17, P15, and P16	State of Maryland
88720	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Between Parking Stalls P11 and P12, P15 and P16, P17 and P18, and P19	State of Maryland
88721	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2: Stall P19	State of Maryland
88722	James Hubert Blake High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 2: Access Aisle between Stalls P15 and P16, and P17 and P18	State of Maryland
88723	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk just north of CR1 down to CR4	ADA
88724	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR2	ADA
88725	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR2	ADA
88726	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	In between CR1 and CR3	ADA
88727	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR3	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88728	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR3	ADA
88729	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Curb Ramp CR3	ADA
88730	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Curb Ramp CR3	ADA
88731	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Egress walkway just south of CR3	ADA
88732	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R1	ADA
88733	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR4	ADA
88734	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR4	ADA
88735	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk north of CR4 to building access	ADA
88736	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR5	ADA
88737	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR5	ADA
88738	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR6	ADA
88739	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	CR9	ADA
88740	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk just North of CR9 up until in between CR11 and CR12	ADA
88741	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR10	ADA
88742	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	CR10	ADA
88743	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	CR11	ADA
88744	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance.	CR11	ADA
88745	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	CR12	ADA
88746	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk in front of school from CR12 towards CR13	ADA
88747	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk in front of school from CR12 to just past CR13	ADA
88748	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Just northwest of CR13	ADA
88749	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from CR13 headed North	ADA
88750	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	CR8	ADA
88751	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	R3	ADA
88752	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	R3	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88753	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from just west of CR8 to CR7 and south	ADA
88754	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	R3	ADA
88755	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk corner just north of basketball courts	ADA
88757	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	R4	ADA
88758	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	R5	ADA
88759	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	R5	ADA
88761	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	R6	ADA
88762	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	R6	ADA
88763	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Sidewalk from Stadium entrance up until the beginning of the basketball courts	ADA
88764	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Sidewalk from CR14 to CR15	ADA
88821	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	R1	ADA
88822	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Car Loading/Unloading zone	ADA
77890	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Vertical Clearance	1	Objects along the interior accessible route suspend from the ceilings lower than 80" AFF.	Interior Stair STR3	ADA
77893	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Main Office Workroom	ADA
78004	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	P/E Laundry Room	ADA
78006	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Controls	1	The height of controls throughout the common area are not compliant.	Staff Spaces and Rooms	ADA
77870	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Controls	1	The height of controls throughout the common area are not compliant.	Switches and Controls	ADA
78029	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Auditorium Stage Stairs	ADA
88343	James Hubert Blake High School	BUILDING INTERIOR	Common Areas	Platform Lift	1	The platform lift requires a key for operation.	Auditorium Stage Lift	ADA
88716	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground PG1	ADA
88717	James Hubert Blake High School	BUILDING EXTERIOR	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	Playground PG1	ADA
88718	James Hubert Blake High School	BUILDING EXTERIOR	Playground	Transfer System	2	A transfer space is not provided at the platform.	Playground PG1	ADA
88756	James Hubert Blake High School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
88760	James Hubert Blake High School	BUILDING EXTERIOR	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Softball Field 1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88765	James Hubert Blake High School	BUILDING EXTERIOR	Tennis Courts	Player Seating	2	A wheelchair space is not provided at the seating for the tennis courts.	Tennis Courts	ADA
88766	James Hubert Blake High School	BUILDING EXTERIOR	Football Field	Player Seating	2	A wheelchair space is not provided at each team seating for the football field.	Stadium	ADA
77993	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Art Classroom E165	ADA
77994	James Hubert Blake High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
78000	James Hubert Blake High School	BUILDING INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Art Classrooms	ADA
78007	James Hubert Blake High School	BUILDING INTERIOR	Common Areas	Counter	2	The counter oriented for a forward approach does not have clear floor space for a forward approach with toe and knee clearance.	Media Center	ADA
78010	James Hubert Blake High School	BUILDING INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Math Resource Office, Science Prep Room	ADA
78017	James Hubert Blake High School	BUILDING INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Science Classrooms	ADA
77828	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restrooms: Boys 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13; Girls 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13; Boys Locker Room Restroom, Girls Locker Room Restroom	ADA
78022	James Hubert Blake High School	BUILDING INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Art Classrooms	ADA
77882	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8; Main Office Restroom 1, Men's Office Restroom 1, 2; Women's Office Restroom 1, 2; Building Services Restroom, Boys & Girls P/E Office Restrooms	ADA
77884	James Hubert Blake High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls Locker Room, Boys Locker Room	ADA
77892	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Main Office Restroom 1	ADA
77973	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restrooms: Student Health Office Restroom	ADA
77974	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms: Men Office Restroom 2, Women's Office Restroom 2, Boy's P/E Office Restroom	ADA
77989	James Hubert Blake High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Boys P/E Office, Girls P/E Office	ADA
77843	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restrooms: Staff 1, 2, 4, 5, 6, 7, 8; Main Office Restroom 1, Men's Office Restroom 1, 2; Women's Office Restroom 1, 2; Boys P/E Office Restroom, Girls P/E Office Restroom, Building Services Restroom	ADA
77874	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Restroom: Boys 1	ADA
77875	James Hubert Blake High School	BUILDING INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator E1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77877	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8; Boys P/E Office Restroom, Girls P/E Office Restroom, Building Services Restroom, Men's Office Restroom 1, 2; Women's Office Restroom 1, 2; Staff Health Office Restroom	ADA
78031	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys P/E Office Restroom Shower, Girls P/E Office Restroom Shower	ADA
78051	James Hubert Blake High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Auditorium	ADA
88336	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Student Health Office Restroom	ADA
88338	James Hubert Blake High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms: Staff Health Office Restroom, Building Services Restroom, Office Restroom 1	ADA