



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Meadow Hall Elementary School
951 Twinbrook Parkway
Rockville, Maryland 20851

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-135.303

Date of Report:

October 28, 2019

On Site Date:

May 8, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Rosemary Hills Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at John T Baker Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Meadow Hall Elementary School	85	18	28	2		133
Grand Total	85	18	28	2		133

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103048	Meadow Hall Elementary School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field	ADA
103074	Meadow Hall Elementary School	ATHLETIC FIELDS	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Basketball Court 2	ADA
102042	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair STR 5	ADA
102043	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair STR 5	ADA
102050	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R14	ADA
102051	Meadow Hall Elementary School	EXTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	West Sidewalk at Parking Lot 3	ADA
103036	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	South Sidewalk	ADA
103037	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR13	ADA
103038	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Parking Lot 1	ADA
103039	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Parking Lot 1	ADA
103040	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Parking Lot 1	ADA
103041	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Parking Lot 2	ADA
103042	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	Parking Lot 2	ADA
103043	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR 8	ADA
101817	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Bike Racks	ADA
101819	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R 11	ADA
101820	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair STR 7	ADA
101822	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Southwest Sidewalk	ADA
101823	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Curb Ramp CR 1	ADA
101824	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	South Sidewalk Between CR1 and CR2	ADA
101826	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Southwest Sidewalk at Circle	ADA
101827	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Stair STR 7	ADA
101828	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair STR 7	ADA
101830	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	West Sidewalk Near Bike Racks	ADA
101831	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk at Door 2	ADA
101833	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk at Door 2	ADA
101835	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R 12	ADA
101839	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	South Sidewalk at Circle Near Main Entrance	ADA
103044	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR 8	ADA
103049	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	East Sidewalk	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103053	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Playground 1	ADA
103056	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair STR8	ADA
103057	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair STR8	ADA
103059	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Playground 3	ADA
103061	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Playground 2	ADA
103062	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	Handrails are not continuous and at a consistent height above ramp surface.	Ramp 3	ADA
103063	Meadow Hall Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	An accessible entrance is not provided.	Door 10	ADA
103064	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair STR9	ADA
103065	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair STR9	ADA
101840	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Flag Pole	ADA
101842	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	South Sidewalk at front of Building Near Main Entrance	ADA
101844	Meadow Hall Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 1	ADA
101848	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The walkway has areas with greater than 1:20 (5%) running slope.	South Sidewalk	ADA
101849	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	South Sidewalk	ADA
101861	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp CR 5 & CR 6	ADA
101863	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR 5	ADA
101865	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR 6	ADA
101867	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R 13	ADA
101868	Meadow Hall Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 19	ADA
102037	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Southeast Sidewalk Near R15	ADA
102038	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair STR 4	ADA
103073	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair STR10	ADA
103075	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp 11	ADA
103077	Meadow Hall Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 8	ADA
103078	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	West Sidewalk	ADA
103079	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Flagpole	ADA
103080	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Student Drop Off	ADA
103318	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR 5	ADA
103319	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR 7	ADA
102039	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair STR 4	ADA
102040	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair STR 4	ADA
103086	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Rear Main Office Door	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103141	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	STR 3 and 4	State of Massachusetts
103142	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	STR 3 and 4	ADA
103143	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R2	ADA
103144	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp R1 and 2	ADA
103145	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp R1	ADA
103152	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair STR2	ADA
103155	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Elevator	1	The emergency communication device is not within reach range.	Elevator EL1	ADA
103156	Meadow Hall Elementary School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
103157	Meadow Hall Elementary School	INTERIOR	Employee Work Areas	Locker Rooms	1	The locker rooms are not accessible.	Gym Office	ADA
101853	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 2-1	ADA
101855	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 2 -2	ADA
101856	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 2	ADA
101858	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 2-1&2	ADA
101859	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	A van space is not provided.	Parking Lot 2	ADA
102044	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 3-1	ADA
102045	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	Compliant signage is not provided at the van stall.	Parking Lot 3-1	ADA
102046	Meadow Hall Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The van parking space is less than 132" wide, where the van aisle is less than 96" wide.	Parking Lot 3-1	ADA
102047	Meadow Hall Elementary School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	Curb ramp is not wholly within the marked crossing.	Curb Ramp CR 7	ADA
102048	Meadow Hall Elementary School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR 7	ADA
102049	Meadow Hall Elementary School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp CR 7	ADA
103090	Meadow Hall Elementary School	RESTROOMS	Interior Access Route	Door	1	The door has less than 32" clear width.	Boys and Girls RR1	ADA
103091	Meadow Hall Elementary School	RESTROOMS	Interior Access Route	Interior Access Route	1	Clear widths at turning area are less than 60" minimum.	Boys and Girls RR 1	ADA
103100	Meadow Hall Elementary School	RESTROOMS	Interior Access Route	Door	1	The door has less than 32" clear width.	Staff RR1	ADA
103046	Meadow Hall Elementary School	ATHLETIC FIELDS	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball Field	ADA
103047	Meadow Hall Elementary School	ATHLETIC FIELDS	Baseball/Softball Field	Lawn Seating	2	The lawn seating and exterior overflow seating areas, where fixed seating is not provided, do not connect to an accessible route.	Baseball Field	ADA
102041	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Reach Range	2	Operable parts or items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Door 18	ADA
103045	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Door 16	ADA
103054	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 1	ADA
103055	Meadow Hall Elementary School	EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Playground 1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
101845	Meadow Hall Elementary School	EXTERIOR	Exterior Access Route	Reach Range	2	Operable parts or items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	Door 1	ADA
103076	Meadow Hall Elementary School	EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Blacktop Area 2	ADA
103158	Meadow Hall Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	ML 999, 931, 1074, 1084 and 1083	ADA
103087	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Signage	2	Means of egress exit signs do not have tactile lettering.	All Exits	ADA
103089	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	All restroom Signage	ADA
103098	Meadow Hall Elementary School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
103050	Meadow Hall Elementary School	PLAYGROUND	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 1	ADA
103051	Meadow Hall Elementary School	PLAYGROUND	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 1	ADA
103052	Meadow Hall Elementary School	PLAYGROUND	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	Playground 1	ADA
103058	Meadow Hall Elementary School	PLAYGROUND	Playground	Play Component	2	The number of existing types of ground level components is less than the required minimum.	Playground 3	ADA
103060	Meadow Hall Elementary School	PLAYGROUND	Playground	Transfer System	2	The transfer steps are higher than 8" each.	Playground 2	ADA
103130	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Boys and Girls RR1, 2, 3 and 4	ADA
103082	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Health Room Restroom	ADA
103083	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Health Room Restroom, Main Office Staff Restrooms	ADA
103084	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Main Office Staff Restrooms	ADA
103085	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Main Office Staff Restrooms	ADA
103092	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls and Boys RR1	ADA
103093	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys RR1	ADA
103094	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Girls and Boys RR1	ADA
103095	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Boys RR1	ADA
103096	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Classroom 9, 10, 11, 12, 13, 14	ADA
103097	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff RR1	ADA
103099	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff RR 1	ADA
103131	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Girls RR2	ADA
103132	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Girls RR2	ADA
103133	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Girls RR2 and Boys RR 4	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103134	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys RR2	ADA
103135	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys RR2	ADA
103136	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	MARYLAND: The water closet has less than the required minimum clearance dimensions, and it is structurally infeasible to create compliant clearance.	Boys RR2	State of Maryland
103137	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys RR2	ADA
103139	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Cafeteria RR	ADA
103140	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Cafeteria RR	ADA
103146	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff RR2	ADA
103147	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys RR3	ADA
103148	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Boys and Girls RR3 and RR4	ADA
103149	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys and Girls RR3	ADA
103150	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff RR3 and RR5	ADA
103151	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff RR3	ADA
103153	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff RR5	ADA
103154	Meadow Hall Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff RR5	ADA
103138	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is not compliant.	Rooms 21, 23, 25, 26, 27, 28, 30, 31, 32, 44, 45, 47,52, G6, G7, G8 and G9.	ADA
103159	Meadow Hall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Entire Building	ADA