



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Thurgood Marshall Elementary School
12260 McDonald Chapel Drive
Gaithersburg, Maryland 20878

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-093.303

Date of Report:

October 25, 2019

On Site Date:

September 28, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Thurgood Marshall Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Thurgood Marshall Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Thurgood Marshall Elementary School	48	15	41	5		109
Grand Total	48	15	41	5		109

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72536	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-1	ADA
72538	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2	State of Maryland
72539	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 2	State of Maryland
72541	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage at the space is not provided.	Parking Lot 2	State of Maryland
72543	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1 (P1A-P1B) Parking Lot 2	State of Maryland
72546	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1, P1A - P1B	State of Maryland
72551	Thurgood Marshall Elementary School	EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1, P1C-P1D	State of Maryland
72556	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete sidewalk adjacent to bus drop off	ADA
72558	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Parking Lot 1	ADA
72560	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Flagpole	ADA
72563	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student drop off area	ADA
72565	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Student drop off area	ADA
72568	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp surface has vertical height changes greater than 1/4" that are not ramped.	CR-2, CR-3	ADA
72569	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Bus drop off to Bldg 1 Main entrance	ADA
72575	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk between Parking Lot 2 and Bldg 1 main entrance	ADA
72578	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Concrete walk from exterior Door 23	ADA
72589	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Parking Lot 1: Sidewalk from CR-1 toward P1A-P1D	ADA
72594	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 1 and 2, Soccer Field	ADA
72680	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp 1	ADA
72729	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Playground 1	ADA
72733	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Playground 1	ADA
72738	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Playground 2	ADA
72739	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Playground 2	ADA
88333	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Concrete walk from exterior Door 23	ADA
88334	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 1	ADA
88335	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus drop off	ADA
72712	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 1	ADA
72714	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 1	ADA
72715	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 1	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72716	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2	ADA
72717	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Elevator	1	The re-opening device is not automatic.	EL-1	ADA
72742	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Room 8, 10, 15, Main Office, Work Room	ADA
72745	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	All Purpose Room stage	ADA
72747	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	All-Purpose Room stage	State of Massachusetts
72754	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Gymnasium	ADA
72755	Thurgood Marshall Elementary School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
72806	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Room 9, Room 11	ADA
72842	Thurgood Marshall Elementary School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 28	ADA
88327	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Elevator	1	The elevator does not have compliant two way emergency communication.	EL-1	ADA
72684	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Portable 1: Ramp 3	ADA
72689	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Ramp	1	The handrails are not compliant.	Portable 1: Ramp 3	ADA
72695	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Portable 1: Ramp 3	ADA
72699	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Portable 5: Stair 5	ADA
72701	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Portable 5: Stair 5	ADA
72709	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Portable 1: Stair 3	ADA
72710	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Stairs	1	Handrails are not provided.	Portable 1: Stair 3	ADA
72711	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Portable 1: Stair 3	ADA
72720	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Entrance to Building	Building Entrance-Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Portable 1	ADA
72731	Thurgood Marshall Elementary School	EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 1 Playground 2, Picnic area adjacent to Playground 2	ADA
72734	Thurgood Marshall Elementary School	EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 1, Playground 2	ADA
72735	Thurgood Marshall Elementary School	EXTERIOR	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Playground 1	ADA
72737	Thurgood Marshall Elementary School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 2	ADA
72899	Thurgood Marshall Elementary School	EXTERIOR	Playground	Play Component	2	The ground level component or elevated component accessed by ramp is required to be on an accessible route but is not within a child's reach range.	Playground 1	ADA
72722	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Staff Lounge, Kitchen	ADA
72723	Thurgood Marshall Elementary School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72724	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Lounge, RM 28, Work Room, BAR T Kitchen	ADA
72752	Thurgood Marshall Elementary School	INTERIOR	Common Areas	Dining And Work Surface	2	Dining Surfaces for Children: Minimum 5% of the dining surface does not have minimum 30" wide section of the dining surface at minimum 26" and maximum 30" height, with knee and toe clearance for children at 24" minimum above floor or ground level.	All-Purpose Room	ADA
72791	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Suite	ADA
72840	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Corridor, Stair 1, Stair 2	ADA
72841	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Corridor fire control doors	ADA
88221	Thurgood Marshall Elementary School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Health Suite	ADA
88328	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Boys Restrooms 1, 2, 3 and 4; Girls Restrooms 1, 2, 3 and 4	ADA
72721	Thurgood Marshall Elementary School	PORTABLE CLASSROOMS	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Portables 3, 4, 5	ADA
72741	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	Exit doors throughout Classroom exits (to exterior) Rooms 1, 3, 5, 7, 25, 27, 29	ADA
72751	Thurgood Marshall Elementary School	INTERIOR	Common Areas	Assembly Area	3	An assistive listening system is required, but not provided.	All-Purpose Room	ADA
72759	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	PE Office Restroom, Bldg Services Restroom	ADA
72760	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	PE Office Restroom, Bldg Services Restroom	ADA
72762	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	PE Office Restroom, Bldg Services Restroom	ADA
72763	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	PE Office Restroom	ADA
72764	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Bldg Services Restroom	ADA
72766	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Bldg Services Restroom	ADA
72767	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Bldg Services Restroom	ADA
72768	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Kitchen Restroom	ADA
72770	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Kitchen Restroom	ADA
72772	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Restroom	ADA
72774	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Kitchen Restroom	ADA
72777	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Main Office Restroom	ADA
72795	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Health Restroom	ADA
72797	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Restroom	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72799	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 139	ADA
72800	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 139	ADA
72802	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Staff Restroom 139	ADA
72836	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff RR 2	ADA
72837	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff RR 2	ADA
72838	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Room 9 Restroom, Room 11 Restroom	ADA
72839	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Room 9 Restroom, Room 11 Restroom; Room 25, 27 and 29 restrooms	ADA
72843	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	MARYLAND: The water closet has less than the required minimum clearance dimensions, and it is structurally infeasible to create compliant clearance.	Room 1, 3 and 5 Restrooms	State of Maryland
72844	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Room 7 Restroom	ADA
72847	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom 4, Boys Restroom 1	ADA
72848	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Restroom 4, Boys Restroom 1, 2 and 3, Girls Restroom 2 and 3	ADA
72849	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Restroom 4, Girls Restroom 4, Boys restrooms 1 and 2, Girls restrooms 1 and 2	ADA
72850	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 4, BAR T Restroom	ADA
72852	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 4, Staff Restroom 3	ADA
72853	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 4, Kitchen Restroom, Main Office Restroom	ADA
72854	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Girls Restroom 1, 2 and 3; Room 25, 27 and 29 restrooms	ADA
72877	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Bar T Staff Restroom	ADA
72882	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	BAR T Restroom	ADA
72891	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Room 25, Room 27, Room 29	ADA
88220	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Main Office Restroom	ADA
88224	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	EL1 Elevator	ADA
88329	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Kindergarten Restrooms (Rooms 1, 3, 5 and 7); Room 25, 27 and 29 Restrooms	ADA
88330	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	PE Office Restroom, Bldg Services Restroom	ADA
88331	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The shower controls are not mounted on the side wall opposite the transfer shower seat at 38" minimum to 48" maximum above the finish floor.	PE Office Restroom, Bldg Services Restroom	ADA
88332	Thurgood Marshall Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Room 25, Room 27, Room 29	ADA
72743	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms throughout	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72845	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	DF-1, DF-2, DF-3, DF-4	ADA
72846	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	DF-2, DF-3	ADA
72946	Thurgood Marshall Elementary School	INTERIOR	Kitchen	Kitchen-Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	BAR T Kitchen	ADA
88219	Thurgood Marshall Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classrooms throughout	ADA