



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Burnt Mills Elementary
11211 Childs Street
Silver Spring, Maryland 20901

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-031.303

Date of Report:

October 24, 2019

On Site Date:

August 29, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Burnt Mills Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Burnt Mills Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Burnt Mills Elementary School	43	16	48	7		114
Grand Total	43	16	48	7		114

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71157	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Northwest Portable	ADA
71159	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Northwest Portable	ADA
71162	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Northwest Portable	ADA
71163	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Northeast Portables	ADA
71164	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Northeast Portable	ADA
71165	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Parking Space P2-A	ADA
71166	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P2-A	ADA
71167	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P2-B	ADA
71168	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Parking Space P2-B	ADA
71169	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P2-C	ADA
71170	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
71171	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P3-A	ADA
71172	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1, Parking Space P3-A	ADA
71173	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P3-B	ADA
71174	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Parking Space P3-C	ADA
71175	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1, Parking Space P2-C	State of Maryland
71176	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2, Parking Space P4-A	State of Maryland
71177	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 1	ADA
71178	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 1	ADA
71179	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 2	ADA
71180	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 2	ADA
71181	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp 3	ADA
71182	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 3	ADA
71183	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 3	ADA
71184	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 3	ADA
71185	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 4	ADA
71186	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 4	ADA
71188	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 6	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71190	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 7	ADA
71191	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 7	ADA
71193	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible Route from Northwest Building to Portable Classrooms	ADA
71194	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Northwest Portable Classroom	ADA
71195	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible Route from East Building Entrance to Play Courts	ADA
71196	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible Route to the Northeast Portables	ADA
73136	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space. Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2, Parking Space P4-A	State of Maryland
73142	Burnt Mills Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space. Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1, Parking Space P2-C	State of Maryland
71135	Burnt Mills Elementary School	BUILDING INTERIOR	Common Areas	Platform Lift	1	A platform lift is required but not provided.	All Purpose Room	ADA
71062	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	North Stairs	ADA
71065	Burnt Mills Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
71154	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width. The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate	Kitchen Staff Restroom	ADA
73165	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The threshold at the accessible door is greater than 1/2" in height.	Staff Restroom 1, 2	ADA
73167	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The threshold at the accessible door is greater than 1/2" in height.	Restroom 5, 6, 7, 8, 10 Boys PE Restroom, Girls PE Restroom	ADA
71197	Burnt Mills Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site. An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	Baseball Field East of School	ADA
71198	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	South Playground	ADA
71199	Burnt Mills Elementary School	BUILDING EXTERIOR	Playground	Ground Surface	2	The ground surface within the use zone does not comply with ASTM F 1292.	Pre-School Playground	ADA
71200	Burnt Mills Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Pre-School Playground	ADA
71201	Burnt Mills Elementary School	BUILDING EXTERIOR	Playground	Ground Surface	2	The ground surface within the use zone does not comply with ASTM F 1292.	School Aged Playground	ADA
71202	Burnt Mills Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	School Aged Playground	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
70569	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Restroom 1, 2	ADA
70581	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Staff Restrooms 3 and 4	ADA
71108	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Classrooms 19, 18, 17, 16, 15, 14, 13, 12, 11, 1, 2, 3, 4, 5, 6, 7, 8, 9, 10	ADA
71122	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Media Center Office	ADA
71124	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Break Room	ADA
71125	Burnt Mills Elementary School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Break Room	ADA
71128	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Break Room	ADA
71139	Burnt Mills Elementary School	BUILDING INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	All Purpose Room	ADA
71141	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Room	ADA
70814	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Girls PE Restroom	ADA
71153	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Health Suite Restroom	ADA
71192	Burnt Mills Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	3	The accessible route has running slopes greater than 1:20 (5%).	Accessible Route East of Parking Lot 2	ADA
70567	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The door has less than 32" clear width.	Staff Restroom 1, 2	ADA
70574	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restrooms 3 and 4	ADA
70575	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restrooms 3 and 4	ADA
70576	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms 3 and 4	ADA
70577	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restrooms 3 and 4	ADA
70579	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restrooms 3 and 4	ADA
70582	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Women's Staff Restroom 4	ADA
70583	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Women's Staff Restroom 4	ADA
70783	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom 5, 6, 7, 8, 9, 10	ADA
71144	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Health Suite Restroom	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71148	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Health Suite Restroom	ADA
70787	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom 5, 7	ADA
70793	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Restroom 5, 6	ADA
70794	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Boys Restroom 5, Girls PE Restroom	ADA
70797	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom 5, 6, Girls PE Restroom	ADA
70798	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	Boys Restroom 5, Girls PE Restroom	ADA
70800	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The side grab bar in the wheelchair stall used primarily by children does not meet children's specifications.	Restroom 5, 6, Boys PE Restroom, Girls PE Restroom	ADA
70801	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms 5, 6	ADA
70802	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom 5, 6	ADA
70803	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Girls Restroom 6	ADA
70805	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls Restroom 6	ADA
70812	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Boys PE Restroom	ADA
70813	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Girls PE Restroom	ADA
70815	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The rear grab bar at the water closet used primarily by children does not meet children's height specifications.	Boys PE Restroom, Girls PE Restroom	ADA
70816	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys PE Restroom, Girls PE Restroom	ADA
70986	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Boy's Restroom 7	ADA
70988	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boy's Restroom 7, 9	ADA
70993	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Boys Restroom 7 and 9	ADA
70997	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Girl's Restroom 8 and 10	ADA
71001	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Girls Restroom 8 and 10	ADA
71002	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Boys Restroom 9	ADA
71043	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Classroom K21	ADA
71044	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The grab bars are not located per children's specifications in the wheelchair stall used primarily by children.	Classroom K21	ADA
71046	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Classroom K21	ADA
71047	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Classroom K21	ADA
71048	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Classroom K21	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
71050	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Classroom K21	ADA
71077	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Gym Staff Restroom	ADA
71078	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Gym Staff Restroom	ADA
71080	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Gym Staff Restroom	ADA
71082	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Gym Staff Restroom	ADA
71085	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Gym Staff Restroom	ADA
71087	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Gym Staff Restroom	ADA
71089	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Gym Staff Restroom	ADA
71149	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Suite Restroom	ADA
71150	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The side grab bar in the wheelchair stall used primarily by children does not meet children's specifications.	Health Suite Restroom	ADA
71152	Burnt Mills Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Health Suite Restroom	ADA
71105	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classrooms 19, 18, 17, 16, 15, 14, 13, 12, 11, 1, 2, 3, 4, 5, 6, 7, 8, 9, 10	ADA
71130	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Staff Break Room, Health Room	ADA
71041	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classroom K21, K20	ADA
71042	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classroom K21	ADA
71054	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classroom K20	ADA
71056	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Corridors	ADA
71101	Burnt Mills Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms 19, 18, 17, 16, 15, 14, 13, 12, 11, 1, 2, 3, 4, 5, 6, 7, 8, 9, 10	ADA