



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Jones Lane Elementary  
15110 Jones Lane  
Gaithersburg, Maryland 20878

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**  
123821.17R000-058.303

**Date of Report:**  
October 25, 2019

**On Site Date:**  
August 21, 2017



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity’s programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the “2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design.” The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Jones Lane Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Jones Lane Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG’s assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Jones Lane Elementary School	81	24	75	12		194
Grand Total	81	24	75	12		194

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73735	Jones Lane Elementary School	EXTERIOR	Exempt Amenity	Amenity Not Evaluated	0	The amenity is a mechanical space accessed by service personnel only, and is exempt from ADA requirements.	Stair ST-3, ST-4	ADA
74149	Jones Lane Elementary School	EXTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity was not maintained and cannot be evaluated.	Outdoor learning classroom	ADA
73706	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	P1-1 & 2	State of Maryland
73707	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Accessible Parking Space P1-1	State of Maryland
73708	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Accessible Parking Space P1-2	State of Maryland
73709	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Accessible Parking Spaces P1-3 and 4	ADA
73711	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Accessible Parking Space P1-3	ADA
73712	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Accessible Parking Space P1-3	ADA
73713	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	Compliant signage is not provided at the van space.	Accessible parking space P1-1 & 2	ADA
73714	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Accessible Parking Space P1-1	State of Maryland
73715	Jones Lane Elementary School	EXTERIOR	Accessible Parking	Parking Space-Car	1	Signage is not provided at the standard accessible space.	Accessible Parking Spaces P1-3 and 4	ADA
73716	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus unloading	ADA
73717	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR-1	ADA
73718	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-1	ADA
73719	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Exterior Door 1 and Curb Ramp CR-1	ADA
73720	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Exterior Door 1 to Curb Ramp 2	ADA
73721	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-2	ADA
73722	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp CR-3	ADA
73723	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp CR-3	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73726	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route between Curb Ramp CR-2 and Stair ST-1	ADA
73727	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-4	ADA
73728	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1	ADA
73729	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-1	ADA
73730	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-1	ADA
73731	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stairs ST-2	ADA
73732	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stairs ST-2	ADA
73733	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Stairs does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	Stair ST-2	ADA
73736	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Exterior Door 6, 7, 9	ADA
73737	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-5	ADA
73738	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route between Curb Ramp CR-5 and Exterior Door 9	ADA
73739	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 9	ADA
73740	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	The accessible route from Ramp R-1 to the North West corner of the School.	ADA
73741	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Between Exterior Door 12 and Ramp R-1	ADA
73742	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-2	ADA
73743	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Accessible Route has areas of vertical level changes in excess of 1/4" that are not ramped.	Ramp R-2	ADA
73744	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Mobile Classroom ML 872, ML 879	ADA
73745	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-3	ADA
73746	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-3	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73793	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-5	ADA
73794	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair St-5	ADA
73795	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Stair ST-5 to the softball field bench	ADA
73797	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route from Exterior Door 13 to the hard playing surface.	ADA
73798	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	The sidewalk on east side of school between the building and the hard playing surface.	ADA
73799	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 15	ADA
74136	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route between Exterior Door 1 and Playground 4	ADA
74137	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 16	ADA
74138	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 17	ADA
74139	Jones Lane Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 18	ADA
74140	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stairs ST-7	ADA
74141	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-7	ADA
74143	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between the brick wall of Playground 4 and the parking lot.	ADA
74145	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-6	ADA
74146	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from Curb Ramp CR-6 to bus drop off zone.	ADA
74147	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk North of Accessible Parking Space P1-4	ADA
74148	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Outdoor Classroom (Reading Space)	ADA
74246	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not at the same level as the loading/unloading area.	Student Drop Off (Car)	ADA
74247	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus Drop off	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73804	Jones Lane Elementary School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Main Office Door	ADA
73898	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Media Center	ADA
73824	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Classroom 30	ADA
73909	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Staff Lounge	ADA
73913	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-2	ADA
73921	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Restrooms RR-2, RR-3	ADA
73922	Jones Lane Elementary School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom RR-2	ADA
73928	Jones Lane Elementary School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Restroom RR-4	ADA
73964	Jones Lane Elementary School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gym	ADA
73975	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Trophy Case between Restrooms RR-10 and RR-11	ADA
74043	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Kitchen	ADA
74055	Jones Lane Elementary School	INTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-4	ADA
74059	Jones Lane Elementary School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-4	ADA
74062	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Ramp R-4	ADA
74064	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Ramp R-4	ADA
74073	Jones Lane Elementary School	INTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	All Purpose Room	ADA
74075	Jones Lane Elementary School	INTERIOR	Exterior Access Route	Stairs	1	The underside of the nosings are abrupt.	Stair ST-6	ADA
74081	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	All Purpose Room	ADA
74084	Jones Lane Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-6	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
74101	Jones Lane Elementary School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Drinking Fountain DF-5 & Restroom RR-7	ADA
74111	Jones Lane Elementary School	INTERIOR	Interior Access Route	Exterior Accessible Route-Width	1	Clear widths at turning area are less than 60" minimum.	Restrooms. RR-6, RR-7	ADA
74216	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Interior doors with door closers	ADA
74218	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	All interior doors with a door closer	ADA
74220	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Interior doors with round door knobs	ADA
74237	Jones Lane Elementary School	INTERIOR	Interior Access Route	Controls	1	The height of controls throughout the common area are not compliant.	Light Switches	ADA
74240	Jones Lane Elementary School	INTERIOR	Interior Access Route	Controls	1	The height of controls throughout the common area are not compliant.	Pencil Sharpeners	ADA
73796	Jones Lane Elementary School	EXTERIOR	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Softball Field	ADA
73801	Jones Lane Elementary School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 3, 4	ADA
74267	Jones Lane Elementary School	EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playgrounds #1, 2, 3, 4	ADA
74268	Jones Lane Elementary School	EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground #2, #4	ADA
74269	Jones Lane Elementary School	EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground #3	ADA
73803	Jones Lane Elementary School	INTERIOR	Office	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Main Office.	ADA
73806	Jones Lane Elementary School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Room	ADA
73814	Jones Lane Elementary School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Work Room - Main Office	ADA
73815	Jones Lane Elementary School	INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Work Room - Main Office	ADA
73896	Jones Lane Elementary School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Media Center	ADA
73900	Jones Lane Elementary School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
73907	Jones Lane Elementary School	INTERIOR	Kitchen	Kitchen	2	Less than minimum one of each type of operable part is within reach range.	Staff Lounge	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73908	Jones Lane Elementary School	INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Staff Lounge	ADA
73924	Jones Lane Elementary School	INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restroom RR-4, RR-6, RR-14	ADA
73963	Jones Lane Elementary School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Computer Lab	ADA
73965	Jones Lane Elementary School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	All Purpose Room, Gym	ADA
73967	Jones Lane Elementary School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Restroom RR-8	ADA
74027	Jones Lane Elementary School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Development	ADA
74028	Jones Lane Elementary School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	Staff Development	ADA
74035	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Restroom RR-12	ADA
74080	Jones Lane Elementary School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining table does not have compliant knee and toe clearance.	All Purpose Room	ADA
74234	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Hallway Fire Control Doors	ADA
74239	Jones Lane Elementary School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Room identification signs, excluding restrooms	ADA
74242	Jones Lane Elementary School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Doors with floor mounted door stops	ADA
73863	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom in Classroom 22	ADA
73808	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom RR-1 (located in Health Room)	ADA
73809	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-1 (located in the Health Room)	ADA
73810	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Restroom RR-1 (Located in the Health Room)	ADA
73811	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-1 (Located in the Health Room)	ADA
73869	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Restroom in Classroom 20, 21	ADA
73870	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom in Classroom 20, 21	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73886	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom in Classroom 21	ADA
73887	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom in Classroom 21	ADA
73888	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom in Classrooms 20, 21	ADA
73890	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom in Classrooms 20, 21	ADA
73893	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom in Classroom 20	ADA
73818	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom between classroom 28 and 30.	ADA
73820	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet is not 16" minimum to 18" maximum from the sidewall.	Restroom between classrooms 28 and 30	ADA
73821	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom between Classrooms 28 and 30	ADA
73822	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom between classroom 28 and 30.	ADA
73823	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Restroom between Classrooms 28 and 30	ADA
73850	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom in Classroom 22	ADA
73854	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Restroom in Classroom 22	ADA
73858	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom in Classroom 22	ADA
73859	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom in Classroom 22	ADA
73862	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom in Classroom 22	ADA
73914	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restrooms RR-2, RR-3	ADA
73915	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms RR-2, RR-3	ADA
73916	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-2, RR3	ADA
73917	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restrooms RR-2, RR-3	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73918	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom RR-3	ADA
73919	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms RR-2, RR-3	ADA
73920	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restrooms RR-2, RR-3	ADA
73923	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restrooms RR-4, RR-5	ADA
73925	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom RR-4	ADA
73926	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Restrooms RR-4, RR-5	ADA
73927	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom RR-4, RR-5	ADA
73960	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom R-5	ADA
73961	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom R-4	ADA
73966	Jones Lane Elementary School	INTERIOR	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom RR-8	ADA
73968	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-8	ADA
73969	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom R-8	ADA
73970	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Restrooms RR-8, RR-9	ADA
73971	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Restroom RR-8	ADA
73972	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Restrooms RR-8, RR-9	ADA
73973	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Restrooms RR-8, RR-9	ADA
73974	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Restrooms RR-8, RR-9	ADA
73976	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Restrooms RR-10, RR-11	ADA
73977	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom RR-10	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73978	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms RR-10, RR-11	ADA
73979	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restrooms RR-10, RR-11	ADA
73980	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restrooms RR-10, RR-11	ADA
73981	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom RR- 6, 7, 10, 11	ADA
74029	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Restroom RR-12	ADA
74030	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom RR-12	ADA
74033	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Restroom RR-12	ADA
74034	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-12	ADA
74036	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Restroom RR-12	ADA
74038	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom RR-12	ADA
74040	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-12	ADA
74041	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Locker	3	The locker area does not have accessible lockers.	Restroom RR-12	ADA
74042	Jones Lane Elementary School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Restrooms RR-9, RR-12	ADA
74069	Jones Lane Elementary School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	All Purpose Room	ADA
74072	Jones Lane Elementary School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	All Purpose Room	ADA
74091	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Restrooms 6, 7, 13, 14	ADA
74092	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom 6, 13	ADA
74093	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-13	ADA
74095	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-14	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
74109	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-6	ADA
74110	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-7	ADA
74115	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Locker	3	The locker area does not have accessible lockers.	RR-9	ADA
74116	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-9	ADA
74117	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-9	ADA
74118	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-9	ADA
74119	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-9	ADA
74121	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Restroom RR-9	ADA
74226	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms RR-1, 4, 5, 6, 7, 13, 14	ADA
74241	Jones Lane Elementary School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	Egress Doors	ADA
75470	Jones Lane Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms RR-2, 3, 8, 9, 10, 11, 12	ADA
73807	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Health Room	ADA
73816	Jones Lane Elementary School	INTERIOR	Common Areas	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	Work Room - Main Office	ADA
73817	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classroom 2, 3, 4, 5, 6, 7, 8, 9, 11, 12, 15, 16, 17, 18, 19, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32	ADA
73865	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classroom 20, 21	ADA
73906	Jones Lane Elementary School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	Staff Lounge	ADA
73825	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-1	ADA
73833	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classroom 22	ADA
73911	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain DF-2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73912	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	Drinking Fountain DR-2	ADA
73962	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-4	ADA
74083	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-6	ADA
74098	Jones Lane Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	Drinking Fountain DF-5	ADA