



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Sherwood Elementary School
1401 Olney-Sandy Spring Road
Sandy Spring, Maryland 20860

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-085.303

Date of Report:

October 25, 2019

On Site Date:

September 14-15, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Sherwood Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Sherwood Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

| Facility / Building | Priority 1 Items | Priority 2 Items | Priority 3 Items | Priority 4 Items | Priority 5 Items | Total Items |
|----------------------------|------------------|------------------|------------------|------------------|------------------|-------------|
| Sherwood Elementary School | 35 | 11 | 44 | 6 | | 96 |
| Grand Total | 35 | 11 | 44 | 6 | | 96 |

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|----------------------------|-------------------|-----------------------|---------------------------|------------------|--|--|-------------------|
| 71242 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Playground 2 | ADA |
| 71245 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Outdoor covered seating / picnic area. | ADA |
| 71247 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Ball fields, track | ADA |
| 71249 | Sherwood Elementary School | BUILDING EXTERIOR | Entrance to Building | Building Entrance-Door | 1 | The maneuvering clearance at the accessible door is not level and clear. | Main Entry - Door 1. | ADA |
| 71250 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | The accessible route has gaps in the surface greater than 1/2" wide. | Concrete walk adjacent to "Community Entrance" - Door 28 Concrete walk from Main Entry to Bus Drop Off. | ADA |
| 71251 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | The accessible route has cross slopes greater than 1:50 (2%). | Concrete walk south of Building 1 along bus drop off. | ADA |
| 71252 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Curb Ramp | 1 | A curb ramp is not provided where the accessible route crosses a curb. | Concrete walk adjacent to Bus drop-off. | ADA |
| 71253 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped. | A 5' x 5' section of concrete walk at east side of Multi Purpose Room south of Door 27. | ADA |
| 71255 | Sherwood Elementary School | BUILDING EXTERIOR | Entrance to Building | Building Entrance-Door | 1 | The maneuvering clearance at the accessible door is not level and clear. | Entry Door 21, Entry Door 18 | ADA |
| 71257 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the property line to the site facilities. | Public right of way at Olney-Sandy Spring Road sidewalk to Building 1 | ADA |
| 71281 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Curb Ramp | 1 | The curb ramp does not meet the slope requirements. | CR-1 | ADA |
| 74890 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp has a rise greater than 6"; however, handrails are not provided. | Exterior access route from Building 1 to Playground 2 | ADA |
| 74894 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp does not have a level landing at the top and/or bottom of each run. | Exterior access route from Building 1 to Playground 2 | ADA |
| 74903 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Soccer field | ADA |
| 74905 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped. | Flagpole | ADA |
| 74913 | Sherwood Elementary School | BUILDING EXTERIOR | Entrance to Building | Building Entrance-Door | 1 | The threshold at the accessible door is greater than 1/2" in height. | Exterior doors 18, 17, 16, 15, 11, 10 | ADA |
| 74925 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Curb Ramp | 1 | A landing at the top of the curb ramp is not present. | CR-1 | ADA |
| 74931 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: The van access aisle is less than 96" wide. | P1A-P1B | State of Maryland |
| 74932 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: Signage is not located at a compliant height. | Parking Lot 1: P1A - P1D | State of Maryland |
| 74936 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: A "Van" space is not provided. | Parking Lot 2 | State of Maryland |
| 74937 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: A van access aisle is not provided. | Parking Lot 2 | State of Maryland |
| 74938 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: Compliant signage is not provided at the space. | Parking Lot 2 | State of Maryland |
| 74939 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided. | Parking Lot 2 | State of Maryland |
| 74941 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Spaces-General | 1 | MARYLAND: The minimum number of accessible parking spaces is not provided. | Parking Lot 2 | State of Maryland |
| 74943 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Car | 1 | MARYLAND: Compliant signage is not provided at the space. | Parking Lot 2 | State of Maryland |
| 75562 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Loading/Unloading Zone | 1 | The access aisle is not marked. | Student Drop-off Area | ADA |



| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|----------------------------|-------------------|-----------------------|---------------------------------------|------------------|--|--|------------------------|
| 75564 | Sherwood Elementary School | BUILDING EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided. | P1A-P1D | State of Maryland |
| 71282 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Stairs | 1 | Steps do not have uniform and compliant riser heights and/or tread depths. | Stair 1 | ADA |
| 71283 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Stairs | 1 | Handrails are not compliant. | 116 - Music Room (to backstage area) | ADA |
| 71284 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Stairs | 1 | Handrails are not provided on the stairs. | Multi-Purpose Room (MPR) stage. | State of Massachusetts |
| 71287 | Sherwood Elementary School | BUILDING INTERIOR | Common Areas | Interior Doors | 1 | The pull side of the accessible door does not have the required maneuvering clearances. | Staff Lounge private telephone room | ADA |
| 71322 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Door | 1 | The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48". | Classrooms, offices and storage rooms on 1st Floor | ADA |
| 71323 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Door | 1 | The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48". | Classroom 129, Multi-Purpose Room | ADA |
| 71517 | Sherwood Elementary School | BUILDING INTERIOR | Common Areas | Interior Doors | 1 | The pull side of the accessible door does not have the required maneuvering clearances. | Classrooms 105, 130, 131, 132, 133, 134, 135, 139, 156, 158 | ADA |
| 71521 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Ramp | 1 | The accessible route does not connect all elements and areas of use that are required to be accessible; including raised areas and speaker platforms | Multi-Purpose Room stage | ADA |
| 71240 | Sherwood Elementary School | BUILDING EXTERIOR | Site Furnishings | Trash Receptacle Without Operable Lid | 2 | A trash receptacle is not located on an accessible route and within reach range. | Playground 2 | ADA |
| 71244 | Sherwood Elementary School | BUILDING EXTERIOR | Exterior Access Route | Gate | 2 | The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate. | Playground 1, Playground 2 | ADA |
| 71246 | Sherwood Elementary School | BUILDING EXTERIOR | Picnic Area | Picnic Table | 2 | The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance. | Outdoor covered seating / picnic area. | ADA |
| 71410 | Sherwood Elementary School | BUILDING EXTERIOR | Playground | Ground Surface-Fibar | 2 | The ground surface has not been inspected and maintained regularly. | Playground 1 and 2 | ADA |
| 71288 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Sink | 2 | The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks). | Staff Lounge | ADA |
| 71296 | Sherwood Elementary School | BUILDING INTERIOR | Common Areas | Dining And Work Surface | 2 | The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance. | Staff Lounge | ADA |
| 71324 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Door | 2 | The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth. | Rooms 120, 102, 103, 143, 105, 131 | ADA |
| 71325 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Door | 2 | The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth. | Rooms 117 (MPR), 149 (Media Center), 129 (Classroom) (Indoor paid-use areas) | ADA |
| 71326 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Signage | 2 | The provided signage is not mounted at the latch side of the door or at a compliant height. | First and second floor doors | ADA |
| 71522 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Signage | 2 | Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge) | Building exit doors on first floor | ADA |
| 74764 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 2 | The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door. | Staff restroom 113D | ADA |
| 71290 | Sherwood Elementary School | BUILDING INTERIOR | Common Areas | Vending Machine | 3 | The vending machines have operable parts which are not within reach range. | Staff Lounge | ADA |

| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|----------------------------|-------------------|----------|--------------------------------|------------------|--|--|-------------------|
| 71330 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Signage | 3 | The provided signage is not mounted at the latch side of the door or at a compliant height. | 123,124,127,138A,140C,144A,100H3,201,200,175A,165,166,177A | ADA |
| 71331 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall in a multi-stall restroom used primarily by children (ages 3-12) does not have the required dimensions. | Student Restrooms 123,124,127 | ADA |
| 71332 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The toilet paper dispenser is not at a compliant location. | Student Restrooms 150,165,201,144A,140C | ADA |
| 71333 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | MARYLAND: The water closet has less than the required minimum clearance dimensions, and it is structurally infeasible to create compliant clearance. | Student Restrooms 165,166,175A,177A | State of Maryland |
| 71334 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom | 3 | Dispenser and/or dispenser controls are not within an allowable reach range. | Student Restrooms 108,124,127,150,154,Room 147 Restroom | ADA |
| 71335 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Mirror | 3 | The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter. | Student Restrooms 165,166 | ADA |
| 71337 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | The lavatory is mounted higher than 34" to the higher of the rim or counter. | Student Restrooms 100H3,166 | ADA |
| 71339 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | Pipes are not insulated. | Student Restrooms 100H3,123,124,127,140C,150,165,166,175A,177A | ADA |
| 71343 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | Knee clearance is not provided. | Student Restrooms 124,127,138A,150,201,200,175A,177A,145A,144A,Room 147 Restroom | ADA |
| 71346 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The wheelchair stall door is not self closing. | Student restrooms 200,201 | ADA |
| 71347 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The hardware at the wheelchair stall door is not compliant. | Student restrooms 200,201 | ADA |
| 71350 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Coat Hook | 3 | The coat hook is not within an allowable reach range. | Student Restrooms 104,108 | ADA |
| 71377 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Urinal | 3 | The urinal dimensions are not compliant. | Staff Restroom 122 | ADA |
| 71378 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The pull side of the accessible door does not have the required maneuvering clearances. | Staff Restroom 121,122 | ADA |
| 71379 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds. | Staff Restrooms 121,122,203,204 | ADA |
| 74735 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Signage | 3 | The provided signage is not mounted at the latch side of the door or at a compliant height. | 104,108,150,154 | ADA |
| 74736 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall in a multi-stall restroom used primarily by children (ages 3-12) does not have the required dimensions. | Student Restrooms 150,154,104,108 | ADA |
| 74746 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Floor Space | 3 | The required turning space within the restroom is not provided. | Student restroom 140C | ADA |
| 74747 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The side grab bar at the water closet is not compliant. | Student Restrooms 175A,177A | ADA |
| 74748 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The rear grab bar at the water closet is not compliant. | Student Restrooms 175A,177A | ADA |
| 74753 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The pull side of the accessible door does not have the required maneuvering clearances. | Staff restrooms 113D,118A | ADA |
| 74762 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The flush control is located on the closed side and/or is not within reach range. | Staff restrooms 118A,119,125,126,152 | ADA |
| 74763 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The flush control is located on the closed side and/or is not within reach range. | Student restroom 140C | ADA |
| 74862 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Floor Space | 3 | The required turning space within the restroom is not provided. | Staff Restrooms 118A,119,113D,125,126,152,153 | ADA |
| 75557 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Staff restrooms 118A,119,125,126,152 | ADA |



| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|----------------------------|-------------------|-----------------------|---|------------------|--|---|-----|
| 75558 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Transfer Shower Stall | 3 | The transfer shower is not compliant. | Staff Restrooms 118A, 119RR | ADA |
| 75559 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Student restroom 140C | ADA |
| 75560 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall. | Room 147 Restroom | ADA |
| 75561 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The side grab bar at the water closet is not compliant. | Room 147 Restroom | ADA |
| 71354 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall. | Student Restrooms 140C, 175A | ADA |
| 71356 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The threshold at the accessible door is greater than 1/2" in height. | Student Restrooms 104, 138A, 145 | ADA |
| 71359 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds. | Student Restrooms 165, 166 | ADA |
| 71363 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The rear grab bar in the wheelchair stall is not compliant. | Student Restroom 201 | ADA |
| 71364 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep. | Staff Restrooms 121, 122 | ADA |
| 71365 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The toilet paper dispenser is not at a compliant location. | Staff Restroom 100D | ADA |
| 71368 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Mirror | 3 | The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter. | Staff Restrooms 100D, 203, 204 | ADA |
| 71369 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | The lavatory is mounted higher than 34" to the higher of the rim or counter. | Staff Restroom 204 | ADA |
| 71370 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | Pipes are not insulated. | Staff Restrooms 100D, 203, 204 | ADA |
| 71371 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Lavatory | 3 | Knee clearance is not provided. | Staff Restroom 121, 122 | ADA |
| 71372 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Coat Hook | 3 | The coat hook is not within an allowable reach range. | Staff Restroom 100D | ADA |
| 71373 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Door | 3 | The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch. | Staff Restroom 121 | ADA |
| 71374 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The rear grab bar at the water closet is not compliant. | Staff Restrooms 100D, 203 | ADA |
| 71375 | Sherwood Elementary School | BUILDING INTERIOR | Restroom | Restroom/Bathroom-Locker | 3 | The locker area does not have accessible lockers. | Staff Restrooms 113D, 118A | ADA |
| 71258 | Sherwood Elementary School | BUILDING EXTERIOR | Site Furnishings | Drinking Fountain/Water Cooler | 4 | The minimum number and types of drinking fountains are not provided. | North exterior wall of Building 1 | ADA |
| 71411 | Sherwood Elementary School | BUILDING EXTERIOR | Playground | Play Component | 4 | The play component which has manipulative or interactive features that require reaching is not within the child's reach range. | Playground 1 | ADA |
| 71516 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | The location of the spout of the wheelchair height drinking fountain is not compliant. | Classrooms 130-135, 137, 140, 145, 155, 156, 158, 175, 205, 206, 208, 209 | ADA |
| 71518 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum. | DF-1, DF-2, DF-3, DF-4, DF-5 | ADA |
| 71519 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low. | DF-6, DF-7 | ADA |
| 71520 | Sherwood Elementary School | BUILDING INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | Knee and toe clearance is not provided at the lower level fountain. | DF-2, DF-4, DF-5 | ADA |