



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Bells Mill Elementary School
8225 Bells Mill Road
Potomac, Maryland 20854

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-024.303

Date of Report:
October 24, 2019

On Site Date:
August 24, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Bells Mill Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Bells Mill Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Bells Mill Elementary School	23	21	52	4		100
Grand Total	23	21	52	4		100

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69066	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1 - Row P1 Stalls 1-3	State of Maryland
69070	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	A van space is not provided.	Parking Lot 1 - Row P1 Stall 4	ADA
69072	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off Area North of Parking Lot 1	ADA
69076	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Student Drop Off Area North of Parking Lot 1	ADA
69080	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk Northeast of Parking Lot 1	ADA
69081	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk Northeast of Parking Lot 1	ADA
69095	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 1, South of Parking Lot 1	ADA
69098	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 2	ADA
69102	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Curb Ramp 2	ADA
69107	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk East of Parking Lot 1	ADA
69161	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Picnic Table North of Basketball Court	ADA
69180	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	South of Stair 2	ADA
69182	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 2	ADA
69186	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	East of Asphalt Play Courts	ADA
71830	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking lot 1- Row P1 Stall 4	State of Maryland
72051	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage at the space is not provided.	Parking lot 1- Row P1- Stall 4	State of Maryland
69254	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Kitchen Serving Area	ADA
69414	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	ADVISORY: A child's height handrail is not provided.	Stair 1, Stair 2, Center lobby stair	ADA
69435	Bells Mill Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
69201	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Small School Aged Playground, North of Building	ADA
69154	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Court	ADA
69174	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball/ Soccer Field 1	ADA
69179	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69097	Bells Mill Elementary School	BUILDING EXTERIOR	Site Furnishings	Trash Receptacle With Operable Lid	2	Clear ground space is not provided at the trash receptacle with lid requiring operation.	East of Parking Lot 1	ADA
69151	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	South of Basketball Court	ADA
69250	Bells Mill Elementary School	BUILDING INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	All Purpose Room	ADA
69416	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Media Center Office	ADA
69428	Bells Mill Elementary School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
69429	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Staff Lounge	ADA
69929	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Health Suite	ADA
72063	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Exit doors	ADA
69193	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Pre-School Age Playground	ADA
69194	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	Clear ground space is not provided at each ground play component, and each elevated play component connected by a ramp.	Pre-School Age Playground	ADA
69198	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Small School Aged Playground- North of Building	ADA
69203	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Small School Aged Playground- North of Building	ADA
69184	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Play Court South of Stair 2	ADA
69187	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Pre-School Playground	ADA
69190	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Pre-School Age Playground	ADA
69205	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Small School Aged Playground - North of Building	ADA
69209	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	The ground level component or elevated component accessed by ramp is required to be on an accessible route but is not within a child's reach range.	Large School Aged Playground -North of Building	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69211	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Large School Aged Playground - North of Building	ADA
69212	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Large School Aged Playground, North of Building	ADA
69213	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer steps are higher than 8" each.	Large School Aged Playground, North of Building	ADA
69214	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Large School Aged Playground	ADA
69256	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Kitchen Restroom	ADA
69257	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Kitchen Restroom	ADA
69259	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Restrooms 142, 140, 113, 230, 204, 206	ADA
69260	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restrooms 142, 140, 113, 115, 23, 230, 204, 206, 220, 224	ADA
69261	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The grab bars are not located per children's specifications in the wheelchair stall used primarily by children.	Restrooms 142, 142, 113, 115, 23, 230, 204, 206, 220, 224	ADA
69262	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms 140, 142, 113, 230, 204, 206, 220, 224	ADA
69263	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms 142, 140, 113, 115, 23, 230, 204, 206, 220	ADA
69387	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 144	ADA
69388	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 144	ADA
69389	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 144	ADA
69390	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 144	ADA
69393	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom 115	ADA
69394	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 111	ADA
69395	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 111	ADA
69396	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 111	ADA
69397	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 111	ADA
69398	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 111	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69399	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 131	ADA
69400	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 131	ADA
69401	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff restroom 131	ADA
69402	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 131	ADA
69403	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff restroom 131	ADA
69404	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 156	ADA
69405	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 156	ADA
69406	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff restroom 156	ADA
69407	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 156	ADA
69408	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 242	ADA
69409	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 242	ADA
69410	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 242	ADA
69411	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Restroom 23	ADA
69412	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Girls Restroom 23	ADA
69413	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Boys Restroom 230	ADA
69438	Bells Mill Elementary School	BUILDING INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Room 147E	ADA
69446	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Room 147E	ADA
69448	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Room 147E	ADA
69453	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Room 147E	ADA
69585	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Room 147E	ADA
69590	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Room 147E	ADA
69596	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA
69601	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The grab bars are not located per children's specifications in the wheelchair stall used primarily by children.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69688	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA
69689	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom 125A, 120A, 129A, 132A, 128A, 164A	ADA
69919	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom 100E	ADA
69921	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom 100E	ADA
69922	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom 100E	ADA
69923	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Restroom 100E	ADA
69926	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom 100E	ADA
69931	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Room 102D	ADA
69932	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Room 102D	ADA
69937	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom 102D	ADA
69391	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 144	ADA
69392	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom 115	ADA
69424	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classrooms 229, 233, 235, 239, 236, 240, 208, 212, 214, 218, 209, 213, 217, 219, 223, 132, 128, 129, 125, 154, 150, 148, 159, 155, 153, 149, 120, 121, 124	ADA
69425	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms 229, 233, 235, 239, 236, 240, 208, 212, 214, 218, 209, 213, 217, 219, 223, 132, 128, 129, 125, 154, 150, 148, 159, 155, 153, 149, 120, 121, 124	ADA
69208	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	4	The play component which has manipulative or interactive features that require reaching is not within the child's reach range.	Small School Aged Playground - North of Building	ADA
69210	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	4	The play component which has manipulative or interactive features that require reaching is not within the child's reach range.	Large School Aged Playground - North of Building	ADA