

ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools 45 West Gude Drive, Suite 4100 Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Rosa M Parks Middle School 19200 Olney Mill Road Olney, Maryland 20832

PREPARED BY:

EMG 10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.EMGcorp.com

EMG CONTACT:

Michael Nelson Program Manager 800.733.0660 x6244 mnelson@emgcorp.com

EMG Project Number: On Site Date: Date of Report:

123821.17R000-080.303 October 30, 2019 September 18-19, 2017

1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Rosa M Parks Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Rosa M Parks Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Rosa M Parks Middle School	23	14	28			65
Grand Total	23	14	28			65

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



ld	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
	Rosa M Parks Middle					The accessible route has gaps in the surface greater		
76072	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	than 1/2" wide.	Flagpole area - Main Entry	ADA
70007	Rosa M Parks Middle	Duithin a Fataria	Fotosias Assass Boots	Overly Danier		The curb ramp has openings in the ground surface	Ourt Danie ODO	A D A
76097	School Rosa M Parks Middle	Building Exterior	Exterior Access Route	Curb Ramp	1	greater than 1/2" wide. Sidewalk has areas of vertical level changes in	Curb Ramp CR2 Sidewalk between Curb Ramp	ADA
76103	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	excess of 1/4" that are not ramped.	CR3 and Tennis Courts	ADA
70103	Rosa M Parks Middle	building Exterior	Exterior Access Route	Exterior Accessible Route	I	Sidewalk has areas of vertical level changes in	CR3 and Termis Courts	ADA
76104	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	excess of 1/4" that are not ramped.	Sidewalk outside Door DR3	ADA
70104	Rosa M Parks Middle	Building Exterior	Exterior 7 tode33 floate	Exterior Addessible Route	'	The accessible route has gaps in the surface greater	Cidewalk outside Bool Bito	/\D/\
76109	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	than 1/2" wide.	Sidewalk outside Door DR3	ADA
	Rosa M Parks Middle				·	The accessible route has greater than 1:20 (5%)	Adjacent Door DR5 and Stair	
76295	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	running slope and 1:50 (2%) cross slope.	STR3	ADA
		<u> </u>				The accessible route has areas of vertical level		
	Rosa M Parks Middle					changes in excess of 1/4" that are not beveled or		
76302	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	ramped.	Sidewalk outside of Door DR10	ADA
						The accessible route has areas of vertical level		
	Rosa M Parks Middle					changes in excess of 1/4" that are not beveled or		
76303	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	ramped.	Sidewalk outside of Door DR10	ADA
70200	Rosa M Parks Middle	Duilding Extension	Exterior Assess Devite	Estavian Associate Deuts		Sidewalk has areas of vertical level changes in	Main Entry Sidewalk - Outside	A D A
76308	School Rosa M Parks Middle	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	excess of 1/4" that are not ramped.	Door DR1 Curb Ramp CRA to Main Entry -	ADA
76918	School	Building Exterior	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Door DR1	ADA
70910	Rosa M Parks Middle	building Exterior	Exterior Access Route	Curb Karrip	I	Toute crosses a curb.	DOOLDK I	ADA
76920	School	Building Exterior	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off	ADA
70020	Concor	Building Exterior	Exterior 7 tode33 floate	Loading/officialing Zoffe	'	A compliant accessible route is not provided to each	Gladent Brop On	/\D/\
	Rosa M Parks Middle					site facility. Wheelchair spaces are not provided at	Pathway to Sports Fields and	
76921	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	team benches.	Baseball team bench areas	ADA
	Rosa M Parks Middle	<u> </u>				A compliant accessible route is not provided to each	Pathway/Sidewalk between	
76922	School	Building Exterior	Exterior Access Route	Exterior Accessible Route	1	site facility.	Baseball Field and Tennis Courts	ADA
	Rosa M Parks Middle	•				The pull side of the accessible door does not have		
76367	School	Building Interior	Interior Access Route	Door	1	the required maneuvering clearances.	P/E Office Employee Corridor	ADA
						The hardware at the accessible door (including		
						sliding doors - both sides) requires tight grasping,		
70000	Rosa M Parks Middle	5 7 7 7 7 7				pinching or twisting of the wrist to operate OR is	Stairwells STR- 1, 2, 3, 4, 5 (13);	454
76369	School	Building Interior	Interior Access Route	Door	1	mounted below 34" or above 48".	Gymnasium, Aux. Gymnasium (2)	ADA
	Rosa M Parks Middle					Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing		
76394	School	Building Interior	Interior Access Route	Ramp	1	surface.	Stage Ramp R1	ADA
70004	Rosa M Parks Middle	Dulluling Interior	Interior Access Notic	Ramp	1	The pull side of the accessible door does not have	Otage Trainp TC1	ADA
76628	School	Building Interior	Interior Access Route	Door	1	the required maneuvering clearances.	Health Room & Stage Ramp	ADA
	Rosa M Parks Middle				·	The pull side of the accessible door does not have		7.27.
76668	School	Building Interior	Interior Access Route	Door	1	the required maneuvering clearances.	Staff Lounge	ADA
	Rosa M Parks Middle	Ŭ						
76827	School	Building Interior	Interior Access Route	Stairs	1	Handrails are not compliant.	Stage stairs	ADA
	Rosa M Parks Middle							
76886	School	Building Interior	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Interior Stairs STR1, STR5	ADA
	Rosa M Parks Middle					MARYLAND: Compliant signage is not provided at		State of
77146	School	Parking Lots	Accessible Parking	Parking Space-Van	1	the van space.	Parking Lot #1 -van stalls	Maryland
77450	Rosa M Parks Middle	Davidia at Lata	A ilala Dankin n	Dadin v On a a a Man		MARYLAND: Signage indicating "No Parking in	Dankin v Lat #4	State of
77150	School	Parking Lots	Accessible Parking	Parking Space-Van	I	Access Aisle" at van access aisle is not provided. ADVISORY: A marked crosswalk is not provided	Parking Lot #1	Maryland
						where the accessible route crosses a vehicular way		
	Rosa M Parks Middle					between the accessible parking aisle and the building	Parking Lot #1 to sidewalk at	
77151	School	Parking Lots	Exterior Access Route	Exterior Accessible Route	1	entrance.	building entrance	ADA
77.101	Rosa M Parks Middle	. arking Loto	Exterior / toooss i touto	Exterior recognists reduce	†	A wheelchair space is not provided at each team	Sanding officiation	, , , , ,
100988	School	Building Exterior	Baseball/Softball Field	Player Seating	2	bench area at the ball field.	Baseball field	ADA
	Rosa M Parks Middle			,		The vending machines have operable parts which are		
76379	School	Building Interior	Common Areas	Vending Machine	2	not within reach range.	Staff Lounge	ADA
•	•			· •	•	Ŭ		

Id	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
						The interior signage does not have compliant visual		
	Rosa M Parks Middle					and tactile characters, with raised or indented		
76606	School	Building Interior	Interior Access Route	Signage	2	characters or symbols.	Staff Interior spaces and rooms	ADA
	Rosa M Parks Middle					The vending machines have operable parts which are		
76612	School	Building Interior	Common Areas	Vending Machine	2	not within reach range.	Corridor outside Gymnasium	ADA
						Service counter does not have 36" wide section that		
						is 36" maximum above finished floor that is oriented		
						for a parallel approach, or the service counter does		
						not have a 30" wide section that is 36" maximum,		
	Rosa M Parks Middle					with knee and toe clearance, that is oriented for a		
76824	School	Building Interior	Common Areas	Counters	2	forward approach.	Media Center Service Counter	ADA
	Rosa M Parks Middle					The stair treads and edge of top landing do not have	Interior Stairs STR1, STR2,	
76855	School	Building Interior	Interior Access Route	Stairs	2	visual contrast on the leading edge.	STR3, STR4, STR5	ADA
						The interior signage does not have compliant visual		
	Rosa M Parks Middle					and tactile characters, with raised or indented		
76358	School	Building Interior	Interior Access Route	Signage	2	characters or symbols.	Interior Spaces & Rooms	ADA
							(1) Main Office Workroom, (1)	
							Prep Workroom, (2) Team Rooms	
							in between D105 & D126, (1)	
							Prep Room off Corridor adjacent	
							to Boys 2 Restroom, (1) Staff	
							Lounge, (2) Team Rooms in	
							between rooms D217 & D241, (2)	
							Team Rooms in between C206 &	
						The accessible sink is not installed with the front of	232, (1) Prep Room adjacent to	
	Rosa M Parks Middle					the higher of the rim or counter surface 34" maximum	Boys 4 Restroom, (1) Prep Room	
76879	School	Building Interior	Kitchen	Sink	2	above finished floor.	near Aux. Gymnasium Corridor	ADA
							(6) Science Classroom sinks	
	Rosa M Parks Middle						B102, B104, B223, B225, C204,	
76890	School	Building Interior	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	C202	ADA
						The sink rim is higher than 34", and does not have		
	Rosa M Parks Middle					knee and toe clearance (does not apply to mop		
76893	School	Building Interior	Interior Access Route	Sink	2	basins, utility sinks, or bar sinks).	Technology Classroom	ADA
							(2) Art Classrooms, (2)	
						The sink rim is higher than 34", and does not have	Technology Classrooms, (2)	
	Rosa M Parks Middle					knee and toe clearance (does not apply to mop	Multi-Purpose Classroom, (2)	
76894	School	Building Interior	Interior Access Route	Sink	2	basins, utility sinks, or bar sinks).	Consumer Lab Classroom	ADA
						The sink rim is higher than 34", and does not have		
	Rosa M Parks Middle					knee and toe clearance (does not apply to mop		
76895	School	Building Interior	Interior Access Route	Sink	2	basins, utility sinks, or bar sinks).	Darkroom/Tech Classroom Sinks	ADA
							Restrooms: Boys 1, 2, 3, 4, 5;	
						The restroom circulation path is not free of objects	Girls 1, 2, 3, 4, 5; Girls Locker	
	Rosa M Parks Middle					protruding more than 4" from wall in the space	Room Restroom, Boys Locker	
76322	School	Restrooms	Restroom	Protruding Object	2	between 27" and 80" height above finish floor.	Room Restroom	ADA
						The restroom circulation path is not free of objects		
	Rosa M Parks Middle					protruding more than 4" from wall in the space		
76380	School	Restrooms	Restroom	Protruding Object	2	between 27" and 80" height above finish floor.	Restroom: Girls1	ADA
	Rosa M Parks Middle							
76366	School	Building Interior	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Technology Education Corridor	ADA
							Boys P/E Office Shower, Girls	
	Rosa M Parks Middle					The spray unit does not have a minimum 59" long	P/E Office Shower, Building	
76389	School	Building Interior	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	hose.	Services Shower	ADA
						A tactile, raised star minimum 2" high is not provided		
	Rosa M Parks Middle					to the left of the floor designation on both jambs at		
76622	School	Building Interior	Interior Access Route	Elevator	3	the main elevator entry level.	Elevator E1	ADA
							Restrooms: Boys 1, 2, 3, 4, 5;	
							Girls 1, 2, 3, 4, 5; Girls Locker	
	Rosa M Parks Middle					The provided signage does not have raised or	Room Restroom, Boys Locker	
76317	School	Restrooms	Restroom	Restroom/Bathroom-Signage	3	indented characters or symbols.	Room Restroom	ADA
	•	•	•	. 5 5	•			

ld	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
							Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8; Boys P/E Office Restroom, Girls P/E Office Restroom, Kitchen Staff Restroom, Building Services Restroom, Office Restroom, Mens Office	
	Rosa M Parks Middle					The provided signage is not mounted at the latch side	Restroom, Womens Office	
76326	School	Restrooms	Restroom	Restroom/Bathroom-Signage	3	of the door or at a compliant height.	Restroom	ADA
70220	Rosa M Parks Middle	Destrooms	Destroom	Destruction / Dethanson Metan Class		The flush control is located on the closed side and/or	Restrooms: Boys 1, Girls 1, Girls	A D A
76330	School Rosa M Parks Middle	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	is not within reach range. The flush control is located on the closed side and/or	Restrooms: Staff 1, 3, 6, 7; Girls P/E Office Restroom, Office Restroom, Kitchen Staff Restroom, Building Services	ADA
76331	School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	is not within reach range.	Restroom	ADA
76333	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Restroom: Boys 5	ADA
70333	Rosa M Parks Middle	Restrooms	Restroom	Restroom/Battiloom-Official	3	The water closet in a wheelchair stall in a multi-stall	Restrooms: Boys 1, Girls 1, Boys	ADA
76349	School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	restroom does not have the required clearance.	5, Girls 5	ADA
76350	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restrooms: Staff:1, 2, 3, 4, 7, 8; Office Restroom, Kitchen Staff Restroom, Building Services Restroom, Boys P/E Office Restroom	ADA
	Rosa M Parks Middle						Restrooms: Staff: 1, 2, 4, 5, 7, 8; Boys P/E Office Restroom, Girls P/E Office Restroom, Office Restroom 1, Kitchen Staff Restroom, Building Services	
76351	School	Restrooms	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom	ADA
76352	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom: Boys 5	ADA
70332	Rosa M Parks Middle		rtestroom		3	The water closet in a single/user or unisex restroom	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8; Building Services Restroom, Kitchen Staff Restroom, Office Restroom, Boys P/E Office Restroom, Girls P/E Office	
76353	School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	does not have the required clearance.	Restroom	ADA
76356	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms: Staff 1, 4 ; Girls P/E Office Restroom, Boys P/E Office Restroom	ADA
76357	Rosa M Parks Middle School	Restrooms	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Boys Locker Room, Girls Locker Room	ADA
70337	Rosa M Parks Middle	Restrooms	Employee Work Areas	Locker Rooms-Deficit	3	The locker room does not have a compliant bench.	Boys P/E Office, Girls P/E Office,	ADA
76360	School	Restrooms	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services	ADA
76374	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys P/E Office Restroom, Girls P/E Office Restroom, Office Restroom 1	ADA
76381	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Boys P/E Office Shower, Girls P/E Office Shower, Building Services Shower	ADA
76384	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Boys P/E Office Shower, Girls P/E Office Shower, Building Services Shower	ADA
76386	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8; Girls P/E Office Restroom; Boys P/E Office Restroom	ADA
	Rosa M Parks Middle		Locker and Dressing	The state of the s		and the state of t	Girls Locker Room, Boys Locker	
76392	School	Restrooms	Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room	ADA

ld	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
	Rosa M Parks Middle	· ·	·	•			·	
76617	School	Restrooms	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Restroom: Boys 2	ADA
76673	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys P/E Office Shower, Girls P/E Office Shower, Building Services Shower	ADA
76817	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Boys P/E Office Shower, Girls P/E Office Shower, Building Services Shower	ADA
76818	Rosa M Parks Middle School	Restrooms	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Boys P/E Office Shower, Girls P/E Office Shower, Building Services Shower	ADA
76834	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restrooms: Staff 1, 2, 3, 4; Office Restroom, Kitchen Staff Restroom, Building Services Restroom	ADA
76836	Rosa M Parks Middle School	Restrooms	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms: Staff 1, 2, 3, 4; Office Restroom, Kitchen Staff Restroom, Building Services Restroom	ADA
. 5366	Rosa M Parks Middle			. toolioon, palantoini viator olooot			Boys Locker Room, Girls Locker	
76876	School	Restrooms	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Room	ADA