



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

John Poole Middle School
17014 Tom Fox Avenue
Poolesville, Maryland 20837

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-157.303

Date of Report:
October 29, 2019

On Site Date:
June 7-8, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at John Poole Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at John Poole Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
John Poole Middle School	73	25	26	5	31	160
Grand Total	73	25	26	5	31	160

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
111858	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 2	ADA
111859	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 2	ADA
111862	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Bus Drop Off sidewalk	ADA
111863	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus Drop Off sidewalk	ADA
111864	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Ramp 2	ADA
111865	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Ramp 2	ADA
111866	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 3	ADA
111867	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 3	ADA
111868	John Poole Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 2	ADA
111869	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Ramp 3	ADA
111873	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Bus Loop Pedestrian Entrance	ADA
111874	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Flag pole	ADA
111875	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Main Entrance Plaza	ADA
111880	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Student Drop Off	ADA
111881	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk adjacent to P1A - P1D	ADA
111885	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route does not have 80" vertical clearance.	Asphalt play area	ADA
112226	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Asphalt play area	ADA
112230	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Sidewalk adjacent to Door 8	ADA
112232	John Poole Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Gymnasium entrance	ADA
112234	John Poole Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp 5	ADA
112235	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Asphalt walkway to Tennis and Basketball Courts	ADA
112237	John Poole Middle School	EXTERIOR	Exterior Access Route	Gate	1	The gate does not have the required maneuvering clearances.	Tennis Court Gate 1	ADA
112238	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 2	ADA
112239	John Poole Middle School	EXTERIOR	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Courts	ADA
112240	John Poole Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 3	ADA
112523	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Asphalt walk between Door 3 / Door 4	ADA
112524	John Poole Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 4	ADA
112525	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Outdoor Classroom	ADA
112602	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 4	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
112604	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 4	ADA
112607	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp 4	ADA
112611	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has openings in the surface greater than 1/2".	Ramp 4	ADA
112614	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Asphalt walkway west of Ramp 4	ADA
112619	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Soccer Field	ADA
112620	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 1	ADA
112623	John Poole Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 5	ADA
112626	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Asphalt walkway to Door 5	ADA
112628	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Asphalt walkway to Door 6	ADA
112629	John Poole Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 6	ADA
112630	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Asphalt walkway between Door 6 and Door 7A	ADA
112632	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 5	ADA
112633	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 5	ADA
112634	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp 5	ADA
112635	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Asphalt walkway northwest of Door 7A	ADA
112711	John Poole Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Cafeteria stage	ADA
112712	John Poole Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp 6	ADA
112763	John Poole Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Cafeteria Foodservice line	ADA
112765	John Poole Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Cafeteria Foodservice line	ADA
112769	John Poole Middle School	INTERIOR	Entrance to Building	Building Entrance-Door	1	MARYLAND: The opening force of the fire door is more than 15#s at the latch, more than 30#s to set door in motion, and more than #15 to move door to fully open.	Main Entrance	ADA
112772	John Poole Middle School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Main Office	ADA
112791	John Poole Middle School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Aux Gym 404	ADA
112796	John Poole Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Main Gym	ADA
112797	John Poole Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Music Suite 501	ADA
112804	John Poole Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Guidance Corridor	ADA
112812	John Poole Middle School	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Room 308	ADA
111820	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1	ADA
111823	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
111824	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp 1	ADA
111826	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Ramp 1	ADA
111828	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 2	ADA
111830	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp 2	ADA
111832	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp 2	ADA
111842	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 3	ADA
111845	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 3	ADA
111848	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 4	ADA
111849	John Poole Middle School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp 4	ADA
112231	John Poole Middle School	PARKING LOTS	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Gymnasium entrance loading zone	ADA
112641	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	P1A, P1B, P1C	State of Maryland
112645	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	P1A-B, P1C	ADA
112646	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	P1A, P1B, P1C	ADA
112647	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	P1A-P1B	ADA
112648	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	P1D	State of Maryland
112649	John Poole Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	P1D	ADA
111856	John Poole Middle School	EXTERIOR	Exterior Access Route	Ramp	2	The ramp has a rise in excess of 30".	Ramp 2	ADA
111882	John Poole Middle School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Door 1	ADA
111883	John Poole Middle School	EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic Area	ADA
112233	John Poole Middle School	EXTERIOR	Exterior Access Route	Reach Range	2	Operable parts or items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Door 8	ADA
112236	John Poole Middle School	EXTERIOR	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
112639	John Poole Middle School	EXTERIOR	Exterior Access Route	Reach Range	2	Operable parts or items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Flagpole	ADA
112709	John Poole Middle School	INTERIOR	Common Areas	Assembly Area	2	An assistive listening system is required, but not provided.	Cafeteria	ADA
112710	John Poole Middle School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Exit doors throughout	ADA
112713	John Poole Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Cafeteria door	ADA
112759	John Poole Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Cafeteria door	ADA
112782	John Poole Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Interior doors throughout	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
112783	John Poole Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Suite	ADA
112786	John Poole Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Media Center	ADA
112789	John Poole Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Aux Gym 404	ADA
112790	John Poole Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Main Gym	ADA
112792	John Poole Middle School	INTERIOR	Common Areas	Assembly Area	2	An assistive listening system is required, but not provided.	Main Gym	ADA
112795	John Poole Middle School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Interior Rooms throughout	ADA
112798	John Poole Middle School	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	School Store	ADA
112799	John Poole Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	300 Corridor	ADA
112801	John Poole Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Gymnasium Entrance Lobby	ADA
112803	John Poole Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Comment Boxes	ADA
112806	John Poole Middle School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Art Room, Room 301	ADA
112809	John Poole Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion are not within reach range.	Room 102, Room 308	ADA
112811	John Poole Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 203, Room 308	ADA
112674	John Poole Middle School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Girls Restroom 4, Boys Restroom 5, Girls Restroom 6, Boys Restroom 7, Girls Restroom 8	ADA
112788	John Poole Middle School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Corridor Lockers	ADA
112672	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Girls Restroom 4, Boys Restroom 5, Girls Restroom 6	ADA
112673	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Girls Restroom 4, Boys Restroom 5, Girls Restroom 6, Boys Restroom 8	ADA
112675	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Girls Restroom 4, Boys Restroom 5, Girls Restroom 6	ADA
112676	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Girls Restroom 4, Boys Restroom 5, Girls Restroom 6, Boys Restroom 7, Girls Restroom 8	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
112677	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Restroom 1, Girls Restroom 2, Girls Restroom 6, Boys Restroom 7, Girls Restroom 8	ADA
112678	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Restroom 1, Girls Restroom 2, Boys Restroom 3, Boys Restroom 5, Girls Restroom 6	ADA
112684	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom 3	ADA
112685	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys Restroom 5, Girls Restroom 6	ADA
112686	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The provided signage does not have raised or indented characters or pictograph symbols.	Girls Restroom 7	ADA
112687	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls Restroom 7	ADA
112688	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys Restroom 7, Girls Restroom 8	ADA
112689	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys Restroom 7, Girls Restroom 8	ADA
112690	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls Locker Room, Boys Locker Room	ADA
112691	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls Locker Room, Boys Locker Room	ADA
112694	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Locker Room, Boys Locker Room	ADA
112695	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls Locker Room, Boys Locker Room	ADA
112696	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Girls Locker Room, Boys Locker Room	ADA
112697	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The location of the roll-in shower controls is not compliant.	Girls Locker Room, Boys Locker Room	ADA
112705	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Locker Room	ADA
112706	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys Locker Room	ADA
112707	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Locker Room	ADA
112708	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Locker Room	ADA
112784	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Restroom 1, Health Restroom 2	ADA
112785	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Health Restroom 2 (Healthy)	ADA
115058	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 406	ADA
112650	John Poole Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	Drinking Fountain 1, Drinking Fountain 2, Drinking Fountain 5	ADA
112651	John Poole Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain 3	ADA
112813	John Poole Middle School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	Room 308	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
112692	John Poole Middle School	RESTROOMS	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Girls Locker Room, Boys Locker Room	ADA
112693	John Poole Middle School	RESTROOMS	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Girls Locker Room, Boys Locker Room	ADA
112526	John Poole Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	5	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Outdoor Classroom	ADA
112669	John Poole Middle School	INTERIOR	Kitchen	Sink	5	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Team Room 104, Team Room 205, Team Room 303	ADA
112773	John Poole Middle School	INTERIOR	Interior Access Route	Sink	5	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Main Office Break Room, Media Center Work Room, Staff Lounge, IDA Office	ADA
112775	John Poole Middle School	INTERIOR	Interior Access Route	Door	5	The bottom of the door vision light is higher than 43" and less than 66".	Principal's Office, 100E Conf Room	ADA
112787	John Poole Middle School	INTERIOR	Interior Access Route	Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	Media Center Work Room	ADA
112793	John Poole Middle School	INTERIOR	Interior Access Route	Controls And Dispensers	5	The height of controls throughout the common area are not compliant.	Staff Lounge	ADA
112794	John Poole Middle School	INTERIOR	Common Areas	Vending Machine	5	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
112658	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	5	The locker room does not have a compliant bench.	Kitchen Staff Restroom	ADA
112659	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	5	The locker room does not have accessible lockers.	Kitchen Staff Restroom	ADA
112660	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	5	The opening force of the interior, non-fire hinged door non-fire door is more than 5 pounds.	Kitchen Staff Restroom	ADA
112661	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	5	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Kitchen Staff Restroom, Bldg Services Restroom	ADA
112662	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Staff Restroom	ADA
112664	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	5	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restroom 1, Staff Restroom 2, Staff Restroom 3, Staff Restroom 4, Staff Restroom 5	ADA
112665	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	5	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restroom 1, Staff Restroom 2	ADA
112666	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 1, Staff Restroom 2, Staff Restroom 3, Staff Restroom 4, Staff Restroom 5, Bldg Services Restroom	ADA
112667	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 2, Staff Restroom 3, Staff Restroom 4	ADA
112668	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	5	The transfer shower is not compliant.	Bldg Services Restroom	ADA
112670	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The toilet paper dispenser is not at a compliant location.	Staff Restroom 4	ADA
112671	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The rear grab bar at the water closet is not compliant.	Staff Restroom 5	ADA
112698	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single/user or unisex restroom does not have the required clearance.	Room 405 Restroom, Room 406 Restroom	ADA
112699	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The toilet paper dispenser is not at a compliant location.	Room 405 Restroom	ADA
112700	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The rear grab bar at the water closet is not compliant.	Room 405 Restroom, Room 406 Restroom	ADA
112701	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Coach's Shower Room	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
112702	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	5	The coat hook is not within an allowable reach range.	Coach's Shower Room	ADA
112703	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Room 406 Restroom	ADA
112704	John Poole Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	5	The locker room does not have accessible lockers.	Room 406	ADA
112777	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	5	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Main Office Restroom	ADA
112778	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single/user or unisex restroom does not have the required clearance.	Main Office Restroom	ADA
112779	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Main Office Restroom	ADA
112780	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The rear grab bar at the water closet is not compliant.	Main Office Restroom	ADA
112781	John Poole Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	Main Office Restroom	ADA