



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850  
James Tokar

## ADA TITLE II ASSESSMENT

Forest Oak Middle School  
651 Saybrooke Oaks Boulevard  
Gaithersburg, Maryland 20877

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**

123821.17R000-002.303

**Date of Report:**

October 22, 2019

**On Site Date:**

June 20-22, 2017



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Forest Oaks Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Forest Oaks Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes. EMG's assessment of the subject property identified the following areas of concern:

### FOREST OAKS MIDDLE SCHOOL - TITLE II ADA COMPLIANCE ASSESSMENT - ACCESSIBILITY SUMMARY

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Forest Oak Middle School	31	14	107	6		158
Grand Total	31	14	107	6		158

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
65652	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide where the van stall is less than 132" wide.	Parking Lot 1 Row P1- First Stall	State of Maryland
65654	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1 Row P1- First Stall	State of Maryland
65656	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1- Row P1 Second Stall	ADA
65657	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide where the van stall is less than 132" wide.	Parking Lot 2 Row P15- First Stall	State of Maryland
65659	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2 Row P16 - First Stall	State of Maryland
65666	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Parking lot 2- adjacent to the accessible parking stalls in row P16	ADA
65669	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Parking Lot 2 Row P16 - Stall 4	ADA
65672	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb ramp 2 adjacent to parking lot 1	ADA
65678	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Exterior Accessible Route	1	A compliant sidewalk is not provided from accessible parking to the public access to the building.	From accessible stalls in parking lot 1 to the main entrance- south side of the building	ADA
65711	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Curb ramp 1	ADA
65749	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1	ADA
65819	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Exterior Accessible Route	1	Sidewalk has areas in excess of 1:50 (2%) cross slope.	Sidewalk immediately east of curb ramp 1	ADA
65820	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Exterior Accessible Route	1	A compliant accessible route is not provided to the site amenities.	Northwest of Parking Lot 1	ADA
65821	Forest Oak Middle School	BUILDING EXTERIOR	Accessible Route	Exterior Accessible Route	1	Sidewalk has areas in excess of 1:50 (2%) cross slope.	West of Parking Lot 2	ADA
66967	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Cafeteria- Rear of Stage	ADA
66968	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Cafeteria- Rear of Stage	ADA
66976	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Interior Stairs at the North, South, and East End of the Building	ADA
66978	Forest Oak Middle School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
66979	Forest Oak Middle School	BUILDING INTERIOR	Fitness Course	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	Room A126	ADA
68001	Forest Oak Middle School	BUILDING INTERIOR	Entrance to Building	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Library, Rooms E104, D127, D204, D218, D207, D208, D230, D229	ADA
68008	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Elevator	1	The clearance between the car platform sill and the edge of the hoistway landing is greater than 1-1/4".	Elevator	ADA
68016	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Elevator	1	The elevator does not have compliant car position indicators.	Elevator	ADA
68020	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	Library, Rooms E104, D127, D204, D218, D207, D208, D230, D229	ADA
68023	Forest Oak Middle School	BUILDING INTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast from the remainder of the surface.	Interior North, South, and East Stairs	ADA
65826	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Accessible Route	Exterior Accessible Route	1	Sidewalk has slopes in excess of 1:20 (5%) running slope and 1:50 (2%) cross slope.	Between northeast building elevation and tennis courts	ADA
65829	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Accessible Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk south of exterior stairs on northwest building elevation	ADA
65830	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Accessible Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk south of exterior stairs on northwest building elevation	ADA
66952	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Accessible Route Around North Fields	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66953	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant sidewalk is not provided from the public access to the amenity.	North Baseball Field	ADA
66954	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Exterior Basketball Court	ADA
68005	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast from the remainder of the surface.	Stairs North of Building Elevation, Stair 1	ADA
66956	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
66966	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria	ADA
66969	Forest Oak Middle School	BUILDING INTERIOR	Concession Stand	Service Counter	2	Tray slides in food service lines are not minimum 28" and maximum 34" high.	Kitchen Service Counter	ADA
66970	Forest Oak Middle School	BUILDING INTERIOR	Employee Work Areas	Work Surface	2	The work surface is not compliant.	Kitchen	ADA
67109	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Media Center Check-Out Counter	ADA
66971	Forest Oak Middle School	BUILDING INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Kitchen	ADA
66972	Forest Oak Middle School	BUILDING INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Kitchen	ADA
66973	Forest Oak Middle School	BUILDING INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	School Store opposite Cafeteria	ADA
68006	Forest Oak Middle School	BUILDING INTERIOR	Kitchen	Sink	2	ADA sink does not have push/lever hardware	Kitchen	ADA
65822	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Accessible Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Handball court south of tennis courts	ADA
65823	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Tennis Courts	Bleacher Seating	2	The wheelchair space is not provided at the bleacher seating for the tennis courts.	West of tennis courts	ADA
65824	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Accessible Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis courts	ADA
66951	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	Adjacent to Stair 1	ADA
66955	Forest Oak Middle School	EXTERIOR ATHLETIC FACILITIES	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	Adjacent to Basketball Court	ADA
67103	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls' Locker Room	ADA
67104	Forest Oak Middle School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls' Locker Room	ADA
67105	Forest Oak Middle School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls' Locker Room	ADA
66977	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Gymnasium	ADA
66980	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom C7	ADA
66981	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys' Restroom C7	ADA
66982	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Boys' Restroom C7	ADA
66983	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys' Restroom C7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66984	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Boys' Restroom C7	ADA
66985	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom C7	ADA
66986	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Boys' Restroom C7	ADA
66987	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Boys' Restroom C7	ADA
66988	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48", with the 30" dimension centered on the urinal.	Boys' Restroom C7	ADA
66989	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Girls' Restroom C6	ADA
66990	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls' Restroom C6	ADA
66991	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls' Restroom C6	ADA
66992	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Girls' Restroom C6	ADA
66993	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls' Restroom C6	ADA
66999	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls' Restroom E22	ADA
67000	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls' Restroom E2	ADA
67001	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls' Restroom E2	ADA
67002	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls' Restroom E2	ADA
67003	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the water closet is not 16" minimum to 18" maximum from the side wall.	Girls' Restroom E2	ADA
67004	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not between 17" to 19".	Girls' Restroom E2	ADA
67005	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls' Restroom E2	ADA
67006	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Staff Restroom opposite Room 126	ADA
67007	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom opposite Room 126	ADA
67008	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom opposite Room 126	ADA
67009	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom opposite Room 126	ADA
67010	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance. The centerline of the water closet is not located minimum 16" and maximum 18" from the side wall.	Staff Restroom opposite Room 126	ADA
67011	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Boys' Restroom opposite Room 106	ADA
67012	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Boys' Restroom opposite Room 106	ADA
67013	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48", with the 30" dimension centered on the urinal.	Boys' Restroom opposite Room 106	ADA
67014	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys' Restroom opposite Room 106	ADA
67015	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Boys' Restroom opposite Room 106	ADA
67016	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys' Restroom opposite Room 106	ADA
67017	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Boys' Restroom opposite Room 106	ADA
67018	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys' Restroom opposite Room 106	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
67019	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the water closet is not 16" minimum and 18" maximum from the side wall.	Boys' Restroom opposite Room 106	ADA
67020	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Girls' Restroom adjacent Room 127	ADA
67021	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls' Restroom adjacent Room 127	ADA
67022	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls' Restroom adjacent Room 127	ADA
67023	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls' Restroom adjacent Room 127	ADA
67024	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Girls' Restroom adjacent Room 127	ADA
67025	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the water closet is not minimum 16" and maximum 18" from the side wall.	Girls' Restroom adjacent Room 127	ADA
67026	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls Restroom adjacent Room 127	ADA
67027	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls' Restroom adjacent Room 127	ADA
67028	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls' Restroom adjacent Room 127	ADA
67029	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Boys' Restroom Adjacent Room 127	ADA
67030	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys' Restroom Adjacent Room 127	ADA
67031	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Boys' Restroom Adjacent Room 127	ADA
67032	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys' Restroom Adjacent Room 127	ADA
67033	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Boys' Restroom Adjacent Room 127	ADA
67034	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the water closet is not 16" minimum and 18" maximum from the side wall.	Boys' Restroom Adjacent Room 127	ADA
67035	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys' Restroom Adjacent Room 127	ADA
67038	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	Staff Restroom B2	ADA
67039	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom B2	ADA
67040	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom B2	ADA
67041	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom B2	ADA
67042	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Restrooms D21 and D22	ADA
67043	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms D21, D22, and D23	ADA
67044	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48", with the 30" dimension centered on the urinal.	Boys' Restroom D21	ADA
67045	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys' Restroom D21	ADA
67046	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls' Restroom D22	ADA
67047	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls' restroom D22	ADA
67048	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	Staff Restroom D23	ADA
67049	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom D23	ADA
67050	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom D23	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
67059	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Boys' Restroom E21	ADA
67062	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Boys' Restroom E21	ADA
67063	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys' Restroom E21	ADA
67065	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys' Restroom E21	ADA
67066	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Boys' Restroom E21	ADA
67072	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet centerline is not 16" minimum to 18" maximum from the side wall.	Boys' Restroom E21	ADA
67073	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Restroom E21	ADA
67074	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Boys' Restroom E21	ADA
67075	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	Staff Restroom E23	ADA
67076	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom E23	ADA
67077	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom E23	ADA
67078	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Girls' Restroom E22	ADA
67079	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls' Restroom E22	ADA
67080	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls' Restroom E22	ADA
67081	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Girls' Restroom E22	ADA
67082	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls' Restroom E22	ADA
67083	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls' Restroom E22	ADA
67084	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls' Restroom E22	ADA
67085	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Boys' Locker Room	ADA
67086	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have a compliant bench.	Boys' Locker Room	ADA
67087	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48", with the 30" dimension centered on the urinal.	Boys' Locker Room	ADA
67088	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the water closet is not 16" minimum to 18" maximum from the side wall.	Boys' Locker Room	ADA
67089	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys' Locker Room	ADA
67090	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys' Locker Room	ADA
67111	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator	ADA
68012	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Elevator	3	Visible and audible signal fixtures indicating which car is answering the call and the car's direction of travel are not compliant.	Elevator	ADA
68027	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys locker room	ADA
67091	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Boys' Locker Room	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
67092	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A transfer seat is provided but is not compliant.	Locker Rooms	ADA
67093	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not provided.	Boys' Locker Room	ADA
67094	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The location of the roll-in shower controls is not compliant.	Boys' Locker Room	ADA
67095	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	Locker Room Offices	ADA
67096	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The shower controls are not mounted on the side wall opposite the transfer shower seat.	Boys and Girls locker room offices	ADA
67097	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Boys and Girls locker room offices	ADA
67098	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A transfer seat is provided but is not compliant.	Boys and Girls locker room offices	ADA
67099	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys and Girls locker room offices	ADA
67100	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls' Locker Room	ADA
67101	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet is less than 60" wide and 59" deep.	Girls' Locker Room	ADA
67102	Forest Oak Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Girls' Locker Room	ADA
66957	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, they are not at two levels or a hi-lo is not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Cafeteria	ADA
67106	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, they are not at two levels or a hi-lo is not provided. If more than 2 are provided, less than 50% are high or less than 50% are low. The drinking fountain protrudes more than 4" into the circulation path.	Girls' Locker Room	ADA
67107	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	Classroom E104	ADA
66974	Forest Oak Middle School	BUILDING INTERIOR	Common Areas	Locker Rooms	4	The lockers does not have at least one of the shelves at 40" minimum and 48" maximum height.	Corridor	ADA
66975	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, they are not at two levels or a hi-lo is not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Corridors	ADA
67110	Forest Oak Middle School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low. The existing drinking fountain is a protruding object.	Classroom D113	ADA