



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Shady Grove Middle School  
8100 Midcounty Highway  
Gaithersburg, Maryland 20877

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**  
123821.17R000-084.303

**Date of Report:**  
October 30, 2019

**On Site Date:**  
August 18, 2017



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Shady Grove Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Shady Grove Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

**SHADY GROVE MIDDLE SCHOOL- TITLE II ADA COMPLIANCE ASSESSMENT - ACCESSIBILITY SUMMARY**

Facility/Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Shady Grove Middle School	35	16	56	3		110
Grand Total	35	16	56	3		110

Order of magnitude costs to address those elements are described individually in Appendix A.

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77475	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1	ADA
77476	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 1	ADA
77477	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 1	ADA
77478	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	East of Main Entrance to Parking lot 2	ADA
77480	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 2	ADA
77481	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 3	ADA
77486	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 3	ADA
77492	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route south of Curb Ramp 3	ADA
77498	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible Route South of Curb Ramp 3	ADA
77501	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 1	ADA
77517	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	East side of Parking Lot 3	ADA
77520	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route East of Parking Lot 3	ADA
77522	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	East of Parking Lot 3	ADA
77523	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	North of Parking Lot 3	ADA
77525	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Northwest of Tennis Courts	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77556	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 4	ADA
77557	Shady Grove Middle School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Bus Drop-Off Area at Main Entrance- Parking lot 1	ADA
77562	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Multipurpose Room Stage	ADA
77565	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Multipurpose Room Stage	ADA
77568	Shady Grove Middle School	BUILDING INTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Multipurpose Room stage	ADA
77932	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	North and South stairs	ADA
77934	Shady Grove Middle School	BUILDING INTERIOR	Fitness Course	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	Auxiliary Gym	ADA
77536	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible Route Adjacent to Tennis Courts	ADA
77543	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Football Field	ADA
77554	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Walkway around Baseball Fields	ADA
77555	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Southwest of Basketball Court	ADA
77469	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2- Row P1, Stall P1-3	State of Maryland
77470	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	Compliant signage is not provided at the van stall.	Parking Lot 2- Row P1, Stall P1-3	ADA
77472	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2- Row P1, Stall P1-1	State of Maryland
77473	Shady Grove Middle School	PARKING LOTS	Exterior Access Route	Exterior Accessible Route	1	ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance.	Vehicular Way South of Parking Lot 2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77502	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 3- Row P2, Stalls P2-1 to P2-3	ADA
77506	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 3- Row P2, Stall P2-3	ADA
77508	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 3- Row P2, Stall P2-3	ADA
77510	Shady Grove Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 3- Row P2	State of Maryland
77524	Shady Grove Middle School	PARKING LOTS	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop-Off Area	ADA
77526	Shady Grove Middle School	BUILDING EXTERIOR	Site Furnishings	Trash Receptacle With Operable Lid	2	Clear ground space is not provided at the trash receptacle with lid requiring operation.	Trash Receptacle Adjacent to Tennis Courts	ADA
77749	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Multipurpose Room	ADA
77754	Shady Grove Middle School	BUILDING INTERIOR	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Kitchen	ADA
77756	Shady Grove Middle School	BUILDING INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Kitchen	ADA
77810	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	School Store	ADA
77831	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room E118	ADA
77833	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Media Center	ADA
77907	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Room D108	ADA
77930	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Classroom D230	ADA
77955	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Lounge	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77956	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
77957	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Room C137	ADA
77533	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
77540	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	West of Baseball Field	ADA
77547	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Football Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the football field.	Football Field	ADA
77552	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball Field	ADA
77764	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Kitchen Staff Restroom	ADA
77765	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Kitchen Staff Restroom	ADA
77766	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Kitchen Staff Restroom	ADA
77774	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Kitchen Staff Restroom	ADA
77776	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Staff Restroom	ADA
77778	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Kitchen Staff Restroom	ADA
77783	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Building Services Staff Restroom	ADA
77784	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Building Services Staff Restroom	ADA
77786	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Building Services Staff Restroom	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77788	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Building Services Staff Restroom	ADA
77789	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Building Services Staff Restroom	ADA
77792	Shady Grove Middle School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Room B106	ADA
77933	Shady Grove Middle School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Gymnasium	ADA
77902	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom D106	ADA
77903	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Boy's Restroom D107	ADA
77904	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boy's Restroom D107, Girls Restroom E216	ADA
77915	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Restroom - Room D108	ADA
77916	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Girls Restroom E216	ADA
77917	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom E216	ADA
77925	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom E215	ADA
77926	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom E215	ADA
77927	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restroom E215	ADA
77793	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Room B106	ADA
77794	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Girls Restroom C156	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77795	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls Restroom C156, Boys Restroom C155, Girls Restroom E113, Girls Restroom E114, Girls Restroom D106, Boys Restroom D107, Girls Restroom E216, Boys Restroom E213, Girls Restroom D212, Boys Restroom D211, Boys and Girls Locker Room	ADA
77796	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Girls Restroom C156	ADA
77797	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom C156	ADA
77798	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Restroom C156, Boys Restroom C155, Girls Restroom E113, Girls Restroom E114, Girls Restroom D106	ADA
77799	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Girls Restroom C156	ADA
77800	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys Restroom C155	ADA
77811	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom E113	ADA
77813	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom E112	ADA
77818	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom E112	ADA
77928	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restroom E215	ADA
77929	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys restroom E213	ADA
77936	Shady Grove Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Boys and Girls Restroom	ADA
77937	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Locker Room and Girls Locker Room	ADA
77938	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys Locker Room and Girls Locker Room	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77939	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Locker Room and Girls Locker Room	ADA
77940	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys Locker Room	ADA
77941	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Boys PE Office and Girls PE Office	ADA
77942	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys PE Office and Girls PE Office	ADA
77820	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom E112	ADA
77824	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Girls Restroom E114, Girls Restroom D106, Boys Restroom E213, Girls Restroom D212	ADA
77825	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls Restroom E114	ADA
77826	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom E114	ADA
77943	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Boys PE Office and Girls PE Office	ADA
77944	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys PE Office	ADA
77946	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys PE Office	ADA
77947	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Boys PE Office	ADA
77951	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Girls PE Office	ADA
77952	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Men's Restroom in Main Office	ADA
77953	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's and Women's Restroom in Main Office	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77954	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Men's Restroom in Main Office	ADA
77958	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Room C137, Men's and Women's Restroom	ADA
77959	Shady Grove Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Health Room C137, Men's Restroom	ADA
77802	Shady Grove Middle School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Corridors	ADA
77532	Shady Grove Middle School	EXTERIOR ATHLETIC FACILITIES	Site Furnishings	Drinking Fountain/Water Cooler	4	The minimum number and types of drinking fountains are not provided.	Adjacent to Tennis Courts	ADA
77935	Shady Grove Middle School	RESTROOMS	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Boys Locker Room	ADA