

ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools 45 West Gude Drive, Suite 4100 Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Eastern Middle School 300 University Boulevard Silver Spring, Maryland 20901

PREPARED BY:

10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.EMGcorp.com

EMG Project Number: 123821.17R000-113.303 Date of Report: October 28, 2019

EMG CONTACT:

Michael Nelson Program Manager 800.733.0660 x6244 mnelson@emgcorp.com

On Site Date:

August 31 - September 1, 2017

1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Eastern Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Eastern Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Eastern Middle School	30	4	41	5		80
Grand Total	30	4	41	5		80

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
70170	Eastern Middle School	Exterior	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking lot 2	State of Maryland
	Euston Middle Concor	Exterior	7 toocoolbio 1 urting	Tarking opace van	<u> </u>	All accessible spaces in the building do not have a	r arking for 2	Ctato or Marylana
70171	Eastern Middle School	Exterior	Interior Access Route	Door	1	compliant means of egress.	DR5, DR8	ADA
						Accessible entries are not identified with the International Symbol of Accessibility, where not all		
70172	Eastern Middle School	Exterior	Entrance to Building	Building Entrance-Door	1	entrances are accessible.	DR1, DR2, DR4, DR7	ADA
						The ramp has a rise greater than 6"; however,		
70173	Eastern Middle School	Exterior	Exterior Access Route	Ramp	1	handrails are not provided.	SW2	ADA
70175	Eastern Middle School	Exterior	Exterior Access Route	Stairs	1	Handrails are not compliant.	STR2	ADA
70470	Factoria Middle Oak and	Fatarian	Futurion Access Boots	Damas		The ramp run rises greater than 6", however no	D4	ADA
70176	Eastern Middle School	Exterior	Exterior Access Route	Ramp		edge protection is provided.	R1	ADA
70177	Eastern Middle School	Exterior	Exterior Access Route	Stairs	1	Handrails are not compliant.	STR1, STR3, STR4	ADA
70178	Eastern Middle School	Exterior	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	SW 4	ADA
						The ramp has a rise greater than 6"; however,		
70179	Eastern Middle School	Exterior	Exterior Access Route	Ramp	1	handrails are not provided.	SW1	ADA
70180	Eastern Middle School	Exterior	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Basketball Court 1	ADA
70100	Lasterri Middle Scriool	LATERIO	Dasketball Court	Sport Court	1	The threshold at the accessible door is greater than	Dasketball Court 1	ADA
70214	Eastern Middle School	Exterior	Interior Access Route	Door	1	½" in height.	DR9	ADA
						The ramp has a running slope in excess of 1:12		
70215	Eastern Middle School	Exterior	Exterior Access Route	Ramp	1	(8.33%) and/or cross slope in excess of 1:48 (2.08%).	R2	ADA
70210	Lustern Wildle Concor	Exterior	Exterior 7 todess 1 todie	ramp	1	The pull side of the accessible door does not have	112	/\D/\
70216	Eastern Middle School	Exterior	Entrance to Building	Building Entrance-Door	1	the required maneuvering clearances.	R2	ADA
						An accessible route does not connect accessible building or facility entrances with all accessible		
						spaces and elements within the building or facility.		
						At least one accessible route shall connect	Sports Fields, Tennis Courts,	
70512	Eastern Middle School	Exterior	Exterior Access Route	Exterior Accessible Route	1	accessible elements that are on the same site.	Basketball Courts	ADA
72785	Eastern Middle School	Exterior	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Sports Fields	ADA
12100	Lustern Wildle Concor	Exterior	Exterior / toocss / toute	Exterior / todessible frome	1	MARYLAND: Signage indicating "No Parking in	oporto i icido	/\D/\
72788	Eastern Middle School	Exterior	Accessible Parking	Parking Space-Van	1	Access Aisle" at van access aisle is not provided.	Parking Lot 1 & 2	State of Maryland
73812	Eastern Middle School	Exterior	Exterior Access Route	Stairs	1	Handrails are not compliant.	SW1, 2, 4	ADA
						All accessible spaces in the building do not have a		
73813	Eastern Middle School	Exterior	Interior Access Route	Door	1	compliant means of egress.	DR10	ADA
							GYM Stage, Girls 2, 102, 105, 106, 107, 109, 110,114,116, 201A, 201B,	
							300,302, 303, 304, 305, 306, 310,	
							311, 601, 602, 603, 604, 605, 606,	
							607, 701, 702, 703, 703A, 704, 705, 706, 707, 709, 711, 800A, 800B, 801,	
						The pull side of the accessible door does not have	801A, 804, 806, 808, 810, 811, 812,	
70183	Eastern Middle School	Interior	Common Areas	Interior Doors	1	the required maneuvering clearances.	813, 814, 815, 816, 901	ADA
70186	Eastern Middle School	Interior	Common Areas	Interior Doors	1	The door has less than 32" clear width.	Boys 1 & 2, Girls 1 & 2	ADA
70204	Eastern Middle School	Interior	Interior Access Route	Stairs	1	Handrails are not compliant.	STR#1, STR#2, STR#3, STR#4, STR#5, STR#7	ADA
70206	Eastern Middle School	Interior	Interior Access Route	Stairs	1	Handrails are not compliant.	STR #5	ADA
70207	Eastern Middle School	Interior	Interior Access Route	Stairs	1	Handrails are not compliant.	STR #6	ADA
70209	Eastern Middle School	Interior	Interior Access Route	Stairs	1	The rear of the stairs is open.	STR #5	ADA
						Double-leaf doors are used and neither side is		
70210	Eastern Middle School	Interior	Interior Access Route	Door	1	compliant.	Main Gymnasium	ADA
70525	Eastern Middle School	Interior	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Staff 6	ADA
10020		1	Interior / toocsa i toute	2001	1 '	and required maneavering electrones.	J.C. C.	,,,,,,

Id	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
70528	Eastern Middle School	Interior	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Boys 7	ADA
72757	Eastern Middle School	Interior	Common Areas	Platform Lift	1	The platform lift requires a key for operation.	Lift 1, Lift 2	ADA
12131	Eastern Middle School	Interior	Common Areas	Plationii Liit	I	The platform lift requires a key for operation.	Building Services Staff Restroom,	ADA
72815	Eastern Middle School	Interior	Common Areas	Interior Doors	1	The door has less than 32" clear width.	Staff Restroom 3 & 4 Corridor door,	ADA
72817	Eastern Middle School	Interior	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Staff 5, Staff 6	ADA
						A wheelchair space is not provided at each team		
70181	Eastern Middle School	Exterior	Baseball/Softball Field	Player Seating	2	bench area at the ball fields.	Sports Fields Rooms 109, 102, 106, 201, 201C,	ADA
						The work surface height is not compliant. Knee and	113, 307, 308, 701, 711, 800, 801,	
70200	Eastern Middle School	Interior	Common Areas	Work Surface	2	toe clearances are not provided.	802, 803, 804, 806, 806A, 811, 905	ADA
70502	Eastern Middle School	Interior	Interior Access Route	Signage	2	The provided signage does not have color contrast and a non-glare finish.	All accessible rooms and common areas.	ADA
						The vending machines have operable parts which	Staff Lounge and corridor near	
70518	Eastern Middle School	Interior	Common Areas	Vending Machine	2	are not within reach range. The mirror is mounted higher than 40" above finish	Cafeteria Restroom - Health Room 1&2, Special	ADA
						floor to the bottom of the reflective surface, where it	ED Restroom 1&2, Boys 1,2,3,5, 6 &	
69264	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Mirror	3	is installed above a lavatory or counter.	7, Girls 1,2, 3, 5 & 6	ADA
				Restroom/Bathroom-Water		The accessible dispensers are not at compliant	Restroom - Boys 1,2,3,5 & 7, Girls 1,2,3 & 6, Boys PE Restroom, Girls	
69333	Eastern Middle School	Interior	Restroom	Closet	3	heights.	PE Restroom,	ADA
69341	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom - Staff 3 & 4	ADA
69345	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Toilet Stall Restroom/Bathroom-Water	3	The wheelchair stall door is not compliant. The water closet in a single/user or unisex restroom	Restroom - Girls 6 Restroom - Special ED Restroom 1&2,	ADA
69350	Eastern Middle School	Interior	Restroom	Closet	3	does not have the required clearance.	Health Restroom 1&2	ADA
69434	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Restroom - Boys 1	ADA
09434	Eastern Middle School	Interior	Restroom	Closet	3	restroom does not have the required clearance.	Restroom - Boys 1,6 &7, Boys PE	ADA
20.455						D	Restroom, Girls 3 & 6, Girls PE	
69455	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom	ADA
69586	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Lavatory Restroom/Bathroom-Water	3	Knee clearance is not provided. The height of the water closet is not 17" minimum to	Restroom - Boys 2, Girls 2 &6	ADA
69603	Eastern Middle School	Interior	Restroom	Closet	3	19" maximum above finished floor.	Restroom - Boys PE Office Restroom	ADA
				5 / 5 / 5			Restroom - Boys PE Office Restroom,	
69687	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Floor Space	3	The required turning space within the restroom is not provided.	Girls PE Office Restroom, Building Services Staff	ADA
69915	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Toilet Stall	3	The grab bar in the wheelchair stall is not compliant.	Restroom - Boys 1 & 6, Girls 2	ADA
09913	Lastern Middle School	interior	Restroom	Nestroom/Batthoom-Tollet Stall	3	The side grab bar is not compliant in the wheelchair	Restroom - Boys 1 & 0, Giris 2	ADA
69917	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Toilet Stall	3	stall.	Restroom - Boys 1	ADA
69924	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom - Boys PE Office Restroom, Staff 3, 4, 5 &6	ADA
70503	Eastern Middle School	Interior	Interior Access Route	Elevator	3	The elevator car dimensions are not compliant.	EL1	ADA
70504	Eastern Middle School	Interior	Interior Access Route	Elevator	3	The hoistway signage is not compliant.	EL1	ADA
						, , , , , , , , , , , , , , , , , , , ,		
70517	Eastern Middle School	Interior	Common Areas Locker and Dressing	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Main Gymnasium Girls Locker Room, Boys Locker	ADA
70519	Eastern Middle School	Interior	Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room	ADA
72740	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	All restrooms	ADA
12140	Lastern Miladie School	IIIIGIIOI	IVESTIONII	Restroom/Bathroom-Water		The flush control is located on the closed side	Restroom - Girls PE Office Restroom,	
72811	Eastern Middle School	Interior	Restroom	Closet	3	and/or is not within reach range.	Staff 5 & 6	ADA
72813	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Restroom - Staff 3, 4, 5 & 6	ADA
72944	Factorn Middle School	Interior	Postroom	Restroom/Bathroom-Water	2	The accessible dispensers are not at compliant	Postroom Stoff 5 % 6	۸۵۸
72814	Eastern Middle School	Interior	Restroom	Closet	3	heights.	Restroom - Staff 5 & 6	ADA

Id	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
69928	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom - Boys 1 , 5 & 6, Boys PE Restroom	ADA
09920	Eastern Middle School	Interior	Restroom	Restroom/Datmoom-Offial	3	The flush control is located on the closed side and is	Restroom	ADA
20000		1		5		more than 48" high, for an obstructed forward reach	Restroom - Boys PE Restroom, Boys	
69930	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Urinal Restroom/Bathroom-Water	3	range of maximum 20" horizontally. The toilet paper dispenser is not at a compliant	2 & 5 Restroom - Special ED Restroom 1 &	ADA
69979	Eastern Middle School	Interior	Restroom	Closet	3	location.	2	ADA
00000	Fastam Middle Oak ad	lata di sa	Destruction	Daratus and /Dath na and Darat		The pull side of the accessible door does not have	Destruction Oids 0	404
69982	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Door	3	the required maneuvering clearances. A wheelchair stall is not provided in a multi-user	Restroom - Girls 2 Restroom - Boys 2, 5 &7, Boys PE	ADA
69990	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Toilet Stall	3	restroom.	Restroom, Girls 1	ADA
							Restroom - Staff 1 & 2, Office Restroom 1, Boys PE Office	
							Restroom, Girls PE Office Restroom,	
70040		1		Restroom/Bathroom-Water		The water closet in a single/user or unisex restroom	Building Services Staff, Kitchen Staff	
70019	Eastern Middle School	Interior	Restroom	Closet Restroom/Bathroom-Floor	3	does not have the required clearance. The required turning space within the restroom is	Restroom	ADA
70021	Eastern Middle School	Interior	Restroom	Space	3	not provided.	Restroom - Boy 4, Girl 4	ADA
70000	5 (M: III O I I		6 1	Restroom/Bathroom-Water		The side grab bar at the water closet is not	D 1 0:1 DE 0" D 1	454
70022	Eastern Middle School	Interior	Restroom	Closet Restroom/Bathroom-Water	3	compliant.	Restroom - Girls PE Office Restroom Restroom - Boys PE Office Restroom,	ADA
70023	Eastern Middle School	Interior	Restroom	Closet	3	The grab bars at the water closet are not compliant.	Building Services Staff	ADA
				D / /D // N/ /		T. 6	Restroom - Special ED Restroom 1	
70024	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	&2, Health Restroom 1 & 2, Boys 6, Girls 6	ADA
				Restroom/Bathroom-Transfer				
70025	Eastern Middle School	Interior	Restroom	Shower Stall Restroom/Bathroom-Transfer	3	The transfer shower is not exactly 36" by 36".	Restroom - Girls PE Office Restroom	ADA
70026	Eastern Middle School	Interior	Restroom	Shower Stall	3	The transfer shower is not exactly 36" by 36".	Restroom - Girls PE Restroom	ADA
							Restroom - Girls PE Office Restroom,	
70027	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Boys PE Office Restroom, Building Services Staff	ADA
10021	Lasterri Middle Oction	Interior	Restroom	Shower Stair	3	A seat is not provided in the transier shower stail.	Restroom - Girls PE Office Restroom,	ADA
		1		Restroom/Bathroom-Transfer		Grab bars are not provided in the transfer shower	Boys PE Office Restroom, Building	
70028	Eastern Middle School	Interior	Restroom	Shower Stall	3	stall.	Services Staff Restroom - Girls PE Office Restroom,	ADA
				Restroom/Bathroom-Transfer		The required clearance at the entry to the transfer	Boys PE Office Restroom, Building	
70030	Eastern Middle School	Interior	Restroom	Shower Stall	3	stall is not provided.	Services Staff	ADA
70031	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Restroom - Boys PE Office Restroom, Building Services Staff	ADA
		interior .				The coat hook is not within an allowable reach		
70166	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Coat Hook	3	range.	Restroom - Staff 5 & 6 Restroom - Staff 1, 2, 5 & 6, Office	ADA
						The mirror is mounted higher than 40" above finish	Restroom 1, Boys PE Office	
						floor to the bottom of the reflective surface, where it	Restroom, Girls PE Office Restroom,	
70168	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Mirror Restroom/Bathroom-Water	3	is installed above a lavatory or counter. The accessible dispensers are not at compliant	Kitchen Staff Restroom Restroom - Staff 1& 2, Boys PE Office	ADA
70169	Eastern Middle School	Interior	Restroom	Closet	3	heights.	Restroom, Girls PE Office Restroom	ADA
700.40	E (M: III O I I		5 .	D (D .)		The coat hook is not within an allowable reach	D / 011 DE D /	454
72948	Eastern Middle School	Interior	Restroom	Restroom/Bathroom-Coat Hook	3	range. Controls and/or dispensers are not within an	Restroom - Girls PE Restroom	ADA
70198	Eastern Middle School	Interior	Common Areas	Controls And Dispensers	4	allowable reach range.	All accessible occupied spaces.	ADA
						The minimum number of drinking fountains is not		
						provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are		
						provided, less than 50% are high or less than 50%	100 Hall, 300 Hall, 400 Hall, 600 Hall,	
70202	Eastern Middle School	Interior	Interior Access Route	Drinking Fountain/Water Cooler	4	are low. The spout of the standing height drinking fountain is	800 Hall & 900 Hall 100 Hall, 300 Hall, 400 Hall, 600 Hall,	ADA
70203	Eastern Middle School	Interior	Interior Access Route	Drinking Fountain/Water Cooler	4	not between 38" minimum and 43" maximum.	800 Hall & 900 Hall	ADA

Id	Facility	Building	Assembly	Туре	Barrier Priority	Detail	Location Description	ADA
						Controls and/or dispensers are not within an		
70520	Eastern Middle School	Interior	Common Areas	Controls And Dispensers	4	allowable reach range.	Classrooms	ADA
						Controls and/or dispensers are not within an		
70521	Eastern Middle School	Interior	Common Areas	Controls And Dispensers	4	allowable reach range.	Classrooms.	ADA