



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

White Oak Middle
2201 New Hampshire Avenue
Silver Spring, Maryland 20904

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-115.303

Date of Report:
October 28, 2019

On Site Date:
November 7, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity’s programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the “2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design.” The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at White Oaks Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at White Oak Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG’s assessment of the subject property identified the following areas of concern:

| Facility / Building | Priority 1 Items | Priority 2 Items | Priority 3 Items | Priority 4 Items | Priority 5 Items | Total Items |
|-------------------------|------------------|------------------|------------------|------------------|------------------|-------------|
| White Oak Middle School | 48 | 22 | 34 | 6 | | 110 |
| Grand Total | 48 | 22 | 34 | 6 | | 110 |

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|-------------------------|----------|-----------------------|---------------------------|------------------|---|--|-------------------|
| 78152 | White Oak Middle School | EXTERIOR | Accessible Parking | Parking Space-Van | 1 | MARYLAND: A "Van" space is not provided. | Parking Lot 1 & 2 | State of Maryland |
| 78156 | White Oak Middle School | EXTERIOR | Accessible Parking | Parking Space-Car | 1 | MARYLAND: Compliant signage is not provided at the space. | Parking Lot 1 - P1 - A, B, C, D | State of Maryland |
| 78158 | White Oak Middle School | EXTERIOR | Accessible Parking | Parking Space-Car | 1 | The slope of the parking space is greater than 1:50 (2%). | Parking Lot 1 - P1 - A, B, C, D | ADA |
| 78160 | White Oak Middle School | EXTERIOR | Accessible Parking | Parking Space-Car | 1 | The access aisle slope is greater than 1:50 (2%). | Parking Lot 1 - P1 - A, B, C, D | ADA |
| 78161 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from accessible parking to the public facility entrance. | Parking Lot 1 - P1 - C, D | ADA |
| 78165 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope. | Sidewalks on North, West, South and East sides of school including sidewalk from public road on South side of building | ADA |
| 78170 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | The accessible route has gaps in the surface greater than 1/2" wide. | Sidewalk on west side of building | ADA |
| 78176 | White Oak Middle School | EXTERIOR | Exterior Access Route | Loading/Unloading Zone | 1 | The access aisle is not marked | Front of building (West side) | ADA |
| 78206 | White Oak Middle School | EXTERIOR | Exterior Access Route | Curb Ramp | 1 | The curb ramp does not meet the slope requirements. | Curb Ramp CR-3 | ADA |
| 78207 | White Oak Middle School | EXTERIOR | Exterior Access Route | Curb Ramp | 1 | The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%). | Curb Ramp CR-1, 2 and 3 | ADA |
| 78208 | White Oak Middle School | EXTERIOR | Exterior Access Route | Curb Ramp | 1 | The slope of the curb ramp flares is greater than 1:10 (10%). | Curb Ramp CR-1 | ADA |
| 78209 | White Oak Middle School | EXTERIOR | Exterior Access Route | Curb Ramp | 1 | A curb ramp is not provided where the accessible route crosses a curb. | Curb Ramp CR-4, 5, 6 | ADA |
| 78210 | White Oak Middle School | EXTERIOR | Exterior Access Route | Stairs | 1 | Steps do not have uniform and compliant riser heights and/or tread depths. | Stair ST-3, 4, 6, 8, 9, and 10 | ADA |
| 78217 | White Oak Middle School | EXTERIOR | Exterior Access Route | Stairs | 1 | Handrails are not provided. | Stair ST-8 and 3 | ADA |
| 78222 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The handrails are not compliant. | Stair ST-3 and 6 | ADA |
| 78223 | White Oak Middle School | EXTERIOR | Exterior Access Route | Stairs | 1 | The stair treads and edge of top landing do not have visual contrast on the leading edge. | Stair ST-3, 4, 6, 8, 9 and 10 | ADA |
| 78312 | White Oak Middle School | EXTERIOR | Entrance to Building | Building Entrance-Door | 1 | The maneuvering clearance at the accessible door is not level and clear. | Door DR-1, 2, 3, 4, 8, 9, 10, 11, 12, 14, 15 and 16 | ADA |
| 78466 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The accessible route to the facility has a stairway, which does not comply with vertical rise requirements. | Door DR-12, 14 and 15 | ADA |
| 78489 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%). | Ramp R-1 | ADA |
| 78499 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Baseball and Softball fields | ADA |
| 78502 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%). | Ramp R-2 | ADA |
| 78503 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp has a rise greater than 6"; however, handrails are not provided. | Ramp R-2 | ADA |
| 78511 | White Oak Middle School | EXTERIOR | Exterior Access Route | Gate | 1 | The gate does not have the required maneuvering clearances. | Tennis courts | ADA |
| 78571 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance. | Parking Lot P-2 | ADA |
| 78572 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped. | West side of building | ADA |
| 78573 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | Handrails are not continuous and at a consistent height above ramp surface. | Ramp R-1 | ADA |
| 78574 | White Oak Middle School | EXTERIOR | Exterior Access Route | Exterior Accessible Route | 1 | A compliant accessible route is not provided from the public access to the amenity. | Picnic tables north side of building | ADA |
| 88651 | White Oak Middle School | EXTERIOR | Exterior Access Route | Curb Ramp | 1 | The slope of the curb ramp flares is greater than 1:10 (10%). | Curb Ramp CR-3 | ADA |

| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|-------------------------|----------|-------------------------|---------------------------|------------------|--|---|-----|
| 88653 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The accessible route to the facility has a stairway, which does not comply with vertical rise requirements. | Door DR-13 | ADA |
| 88654 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The accessible route to the facility has a stairway, which does not comply with vertical rise requirements. | Door DR-8 | ADA |
| 88655 | White Oak Middle School | EXTERIOR | Exterior Access Route | Ramp | 1 | The ramp has a rise greater than 6"; however, handrails are not provided. | Door #13 | ADA |
| 88656 | White Oak Middle School | EXTERIOR | Entrance to Building | Building Entrance-Door | 1 | The pull side of the accessible door does not have the required maneuvering clearances. | Door DR-1, 2, 3, 4, 8, 9, 10, 11, 12, 14, 15 and 16 | ADA |
| 78583 | White Oak Middle School | INTERIOR | Interior Access Route | Ramp | 1 | The ramp running slope exceeds 1:12 (8.33%). | Ramp R-3 | ADA |
| 78584 | White Oak Middle School | INTERIOR | Interior Access Route | Ramp | 1 | The clear width of the ramp is less than 36". | Ramp R-1 | ADA |
| 78585 | White Oak Middle School | INTERIOR | Interior Access Route | Ramp | 1 | Handrail heights are not compliant. | Ramp R-1, 3 and 4 | ADA |
| 78586 | White Oak Middle School | INTERIOR | Interior Access Route | Ramp | 1 | Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface. | Ramp R-1, 2, 5 | ADA |
| 78589 | White Oak Middle School | INTERIOR | Interior Access Route | Door | 1 | The opening force of the accessible, hinged, non-fire door is more than 5 pounds. | Doors to rooms 108, 201, 202, 210, 216, 221, 120b, 132b, 201b, 208b, 214a | ADA |
| 78590 | White Oak Middle School | INTERIOR | Interior Access Route | Door | 1 | The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch. | Doors 108, 201, 210, 132b | ADA |
| 78593 | White Oak Middle School | INTERIOR | Interior Access Route | Door | 1 | The pull side of the accessible door does not have the required maneuvering clearances. | Interior Doors throughout building | ADA |
| 78594 | White Oak Middle School | INTERIOR | Common Areas | Interior Doors | 1 | Maneuvering clearance at the door is not level and clear. | Doors at rooms 102, 104, 219, 220, 110a, 201a1, 205a1 | ADA |
| 78596 | White Oak Middle School | INTERIOR | Interior Access Route | Protruding Object | 1 | Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route. | Room 110 | ADA |
| 78652 | White Oak Middle School | INTERIOR | Interior Access Route | Interior Accessible Route | 1 | The interior accessible route has less than 36" clear width. | Room 120 | ADA |
| 78653 | White Oak Middle School | INTERIOR | Fitness Course | Exercise Equipment | 1 | Clear floor space is not provided at the transfer point to the exercise equipment. | Room 129 | ADA |
| 78701 | White Oak Middle School | INTERIOR | Interior Access Route | Platform Lift | 1 | The platform lift is not compliant. | Platform lift PL- 2 | ADA |
| 88641 | White Oak Middle School | INTERIOR | Interior Access Route | Platform Lift | 1 | The platform lift is not compliant. | Platform lift PL- 1 | ADA |
| 78579 | White Oak Middle School | INTERIOR | Interior Access Route | Stairs | 1 | Steps do not have uniform and compliant riser heights and/or tread depths. | Stairs ST-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11 and 14 | ADA |
| 78581 | White Oak Middle School | INTERIOR | Interior Access Route | Stairs | 1 | Handrails are not compliant. | Stairs ST-1, 6, 7, 9, 10, 11, 12, 14 | ADA |
| 78582 | White Oak Middle School | INTERIOR | Interior Access Route | Stairs | 1 | Handrail extensions are not compliant. | Stairs ST-1, 2, 3, 5, 6, 7, 9, 10, 11, 12, 14 | ADA |
| 78505 | White Oak Middle School | EXTERIOR | Baseball/Softball Field | Player Seating | 2 | A wheelchair space is not provided at each team bench area at the ball field. | Baseball and Softball fields | ADA |
| 78507 | White Oak Middle School | EXTERIOR | Baseball/Softball Field | Bleacher Seating | 2 | The required number of wheelchair spaces is not provided at the bleacher seating for the ball field. | Baseball and Softball fields | ADA |
| 78510 | White Oak Middle School | EXTERIOR | Exterior Access Route | Gate | 2 | The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate. | Tennis Courts | ADA |
| 78575 | White Oak Middle School | EXTERIOR | Picnic Area | Picnic Table | 2 | The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance. | Picnic area North side of building | ADA |
| 78588 | White Oak Middle School | INTERIOR | Interior Access Route | Door | 2 | The bottom of the door vision light is higher than 43" and less than 66". | All Interior Door with Glass | ADA |
| 78591 | White Oak Middle School | INTERIOR | Interior Access Route | Signage | 2 | The provided signage is not mounted at the latch side of the door or at a compliant height. | Rooms 102, 106, 108, 227, 256, 101a, 106a, 107a, 107b, 107c, 107d, 110a, 205a1, 205a2, 205a3, 205a4 | ADA |

| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|-------------------------|----------|-----------------------|--------------------------------|------------------|--|---|-----|
| 78592 | White Oak Middle School | INTERIOR | Interior Access Route | Signage | 2 | The provided signage is not mounted at the latch side of the door or at a compliant height. | Rooms 103, 104, 114, 125, 132, 134, 120b, 122b | ADA |
| 78595 | White Oak Middle School | INTERIOR | Interior Access Route | Door | 2 | The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth. | Doors to rooms 108, 124, 132a, 202a, 202b, 208b, 214a | ADA |
| 78639 | White Oak Middle School | INTERIOR | Interior Access Route | Sink | 2 | The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks). | Rooms 108, 132, 205, 300 | ADA |
| 78645 | White Oak Middle School | INTERIOR | Common Areas | Counters | 2 | Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach. | Room 108, 132, 110, 201A, Clinic, 202b, 300, 312b | ADA |
| 78647 | White Oak Middle School | INTERIOR | Common Areas | Work Surface | 2 | The work surface height is not compliant. Knee and toe clearances are not provided. | Counters in room 110, Desk in room 108 | ADA |
| 78649 | White Oak Middle School | INTERIOR | Common Areas | Laundry- Washer | 2 | The washing machine controls are not within reach range. | room 108 | ADA |
| 78712 | White Oak Middle School | INTERIOR | Interior Access Route | Elevator | 2 | The elevator operation is not automatic | Elevator E-1 | ADA |
| 78716 | White Oak Middle School | INTERIOR | Interior Access Route | Reach Range | 2 | Items that require a forward reach motion require more than 48" height reach. | Throughout building | ADA |
| 88367 | White Oak Middle School | INTERIOR | Common Areas | Counters | 2 | Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach. | Room 237, 241, 243, 301, 303 | ADA |
| 88369 | White Oak Middle School | INTERIOR | Interior Access Route | Sink | 2 | The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks). | Rooms 237, 241, 243, 301, 303 | ADA |
| 88658 | White Oak Middle School | INTERIOR | Interior Access Route | Reach Range | 2 | Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor. | Various rooms throughout school | ADA |
| 88659 | White Oak Middle School | INTERIOR | Interior Access Route | Sink | 2 | The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks). | Rooms 106a, 301, 303, 237, 241 | ADA |
| 78580 | White Oak Middle School | INTERIOR | Interior Access Route | Stairs | 2 | The stair treads and edge of top landing do not have visual contrast on the leading edge. | Stair ST-1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13 & 14 | ADA |
| 88660 | White Oak Middle School | INTERIOR | Interior Access Route | Sink | 2 | The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks). | Rooms 208, 201A, 312B | ADA |
| 88661 | White Oak Middle School | INTERIOR | Common Areas | Vending Machine | 2 | The vending machines have operable parts which are not within reach range. | Room 104 | ADA |
| 88662 | White Oak Middle School | INTERIOR | Common Areas | Vending Machine | 2 | The vending machines have operable parts which are not within reach range. | Corridor outside Gym | ADA |
| 78587 | White Oak Middle School | INTERIOR | Interior Access Route | Signage | 3 | Means of egress signage is not provided. | All Exterior Doors | ADA |
| 78597 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Floor Space | 3 | The required turning space within the restroom is not provided. | Restroom RR-1, 2, 6, 7 15, 16, 17, 18 | ADA |
| 78617 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The toilet paper dispenser is not at a compliant location. | Restroom RR-1, 2, 3, 6, 7, 10, 11, 15, 16, 17, 18, 20, 21 | ADA |
| 78619 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | A wheelchair stall is not provided in a multi-user restroom. | Restroom RR-1, 17, and 20 | ADA |
| 78620 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The ambulatory stall size is not compliant, or an ambulatory stall is not provided. | Restroom RR-6, 7, 18 and 20 | ADA |
| 78621 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Mirror | 3 | The bottom of the reflective surface of the mirror is mounted higher than 40". | Restroom RR-1, 2, 3, 6, 7, 10, 11, 15, 16, 17, 18, 20, 21 | ADA |
| 78622 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The height of the water closet is not 17" minimum to 19" maximum above finished floor. | Restroom RR-12 | ADA |
| 78623 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The flush control is located on the closed side and/or is not within reach range. | Restroom RR- 2, 3, 6, 10, 11, 15, 18 | ADA |



| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|-------------------------|----------|---------------------------|--|------------------|---|--|-----|
| 78627 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Restroom RR-13, 14 | ADA |
| 78630 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Restroom RR-1, 2, 6, 7, 10, 11, 15, 16, 17, 18, 20, 21 | ADA |
| 78632 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep. | Restroom RR-2, 16, 18 | ADA |
| 78635 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The water closet in a single/user or unisex restroom does not have the required clearance. | Restroom RR-4, 5, 12 & 19 | ADA |
| 78637 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall. | Restroom RR-2, 3, 16 | ADA |
| 78638 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall door is not compliant. | Restrooms RR-1, 2, 6, 7, 15, 16, 17, 18, 20, 21 | ADA |
| 78651 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Restroom RR-3 | ADA |
| 78656 | White Oak Middle School | INTERIOR | Locker and Dressing Rooms | Locker and Dressing Rooms | 3 | The locker room does not have a compliant bench. | Girls and boys locker room | ADA |
| 78663 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Roll-In Shower Stall | 3 | A transfer seat is provided but is not compliant. | Girls and boys locker room | ADA |
| 78664 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Roll-In Shower Stall | 3 | Grab bars are not compliant. | Girls and boys locker room roll-in shower | ADA |
| 78675 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Roll-In Shower Stall | 3 | The location of the roll-in shower controls is not compliant. | Girls and boys locker room roll in shower | ADA |
| 78714 | White Oak Middle School | INTERIOR | Interior Access Route | Elevator | 3 | Visible and audible signal fixtures indicating which car is answering the call and the car's direction of travel are not compliant. | Elevator E-1 | ADA |
| 88370 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall door is not compliant. | Restrooms RR-13, 14 | ADA |
| 88371 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | The wheelchair stall door is not compliant. | Restrooms RR-8, 9 | ADA |
| 88372 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The toilet paper dispenser is not at a compliant location. | Restroom RR-4, 5, 8, 9, 12, 19 | ADA |
| 88373 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The toilet paper dispenser is not at a compliant location. | Restroom RR-13, 14 | ADA |
| 88374 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Toilet Stall | 3 | A wheelchair stall is not provided in a multi-user restroom. | Restroom RR-8, 9 | ADA |
| 88375 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The flush control is located on the closed side and/or is not within reach range. | Restroom RR- 14 | ADA |
| 88376 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Mirror | 3 | The bottom of the reflective surface of the mirror is mounted higher than 40". | Restroom RR-13, 14 | ADA |
| 88377 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Mirror | 3 | The bottom of the reflective surface of the mirror is mounted higher than 40". | Restroom RR-4, 5, 8, 9, 12, 19 | ADA |
| 88378 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Restroom RR-4, 5, 8, 9, 19 | ADA |
| 88382 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The grab bars at the water closet are not compliant. | Restroom RR-12 | ADA |
| 88634 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The space between the grab bar and projecting objects above the grab bar is less than 12" minimum. | Restroom RR-10 | ADA |
| 88639 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The water closet in a single/user or unisex restroom does not have the required clearance. | Restroom RR-10, 11 | ADA |
| 88640 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Water Closet | 3 | The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall. | Restroom RR-4, 8 | ADA |
| 88657 | White Oak Middle School | INTERIOR | Restroom | Restroom/Bathroom-Coat Hook | 3 | The coat hook is not within an allowable reach range. | Restroom RR-12 | ADA |
| 78648 | White Oak Middle School | INTERIOR | Interior Access Route | Turning Space | 4 | A compliant turning space is not provided. | Room 110 | ADA |
| 78650 | White Oak Middle School | INTERIOR | Kitchen | Kitchen- Range/Cooktop/Oven | 4 | The location of the controls requires reaching across burners. | Room 108 | ADA |

| Id | Facility | Building | Assembly | Type | Barrier Priority | Detail | Location Description | ADA |
|-------|-------------------------|----------|-----------------------|--------------------------------|------------------|--|--|-----|
| 78655 | White Oak Middle School | INTERIOR | Common Areas | Locker Rooms | 4 | The locker room does not have at least one of the shelves at 40" minimum and 48" maximum height. | Lockers in Halls | ADA |
| 88383 | White Oak Middle School | INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low. | Drinking Fountain DF -1, 2, 3, 4, 5, 6, 7, 9, 10, 11, 12 | ADA |
| 88384 | White Oak Middle School | INTERIOR | Interior Access Route | Drinking Fountain/Water Cooler | 4 | The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum. | Drinking Fountain DF-8 | ADA |
| 88644 | White Oak Middle School | INTERIOR | Kitchen | Kitchen- Oven/ Public | 4 | The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance. | Room 108 | ADA |