



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Earle B. Wood Middle School
14615 Bauer Drive
Rockville, Maryland 20853

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-127.303

Date of Report:

October 28, 2019

On Site Date:

May 3-4, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Earle B Wood Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Earle B Wood Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Earle B Wood Middle School	85	19	76	2		182
Grand Total	85	19	76	2		182

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103958	Earle B Wood Middle School	ATHLETIC FIELDS	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-13	ADA
103959	Earle B Wood Middle School	ATHLETIC FIELDS	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-12	ADA
103964	Earle B Wood Middle School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Stair ST-13	ADA
103900	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-3	ADA
103902	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-4	ADA
103903	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-7	ADA
103907	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-1	ADA
103908	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-2	ADA
103911	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-3	ADA
103916	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The landing at the top of the curb ramp is not a compliant size.	Curb Ramp CR-3	ADA
103918	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-5	ADA
103924	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-5	ADA
103936	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-6	ADA
103940	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-10	ADA
103943	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-10	ADA
103945	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-10	ADA
103946	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-11	ADA
103947	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-11	ADA
103948	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-11	ADA
103952	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-12	ADA
103953	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-12	ADA
103972	Earle B Wood Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-1	ADA
103974	Earle B Wood Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-9	ADA
103975	Earle B Wood Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-11	ADA
103977	Earle B Wood Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-15	ADA
103986	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	City Sidewalk to Southwest corner of Building	ADA
103988	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	City Sidewalk to Southwest corner of Building	ADA
103991	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	At Driveway on West Side of Building	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103996	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-4	ADA
103999	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-4	ADA
104002	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-3	ADA
104003	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-3	ADA
104016	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	West Side of Building	ADA
104018	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	North Side of Building	ADA
104023	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	North Side of Building	ADA
104031	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Turn from West Side of Building to North Side	ADA
104036	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	East Side of Building	ADA
104039	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	South Side of Building	ADA
104040	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-5	ADA
104041	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-5	ADA
103839	Earle B Wood Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain - DF-8, DF-11, DF-10	ADA
103840	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1, ST-2, ST-3, ST-4	ADA
103841	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-1, ST-2, ST-3, ST-4	ADA
103842	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-1, ST-2, ST-3, ST-4	ADA
103843	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-5	ADA
103844	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-5, ST-6	ADA
103845	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-5, ST-6	ADA
103846	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-6	ADA
103847	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-7	ADA
103848	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-8	ADA
103849	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-7, ST-8	ADA
103850	Earle B Wood Middle School	INTERIOR	Interior Access Route	Vertical Level Change	1	In areas along the interior route there are level changes between 1/4" and 1/2".	Stair ST-7	ADA
103852	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	Stair ST-9	State of Massachusetts
104096	Earle B Wood Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	4 Team Room	ADA
104113	Earle B Wood Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Room 287, Hallway	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
104122	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	54% of All Doors to Classrooms, Offices, Workrooms, Team Rooms that Require Pulling to Exit Room	ADA
104123	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	57% of All Doors to Classrooms, Offices, Workrooms, Team Rooms that Require Pushing to Exit Room	ADA
104124	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 254, 232, 232B, 234, 221, 221 2nd door, Boys Locker Room @ Vestibule, 107, 302D, 101D, 288, 261, 259, 212, 230, 301E, 304, 305A	ADA
103856	Earle B Wood Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp - R-1	ADA
103858	Earle B Wood Middle School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp - R-1	ADA
103860	Earle B Wood Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp - R-1	ADA
103863	Earle B Wood Middle School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp - R-2	ADA
103864	Earle B Wood Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp - R-2	ADA
104043	Earle B Wood Middle School	INTERIOR	Interior Access Route	Platform Lift	1	The platform lift is not compliant.	Platform Lift PL-1, PL-2	ADA
104050	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Doors Throughout Building to Classrooms, Offices, Etc.	ADA
104052	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Doors Throughout Building to Classrooms, Offices, Etc.	ADA
104053	Earle B Wood Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Main Gym Room 300	ADA
104089	Earle B Wood Middle School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Girls Locker Room, Boys Locker Room	ADA
104091	Earle B Wood Middle School	INTERIOR	Interior Access Route	Head Room	1	The height of the interior accessible route is less than 80" AFF.	3B Phys Ed Room, Room 287 Office	ADA
104125	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Room 300D, 232A, 276 Office, 309A, Boys vestibule to exterior, 308, 261, 259, 292, 305, 263	ADA
104142	Earle B Wood Middle School	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Room, 251B, 265, 232, 234, 276, 221, 100A, 102, 103, 202, 284, 286, 283A, 287, 288, 243, 230, 212, 272, 252, 304	ADA
104144	Earle B Wood Middle School	INTERIOR	Entrance to Building	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Door D-1, 2, 3, 4, 8, 9, 10, 11, 12, 15, 16, 18, 19, 20	ADA
104149	Earle B Wood Middle School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Hall in Building Services Area	ADA
103872	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot A Space P2-A	State of Maryland
103877	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot A Space P2-A, P2-B	ADA
103879	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot A Space P2-A, P2-B	State of Maryland
103880	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot A Space P2-A, P2 B Access Aisle	State of Maryland
103882	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot B	State of Maryland
103886	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot B Space P4-A	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103888	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot B Space P3-A, P4-A	ADA
103891	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot B Space P4-A, P4-C, P4-D, P4-E	ADA
104126	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot B Space P3-A, P4-A, P4-B, P4-C, P4-D, P4-E	State of Maryland
104127	Earle B Wood Middle School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot A Space P2-A, P2-B	State of Maryland
105741	Earle B Wood Middle School	PARKING LOT	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus Parking Area East of Parking Lot A	ADA
105747	Earle B Wood Middle School	PARKING LOT	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not at the same level as the loading/unloading area.	Car Loading/Unloading Area to North of Parking Lot A	ADA
104143	Earle B Wood Middle School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
104013	Earle B Wood Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	West Side of Building	ADA
103853	Earle B Wood Middle School	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - ST-1, ST-2, ST-3, ST-4, ST-5, ST-6, ST-8	ADA
104111	Earle B Wood Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Room 252	ADA
104115	Earle B Wood Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
104116	Earle B Wood Middle School	INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	School Store	ADA
104044	Earle B Wood Middle School	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic	Elevator E-1	ADA
104049	Earle B Wood Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Doors Throughout Building to Classrooms, Offices, Etc.	ADA
104078	Earle B Wood Middle School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Doors Throughout Building to Classrooms, Offices, Storage Rooms, Etc.	ADA
104080	Earle B Wood Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 251, 234, 100A, 102, 104, 106C, 202, 281, 286, 243, 261, 212,	ADA
104085	Earle B Wood Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria Room 307	ADA
104128	Earle B Wood Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 252B, 232A, 232B, PE4, 100D Storage, 283A, 283B, 301, 252, 304	ADA
104132	Earle B Wood Middle School	INTERIOR	Kitchen	Sink	2	The accessible sink does not have push/lever hardware.	Room 106C	ADA
104133	Earle B Wood Middle School	INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Room 265, 276, 221, 287, 288, 230	ADA
105686	Earle B Wood Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria, Hallway	ADA
105696	Earle B Wood Middle School	INTERIOR	Interior Access Route	Reach Range	2	Operable parts or items requiring an obstructed forward reach motion are higher than 48" maximum height where the depth of the obstruction is 20" maximum, or greater than 44" maximum height where the depth of the obstruction is 20" to 25" maximum, or lower than minimum 15" height above finish floor.	Rooms 265, 276, 221, 287, 238, 230	ADA
103790	Earle B Wood Middle School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restroom Girls RR-14	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103794	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Restroom - Boys RR-5, Girls RR-6, Boys RR-18, Girls RR-17, Girls RR-12	ADA
103795	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Restroom - Girls RR-25, Girls RR-20, Boys RR-19	ADA
103869	Earle B Wood Middle School	INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Main Gym Room 300	ADA
104045	Earle B Wood Middle School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator E-1	ADA
104046	Earle B Wood Middle School	INTERIOR	Interior Access Route	Elevator	3	The hoistway signage is not compliant.	Elevator E-1	ADA
104145	Earle B Wood Middle School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All Stair ways and exterior doors	ADA
104148	Earle B Wood Middle School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Hallways	ADA
104213	Earle B Wood Middle School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	Main Gym	ADA
103483	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom - Girls RR-17, Boys RR-18	ADA
103484	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom - Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-9, Staff RR-15, Staff RR-16, Staff RR-27	ADA
103485	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom - Staff RR- 15, Staff RR-16, Staff RR- 21, Staff RR- 27, Staff RR- 28	ADA
103490	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom - Boys RR- 11, Girls RR-12	ADA
103502	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom - Staff RR-7, Staff RR-8, Staff RR-9,	ADA
103503	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom Girls RR-12	ADA
103505	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom Boys RR-11	ADA
103506	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory faucet hardware is not compliant.	restroom Staff RR-15	ADA
103604	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Staff RR-9, Staff RR-10, Staff Men's RR-2, Staff RR-7, Staff RR-22, Staff RR-21, Staff RR-26, Staff RR-27	ADA
103608	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Staff RR-16, Staff RR-24	ADA
103614	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Staff RR-15	ADA
103615	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Staff RR-28	ADA
103617	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Staff RR-29, Staff Women's RR-3	ADA
103618	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Boys RR-13	ADA
103619	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Girls RR-14	ADA
103622	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom - Girls RR-4	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103623	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom - Girls RR-12	ADA
103628	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Boys RR-5, Girls RR-6, Girls RR-12, Boys RR-11	ADA
103629	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Girls RR-17, Boys RR-18	ADA
103630	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Staff RR-9, Staff RR-10, Staff Men's RR-2, Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-15, Staff RR-16, Staff RR-21, Staff RR-22, Staff RR-26, Staff RR-27, Staff RR-24, Staff RR-28, Staff RR-29	ADA
103631	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Boys RR-19	ADA
103632	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Girls RR-4, Boys RR-1, Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19, Girls RR-14, Boys RR-13	ADA
103633	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom - Staff RR-9, Staff RR-10, Staff Men's RR-2, Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-15, Staff RR-16, Staff RR-21, Staff RR-22, Staff RR-26, Staff RR-27, Staff RR-24, Staff RR-28, Staff RR-29	ADA
103634	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom - Staff RR-9, Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-27	ADA
103635	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom - Girls RR-14	ADA
103636	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom - Boys RR-13	ADA
103637	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom Girls RR-14, Boys RR-13	ADA
103638	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Staff RR-9, Staff RR-10, Staff Men's RR-2, Staff Women's RR-3, Staff RR-15, Staff RR-16, Staff RR-21, Staff RR-22, Staff RR-26, Staff RR-24, Staff RR-28, Staff RR-29	ADA
103639	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Staff RR-7, Staff RR-8	ADA
103640	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Girls RR-6, Boys RR-5, Girls RR-17, Boys RR-18, Girls RR-12, Boys RR-11	ADA
103641	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Girls RR-4, Boys RR-1, Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103646	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Restroom Boys RR-5, Boys RR-11	ADA
103647	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Restroom Boys RR-19	ADA
103651	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom - Boys RR-5	ADA
103655	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Restroom - Girls RR-6	ADA
103656	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Restroom - Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103659	Earle B Wood Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Staff RR-10, Staff Men's RR--2, Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-15, Staff RR-16,	ADA
103665	Earle B Wood Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Girls RR-4, Boys RR-1, Girls RR-20	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103673	Earle B Wood Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Girls RR-6, Boys RR-5	ADA
103675	Earle B Wood Middle School	RESTROOMS	Portable Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is raised between 1/4" and 1/2", however the edges are not beveled.	Restroom - Boys RR-5, Girls RR-6, Boys RR-18, Girls RR-17, Girls RR-12, Boys RR-11	ADA
103676	Earle B Wood Middle School	RESTROOMS	Portable Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is raised between 1/4" and 1/2", however the edges are not beveled.	Restroom - Staff RR-9, Staff RR-10, Staff Men's RR-2, Staff Women's RR-3, Staff RR-7, Staff RR-8, Staff RR-15, Staff RR-16, Staff RR-21, Staff RR-22, Staff RR-26, Staff RR-27, Staff RR-24, Staff RR-28, Staff RR-29	ADA
103678	Earle B Wood Middle School	RESTROOMS	Portable Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is raised between 1/4" and 1/2", however the edges are not beveled.	Restroom - Girls RR-4, Boys RR-1, Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19, Girls RR-14, Boys RR-13	ADA
103679	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Restroom - Girls RR-4, Boys RR-1, Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103680	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Restroom - Girls RR-6, Girls RR-17, Girls RR-12	ADA
103681	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom - Boys RR-5, Girls RR-6, Boys RR-18, Girls RR-17, Girls RR-12, Boys RR-11	ADA
103682	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom - Girls RR-4, Boys RR-1, Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103703	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom - Boys RR-5, Girls RR-17, Girls RR-12, Boys RR-11	ADA
103732	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom - Boys RR-25, Girls RR-23, Girls RR-20, Boys RR-19	ADA
103759	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom - Staff RR-7, Staff RR-8, Staff RR-15, Staff RR-16, Staff RR-21, Staff RR-22, Staff RR-26, Staff RR-27, Staff RR-24, Staff RR-28, Staff RR-29	ADA
103791	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom - Staff RR-7	ADA
103792	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Restroom Staff Men's RR-2	ADA
103796	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom - Staff RR-10, Staff Men's RR-2, Staff Women's RR-3, Staff RR-7, Staff RR-8	ADA
103819	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Restroom - Staff Men's RR-2	ADA
103820	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Restroom - Staff RR-15, Staff RR-16	ADA
103821	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Restroom - Staff RR-29	ADA
103822	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom Boys RR-14, Girls RR-13	ADA
103823	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom - Staff RR-15, Staff RR-16, Staff RR-22, Staff RR-21, Staff RR-26, Staff RR-27, Staff RR-28, Staff RR-29	ADA
103824	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom Girls RR-25	ADA
103825	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom Boys RR-5, Girls RR-6, Boys RR-18, Girls RR-17, Girls RR-12, Boys RR-11	ADA
103826	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom - Girls RR-6, Girls RR-12, Boys RR-11	ADA
103827	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom - Staff RR-7, Staff RR-8	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
103828	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom - Staff RR-7, Staff RR-8	ADA
103829	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom - Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103830	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom - Girls RR-25, Boys RR-23, Girls RR-20, Boys RR-19	ADA
103831	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not compliant.	Girls Locker Room, Boys Locker Room	ADA
103832	Earle B Wood Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not compliant.	Restroom - Staff RR-9, Staff Men's RR-2, Staff Women's RR-3	ADA
103833	Earle B Wood Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls Locker Room, Boys Locker Room	ADA
103834	Earle B Wood Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls Locker Room, Boys Locker Room	ADA
103835	Earle B Wood Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Restroom - Staff Men's RR-2, Staff Women's RR-3, Building Services in Room 311A and Room without sign	ADA
103836	Earle B Wood Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Restroom - Staff Men's RR-2, Staff Women's RR-3, Building Services in Room 311A and Room without sign	ADA
103837	Earle B Wood Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain - DF-1, DF-2, DF-6, DF-7, DF-12, DF-11	ADA
103838	Earle B Wood Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain - DF-7	ADA