



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Rockville High School
2100 Baltimore Road
Rockville, Maryland 20851

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-147.303

Date of Report:

October 28, 2019

On Site Date:

May 16-18, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Rockville High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Rockville High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

ROCKVILLE HIGH SCHOOL- TITLE II ADA COMPLIANCE ASSESSMENT - ACCESSIBILITY SUMMARY

Facility/Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Rockville High School	110	34	68	6		218
Grand Total	110	34	68	6		218

Order of magnitude costs to address those elements are described individually in Appendix A.

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107492	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 1	ADA
107493	Rockville High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 1	ADA
107494	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Concrete plaza east of Door 1	ADA
107495	Rockville High School	EXTERIOR	Exterior Access Route	Raised Island/Cut-through median	1	The cut-through at the raised island has a running slope greater than 1:20 (5%) and cross slope greater than 1:48 (2.08%).	Adjacent to P1A	ADA
107496	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 2	ADA
107498	Rockville High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 4	ADA
107504	Rockville High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 6	ADA
107505	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from south pedestrian entrance to CR 2	ADA
107506	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between CR1 and CR2	ADA
107508	Rockville High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 2	ADA
107509	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete plaza between Door 1 and Bus Drop Off	ADA
107510	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete sidewalk from north pedestrian entrance to CR3	ADA
107511	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp surface has vertical height changes greater than 1/4" that are not ramped.	Curb Ramp 3	ADA
107512	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 4	ADA
107513	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp surface has vertical height changes greater than 1/4" that are not ramped.	Curb Ramp 4	ADA
107514	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Curb Ramp 4 and Curb Ramp 5	ADA
107516	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 8	ADA
107517	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 8	ADA
107518	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 5	ADA
107519	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Curb Ramp 5 and Curb Ramp 6	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107520	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 6	ADA
107521	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk at Bus Drop Off	ADA
107522	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk along Bus Drop Off	ADA
107523	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 7	ADA
107524	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk between Student Drop Off and Curb Ramp 8	ADA
107525	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Student Drop Off and Curb Ramp 8	ADA
107527	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 9	ADA
107528	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Stadium Ticket Counters	ADA
107530	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 10	ADA
107531	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Parking Lot 2 and Stadium seating	ADA
107534	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	Sidewalk between Parking Lot 2 and Stadium seating	ADA
107535	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp 11	ADA
107536	Rockville High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 11	ADA
107538	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk between Stair 11 and Door 16	ADA
107539	Rockville High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 11	ADA
107540	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete sidewalk east side of Parking Lot 2	ADA
107541	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 9	ADA
107542	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 9	ADA
107543	Rockville High School	EXTERIOR	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Courts	ADA
107545	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 2	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107546	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 10	ADA
107547	Rockville High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 11	ADA
107548	Rockville High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair 12	ADA
107549	Rockville High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off areas	ADA
107550	Rockville High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 1	ADA
109247	Rockville High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp 9	ADA
107491	Rockville High School	EXTERIOR	Exterior Access Route	Raised Island/Cut-through median	1	The cut-through at the raised island has a running slope greater than 1:20 (5%) and cross slope greater than 1:48 (2.08%).	Adjacent to P1B-P1G	ADA
106142	Rockville High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	First Floor: Stair 7	ADA
106144	Rockville High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountains	ADA
106148	Rockville High School	INTERIOR	Interior Access Route	Elevator	1	The re-opening device is not compliant.	Elevator 1	ADA
106150	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 1	ADA
106151	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2	ADA
106152	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 3	ADA
106153	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	The rear of the stairs is open.	Stair 3	ADA
106154	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 4	ADA
106156	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 5	ADA
106157	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Stair 6	ADA
106158	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 8	ADA
106159	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 9	ADA
106160	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 10	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106167	Rockville High School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	1071 Women's Dressing Room, 1073 Men's Dressing Room	ADA
106168	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp 3, Ramp 4	ADA
106169	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp 3, Ramp 4	ADA
106170	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp 1, Ramp 2	ADA
106293	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Room 1001	ADA
106580	Rockville High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Room 1070	ADA
106584	Rockville High School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Room 3023	ADA
106592	Rockville High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Room 3014	ADA
106600	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Room 2067	ADA
106619	Rockville High School	INTERIOR	Interior Access Route	Vertical Clearance	1	Objects along the interior accessible route suspend from the ceilings lower than 80" AFF.	TV Studio Room 2000	ADA
106626	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp 5	ADA
106627	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp 5	ADA
106628	Rockville High School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Gymnasium 1097	ADA
106629	Rockville High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Gymnasium 1097	ADA
107591	Rockville High School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Interior doors throughout	ADA
106065	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1A	State of Maryland
106068	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: P1A	ADA
106069	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: P1A	ADA
106070	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1D, P1G	State of Maryland
106071	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1E	State of Maryland



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106072	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1: P1B-P1C	State of Maryland
106073	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 1: P1B-P1C and P1F-P1G	State of Maryland
106076	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The van parking stall is less than 96" wide minimum.	Parking Lot 1: P1E	ADA
106077	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: P1B	ADA
106078	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: P1B-P1C	State of Maryland
106079	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: P1C	ADA
106081	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: P1D	ADA
106082	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: P1D-P1E	State of Maryland
106083	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: P1E	ADA
106084	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: P1F	ADA
106088	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: P1F-P1G	State of Maryland
106094	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: P1G	ADA
106097	Rockville High School	PARKING LOTS	Accessible Parking	Parking Spaces-General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot 2	State of Maryland
106099	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2	State of Maryland
106100	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 2	ADA
106101	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2	State of Maryland
106102	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 2	State of Maryland
106103	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2	State of Maryland
106104	Rockville High School	PARKING LOTS	Accessible Parking	Parking Spaces-General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot 3	State of Maryland
106105	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3	State of Maryland



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106107	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 3	ADA
106108	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: P3A	State of Maryland
106109	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: P3B	State of Maryland
106110	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 3: P3A-B	State of Maryland
106112	Rockville High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 3: P3A-B	State of Maryland
107467	Rockville High School	STADIUM	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk adjacent to restroom entrance	ADA
107470	Rockville High School	STADIUM	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Plaza	ADA
107473	Rockville High School	STADIUM	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete walk between entrance gates and ramp	ADA
107484	Rockville High School	STADIUM	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 6	ADA
107486	Rockville High School	STADIUM	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 7	ADA
107499	Rockville High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 1	ADA
107500	Rockville High School	EXTERIOR	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	Playground 1	ADA
107502	Rockville High School	EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 1	ADA
107503	Rockville High School	EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 1	ADA
107544	Rockville High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
107551	Rockville High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Baseball Field 1	ADA
106126	Rockville High School	EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Courtyard	ADA
106127	Rockville High School	EXTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Courtyard	ADA
106147	Rockville High School	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic	Elevator 1, Elevator 2, Elevator 3	ADA
106161	Rockville High School	INTERIOR	Interior Access Route	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	1071 Women's Dressing Room, 1073 Men's Dressing Room	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106162	Rockville High School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	1073 Men's Dressing Room	ADA
106186	Rockville High School	INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 30", where a forward approach is present.	Main Office	ADA
106285	Rockville High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Rooms 1039, 1023, 2063	ADA
106286	Rockville High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Rooms 1015, 1017, 1021, 1027, 1033, 2030, 2033, 2051, 2053, 2093, 2094, 2103, 2105, 2115	ADA
106288	Rockville High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Room 1033	ADA
106289	Rockville High School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Rooms 1015, 1011A, 1095, 1095C	ADA
106290	Rockville High School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 1013	ADA
106292	Rockville High School	INTERIOR	Common Areas	Laundry- Washer	2	The height of the washing machine is greater than 36" to the top of the unit.	Room 1024	ADA
106295	Rockville High School	INTERIOR	Common Areas	Laundry- Dryer	2	The dryer controls are not within reach range.	Room 1080	ADA
106296	Rockville High School	INTERIOR	Interior Access Route	Shelving	2	The height of the shelving is not within reach range.	Room 1080	ADA
106579	Rockville High School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Room 1080	ADA
106587	Rockville High School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Room 3019	ADA
106588	Rockville High School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Room 3011	ADA
106590	Rockville High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Room 3003	ADA
106601	Rockville High School	INTERIOR	Interior Access Route	Reach Range	2	Operable parts or items requiring an obstructed forward reach motion are higher than 48" maximum height where the depth of the obstruction is 20" maximum, or greater than 44" maximum height where the depth of the obstruction is 20" to 25" maximum, or lower than minimum 15" height above finish floor.	Room 2081	ADA
106603	Rockville High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Room 2020	ADA
106605	Rockville High School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Room 2020	ADA
106621	Rockville High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Dining Room 1050	ADA
106622	Rockville High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria	ADA
106623	Rockville High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridor between Gymnasium and Cafeteria	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106624	Rockville High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridor between Gymnasium and Room 1096	ADA
106625	Rockville High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridor between Auditorium and 1067	ADA
107578	Rockville High School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Boys 1, Girls 2, Boys 3, Girls 4, Boys 5, Girls 6, Boys 7, Girls 8, Boys 9, Girls 10, Boys 11, Girls 12, Boys 15, Girls 16, Boys 17, Girls 18	ADA
107481	Rockville High School	STADIUM	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Stadium gates	ADA
106149	Rockville High School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator 3	ADA
106763	Rockville High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 1105 Coaches' Office	ADA
106766	Rockville High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Boys Locker Room, Girls Locker Room, 1101 B, 1101 C, 2125 C, 2125F	ADA
109267	Rockville High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 1105, 2129 Coaches' Office	ADA
109268	Rockville High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	1101 B, 1101 C, 2125 C, 2125F	ADA
106163	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	1071B Men's Dressing Restroom, 1073B Women's Dressing Restroom	ADA
106164	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	1071B Men's Dressing Restroom, 1073B Women's Dressing Restroom	ADA
106165	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	1071B Men's Dressing Restroom, 1073B Women's Dressing Restroom	ADA
106166	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	1071B Men's Dressing Restroom, 1073B Women's Dressing Restroom	ADA
106171	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Suite Student Restroom	ADA
106172	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Health Suite Student Restroom	ADA
106173	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Health Suite Student Restroom	ADA
106174	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Suite Student Restroom	ADA
107557	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 1, Staff Restroom 2, Staff Restroom 3, Staff Restroom 4, Staff Restroom 5, Staff Restroom 6, Staff Restroom 7, Staff Restroom 9	ADA
107558	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 1, Staff Restroom 2, Staff Restroom 3, Staff Restroom 4, Staff Restroom 5, Staff Restroom 6, Staff Restroom 7, Staff Restroom 9	ADA
107559	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom 1, Staff Restroom 2, Staff Restroom 3, Staff Restroom 4, Staff Restroom 5, Staff Restroom 6, Staff Restroom 7, Staff Restroom 8, Staff Restroom 9	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107560	Rockville High School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	1055C	ADA
107561	Rockville High School	RESTROOMS	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	1055C	ADA
107562	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	1055D, 1060A, Staff Restroom 3, Staff Restroom LFI, Staff Restroom 4, Staff Restroom 5, Staff Restroom 6, Staff Restroom 7, Staff Restroom 9	ADA
107563	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	1055D, 1060A	ADA
107564	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	1055D, 1060A	ADA
107565	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	1055D, 1060A	ADA
107566	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The shower enclosure is not 30" minimum by 60" minimum.	1060A	ADA
107567	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	1060A	ADA
107568	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	1060A	ADA
107569	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 3	ADA
107570	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Staff Restroom 3, Staff Restroom 9	ADA
107572	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Staff Restroom LFI	ADA
107573	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom LFI	ADA
107574	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Staff Restroom 4	ADA
107575	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 8	ADA
107576	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 8	ADA
107577	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 8	ADA
106175	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Health Suite Student Restroom	ADA
106176	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Suite Staff Restroom, 1003 Staff Restroom	ADA
106177	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Health Suite Staff Restroom	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106178	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Health Suite Staff Restroom, 1003 Staff Restroom	ADA
106179	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Suite: Staff Restroom, 1003 Staff Restroom	ADA
106180	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Health Suite Staff Restroom, 1003 Staff Restroom	ADA
106182	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Health Suite Staff Restroom, 1003 Staff Restroom	ADA
106294	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall in a multi-stall restroom used primarily by children (ages 3-12) does not have the required dimensions.	Room 1280 training restroom	ADA
106774	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Boys Locker Room, Girls Locker Room	ADA
106775	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Locker Room	ADA
107579	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys 1, Boys 3, Boys 5, Boys 7, Boys 9, Boys 11, Boys 15, Boys 17	ADA
107580	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Boys 1, Girls 2, Boys 3, Girls 4, Boys 5, Girls 6, Boys 7, Girls 8, Boys 9, Girls 10, Boys 11, Girls 12, Boys 15, Boys 17, Gils 18	ADA
107581	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys 1, Boys 9, Boys 15, Girls 16, Boys 17, Girls 18	ADA
107582	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys 1, Girls 2, Boys 3, Girls 4, Boys 5, Girls 6, Boys 7, Girls 8, Boys 9, Girls 10, Boys 11, Girls 12, Boys 13, Girls 14, Boys 15, Girls 16, Boys 17, Girls 18	ADA
107583	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Boys 1, Boys 3, Boys 5, Boys 7, Boys 9, Boys 11, Boys 13, Boys 15, Boys 17	ADA
107584	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys 1, Girls 2, Boys 3, Girls 4, Boys 5, Girls 6, Boys 7, Girls 8, Boys 9, Girls 10, Boys 11, Girls 12, Boys 13, Girls 14, Boys 15, Girls 16, Boys 17, Girls 18	ADA
107585	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bars are not compliant in the ambulatory stall.	Girls 2	ADA
107586	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Girls 2	ADA
107587	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls 2, Boys 3, Girls 4, Boys 5, Boys 7, Girls 8, Girls 10, Girls 12, Boys 13	ADA
107588	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Girls 4, Boys 5, Girls 6, Boys 7, Girls 8, Girls 10, Girls 12, Boys 15, Girls 16, Boys 17	ADA
107589	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys 5, Girls 6, Boys 9, Boys 13, Girls 14, Boys 15, Girls 16, Boys 17	ADA
107590	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys 7, Boys 13	ADA
107592	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Boys 13	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107593	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height	Boys 13, Girls 14	ADA
106776	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Locker Room	ADA
106777	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The shower enclosure is not 30" minimum by 60" minimum.	Girls Locker Room	ADA
106779	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	Girls Locker Room	ADA
107555	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restrooms throughout	ADA
107556	Rockville High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 1, Staff Restroom 5, Staff Restroom 7, Staff Restroom 9	ADA
107452	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Men's Restroom, Women's Restroom	ADA
107454	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Men's Restroom	ADA
107456	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's Restroom, Women's Restroom	ADA
107458	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Men's Restroom, Women's Restroom	ADA
107460	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Men's Restroom, Women's Restroom	ADA
107463	Rockville High School	STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Men's Restroom, Women's Restroom	ADA
106131	Rockville High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	First Floor Drinking Fountains: DF2, DF3 and DF6	ADA
106135	Rockville High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	First Floor Drinking Fountains: DF5	ADA
106136	Rockville High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Second Floor Drinking Fountains: DF10, DF11	ADA
106139	Rockville High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Third Floor Drinking Fountain DF13	ADA
106291	Rockville High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Room 1013	ADA
109261	Rockville High School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	Room 2081	ADA

