



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Thomas S. Wootton High School
2100 Wootton Parkway
Rockville, Maryland 20850

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-186.303

Date of Report:

October 28, 2019

On Site Date:

October 22-25, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity’s programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the “2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design.” The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Thomas S. Wootton High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Thomas S. Wootton High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG’s assessment of the subject property identified the following areas of concern:

THOMAS S. WOOTTON HIGH SCHOOL - TITLE II ADA COMPLIANCE ASSESSMENT - ACCESSIBILITY SUMMARY

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Thomas S Wootton	215	50	58	9	48	380
Grand Total	215	50	58	9	48	380

Order of magnitude costs to address those elements are described individually in Appendix A.

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145500	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Tennis Courts	ADA
145502	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Gate	1	The gate does not have the required maneuvering clearances.	Tennis Courts	ADA
145531	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	From stands to restrooms at football field	ADA
145477	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	1	A compliant accessible route is not provided.	Baseball field	ADA
145478	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Baseball field	ADA
145479	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	1	The accessible route has gaps in the surface greater than 1/2" wide.	Baseball field	ADA
145480	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Baseball field	ADA
145532	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	At track	ADA
145534	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Concession stand at football field	ADA
145535	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	1	The push side of the accessible door does not have the required maneuvering clearances.	Concession stand at football field	ADA
145538	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	1	The ramp run rises 6" or greater but has no handrails.	Concession stand at football field	ADA
145539	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	Football field	ADA
145574	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	1	The ramp does not have a level landing at the top and/or bottom of each run.	Concession stand at football field	ADA
145482	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Gate	1	The gate does not have the required maneuvering clearances.	Baseball field	ADA
145208	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-12	ADA
145209	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-12	ADA
145210	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-12	ADA
145411	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-1	ADA
145412	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp CR-1	ADA
145413	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-2	ADA
145414	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-2	ADA
145415	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR-2	ADA
145416	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp CR-2	ADA
145417	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	From curb ramp CR-1 to curb ramp CR-2	ADA
145418	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	From curb ramp CR-2 to curb ramp CR-3	ADA
145419	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	From curb ramp CR-2 to curb ramp CR-3	ADA
145420	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	From curb ramp CR-2 to curb ramp CR-3	ADA
145421	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	From front sidewalk to door D-25	ADA
145422	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp CR-3	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145423	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp CR-3 to stair ST-2	ADA
145424	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	From front sidewalk to door D-1	ADA
145425	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	From Stair ST-12 to stair ST-14	ADA
145426	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-6	ADA
145427	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The rise of the ramp run exceeds 30".	Ramp R-6	ADA
145428	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-6	ADA
145429	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	From front of building down the left side	ADA
145430	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-4	ADA
145431	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-5	ADA
145211	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-12	ADA
145213	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-13	ADA
145214	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-13	ADA
145216	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-14	ADA
145217	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-14	ADA
145218	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-14	ADA
145220	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-15	ADA
145221	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-15	ADA
145223	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-1	ADA
145224	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-1	ADA
145432	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp CR-5 to curb ramp CR-6	ADA
145433	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Curb ramp CR-5 to curb ramp CR-6	ADA
145434	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Curb ramp CR-5 to curb ramp CR-6	ADA
145435	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	From sidewalk to door D-9	ADA
145436	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	From sidewalk to door D-9	ADA
145437	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-6	ADA
145438	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-6	ADA
145439	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp CR-6 to curb ramp CR-7	ADA
145440	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-7	ADA
145441	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-7	ADA
145442	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp R-7 to stair ST-16	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145443	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-8	ADA
145444	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-8	ADA
145445	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stair ST-18 to Stair ST-19	ADA
145446	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Door D-17 to Ramp R-6	ADA
145447	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-7	ADA
145448	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp R-7	ADA
145449	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-7	ADA
145450	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-8	ADA
145451	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-8	ADA
145452	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has openings in the surface greater than 1/2".	Ramp R-8	ADA
145453	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-8	ADA
145454	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-9	ADA
145455	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-9	ADA
145456	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has openings in the surface greater than 1/2".	Ramp R-9	ADA
145457	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-9	ADA
145225	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-3	ADA
145226	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-16	ADA
145227	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Stair ST-16	ADA
145229	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-17	ADA
145230	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-17	ADA
145238	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-11	ADA
145458	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp R-10	ADA
145459	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-10	ADA
145460	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-11, R-12, R-13	ADA
145461	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-14	ADA
145462	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-14	ADA
145463	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-13	ADA
145464	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Turn from rear sidewalk to door D-21	ADA
145465	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Turn from rear sidewalk to door D-21	ADA
145466	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Turn from rear side walk to door D-21	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145467	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R-15	ADA
145468	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-15	ADA
145469	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-16	ADA
145470	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-16	ADA
145240	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-14	ADA
145241	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-2	ADA
145242	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp R-2	ADA
145243	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp R-2	ADA
145244	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Handrails are not continuous or are not at a continuous height above the ramp surface.	Ramp R-2	ADA
145245	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-2	ADA
145246	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Ramp R-2	ADA
145247	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has openings in the surface greater than 1/2".	Ramp R-2	ADA
145248	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-18	ADA
145249	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-18	ADA
145251	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-19	ADA
145252	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-19	ADA
145471	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-17	ADA
145472	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-17	ADA
145473	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-18	ADA
145474	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-18	ADA
145483	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp R-19	ADA
145484	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-19	ADA
145486	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	1st Turn from parking lot A toward front of building	ADA
145487	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	1st turn parking lot A to 2nd turn toward front of building	ADA
145488	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	2nd Turn from parking lot A toward front of building	ADA
145489	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	3rd Turn from parking lot A toward front of building	ADA
145491	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp R-20	ADA
145492	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-20	ADA
145493	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-20	ADA
145254	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-15	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145255	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-3	ADA
145256	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-3	ADA
145257	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	Handrails are not continuous or are not at a continuous height above the ramp surface.	Ramp R-3	ADA
145258	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-20	ADA
145259	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair ST-20	ADA
145280	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Door D-1 thru D-27	ADA
145303	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-17	ADA
145304	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-18	ADA
145305	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-20	ADA
145307	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-21	ADA
145308	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-21	ADA
145309	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-21	ADA
145312	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-22	ADA
145313	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-22	ADA
145314	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-23	ADA
145315	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-23	ADA
145320	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-24	ADA
145321	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-24	ADA
145322	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-24	ADA
145323	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-23	ADA
145403	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-4	ADA
145404	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp R-4	ADA
145405	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-4 and R-5	ADA
145406	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-5	ADA
145407	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-5	ADA
145408	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-4	ADA
145409	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-5	ADA
145410	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-1	ADA
145494	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-9	ADA
145495	Thomas S Wootton	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-10	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145496	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The rise of the ramp run exceeds 30".	Ramp R-21	ADA
145497	Thomas S Wootton	EXTERIOR	Exterior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-21	ADA
145498	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Door D-24 to stair ST-24	ADA
145510	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route does not have 80" vertical clearance.	Courtyard at cafeteria	ADA
145511	Thomas S Wootton	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Courtyard at cafeteria	ADA
145523	Thomas S Wootton	EXTERIOR	Football Field	Exterior Accessible Route	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-25, ST-26	ADA
145260	Thomas S Wootton	INTERIOR	Interior Access Route	Interior Access Route	1	Clear widths are less than 36" minimum, including protruding objects.	Cafeteria	ADA
145546	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-1, ST-2, ST-3, ST-4, ST-5, ST-6, ST-7, ST-8, ST-9 ST-28, ST-29	ADA
145571	Thomas S Wootton	INTERIOR	Interior Access Route	Vertical Level Change	1	In areas along the interior route there are level changes between ¼" and ½".	Girls Locker Room, boys Locker Room	ADA
146074	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-31, ST-36	ADA
146076	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-32, ST-35	ADA
146078	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-32, ST-35	ADA
145281	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Throughout building	ADA
145282	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Throughout building	ADA
145283	Thomas S Wootton	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Throughout building	ADA
145292	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Throughout building	ADA
145293	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Throughout building	ADA
145300	Thomas S Wootton	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Room 30	ADA
145325	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Throughout building	ADA
145326	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 112	ADA
145328	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Throughout building	ADA
145338	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Room 123	ADA
145339	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Room 123	ADA
145340	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Room 124	ADA
145341	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Room 124	ADA
145342	Thomas S Wootton	INTERIOR	Interior Access Route	Ramp	1	A ramp is required but not provided.	Room 123 and 124	ADA
145343	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Room 123 and 124	ADA
145354	Thomas S Wootton	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Throughout building	ADA
145355	Thomas S Wootton	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Throughout building	ADA
145357	Thomas S Wootton	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-3, DF-5, DF-6, DF-12	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145540	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-30 (At room 24 dance)	ADA
145541	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-30 (At room 24 dance)	ADA
145545	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1, ST-2, ST-3, ST-4, ST-5, ST-6, ST-7, ST-8, ST-9 ST-28, ST-29	ADA
146079	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-33, ST-34	ADA
146080	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-33, ST-34	ADA
146081	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-10, T-11	ADA
146150	Thomas S Wootton	INTERIOR	Interior Access Route	Ramp	1	The rise of the ramp run exceeds 30".	Ramp R-22	ADA
145485	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Spaces-General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot A (staff)	State of Maryland
145490	Thomas S Wootton	PARKING LOT	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Parking lot A 2nd turn to 3rd turn	ADA
145503	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot B (in front of school)	State of Maryland
145504	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle is less than 60" wide.	Parking Lot B Space P1-A and B (in front of school)	ADA
145505	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle is less than 60" wide.	Parking Lot B Space P1-C and D (in front of school)	ADA
145506	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot B Space P1-A	ADA
145507	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot B Space P1-A (in front of school)	ADA
145508	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot B Space P1-B (in front of school)	ADA
145509	Thomas S Wootton	PARKING LOT	Accessible Parking	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Parking Lot B from accessible spaces to building	ADA
145512	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot C Space P1-C (front student)	State of Maryland
145513	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle is less than 60" wide.	Parking Lot C Space P1-C (front student)	ADA
145514	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot C Space P1-A (front student)	ADA
145515	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot C Space P1-A and B (front student)	ADA
145516	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot C Space P1-B (front student)	ADA
145517	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot C Space P1-C (front student)	ADA
145518	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot D (rear student)	State of Maryland
145519	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot D Space P1-A (rear student)	ADA
145520	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot D Space P1-A and B (rear student)	ADA
145521	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot D Space P1-B (rear student)	ADA
145522	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space - Car	1	Openings in ground surfaces are greater than 1/2" wide.	Parking Lot D Space P1-B (rear student)	ADA
145568	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot B (in front of school)	State of Maryland
145569	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Spaces-General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot C (front student)	State of Maryland
145570	Thomas S Wootton	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot D (rear student)	State of Maryland



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145367	Thomas S Wootton	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom RRG-1, RRG-2, RRB-2, RRB-3, RRG-3, RRG-4, RRB-4, RRG-5, RRB-5, RRG-6, RRB-6, RRG-7, RRB-7, RRG-8, RRG-9, RRB-9, RRG-10, RRB-10	ADA
145379	Thomas S Wootton	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom in Room 174	ADA
145390	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	1	The space between two doors in a series is less than 48" clear with doors open 90 degrees.	Restroom RRG-2, RRB-2	ADA
145401	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Floor Space	1	The interior accessible route has less than 36" clear width.	Restroom RRG-3	ADA
145402	Thomas S Wootton	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom RRB-3, RRG-3	ADA
145525	Thomas S Wootton	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom Men's and Women's at Football Stadium	ADA
145499	Thomas S Wootton	ATHLETIC FIELDS	Tennis Courts	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Tennis Courts	ADA
145501	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Tennis Courts	ADA
145475	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball field	ADA
145476	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball field	ADA
145533	Thomas S Wootton	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Football field	ADA
145536	Thomas S Wootton	ATHLETIC FIELDS	Football Field	Exterior Accessible Route	2	The bottom of the entry door vision light is higher than 43" maximum.	Concession stand at football field	ADA
145537	Thomas S Wootton	ATHLETIC FIELDS	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Concession stand at football field	ADA
145481	Thomas S Wootton	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Baseball field	ADA
145212	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-12	ADA
145215	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-13	ADA
145219	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-14	ADA
145222	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-15	ADA
145228	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-16	ADA
145231	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-17	ADA
145235	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Door D-9, D-12, D-13, D-15	ADA
145250	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-18	ADA
145253	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-19	ADA
145316	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-20	ADA
145317	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-21	ADA
145318	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-23	ADA
145319	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-22	ADA
145324	Thomas S Wootton	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-24	ADA
145261	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Cafeteria	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145278	Thomas S Wootton	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
145279	Thomas S Wootton	INTERIOR	Common Areas	Controls And Dispensers	2	The vending machines have operable parts which are not within reach range.	Cafeteria	ADA
145564	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Hallway	ADA
145575	Thomas S Wootton	INTERIOR	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Auditorium	ADA
145576	Thomas S Wootton	INTERIOR	Common Areas	Assembly Area	2	Assembly areas do not provide wheelchair spaces.	Auditorium	ADA
145577	Thomas S Wootton	INTERIOR	Common Areas	Assembly Area	2	Assembly areas do not provide compliant aisle seats.	Auditorium	ADA
145284	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	The sink used primarily by children aged 6 to 12 has over 31" max. ht. rim. OR does not have knee clearance of 24" min. above finished floor (parallel approach permitted for children aged 5 and younger).	Room 42	ADA
145288	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	The accessible sink does not have push/lever hardware.	Throughout building	ADA
145289	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	Sinks do not have knee and/or toe clearance.	Throughout Building	ADA
145290	Thomas S Wootton	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Room 42	ADA
145294	Thomas S Wootton	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Room 42	ADA
145299	Thomas S Wootton	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Throughout building	ADA
145301	Thomas S Wootton	INTERIOR	Common Areas	Locker Rooms	2	The locker room does not have accessible lockers.	Hallways	ADA
145302	Thomas S Wootton	INTERIOR	Common Areas	Locker Rooms	2	The hardware at the accessible door requires tight grasping, pinching or twisting of the wrist to operate	Hallway lockers	ADA
145327	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout building	ADA
145329	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Throughout building	ADA
145330	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 109, 118	ADA
145331	Thomas S Wootton	INTERIOR	Interior Access Route	Interior Access Route	2	The work surface is not compliant.	Room 111,110	ADA
145335	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	The height of the washing machine is greater than 36" to the top of the unit.	Room 106	ADA
145336	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	2	The height of the dryer is greater than 36" to the top of the unit.	Room 106	ADA
145344	Thomas S Wootton	INTERIOR	Basketball Court	Bleacher Seating	2	A wheelchair space is not provided or is not compliant at the bleacher seating.	Main gym	ADA
145356	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	Sinks do not have knee and/or toe clearance.	Room 42, 43	ADA
145387	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	Room 186	ADA
145388	Thomas S Wootton	INTERIOR	Interior Access Route	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Room 186, 187, 188, 189	ADA
145542	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-30 (At room 24 dance)	ADA
145543	Thomas S Wootton	INTERIOR	Interior Access Route	Elevator	2	The hoistway signage is not compliant.	Elevator E-1	ADA
145544	Thomas S Wootton	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic.	Elevator E-1, E-2	ADA
145239	Thomas S Wootton	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Trash Cans by Doors D-12 and D-13	ADA
145548	Thomas S Wootton	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls locker room,boys locker room	ADA
145549	Thomas S Wootton	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls locker room,boys locker room	ADA
145578	Thomas S Wootton	INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Auditorium	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145334	Thomas S Wootton	INTERIOR	Interior Access Route	Interior Access Route	3	The bottom shelf of the upper cabinets mounted above work counters are higher than 48".	Room 106	UFAS
146151	Thomas S Wootton	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	Stairs and Exterior Doors	ADA
145565	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Healthroom Restroom 1	ADA
145566	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Healthroom Restroom 2	ADA
145567	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Healthroom Restroom 2	ADA
145580	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRG-5	ADA
145581	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom Staff Men's RRSM-5	ADA
146060	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Ambulatory Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Restroom RRB-11	ADA
146061	Thomas S Wootton	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Restroom RRG-11, RRB-11	ADA
146062	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom RRB-11	ADA
146063	Thomas S Wootton	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom RRG-11, RRB-11	ADA
146064	Thomas S Wootton	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom RRB-11	ADA
145295	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom in Room 42	ADA
145296	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom in Room 42	ADA
145297	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom in Room 42	ADA
145298	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom in Room 42	ADA
145358	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom RRG-1, RRB-1, RRG-4, RRB-4, RRG-5, RRB-5	ADA
145359	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	Pipes are not insulated.	Restroom RRG-1, RRG-2, RRB-2, RRB-3, RRG-3, RRG-4, RRB-4, RRB-5	ADA
145360	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Restroom RRG-1, RRG-2, RRB-2	ADA
145361	Thomas S Wootton	RESTROOMS	Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	Restroom RRG-1	ADA
145362	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The wheelchair stall door is not self closing.	Restroom RRG-1, RRB-1, RRG-2, RRB-2, RRG-5, RRG-6, RRB-6, RRG-7, RRB-7, RRG-8, RRG-10, RRB-10	ADA
145363	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom RRG-1, RRB-1, RRG-2, RRB-2, RRG-4, RRG-5, RRB-5, RRG-6, RRB-6, RRG-7, RRB-7, RRG-8, RRG-10, RRB-10	ADA
145364	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom RRG-1, RRB-1	ADA
145365	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RRG-1, RRB-1, RRB-2, RRG-4, RRG-5, RRG-6, RRG-7, RRG-8, RRB-8, RRG-10, RRB-10	ADA
145366	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The toilet paper dispenser location is not compliant.	Restroom RRG-1, RRB-7	ADA
145368	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Restroom RRG-1, RRB-1	ADA
145369	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The toilet paper dispenser location is not compliant.	Restroom RRB-1, RRB-2, RRG-4, RRB-5, RRB-6, RRB-8, RRG-9, RRB-9	ADA
145373	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom in Room 174	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145374	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The grab bars at the water closet are not compliant.	Restroom in Room 174	ADA
145375	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	3	The transfer shower is not compliant.	Restroom in Room 174	ADA
145376	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The toilet paper dispenser location is not compliant.	Restroom in Room 174	ADA
145377	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom in Room 174	ADA
145378	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom in Room 174	ADA
145391	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom RRG-2, RRB-2, RRB-3, RRG-3, RRG-4, RRB-5, RRG-9, RRB-9	ADA
145392	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom RRG-2, RRB-2, RRB-3, RRG-3, RRG-4, RRG-5, RRB-5, RRG-6, RRB-6, RRG-7, RRB-7, RRG-8, RRB-8, RRG-9, RRB-9, RRG-10, RRB-10, RRG-11, RRB-11	ADA
145393	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom RRG-2, RRB-2, RRB-3, RRG-3, RRG-4, RRG-5, RRB-5	ADA
145394	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom RRG-2, RRB-2, RRG-5, RRB-5, RRG-6, RRB-6, RRG-7, RRB-7, RRG-9, RRB-9	ADA
145395	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRG-2, RRB-2, RRG-4, RRB-5, RRG-6, RRB-6, RRG-7, RRB-7, RRB-8, RRG-9, RRB-9,	ADA
145396	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Restroom RRG-2, RRB-2, RRB-4	ADA
145397	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Urinal	3	The urinal dimensions are not compliant.	Restroom RRB-2, RRB-4, RRB-10	ADA
145398	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Restroom RRB-3, RRG-3	ADA
145399	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	The side grab bars are not compliant in the ambulatory stall.	Restroom RRB-3, RRG-3	ADA
145400	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	The centerline of the toilet in the ambulatory stall is not 17" minimum to 19" maximum from the sidewall.	Restroom RRB-3, RRG-3	ADA
145524	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom Men's at Football Stadium	ADA
145526	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom Men's at Football Stadium	ADA
145527	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom Men's and Women's at Football Stadium	ADA
145528	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The wheelchair stall door is not self closing.	Restroom Men's at Football Stadium	ADA
145529	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom Men's and Women's at Football Stadium	ADA
145530	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom Men's and Women's at Football Stadium	ADA
145547	Thomas S Wootton	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower does not have sidewalls or grab bars.	Girls locker room,boys locker room	ADA
145551	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom RRG-4, RRB-10	ADA
145552	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom RRG-4	ADA
145553	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom RRG-4	ADA
145554	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Ambulatory Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Restroom RRB-4	ADA
145550	Thomas S Wootton	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Girls locker room,boys locker room	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145285	Thomas S Wootton	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Room 42	ADA
145286	Thomas S Wootton	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	The minimum number and types of drinking fountains are not provided.	Room 42	ADA
145287	Thomas S Wootton	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	A clear space is not positioned at the drinking fountain for a forward approach and centered on the unit.	Room 42	ADA
145291	Thomas S Wootton	INTERIOR	Kitchen	Kitchen-Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Room 42	ADA
145332	Thomas S Wootton	INTERIOR	Interior Access Route	Interior Access Route	4	The location of the controls requires reaching across burners.	Room 106	ADA
145333	Thomas S Wootton	INTERIOR	Interior Access Route	Interior Access Route	4	The oven door is not located adjacent to a minimum 30" wide work surface.	Room 106	ADA
145337	Thomas S Wootton	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-1, DF-2, DF-4, DF-8, DF-13, DF-14, DF-15, DF-16, DF-17	ADA
145389	Thomas S Wootton	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain DF-5, DF-6	ADA
145232	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	5	The bottom of the entry door vision light is higher than 43" maximum.	Door D-5, D-6; D-7	ADA
145233	Thomas S Wootton	EXTERIOR	Exterior Access Route	Reach Range	5	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Door D-6	ADA
145234	Thomas S Wootton	EXTERIOR	Entrance to Building	Building Entrance - Door	5	The maneuvering clearance at the accessible door is not level and clear.	Door D-8	ADA
145262	Thomas S Wootton	INTERIOR	Interior Access Route	Reach Range	5	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Kitchen	ADA
145263	Thomas S Wootton	INTERIOR	Kitchen	Dispenser	5	Controls and/or dispensers are not within reach range.	Kitchen	ADA
146077	Thomas S Wootton	INTERIOR	Interior Access Route	Stairs	5	Handrails are not compliant.	Stair ST-31, ST-36	ADA
145560	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The side grab bar at the water closet is not compliant.	Restroom Staff Women's RRSW-5	ADA
145561	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The toilet paper dispenser location is not compliant.	Restroom Staff Women's RRSW-5	ADA
145562	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The rear grab bar at the water closet is not compliant.	Restroom Staff Women's RRSW-5	ADA
145563	Thomas S Wootton	RESTROOMS	Restroom	Controls And Dispensers	5	The height of controls are not compliant.	Restroom Staff Women's RRSW-5	ADA
145264	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom Staff RRS-5D	ADA
145265	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Mirror	5	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Restroom Staff RRS-5D	ADA
145266	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	Pipes are not insulated.	Restroom Staff RRS-5D	ADA
145267	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	5	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom Staff RRS-5D	ADA
145268	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The grab bars at the water closet are not compliant.	Restroom Staff RRS-5D	ADA
145269	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The toilet paper dispenser location is not compliant.	Restroom Staff RRS-5D	ADA
145270	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom Staff RRS-5D	ADA
145271	Thomas S Wootton	RESTROOMS	Restroom	Controls And Dispensers	5	The height of controls are not compliant.	Restroom Staff RRS-5D	ADA
145272	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom Staff RRS-5D	ADA
145273	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The hardware at the wheelchair stall door is not compliant.	Restroom Staff RRS-5D	ADA
145274	Thomas S Wootton	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	5	The locker room does not have a compliant bench.	Restroom Staff RR-5D	ADA
145275	Thomas S Wootton	RESTROOMS	Employee Work Areas	Locker Rooms	5	The locker room does not have accessible lockers.	Restroom Staff RR-5D	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
145276	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom Staff RRS-5D	ADA
145277	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom Staff RRS-5D	ADA
145345	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-5, RRSW-5, RRS-6	ADA
145346	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The rear grab bar at the water closet is not compliant.	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-3, RRSM-5, RRS-6, RRS-BS9	ADA
145347	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The side grab bar at the water closet is not compliant.	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-3, RRSW-3, RRSM-5, RRSM-5, RRS-BS9	ADA
145348	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-3, RRSW-3, RRSM-5, RRSW-5, RRS-6, RRS-BS9	ADA
145349	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Coat Hook	5	The coat hook is not within an allowable reach range.	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-3, RRSW-3	ADA
145350	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The hardware at the accessible door requires tight grasping, pinching or twisting of the wrist to operate	Restroom Staff Men's and Women's RRSM-2, RRSW-2, RRSM-3, RRSW-3, RRSW-5	ADA
145351	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Restroom Staff Women's RRSW-2	ADA
145352	Thomas S Wootton	RESTROOMS	Restroom	Controls And Dispensers	5	Controls on dispensers are not compliant.	Restroom Staff Women's RRSW-2	ADA
145353	Thomas S Wootton	RESTROOMS	Restroom	Protruding Object	5	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom Staff Women's RRSW-2	ADA
145370	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The toilet paper dispenser location is not compliant.	Restroom Staff Men's and Women's RRSM-3, RRSW-3	ADA
145371	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The rear grab bar at the water closet is not compliant.	Restroom Staff Women's RRSW-3	ADA
145372	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The side grab bar at the water closet is not compliant.	Restroom Staff Women's RRSW-3	ADA
145380	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom Staff Men's and Women's RRSM-4, RRSW-4, RRSM-5	ADA
145381	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Floor Space	5	The interior accessible route has less than 36" clear width.	Restroom Staff Men's and Women's RRSM-4, RRSW-4	ADA
145382	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	5	A wheelchair stall is not provided in a multi-user restroom.	Restroom Staff Men's and Women's RRSM-4, RRSW-4	ADA
145383	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom Staff Men's and Women's RRSM-4, RRSW-4, RRSM-5, RRSW-5, RRS-BS9	ADA
145384	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	Pipes are not insulated.	Restroom Staff Men's and Women's RRSM-4, RRSW-4	ADA
145385	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Signage	5	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom Staff Men's RRSM-4, RRS-6	ADA
145386	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Urinal	5	The urinal dimensions are not compliant.	Restroom Staff Men's RRSM-4, RRSM-5	ADA
145555	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The wheelchair stall door is not self closing.	Restroom Staff RRS-BS9	ADA
145556	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The hardware at the wheelchair stall door is not compliant.	Restroom Staff RRS-BS9	ADA
145557	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	5	The transfer shower is not exactly 36" by 36".	Restroom Staff RRS-BS9	ADA
145558	Thomas S Wootton	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	5	The spray unit does not have a minimum 59" long hose.	Restroom Staff RRS-BS9	ADA
145559	Thomas S Wootton	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	5	Grab bars are not compliant or are not provided in the transfer shower stall.	Restroom Staff RRS-BS9	ADA