



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Walter Johnson High School  
6400 Rock Spring Drive  
Bethesda, Maryland 20814

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**  
123821.17R000-096.303

**Date of Report:**  
October 25, 2019

**On Site Date:**  
June 4-6, 2018



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Walter Johnson High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Walter Johnson High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

**WALTER JOHNSON HIGH SCHOOL- TITLE II ADA COMPLIANCE ASSESSMENT- ACCESSIBILITY SUMMARY**

Facility/Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Walter Johnson High School	106	40	123	10		279
Grand Total	106	40	123	10		279

Order of magnitude costs to address those elements are described individually in Appendix A.

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107702	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Softball Field	ADA
107703	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk south of Softball Field	ADA
107704	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk west of Baseball Field	ADA
107705	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk west of Baseball Field	ADA
107706	Walter Johnson High School	EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	Sidewalk west of Baseball Field	ADA
107708	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Baseball Field	ADA
107709	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Courtyard 1	ADA
107710	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Courtyard 1	ADA
107711	Walter Johnson High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Courtyard 2	ADA
107712	Walter Johnson High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Courtyard 2	ADA
107713	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Courtyard 2	ADA
107717	Walter Johnson High School	EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	Courtyard 2	ADA
107719	Walter Johnson High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Courtyard 3	ADA
107724	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Courtyard 3	ADA
107725	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Courtyard 5	ADA
107727	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Courtyard 5	ADA
107784	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 36	ADA
107785	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 6 adjacent to Door 35	ADA
107787	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk at Bus Drop Off between Door 34 and 35	ADA
107788	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Door 34	ADA
107789	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Door 33	ADA
107805	Walter Johnson High School	EXTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp 7	ADA
107806	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 7	ADA
107808	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 30	ADA
107813	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk connecting Parking Lot 2 and Parking Lot 3	ADA
107814	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is curved and does not have landings at directional turns.	Ramp 8	ADA
107815	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 8	ADA
107816	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk at northwest corner of Building 1	ADA
107831	Walter Johnson High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 16	ADA
107844	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 9 - Tennis Court	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107845	Walter Johnson High School	EXTERIOR	Exterior Access Route	Gate	1	The gate does not have the required maneuvering clearances.	Ramp 9 - Tennis Court	ADA
107848	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 4	ADA
107851	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Stair 17	ADA
107853	Walter Johnson High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off, Auditorium Drop Off	ADA
107854	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Outdoor amphitheater	ADA
107858	Walter Johnson High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Parking Lot 3 and Tennis Courts	ADA
111463	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Ramp 7	ADA
111465	Walter Johnson High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Stair 17	ADA
107731	Walter Johnson High School	INTERIOR	Exterior Access Route	Platform Lift	1	The platform lift is not compliant.	Student Commons	ADA
108178	Walter Johnson High School	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Interior Rooms throughout	ADA
107862	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Stair 11	ADA
107865	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 11	ADA
107866	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 12	ADA
107869	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 3	ADA
107874	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2	ADA
107875	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 2	ADA
107877	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 13	ADA
107878	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 14	ADA
107887	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 5	ADA
107889	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 6	ADA
107891	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 6	ADA
108181	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Dance Studio	ADA
108186	Walter Johnson High School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Second Gym	ADA
108187	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width.	G76 Office	ADA
108190	Walter Johnson High School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Kitchen Staff Locker area, 185 Bldg Services Locker area	ADA
107893	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 7	ADA
107894	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 7	ADA
107895	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	The stairway has less than 80" vertical clearance along the stair flight.	Stair 7	ADA
107896	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 8	ADA
107897	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 8	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107898	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 10	ADA
108022	Walter Johnson High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Boys Locker Room , Girls Locker Room	ADA
108029	Walter Johnson High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Girls Locker Room	ADA
108204	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Backstage stairs	ADA
108205	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Backstage stairs	ADA
108206	Walter Johnson High School	INTERIOR	Interior Access Route	Platform Lift	1	The platform lift is not compliant.	Auditorium Orchestra pit	ADA
108207	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Auditorium Orchestra Pit	ADA
108208	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Auditorium Orchestra pit	ADA
108209	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Auditorium Stage stairs	ADA
108210	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Auditorium Stage stairs	ADA
108211	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Auditorium Stage stairs	ADA
108213	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Backstage stairs to Lower Level	ADA
108216	Walter Johnson High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Classroom 190	ADA
108217	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	A ramp is required but not provided.	Classroom 190	ADA
108218	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Classroom 190	ADA
108221	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	A ramp is required but not provided.	Classroom 191	ADA
108225	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	G77B	ADA
108229	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 224	ADA
108230	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 226	ADA
108231	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 215	ADA
108232	Walter Johnson High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 211, Room 214	ADA
108241	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp 1	ADA
108248	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp 2	ADA
108250	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp 2	ADA
108254	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp 3	ADA
108255	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp 4	ADA
108256	Walter Johnson High School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp 4	ADA
107640	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 1: P1A	ADA
107641	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 1: P1B	ADA
107642	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Parking Lot 1: P1A - P1B	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107643	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Parking Lot 1: P1C - P1D	ADA
107644	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The van parking stall is less than 96" wide minimum.	Parking Lot 3: P3C	ADA
107645	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1	ADA
107646	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 2	ADA
107647	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 3: P3E - P3F	State of Maryland
107648	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 3	ADA
107649	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp 3	ADA
107650	Walter Johnson High School	PARKING LOTS	Exterior Access Route	Curb Ramp	1	The curb ramp surface has vertical height changes greater than 1/4" that are not ramped.	Curb Ramp 3	ADA
107697	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Spaces-General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot 3	State of Maryland
107698	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3	State of Maryland
107699	Walter Johnson High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 3	ADA
107655	Walter Johnson High School	STADIUM	Entrance to Building	Building Entrance-Door	1	The non-fire, automatic accessible door requires more than 5 pounds of pressure to operate.	Stadium restrooms	ADA
107658	Walter Johnson High School	STADIUM	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp 6	ADA
107659	Walter Johnson High School	STADIUM	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk behind stadium bleachers	ADA
107660	Walter Johnson High School	STADIUM	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 6	ADA
107662	Walter Johnson High School	STADIUM	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk at east end of Stadium seating	ADA
107700	Walter Johnson High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
107701	Walter Johnson High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Softball Field	ADA
107707	Walter Johnson High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Baseball Field	ADA
107718	Walter Johnson High School	EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Courtyard 3, Courtyard 5	ADA
107720	Walter Johnson High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Courtyard 3	ADA
107721	Walter Johnson High School	EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Courtyard 3 Playground	ADA
107723	Walter Johnson High School	EXTERIOR	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Courtyard 3 Playground	ADA
107783	Walter Johnson High School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Flag poles	ADA
107809	Walter Johnson High School	EXTERIOR	Site Furnishings	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic area adjacent to Cafeteria and Door 30	ADA
111467	Walter Johnson High School	EXTERIOR	Baseball/Softball Field	Bleacher Seating	2	The wheelchair space is not the minimum required dimensions at the bleacher seating for the baseball field.	Baseball Field	ADA
107732	Walter Johnson High School	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic	Elevator A, Elevator C	ADA
108167	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Health Suite	ADA
108168	Walter Johnson High School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Health Suite	ADA
108176	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Rooms with sidelight vision panel throughout	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108177	Walter Johnson High School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Rooms with sidelight vision panel throughout	ADA
108179	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Corridor fire doors	ADA
108180	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Main Gym, Second Gym, Wrestling Room	ADA
107867	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Stair 3	ADA
107873	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Stair 2	ADA
107880	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Stair 4	ADA
107885	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Stair 5, Stair 6, Stair 7, Stair 8, Stair 10	ADA
108182	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Counseling Services	ADA
108184	Walter Johnson High School	INTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	G03 Food Lab, G27 Workroom	ADA
108185	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	G25 Seminar	ADA
108188	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Student Dining	ADA
108202	Walter Johnson High School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Building exit doors throughout	ADA
108203	Walter Johnson High School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Auditorium, Stage	ADA
108214	Walter Johnson High School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance.	Media Center	ADA
108215	Walter Johnson High School	INTERIOR	Common Areas	Service Counter	2	The service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Media Center	ADA
108219	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Classroom 191	ADA
108220	Walter Johnson High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Classroom 190	ADA
108223	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Vending machines across from Staff Restrooms 1 and 2	ADA
108224	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Lower Level near Stair 08	ADA
108233	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Vending area adjacent to Drinking Fountain 6	ADA
108238	Walter Johnson High School	INTERIOR	Common Areas	Service Counter	2	The service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	School Store 171C	ADA
108252	Walter Johnson High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Vending machines near Ramp 3	ADA
111693	Walter Johnson High School	INTERIOR	Common Areas	Assembly Area	2	An assistive listening system is required, but not provided.	Student Dining	ADA
107653	Walter Johnson High School	STADIUM	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 30", where a forward approach is present.	Ticket Sales Counter	ADA
107654	Walter Johnson High School	STADIUM	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Stadium entrance gates	ADA
111466	Walter Johnson High School	STADIUM	Common Areas	Assembly Area	2	An assistive listening system is required, but not provided.	WJ Stadium	ADA
107733	Walter Johnson High School	INTERIOR	Interior Access Route	Elevator	3	The illumination at car controls, car platform, car threshold and car landing sill is less than 5 foot candles (54 lux).	Elevator A, Elevator C	ADA
108044	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	G60 Team Room, G58 Team Room, G56 Small Team Room	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108056	Walter Johnson High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	G60 Team Room, G58 Team Room, G57A Team Room, G56 Team Room	ADA
108057	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Locker	3	The locker area does not have a compliant bench.	G60 Team Room, G58 Team Room, G57A Team Room, G56 Team Room	ADA
108156	Walter Johnson High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Boys Dressing Room, Girls Dressing Room	ADA
107734	Walter Johnson High School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator A, Elevator C	ADA
108189	Walter Johnson High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Kitchen Staff Locker area, 185 Bldg Services Locker area	ADA
108023	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys Locker Room	ADA
108024	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Locker Room	ADA
108025	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys Locker Room	ADA
108026	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Boys Locker Room, Girls Locker Room	ADA
108027	Walter Johnson High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Boys Locker Room, Girls Locker Room	ADA
108028	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Locker	3	The locker area does not have a compliant bench.	Boys Locker Room, Girls Locker Room	ADA
108030	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Locker Room, Girls Locker Room	ADA
108031	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Locker Room	ADA
108032	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Girls Locker Room	ADA
108033	Walter Johnson High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls PE Coach Office, Boys PE Coach Office, Kitchen Staff Locker area, 185 Bldg Services Locker area	ADA
108034	Walter Johnson High School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Girls PE Coach Office, Boys PE Coach Office	ADA
108035	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Girls PE Coach Office, Boys PE Coach Office	ADA
108036	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Girls PE Coach Office	ADA
108037	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Boys PE Coach Office	ADA
108038	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls PE Coach Office, Boys PE Coach Office	ADA
108039	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Girls PE Coach Office, Boys PE Coach Office	ADA
108040	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Girls PE Coach Office, Boys PE Coach Office	ADA
108041	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys PE Coach Office	ADA
108212	Walter Johnson High School	INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide compliant aisle seats.	Auditorium	ADA
108222	Walter Johnson High School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Corridor Lockers	ADA
108042	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys PE Coach Office	ADA
108043	Walter Johnson High School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Girls PE Coach Office, Boys PE Coach Office	ADA
108110	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Women's Staff Restroom 186, Men's Staff Restroom 188	ADA
108111	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Women's Staff Restroom 186, Men's Staff Restroom 188	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108114	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Men's Staff Restroom 1, Women's Staff Restroom 2, Women's Staff Restroom 4, Men's Staff Restroom 5, Women's Staff Restroom 6, Men's Staff Restroom 9, Women's Staff Restroom 10, Men's Staff Restroom 15, Women's Staff Restroom 16	ADA
108117	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Men's Staff Restroom 1, Women's Staff Restroom 2, Men's Staff Restroom 5, Women's Staff Restroom 6, Men's Staff Restroom 9, Women's Staff Restroom 10	ADA
108118	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Men's Staff Restroom 1, Women's Staff Restroom 2, Men's Staff Restroom 9, Women's Staff Restroom 10	ADA
108120	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Men's Staff Restroom 1, Women's Staff Restroom 2, Men's Staff Restroom 9, Women's Staff Restroom 10, 185A Bldg Services Restroom	ADA
108121	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Men's Staff Restroom 1, Women's Staff Restroom 2, Men's Staff Restroom 7, Women's Staff Restroom 8, Men's Staff Restroom 9, Women's Staff Restroom 10, Men's Staff Restroom 11, Women's Staff Restroom 12, Men's Staff Restroom 13, Women's Staff Restroom 14, Men's Staff Restroom 15, Women's Staff Restroom 16	ADA
108122	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Men's Staff Restroom 1, Women's Staff Restroom 2, Men's Staff Restroom 9, Women's Staff Restroom 10	ADA
108123	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Men's Staff Restroom 3, Women's Staff Restroom 4, Men's Staff Restroom 5, Women's Staff Restroom 6, Men's Staff Restroom 7, Women's Staff Restroom 8, Men's Staff Restroom 11, Women's Staff Restroom 12, Men's Staff Restroom 13, Women's Staff Restroom 14, Men's Staff Restroom 15, Women's Staff Restroom 16, Staff Restroom 17, Women's Staff Restroom 18	ADA
108124	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Men's Staff Restroom 3, Men's Staff Restroom 7, Women's Staff Restroom 8, Men's Staff Restroom 9, Women's Staff Restroom 10, Men's Staff Restroom 11, Women's Staff Restroom 12	ADA
108125	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Men's Staff Restroom 3, Women's Staff Restroom 4, Men's Staff Restroom 5, Women's Staff Restroom 6, Men's Staff Restroom 7, Women's Staff Restroom 8, Men's Staff Restroom 11, Men's Staff Restroom 13, Men's Staff Restroom 15, Women's Staff Restroom 16	ADA
108058	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Boys 1, Girls 2, Boys 5, Girls 6, Boys 7, Girls 8, Boys 15, Girls 16	ADA
108060	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys 1, Boys 5, Boys 7, Boys 15	ADA
108061	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys 1, Girls 2, Boys 3, Boys 9, Girls 10	ADA
108062	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys 1, Girls 2, Boys 5, Boys 9	ADA
108064	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Main Level Boys Restrooms, Main Level Girls Restrooms, Boys 15, Girls 16	ADA
108066	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Girls 2, Boys 3, Girls 4, Boys 5, Girls 6, Boys 9, Girls 10, Boys 15, Girls 16	ADA
108067	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls 2, Boys 3, Girls 4, Girls 8, Boys 15	ADA
108068	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys 3, Boys 9, Girls 10	ADA
108069	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys 3	ADA
108070	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys 3, Girls 4, Boys 9, Girls 10	ADA
108071	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls 4, Boys 5, Girls 10	ADA
108072	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls 4	ADA
108073	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Girls 4	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108074	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Main Level Boys Restrooms, Main Level Girls Restrooms, Boys 15, Girls 16	ADA
108126	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Women's Staff Restroom 4, Men's Staff Restroom 5, Women's Staff Restroom 6, Men's Staff Restroom 7, Women's Staff Restroom 8, Men's Staff Restroom 11, Women's Staff Restroom 12, Men's Staff Restroom 13, Women's Staff Restroom 14, Men's Staff Restroom 15, Women's Staff Restroom 16, Staff Restroom 17, Women's Staff Restroom 18	ADA
108130	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Men's Staff Restroom 7, Women's Staff Restroom 8	ADA
108133	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Men's Staff Restroom 11, Men's Staff Restroom 13	ADA
108134	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Men's Staff Restroom 11, Women's Staff Restroom 12	ADA
108135	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Men's Staff Restroom 11	ADA
108136	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Women's Staff Restroom 14	ADA
108138	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Women's Staff Restroom 16	ADA
108139	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Restroom 17	ADA
108140	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Staff Restroom 17	ADA
108141	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Staff Restroom 17	ADA
108142	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Staff Restroom 17	ADA
108143	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 17	ADA
108145	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 17	ADA
108147	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 17	ADA
108157	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108158	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys Dressing Room Restroom	ADA
108160	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108161	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108162	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108163	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108164	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A transfer seat is provided but is not compliant.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108165	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108166	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys Dressing Room Restroom, Girls Dressing Room Restroom	ADA
108169	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Health Suite Restroom 1, Health Suite Restroom 2	ADA
108170	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Health Suite Restroom 1	ADA
108171	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Suite Restroom 1, Health Suite Restroom 2	ADA
108075	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Boys 9	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108077	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Girls 10	ADA
108079	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Boys 11, Girls 12, Boys 13, Girls 14, Boys 19, Girls 20, Classroom G03 Restroom	ADA
108080	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Upper Level Boys Restrooms, Upper Level Girls Restrooms, Boys 17, Girls 18, Boys 19, Girls 20	ADA
108081	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Upper Level Boys Restrooms, Upper Level Girls Restrooms, Boys 17, Girls 18, Boys 19, Girls 20	ADA
108082	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys 11, Boys 13	ADA
108083	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls 12, Girls 14, Boys 17, Girls 18, Girls 20	ADA
108084	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys 13, Girls 14, Boys 17	ADA
108085	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys 13	ADA
108089	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys 17, Girls 18	ADA
108090	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Boys 17	ADA
108091	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys 17, Girls 18, Boys 19	ADA
108092	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys 17, Girls 18	ADA
108094	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys 17, Girls 18	ADA
108172	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Health Suite Restroom 1	ADA
108173	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Suite Restroom 1, Health Suite Restroom 2	ADA
108174	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Health Suite Restroom 1	ADA
108175	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Health Suite Restroom 1, Health Suite Restroom 2, Room 166 Restroom	ADA
108192	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Kitchen Staff Restroom, 185A Bldg Services Restroom	ADA
108193	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Staff Restroom	ADA
108194	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Kitchen Staff Restroom	ADA
108195	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Kitchen Staff Restroom, 185A Bldg Services Restroom	ADA
108196	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Kitchen Staff Restroom, 185A Bldg Services Restroom	ADA
108197	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	185A Bldg Services Restroom	ADA
108198	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	185A Bldg Services Restroom	ADA
108199	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	185A Bldg Services Restroom	ADA
108200	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	185A Bldg Services Restroom	ADA
108095	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Boys 19, Girls 20, Classroom G03 Restroom	ADA
108096	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys 19, Girls 20	ADA
108097	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Boys 19	ADA
108100	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall in a multi-stall restroom used primarily by children (ages 3-12) does not have the required dimensions.	Classroom G03 Restroom	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
108101	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Classroom G03 Restroom	ADA
108104	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restrooms throughout	ADA
108105	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Women's Staff Restroom 186, Men's Staff Restroom 188	ADA
108106	Walter Johnson High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Women's Staff Restroom 186, Men's Staff Restroom 188	ADA
108107	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Women's Staff Restroom 186	ADA
108108	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Men's Staff Restroom 188	ADA
108109	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Women's Staff Restroom 186, Men's Staff Restroom 188	ADA
108201	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	185A Bldg Services Restroom	ADA
108234	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Room 166 Classroom, Room 167 Classroom	ADA
108235	Walter Johnson High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Room 166 Restroom, Room 167 Classroom	ADA
107656	Walter Johnson High School	STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Men's Restroom	ADA
107657	Walter Johnson High School	STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Men's Restroom	ADA
107833	Walter Johnson High School	EXTERIOR	Signage	Exterior Accessible Route-Signage	4	Signage directing pedestrians to the nearest accessible building entrance on an accessible route is not present.	Rockledge Blvd pedestrian entrance	ADA
108183	Walter Johnson High School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	G03 Food Lab	ADA
108191	Walter Johnson High School	INTERIOR	Common Areas	Locker Rooms	4	The locker room does not have at least one of the coat hooks within reach range.	Kitchen Staff Locker area	ADA
108021	Walter Johnson High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Boys Locker Room, Girls Locker Room	ADA
108226	Walter Johnson High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain 4	ADA
108227	Walter Johnson High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain 5	ADA
108228	Walter Johnson High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain 5	ADA
108236	Walter Johnson High School	INTERIOR	Kitchen	Kitchen- Pass Through Layout	4	The clearance between opposing base cabinets, counter tops, appliances or walls within kitchen work areas are less than 40".	Room 166 Kitchen	ADA
108237	Walter Johnson High School	INTERIOR	Kitchen	Pass Through Layout	4	The pass-through kitchen does not have two entries to the floor area between opposing base cabinets, counter tops, appliances or walls.	Room 166 Kitchen	ADA
108239	Walter Johnson High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain 7	ADA