



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Walt Whitman High School
7100 Whittier Boulevard
Bethesda, Maryland 20817

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-095.303

Date of Report:
October 25, 2019

On Site Date:
October 2nd-4th, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Walt Whitman High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Walt Whitman High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

WALT WHITMAN HIGH SCHOOL - TITLE II ADA COMPLIANCE ASSESSMENT - ACCESSIBILITY SUMMARY

Facility/Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Walt Whitman High School	76	22	36			134
Grand Total	76	22	36			134

Order of magnitude costs to address those elements are described individually in Appendix A.

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
74872	Walt Whitman High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Stall P1	ADA
74874	Walt Whitman High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	P1 - P2 Access Aisle	ADA
74879	Walt Whitman High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Stall P8	ADA
74886	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route From Portables to Left Main Entrance	ADA
74888	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR4	ADA
74893	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	Unloading/Loading Zone Signage	ADA
74895	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR5	ADA
74897	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk east of CR5 towards Stair 1	ADA
74904	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Treads have slopes greater than 1:48.	Stair ST1	ADA
76641	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp 1	ADA
76643	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R1	ADA
76649	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk by Ramp 1 top landing	ADA
76650	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR 6	ADA
76651	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk by Curb Ramp 6	ADA
76654	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk east of Curb Ramp 7	ADA
76657	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk in southwest corner of parking lot 1 to CR 1	ADA
76658	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route to stadium entrance from gray concrete portion	ADA
76687	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR 4	ADA
76689	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR5	ADA
76692	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R2	ADA
76694	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp R2	ADA
76695	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R2	ADA
77491	Walt Whitman High School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The accessible door has less than 32" clear width.	Exterior Door DR2, DR3, DR4	ADA
77674	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Courtyard	ADA
88119	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Softball Field 1	ADA
88121	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Stadium Entrance	ADA
88122	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Walkway between R2 and ST2	ADA
88123	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	ST-2	ADA
88124	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Treads have slopes greater than 1:48.	ST-2	ADA
88125	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	CR-9	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88126	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-9	ADA
88127	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk portion left of CR9	ADA
88128	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 1	ADA
88129	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Baseball Field	ADA
88130	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Baseball Field Auxiliary Parking	ADA
88131	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-8	ADA
88132	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	CR-8	ADA
88134	Walt Whitman High School	BUILDING EXTERIOR	Interior Access Route	Ramp	1	Handrails are not continuous or are not at a continuous height above the ramp surface.	R-4	ADA
88135	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	ST-4	ADA
88136	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between ST-7 and CR-8	ADA
88137	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	R-3	ADA
88139	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Accessible Route to stadium bleachers	ADA
88140	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from Bleachers to stadium entrance patio area	ADA
88141	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	ST-8, ST-9, ST-10, ST-11	ADA
88142	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	R-3	ADA
88143	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Stadium Announcer Booth (R-3 side)	ADA
88144	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stadium Patio Area	ADA
88145	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Stadium Patio Area	ADA
88146	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Drainage by north east corner of stadium	ADA
88147	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Walkway paralleling Braeburn Pkwy	ADA
88148	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Walkway from CR-10 towards east	ADA
88149	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Storm drainage by drive aisle entrance off Braeburn Pkwy	ADA
88150	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Storm drainage by drive aisle entrance off Braeburn Pkwy	ADA
88545	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST1	ADA
88546	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Stair 1 Egress	ADA
88548	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Stair 1 Egress	ADA
88663	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR4	ADA
88664	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR4	ADA
88665	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR5	ADA
88666	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	South Side of Tennis Courts by ST2	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88667	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	South Side of Tennis Courts by ST2	ADA
77186	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Door	1	The door has less than 32" clear width.	Restroom: Boys 1, Girls 1	ADA
77205	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Health Room	ADA
77279	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Interior Corridors - Display Cases	ADA
77289	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Auditorium (8), Gymnasium (12), Aux. Gymnasium (4), Weight Room (2), Media Center (4)	ADA
77485	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Boys 1	ADA
77493	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	Cafeteria Doors (6), Gymnasium (8)	ADA
77495	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Weight Room	ADA
77497	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Weight Room	ADA
77553	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Auditorium Stairs - Stage Stairs 1 & 2	ADA
77582	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	Staff 1, 2, Guidance Office	ADA
77643	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Interior Ramp R1	ADA
77644	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Interior Stair - Stage 2 Stairs	ADA
77645	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp has no edge protection.	Interior Ramp R1 - Small Auditorium/Classroom Stage	ADA
88269	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Auditorium - Stage Stair 1 & 2	ADA
88293	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Platform Lift	1	The platform lift requires a key for operation.	Main Auditorium - Stage Lift	ADA
76691	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
88120	Walt Whitman High School	BUILDING EXTERIOR	Baseball/Soft ball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Softball Field 1	ADA
88133	Walt Whitman High School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Portable Classrooms	ADA
88138	Walt Whitman High School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Bottom of R-3	ADA
88668	Walt Whitman High School	BUILDING EXTERIOR	Tennis Courts	Bleacher Seating	2	The wheelchair space is not the minimum required dimensions at the bleacher seating for the tennis courts.	Tennis Courts	ADA
88669	Walt Whitman High School	BUILDING EXTERIOR	Baseball/Soft ball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Softball Field	ADA
88670	Walt Whitman High School	BUILDING EXTERIOR	Football Field	Player Seating	2	A wheelchair space is not provided at each team seating for the football field.	Football Stadium	ADA
77199	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Instrumental Music Room, Art Classrooms (4)	ADA
77263	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Interior Spaces & Rooms	ADA
77499	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Lounge, Social Studies Resource Room, English Resource Room, Health Room, Main Office Workroom, Staff Kitchen Dining, Guidance Office Workroom, Math Resource Room, Science Resource Room, Art Prep Room	ADA
77500	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Staff Spaces & Rooms	ADA
77516	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77518	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Gymnasium Lobby	ADA
77578	Walt Whitman High School	BUILDING INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Gymnasium Lobby	ADA
77579	Walt Whitman High School	BUILDING INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Concessions near Elevator EL1	ADA
77580	Walt Whitman High School	BUILDING INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Attendance Service Windows	ADA
77581	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Media Center Desk	ADA
77664	Walt Whitman High School	BUILDING INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restrooms: Boys Locker Room, Girls Locker Room; Girls 6, Boys 6	ADA
88235	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Science Classrooms - C326, C320, C337, C331, C328, C303, C335, D308	ADA
88242	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Interior Rooms & Spaces	ADA
88245	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Staff Spaces & Rooms	ADA
88288	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Counter	2	Counters with windows have security glazing to separate personnel from the public.	Attendance Service Counter	ADA
77161	Walt Whitman High School	BUILDING INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator E1	ADA
77163	Walt Whitman High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls Locker Room, Boys Locker Room	ADA
77171	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restrooms: Staff 1, 2, 3, 4, Boys P/E Office Restroom, Girls P/E Office Restroom, Building Services Restroom, Office Restroom 1	ADA
77172	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restrooms: Girls 1, Child Care Dev., Student Health Office Restroom	ADA
77173	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restrooms: Staff 1, 2, 3, 4, 5, 8, 9, Boys P/E Office Restroom, Girls P/E Office Restroom, Building Services Restroom, Office Restroom 1	ADA
77174	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restrooms: Boys 1, Girls 1	ADA
77185	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms: Boys Locker Room, Girls Locker Room, Boys 1, 2, 3, 4, 5, 6, 7, 8; Girls 1, 2, 3, 4, 5, 6, 7, 8	ADA
77196	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Restrooms: Boys 1; Girls 2	ADA
77197	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restrooms: Boys 1; Girls 1, Special Education Restroom	ADA
77200	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8, 9, Main Office Workroom	ADA
77201	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8, 9; Boys P/E Office Restroom, Boys P/E Office Restroom, Boys Coaches Restroom, Girls Coaches Restroom, Men's Office Restroom, Women's Office Restroom, Office Restroom 1, Staff Health Restroom	ADA
77206	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restrooms: Boys 2, 3; Girls 2, 3	ADA
77207	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restrooms: Boys 1, Girls 1; Child Dev. Classroom	ADA
77208	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms: Boys 1, Girls 1, Child Dev. Room	ADA
77217	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8, 9; Boys P/E Office Restroom, Boys P/E Office Restroom, Boys Coaches Restroom, Girls Coaches Restroom, Men's Office Restroom, Women's Office Restroom, Office Restroom 1, Staff Health Restroom	ADA
77278	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Restrooms: Boys 1, 2, 3, 4, 5, 7; Girls 1, 2, 3, 4, 5, 7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
77285	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory faucet hardware is not compliant.	Restrooms: Girls 1, Boys 1	ADA
77288	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restrooms: Student Health Restroom, Special Education Restroom	ADA
77290	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Student Lockers	ADA
77519	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Special Education Restroom Shower	ADA
77521	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Special Education Restroom Shower	ADA
77684	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8, 9; Boys P/E Office Restroom, Boys P/E Office Restroom, Boys Coaches Restroom, Girls Coaches Restroom, Men's Office Restroom, Women's Office Restroom, Office Restroom 1, Staff Health Restroom	ADA
77692	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys P/E Office Restroom, Girls P/E Office Restroom	ADA
77723	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Boys P/E Office Restroom Shower, Building Services Shower	ADA
77724	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Girls & Boys P/E Office Restroom Showers, Building Services Restroom Shower	ADA
77725	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Girls & Boys P/E Office Shower, Building Services Office Shower	ADA
77726	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Bath Tub	3	The spray unit does not have a minimum 59" long hose	Girls & Boys P/E Office Restroom Shower, Building Services Shower	ADA
77727	Walt Whitman High School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-	3	Controls on dispensers are not compliant	Girls & Boys P/E Office Showers, Building Services Showers	ADA
77728	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls & Boys P/E Office Restroom, Building Services Restroom	ADA
77729	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys & Girls P/E Office Restroom, Building Services Restroom	ADA
77730	Walt Whitman High School	BUILDING INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Girls & Boys P/E Office Locker Room, Building Services Lockers	ADA
77819	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Main Auditorium	ADA
77821	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Main Gymnasium	ADA
88241	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms: Boys 1, 2, 3, 4, 5, 6, 7, 8; Girls 1, 2, 3, 4, 5, 6, 7, 8; Health Student Restroom, Boys Locker Room, Girls Locker Room	ADA
88292	Walt Whitman High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide compliant aisle seats.	Main Auditorium	ADA
88294	Walt Whitman High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms: Staff 1, 2, 3, 4, 5, 6, 7, 8, 9; Boys P/E Office Restroom, Boys P/E Office Restroom, Boys Coaches Restroom, Girls Coaches Restroom, Men's Office Restroom, Women's Office Restroom, Office Restroom 1, Staff Health Restroom	ADA

