



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Gaithersburg High School
101 Education Boulevard
Gaithersburg, Maryland 20877

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-173.303

Date of Report:

October 29, 2019

On Site Date:

November 5-8, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Gaithersburg High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Gaithersburg High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Gaithersburg High School	125	39	62	4	23	256
Grand Total	125	39	62	4	23	256

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144756	Gaithersburg High School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity was not accessible and therefore could not be evaluated.	Gym II	ADA
144757	Gaithersburg High School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity was not accessible and therefore could not be evaluated.	Main Gym	ADA
144753	Gaithersburg High School	RESTROOMS	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity was not accessible and therefore could not be evaluated.	Restroom RRSM-3067A	ADA
144626	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Sidewalk access to Tennis courts	ADA
144628	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Tennis courts	ADA
144634	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Baseball field 1 visitor bleachers to press box	ADA
144635	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Baseball field 1 home bleachers to entrance from football field	ADA
144644	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Baseball field 2 Behind home plate To home bleachers	ADA
144645	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Baseball field 2 Home bleachers to Curb ramp CR-1	ADA
144694	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Gate	1	The gate hardware is not compliant.	Football field	ADA
144701	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	From patio at football field to Bleachers	ADA
144624	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	All sidewalks	ADA
144625	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	At Tennis courts and In Sidewalk along Summit Avenue	ADA
144627	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	At Tennis courts and In Sidewalk along Summit Avenue	ADA
144629	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	From tennis courts toward football field	ADA
144630	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	From tennis courts to curb ramp CR-1	ADA
144638	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Flagpole to concession Stand	ADA
144639	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Flagpole to concession Stand	ADA
144646	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-1	ADA
144647	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Curb ramp CR-1 to concession stand	ADA
144648	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Curb ramp CR-1 to concession stand	ADA
144650	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-2	ADA
144651	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-2	ADA
144652	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Curb ramp CR-2 to turn in sidewalk	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144653	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	First turn on sidewalk from curb ramp CR-2 to school	ADA
144654	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Turn 1 to turn 2 sidewalk from curb ramp CR-2 to school	ADA
144655	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Second turn in sidewalk from curb ramp CR-2 to school	ADA
144657	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	In front of basketball court to curb ramp CR-3	ADA
144658	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-3	ADA
144659	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-3	ADA
144660	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-3	ADA
144661	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route does not have 80" vertical clearance.	Curb ramp CR-4 to curb ramp CR-5	ADA
144662	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-6	ADA
144663	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-17	ADA
144664	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-17	ADA
144665	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp CR-6 to curb ramp CR-7	ADA
144666	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The parallel curb ramp landing is not compliant.	Curb Ramp CR-8	ADA
144667	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp CR-10	ADA
144692	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair ST-18	ADA
144693	Gaithersburg High School	EXTERIOR	Exterior Access Route	Gate	1	The gate does not have the required maneuvering clearances.	At Stair ST-18	ADA
144696	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	At football field from visitor side to home side	ADA
144697	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-23, ST-26	ADA
144698	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-24, ST-25	ADA
144699	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-27, ST-28	ADA
144710	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Parking to curb ramp CR-12	ADA
144711	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-12	ADA
144712	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	To door D-8	ADA
144713	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Door D-1 toward door D-2	ADA
144715	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-29	ADA
144716	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-30	ADA
144717	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stair ST-29 to stair ST-30	ADA
144718	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-31	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144719	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-32	ADA
144720	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	To door D-17	ADA
144721	Gaithersburg High School	EXTERIOR	Entrance to Building	Building Entrance - Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Door 18 and 19	ADA
144722	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-33	ADA
144723	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair ST-33	ADA
144726	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Stair ST-34 to city sidewalk	ADA
144727	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stair ST-34 to city sidewalk	ADA
144728	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	City sidewalk to door D-23	ADA
144729	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-35	ADA
144730	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-36	ADA
144736	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-38	ADA
144737	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-19	ADA
144738	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR-19	ADA
144739	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Corner of cafeteria to front of building	ADA
144740	Gaithersburg High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-20	ADA
144741	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-39	ADA
144742	Gaithersburg High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Curb ramp CR-20 to curb ramp CR-21	ADA
144750	Gaithersburg High School	EXTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-40, ST-41	ADA
144751	Gaithersburg High School	EXTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-17, ST-18	ADA
146655	Gaithersburg High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Parent pick up and drop off	ADA
144686	Gaithersburg High School	INTERIOR	Interior Access Route	Ramp	1	Handrail heights are not compliant.	Ramp R-3	ADA
143871	Gaithersburg High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Cafeteria	ADA
143872	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-2, ST-6, ST-1, St-5, ST-4, ST-3	ADA
143873	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-2, ST-6, ST-5	ADA
143874	Gaithersburg High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-1, DF-3, DF-4, DF-7, DF-9, DF-10, DF-14, DF-15, DF-16, DF-18, Df-19, DF-20, DF-21	ADA
143892	Gaithersburg High School	INTERIOR	Interior Access Route	Ramp	1	Handrail heights are not compliant.	Ramp R-1	ADA
143893	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
143894	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-7	ADA
143895	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-8	ADA
143896	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-8	ADA
143897	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-8	ADA
143898	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-9	ADA
143914	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-10	ADA
143915	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-10	ADA
144562	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-11	ADA
144563	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Interior doors with door closures	ADA
144564	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Interior doors with door closures	ADA
144565	Gaithersburg High School	INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Boys Locker Room 1045, Girls Locker Room 1049	ADA
144573	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Classrooms throughout building	ADA
144575	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Classrooms throughout building	ADA
144581	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Room 1016A	ADA
144589	Gaithersburg High School	INTERIOR	Entrance to Building	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Entry Doors with door closures	ADA
144598	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-12	ADA
144599	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-12	ADA
144600	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-13	ADA
144601	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-13	ADA
144602	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-14, ST-15	ADA
144603	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-14, ST-15	ADA
144604	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-14, ST-15	ADA
144605	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-16	ADA
144606	Gaithersburg High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-16	ADA
144608	Gaithersburg High School	INTERIOR	Interior Access Route	Platform Lift	1	A platform lift is required but not provided.	Projection booth	ADA
144609	Gaithersburg High School	INTERIOR	Interior Access Route	Interior Access Route	1	Clear widths are less than 36" minimum, including protruding objects.	Auditorium	ADA
144615	Gaithersburg High School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Room 1063	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144616	Gaithersburg High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Classrooms throughout building	ADA
144668	Gaithersburg High School	INTERIOR	Interior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-2	ADA
146170	Gaithersburg High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Stair ST-2, ST-3, ST-4, ST-5, ST-6	ADA
144683	Gaithersburg High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Classrooms throughout building	ADA
144703	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot A Space P1	State of Maryland
144704	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot A Space P5	State of Maryland
144705	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot A Space P6	State of Maryland
144706	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The van parking space is less than 96" wide minimum.	Parking Lot A Space P7	State of Maryland
144707	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot A Space P6	State of Maryland
144708	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot A Space P7	ADA
144709	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot A Space P8	State of Maryland
144743	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot B Space P1	State of Maryland
144744	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot B Space P2	ADA
146192	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot A	State of Maryland
146193	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - General	1	MARYLAND: The minimum number of accessible parking spaces is not provided.	Parking Lot C	State of Maryland
146194	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot A	State of Maryland
146195	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot C	State of Maryland
146196	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space - Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot C	State of Maryland
147839	Gaithersburg High School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot C	State of Maryland
143904	Gaithersburg High School	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom RRB-1068, RRG-1076, RRB-2020, RRG-2022, RR-2049C	ADA
144591	Gaithersburg High School	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom RR-1015D, RR-1015M, RR-1017E, RR-1017D, RRB-314C2, RRG-314D2, RR-1107A, RR-1113A, RR-2057B, RR-2066B	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144702	Gaithersburg High School	RESTROOMS	Restroom	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom RRB-0009, RRG-0007	ADA
144622	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Tennis courts	ADA
144631	Gaithersburg High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball Field 1 Bleachers Home and Visitor	ADA
144636	Gaithersburg High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Baseball Field 1	ADA
144640	Gaithersburg High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball Field 2 Bleachers Home and Visitor	ADA
144641	Gaithersburg High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Baseball Field 2	ADA
144643	Gaithersburg High School	ATHLETIC FIELDS	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball Field 2 Team Seating Home and Visitor	ADA
144649	Gaithersburg High School	ATHLETIC FIELDS	Tennis Courts	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Tennis courts	ADA
144656	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Basketball Court	ADA
144695	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Football field	ADA
144700	Gaithersburg High School	ATHLETIC FIELDS	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Football field	ADA
146663	Gaithersburg High School	ATHLETIC FIELDS	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Football Field	ADA
146664	Gaithersburg High School	ATHLETIC FIELDS	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Baseball Field 1	ADA
144637	Gaithersburg High School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Flagpole near concession stand	ADA
144724	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-31, ST-32, ST-33	ADA
144746	Gaithersburg High School	EXTERIOR	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground	ADA
144747	Gaithersburg High School	EXTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Courtyard 1	ADA
144748	Gaithersburg High School	EXTERIOR	Common Areas	Interior Access Route	2	An accessible route is not provided to all spaces and elements.	Courtyard 1	ADA
144749	Gaithersburg High School	EXTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Courtyard 2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
143869	Gaithersburg High School	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
144687	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Classrooms throughout building	ADA
143870	Gaithersburg High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria	ADA
143883	Gaithersburg High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Hallway by Room 1010	ADA
143891	Gaithersburg High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Hallway by Room 1024	ADA
144574	Gaithersburg High School	INTERIOR	Interior Access Route	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	Classrooms throughout building	ADA
144582	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	2	Sinks do not have knee and/or toe clearance.	Classrooms throughout building	ADA
144583	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	2	The accessible sink does not have push/lever hardware.	Classrooms throughout building	ADA
144595	Gaithersburg High School	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic.	Elevator E-1, E-2	ADA
144596	Gaithersburg High School	INTERIOR	Common Areas	Assembly Area	2	Assembly areas do not provide compliant aisle seats.	Auditorium	ADA
144597	Gaithersburg High School	INTERIOR	Common Areas	Assembly Area	2	Assembly areas do not provide wheelchair spaces.	Auditorium	ADA
144607	Gaithersburg High School	INTERIOR	Interior Access Route	Interior Access Route	2	An accessible route is not provided to all spaces and elements.	Auditorium	ADA
144610	Gaithersburg High School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance.	Backstage	ADA
144611	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Backstage	ADA
146662	Gaithersburg High School	INTERIOR	Common Areas	Assembly Area	2	The assistive listening device is not compliant or is not provided.	Auditorium	ADA
144673	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	2	The dryer controls are not within reach range.	Room 1107B, 1113B, 2057A	ADA
144674	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	2	The washing machine controls are not within reach range.	Room 1107B, 1113B, 2057A	ADA
144675	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Room 1107B, 1113B, 2057A	ADA
144680	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 2031	ADA
144681	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	2	The accessible sink does not have push/lever hardware.	Room 2031	ADA
144682	Gaithersburg High School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance.	Classrooms throughout building	ADA
144632	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	3	A compliant accessible route is not provided.	Baseball field 1 to both teams seating areas	ADA
144642	Gaithersburg High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	3	A compliant accessible route is not provided.	Baseball field 2 to both teams seating areas	ADA
144688	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Hallways	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144689	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Hallways	ADA
144566	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Boys Locker Room 1045, Girls Locker Room 1049	ADA
144567	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Boys Locker Room 1045, Girls Locker Room 1049	ADA
144580	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 1043, 1016A, 1020A, 1051, 1140	ADA
144587	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 1026, 1030, 1032, 1038, 1040, 1046, 1048	ADA
144588	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 1026, 1030, 1032, 1038, 1040, 1046, 1048	ADA
144612	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 314C	ADA
144613	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 314C	ADA
144617	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 1092E, 1090F, 1092D, 2049D	ADA
144618	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 1092E, 1090F, 1092D, 2049D	ADA
144754	Gaithersburg High School	INTERIOR	Signage	Signage	3	Means of egress signage is not provided.	Stairs and Exterior Doors	ADA
144684	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 2067	ADA
144685	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 2067	ADA
143875	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom Staff RRSW-1003, RRSW-1007, RRSW-1070, RRSW-1074, RRSW-1086, RRSW-1088, RRSW-1139A, RRSW-1143A, RRSW-1016B, RRSW-1020B, RRSW-2009A, RRSW-2011, RRSW-2013, RRSW-2020A, RRSW-2022A, RRSW-2083A, RRSW-2085A, RRSW-3015, RRSW-3017, RRSW-3026A, RRSW-3028A, RRSW-3065A	ADA
144593	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom RR-1015D, RR-1015M, RR-1017E, RR-1017D, RRB-314C2, RRG-314D2, RR-1107A, RR-1113ARR-2057B, RR-2066B	ADA
144594	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-1015D, RR-1017E, RRB-314C2, RRG-314D2, RR-1107A, RR-1113A	ADA
144614	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Shower	3	The shower spray unit is not compliant.	Restroom RRB-314C1, RRG-314D1, RR-1107A, RR-1113A, RR-2057B, RR-2066B	ADA
144669	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Restroom RR-1107A, RR-1113A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144670	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	3	Grab bars are not provided or are not compliant.	Restroom RR-1107A, RR-1113A, RR-2057B, RR-2066B	ADA
144676	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom RR-1107A, RR-1113A, RR-2066B	ADA
144677	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom Staff RRSM-1000U, RRSW-1000N, RRS-1000T	ADA
143884	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom RRB-1013, RRG-1011, RRG-1057, RRB-1059, RRG-1139, RRB-1143	ADA
143885	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom RRB-1013, RRG-1011, RRG-1057, RRB-1059, RRG-1139, RRB-1143, RR-0014, RRG-0007	ADA
143886	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RRB-1013	ADA
143887	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRB-1013	ADA
143888	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom RRB-1013, RRG-1011, RRG-1057, RRB-1059, RRG-1139, RRB-1143	ADA
143889	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Restroom RRG-1011	ADA
143890	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The wheelchair stall door is not self closing.	Restroom RRG-1011, RRG-1139, RRB-1143, RRG-0007, RRB-0009	ADA
143899	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRG-1057, RRB-1059	ADA
143900	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Toilet Stall	3	The wheelchair stall door is not compliant.	Restroom RRG-1057, RRB-1059	ADA
143901	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Restroom RRB-1068, RRG-1076, RRB-1105, RRG-1103, RR-1015D, RR-1015M, RRB-2020, RRG-2022, RR-2066B, RRG-2083, RRB-2085, RRG-2051, RRB-2053, RRB-3026, RRG-3028, RRG-3065, RRB-3067, RRG-3047, RRB-3049	ADA
143902	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	Pipes are not insulated.	Restroom RRG-1076, RRB-2020	ADA
143903	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Restroom RRG-1076	ADA
143905	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The wheelchair stall door is not self closing.	Restroom RRB-1068, RRG-1076, RRB-1105, RRG-1103, RRB-2020, RRG-2022, RRB-2085, RRB-2053, RRB-3067, RRG-3047, RRB-3049	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
143906	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom RRB-1068, RRG-1076, RRB-1105, RRG-1103, RR-1015D, RR-1015M, RR-1017E, RRB-2020, RR-2049C, RRG-2051, RRB-2053, RRG-3047, RRB-3049	ADA
143907	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRG-1076, RRG-1103, RR-1015D, RRB-314C2, RRG-314D2, RRB-2020, RRB-2053,	ADA
143908	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom RRB-1068, RRG-1076, RRB-2020, , RG-2022,	ADA
143909	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom RRB-1068, RRG-1076, RR-2009A, RRB-2020, RRG-2022, RR-2049C	ADA
143910	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom RRB-1068	ADA
144557	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Restroom RRB-1143	ADA
144558	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	Pipes are not insulated.	Restroom RRB-1143	ADA
144559	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RRB-1105, RR-1017E, RR-1017D, RR2057B	ADA
144560	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom RRG-1103, RR1015D, RR-1015M, RR-1017E, RR-1017D, RRB-2020, RRG-2022, RR-2066B, RRG-2051, RRB-2053	ADA
144561	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Restroom RRG-1003, RRG-2051	ADA
144568	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Locker Room 1045, Girls Locker Room 1049, RRB-314C2, RRG-314D2, RR-1107A, RR-1113A, RRB-2020, RR2057B, RR-2066B	ADA
144569	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	Boys Locker Room 1045	ADA
144570	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Boys Locker Room 1045	ADA
144571	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Boys Locker Room 1045, Girls Locker Room 1049	ADA
144572	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	3	Grab bars are not provided or are not compliant.	Boys Locker Room 1045, Girls Locker Room 1049, RRB-314C1, RRG-314D1	ADA
144584	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	Girls Locker Room 1049, RR-1107A, RR-1113A	ADA
144585	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	3	The wheelchair stall door is not self closing.	Girls Locker Room 1049	ADA
144586	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Shower	3	The shower spray unit is not compliant.	Boys Locker Room 1045	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144590	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom RR-1015D, RR-1015M	ADA
144592	Gaithersburg High School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom RR-1015D, RR-1015M, RR-1017E, RR-1017D, RRB-314C2, RRG-314D2, RR-1107A, RR-1113A	ADA
144678	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Restroom Staff RRSW-1000N	ADA
144679	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RRG-2022	ADA
144690	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	Pipes are not insulated.	Restroom RR-0014	ADA
144691	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-0014	ADA
144752	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	Restroom RRSM-3026A	ADA
143913	Gaithersburg High School	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-4, DF-11, DF-12, DF-15	ADA
143916	Gaithersburg High School	INTERIOR	Interior Access Route	Drinking Fountain / Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-5	ADA
144671	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	4	The location of the controls requires reaching across burners.	Room 1107B, 1113B, 2057A	ADA
144672	Gaithersburg High School	INTERIOR	Interior Access Route	Reach Range	4	The door is not located next to a minimum 30" wide work surface.	Room 1107B, 1113B, 2039, 2057A	ADA
144725	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	5	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-34	ADA
144733	Gaithersburg High School	EXTERIOR	Exterior Access Route	Ramp	5	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-4	ADA
144734	Gaithersburg High School	EXTERIOR	Exterior Access Route	Ramp	5	Handrail heights are not compliant.	Ramp R-4	ADA
144735	Gaithersburg High School	EXTERIOR	Exterior Access Route	Stairs	5	Stairs have open risers.	Stair ST-37	ADA
144576	Gaithersburg High School	INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	5	The locker room does not have accessible lockers.	Room 1043, 1016A, 1020A, 1051, 1140, 1148B	ADA
144619	Gaithersburg High School	INTERIOR	Common Areas	Vending Machine	5	The vending machines have operable parts which are not within reach range.	Room 1144, 2094, 3079	ADA
144620	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	5	Sinks do not have knee and/or toe clearance.	Room 1144, 1001L, 1000C, 2094, 3079	ADA
144621	Gaithersburg High School	INTERIOR	Interior Access Route	Sink	5	The accessible sink does not have push/lever hardware.	Room 1144, 1001L, 1000C, 2094, 3079	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
143876	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Restroom Staff RRSW-1003, RRSM-1007, RRSM-1086, RRSW-1088, RRSW-1139A, RRSM-1143A, RRSM-1016B, RRSW-1020B, RRS-2009A, RRSW-2011, RRSM-2013, RRSM-2020A, RRSW-2022A, RRSW-2083A, RRSM-2085A, RRSSW-3015, RRSM-3017, RRSM-3026A, RRSW-3028A, RRSW-3065A	ADA
143877	Gaithersburg High School	RESTROOMS	Restroom	Protruding Object	5	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Restroom Staff RRSW-1003, RRSM-1007, RRSW-1074, RRSM-1086, RRSW-1088, RRSW-1139A, RRSM-1143A, RRSM-1016B, RRSW-1020B, RRS-1140A, RRS-1148C, RRSW-1001P, RRSM-1001Q, RRSM-1000U, RRSW-1000N, RRS-1000T, RRS-2009A, RRSW-2011, RRSM-2013, RRSM-2020A, RRSW-2022A, RRSW-2083A, RRSM-2085A, RRSW-3015, RRSM-3017, RRSM-3026A, RRSW-3028A, RRSW-3065A	ADA
143878	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom Staff RRSW-1003, RRSM-1007, RRSW-1074, RRSM-1086, RRSW-1088, RRSW-1139A, RRSM-1143A, RRSM-1016B, RRSW-1020B, RRS-1140A, RRS-1148C, RRSW-1001P, RRSM-1001Q, RRSM-1000U, RRSW-1000N, RRS-1000T, RRS-2009A, RRSW-2011, RRSM-2013, RRSM-2020A, RRSW-2083A, RRSM-2085A, RRSW-3015, RRSM-3017,	ADA
143879	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	Pipes are not insulated.	Restroom Staff RRSW-1003, RRSW-2022A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
143880	Gaithersburg High School	RESTROOMS	Restroom	Controls And Dispensers	5	The height of controls are not compliant.	Restroom Staff RRSW-1003, RRSW-1007, RRSW-1070, RRSW-1074, RRSW-1086, RRSW-1088, RRSW-1139A, RRSW-1143A, RRS-1140A, RRS-1148C, RRSW-1001P, RRSW-1001Q, RRSW-1000U, RRSW-1000N, RRS-1000T, RRS-2009A, RRSW-2011, RRSW-2013, RRSW-2020A, RRSW-2022A, RRSW-2083A, RRSW-2085A, RRSW-3015RRSM-3017, RRSW-3026A, RRSW-3028ARRSW-3065A	ADA
143881	Gaithersburg High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Restroom Staff RRSW-1003, RRSW-1007, RRSW-1086, RRSW-1088, RRSW-1139A, RRSW-1143A, RRS-1140A, RRS-1148C, RRSW-2011, RRSW-2013, RRSW-2022A, RRSW-2083A, RRSW-2085A, RRSW-3015, RRSW-3017, RRSW-3026A, RRSW-3028A, RRSW-3065A	ADA
143882	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The rear grab bar at the water closet is not compliant.	Restroom Staff RRSW-1007, RRSW-1088	ADA
143911	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The rear grab bar at the water closet is not compliant.	Restroom Staff RRSW-1070, RRSW-1074, RRSW-1139A, RRSW-1143A, RRS-1140A, RRSW-1001P, RRSW-1001Q, RRSW-1000P, RRS-2009A, RRSW-2085A, RRSW-3015, RRSW-3017, RRSW-3065A	ADA
143912	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The side grab bar at the water closet is not compliant.	Restroom Staff RRSW-1070, RRSW-1074, RRSW-1088, RRS-1148C, RRS-2009A, RRSW-2011, RRSW-2020A, RRSW-2022A, RRSW-2085A	ADA
143917	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom Staff RRSW-1086, RRSW-1088	ADA
143918	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom Staff RRSW-1088, RRSW-1000U, RRSW-1000N, RRS-1000T	ADA
144556	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	Restroom Staff RRSW-1139A, RRSW-1143A, RRSW-2083A, RRSW-2085A	ADA
144577	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Lavatory	5	The lavatory faucet hardware is not compliant.	Restroom Staff RRSW-1016B, RRSW-1020B, RRSW-3026A, RRSW-3028A	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
144578	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Transfer Shower Stall	5	Grab bars are not provided or are not compliant.	Restroom RRSM-1016B, RRSW-1020B, Room 1140	ADA
144579	Gaithersburg High School	RESTROOMS	Restroom	Restroom / Bathroom - Shower	5	The shower spray unit is not compliant.	Restroom RRSM-1016B, RRSW-1020B, Room 1140	ADA