



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Winston Churchill High School  
11300 Gainsborough Road  
Potomac, Maryland 20854

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

### EMG Project Number:

123821.17R000-103.303

### Date of Report:

October 28, 2019

### On Site Date:

October 18-20, 2017



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Winston Churchill High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Winston Churchill High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Winston Churchill High School	83	15	104	7		209
Grand Total	83	15	104	7		209

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76857	Winston Churchill High School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 6	ADA
76858	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	CR-1	ADA
76860	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	CR-2	ADA
76861	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-3	ADA
76863	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-4	ADA
76865	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-5	ADA
76867	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-7	ADA
76870	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-8	ADA
76874	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	CR-9	ADA
76878	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	CR-10	ADA
76883	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Bus Drop Off	ADA
76884	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Parking Lot 2 - Sidewalk	ADA
76888	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Exterior Ramp 1	ADA
76889	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Student Drop Off	ADA
76892	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Exterior Ramp 1	ADA
76897	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Exterior Ramp 2	ADA
76898	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair 2	ADA
76899	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair 4	ADA
76900	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair 5	ADA
76901	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Exterior Stair 5	ADA
76902	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Exterior Stair 6	ADA
76903	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair 7	ADA
76904	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Exterior Stair 7	ADA
76905	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1	State of Maryland
76906	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
76907	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1	State of Maryland
76908	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1	State of Maryland
76909	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	A standard accessible stall is not provided.	Parking Lot 1	ADA
76910	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76911	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: P1A, P1C-E	ADA
76912	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1: P1B	ADA
76913	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1A, P1C-E	State of Maryland
76914	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1B	State of Maryland
76915	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: 2 access aisles for P1C-P1E	ADA
76916	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: P1B access aisle	State of Maryland
76917	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 1: P1B access aisle	State of Maryland
76923	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 2: P2A	State of Maryland
76924	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2: P2A	State of Maryland
76925	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2: P2A	State of Maryland
76926	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 2: P2A	State of Maryland
76927	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	The access aisle has a slope more than 1:50 (2%).	Parking Lot 2: P2A	ADA
76928	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 2: P2B, P2C	ADA
76929	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 2: P2C access aisle	ADA
76930	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3	State of Maryland
76931	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	A standard accessible stall is not provided.	Parking Lot 3	ADA
76932	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 3	State of Maryland
76933	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 3	State of Maryland
76934	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3	State of Maryland
76935	Winston Churchill High School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 3	State of Maryland
76973	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Tennis courts	ADA
76974	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Tennis courts	ADA
76976	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Soccer Field	ADA
76977	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 1	ADA
76978	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 2	ADA
76979	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student drop-off	ADA
87990	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	CR-9	ADA
87991	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	CR-10	ADA
87992	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Exterior stairs	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
87996	Winston Churchill High School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	Accessible entries are not identified with the International Symbol of Accessibility, where not all entrances are accessible.	Main Entrance, accessible entrances	ADA
76365	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2, Stair 3	ADA
76368	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 4	ADA
76372	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 5	ADA
76373	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 6	ADA
76376	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 7	ADA
76383	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 9	ADA
76388	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 10, Stair 11	ADA
76401	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope is greater than 1:12 (8.33%) and the cross slope is greater than 1:48 (2.08%).	Ramp 3	ADA
76578	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Platform Lift	1	The platform lift requires a key for operation.	PL-1, PL-2, PL-3	ADA
76590	Winston Churchill High School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Auxiliary Gym	ADA
76599	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	Media Center	ADA
76601	Winston Churchill High School	BUILDING INTERIOR	Fitness Course	Exercise Equipment	1	An accessible route is not provided to the exercise equipment.	Weight Room	ADA
76611	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Rm 174	ADA
76828	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Auditorium - Stage stairs right and left hand side	ADA
76833	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Auditorium egress stair	ADA
76835	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	Auditorium - backstage egress stair	State of Massachusetts
76838	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Auditorium egress stair	ADA
76955	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair 8, 9	ADA
76963	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Ramp	1	The ramp is required but not provided.	P2A-P2C to stadium entrance	ADA
76965	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk at entry gates	ADA
76966	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete walkway from entry to Home seating area	ADA
76968	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Track entrance gate	ADA
76970	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Home Field seating	ADA
76971	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Exterior Accessible Route	1	Sidewalk does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	Sidewalk to Visitor's seating area	ADA
76972	Winston Churchill High School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis courts	ADA
76975	Winston Churchill High School	BUILDING EXTERIOR	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball Field 1 and 2	ADA
76406	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
76411	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridors, Cafeteria	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76576	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Elevator	2	No characters or numbers are present on the hoist ways.	EL-1	ADA
76583	Winston Churchill High School	BUILDING INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Concessions	ADA
76585	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Ticket sales - Gymnasium, Auditorium	ADA
76592	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Media Center	ADA
76609	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 151	ADA
76610	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Interior doors throughout	ADA
76688	Winston Churchill High School	BUILDING INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Building Services	ADA
76956	Winston Churchill High School	SHEPHERD STADIUM	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Ticket Sales	ADA
76964	Winston Churchill High School	SHEPHERD STADIUM	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	The Dawg Dish Concessions	ADA
76967	Winston Churchill High School	SHEPHERD STADIUM	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Track entrance	ADA
76969	Winston Churchill High School	SHEPHERD STADIUM	Football Field	Bleacher Seating	2	The wheelchair space is not the minimum required dimensions at the bleacher seating for the football field.	Home Field seating	ADA
76577	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	EL-1	ADA
76597	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	Exit doors	ADA
76809	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Boys Restroom 3, Girls Restroom 3	ADA
76810	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Boys Restroom 3, 5 Girls Restroom 5, 8	ADA
76811	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom 3, 5, 6 Girls Restroom 3, 5	ADA
76812	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Boys Restroom 4 Girls Restroom 7	ADA
76814	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys Restroom 4, 5, 6 Girls Restroom 4, 5, 6	ADA
76815	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bars are not compliant in the ambulatory stall.	Girls Restroom 4	ADA
76816	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Girls Restroom 4	ADA
76820	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom 5, 6 Girls Restroom 5, 6, 7	ADA
76822	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom 7, 8 Girls Restroom 6, 8	ADA
76626	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restroom 1 - Men's and Women's, Health Restroom - Staff, Staff Restroom 4 - Men's and Women's	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76629	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Staff Restroom 1 - Men's and Women's, Staff Restroom 4 - Men's and Women's, Staff Restroom 7 - Men's and Women's, Staff Restroom 8 - Men's and Women's	ADA
76630	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Staff Restroom 1 - Women's Restroom, Building Services	ADA
76634	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 1 - Women's Restroom, Principal's Restroom, Staff Restroom 4 - Men's, Building Services	ADA
76635	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 1 - Men's and Women's Restroom, Health Restroom - Staff, Staff Restroom 2, Staff Restroom 3, Principal's restroom, Staff Restroom 4 - Women's, Building Services, Kitchen Restroom	ADA
76636	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff Restroom 1 - Men's Restroom, Health Restroom - Staff, Staff Restroom 6, Building Services	ADA
76638	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 1 - Men's Restroom, Staff Restroom 2, Staff Restroom 3	ADA
76639	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Health Restroom - Student	ADA
76640	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Restroom - Student	ADA
76642	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Health Restroom - Student	ADA
76644	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Restroom - Student	ADA
76840	Winston Churchill High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Dressing Rooms - Men and Women	ADA
76842	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Dressing Rooms - Men and Women's restroom	ADA
76843	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Dressing Rooms - Men's and Women's restroom	ADA
76844	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Dressing Rooms - Men's and Women's restroom	ADA
76845	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Dressing Rooms - Men's and Women's restroom	ADA
76847	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Dressing Rooms - Men's and Women's restroom	ADA
76848	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Dressing Rooms - Men's and Women's restroom	ADA
76849	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Dressing Rooms - Men's and Women's restroom	ADA
76852	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Dressing Rooms - Men's and Women's restroom	ADA
76645	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 1 - Men's and Women's, Staff Restroom 2, Staff Restroom 3, Principal's restroom, Staff Restroom 4 - Men's and Women's, Building Services, Kitchen Restroom	ADA
76646	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Restroom - Staff, Staff Restroom 6	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76647	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Health Restroom - Student	ADA
76648	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Restroom - Staff	ADA
76653	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 2, Kitchen Restroom	ADA
76662	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom 4 - Men's and Women's, Building Services	ADA
76663	Winston Churchill High School	BUILDING INTERIOR	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Staff Restroom 4 - Men's	ADA
76666	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 4 - Men's and Women's, Building Services	ADA
76669	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 5	ADA
76670	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 5	ADA
76671	Winston Churchill High School	BUILDING INTERIOR	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Staff Restroom 5	ADA
76674	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	Staff Restroom 5, Building Services	ADA
76677	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	A transfer seat is provided but is not compliant.	Staff Restroom 5	ADA
76683	Winston Churchill High School	BUILDING INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Building Services, Kitchen Restroom	ADA
76686	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The curb of the roll-in shower stall is more than 1/2" high.	Building Services	ADA
76690	Winston Churchill High School	BUILDING INTERIOR	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Kitchen Restroom	ADA
76712	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Lounge Restroom, Staff Restroom 7 - Men's and Women's, Staff Restroom 8 - Men's and Women's	ADA
76713	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Lounge Restroom, Staff Restroom 7 - Men's and Women's, Staff Restroom 8 - Men's and Women's	ADA
76714	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Lounge Restroom, Staff Restroom 8 - Men's	ADA
76715	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Lounge Restroom	ADA
76716	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Staff Restroom 7 - Men's and Women's	ADA
76717	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Staff Restroom 7 - Men's and Women's	ADA
76718	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 7 - Men's and Women's, Staff Restroom 8 - Men's and Women's	ADA
76720	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restroom 7 - Women's	ADA
76721	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Staff Restroom 7 - Women's, Staff Restroom 8 - Women's	ADA
76853	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Dressing Rooms - Women's restroom	ADA
76854	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Dressing Rooms - Women's restroom	ADA
76936	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	PE Office 167 Restroom, PE Office 141 Restroom	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76937	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	PE Office 167 Restroom, PE Office 141 Restroom	ADA
76938	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The curb of the roll-in shower stall is more than ½" high.	PE Office 167 Restroom, PE Office 141 Restroom	ADA
76939	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	PE Office 167 Restroom, PE Office 141 Restroom	ADA
76940	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The shower enclosure is not 30" minimum by 60" minimum.	PE Office 167 Restroom, PE Office 141 Restroom	ADA
76941	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	A transfer seat is provided but is not compliant.	PE Office 167 Restroom, PE Office 141 Restroom	ADA
76943	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not compliant.	Boys Locker Room, Girls Locker Room	ADA
76944	Winston Churchill High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Boys Locker Room, Team Room 169A, Team Room 169B, Girls Locker Room, Team Room 139A, Team Room 139B	ADA
76945	Winston Churchill High School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Boys Locker Room, Team Room 169A, Team Room 169B, Girls Locker Room, Team Room 139A, Team Room 139B	ADA
76946	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Locker Room	ADA
76947	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Locker Room, Girls Locker Room	ADA
76722	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Staff Restroom 7 - Men's and Women's	ADA
76723	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restroom 7 - Men's and Women's, Staff Restroom 8 - Men's and Women's	ADA
76724	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Staff Restroom 7 - Men's and Women's	ADA
76725	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Staff Restroom 7 - Men's	ADA
76726	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom 8 - Men's and Women's	ADA
76727	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 8 - Men's and Women's	ADA
76731	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Boys Restrooms 1, 2, 3, 4, 5, 6, 7, 8 Girls Restrooms 1, 2, 3, 4, 5, 6, 7, 8	ADA
76732	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Boys Restrooms 1, 2, 3, 4, 5, 6, 7, 8 Girls Restrooms 1, 2, 3, 5, 6, 7, 8	ADA
76733	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Boys Restroom 1, Girls Restroom 1	ADA
76734	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys Restroom 1, 4, 5, 6, 8 Girls Restroom 1, 5, 6, 8	ADA
76735	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Restroom 1, 4, 5, 6, 7, 8 Girls Restroom 1, 2, 3, 4, 5, 6, 7, 8	ADA
76736	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Restroom 1, 2, 3, 4, 5, 6, 7, 8 Girls Restroom 1, 2, 3, 4, 5, 6, 7, 8	ADA
76737	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Restroom 1, 2, 4 Girls Restroom 1, 2, 4, 5	ADA
76738	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Boys Restroom 1	ADA
76740	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Restroom 2, 3, 4, 5, 6, 7, 8 Girls Restroom 1, 2, 3, 5, 6, 8	ADA
76743	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Boys Restroom 2, 4, 5, 6, 7, 8 Girls Restroom 2, 3, 4, 6, 7, 8	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76745	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys Restroom 2 Girls Restroom 3	ADA
76747	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom 2, 4, 5, 7, 8	ADA
76748	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom 2	ADA
76749	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys Restroom 2, 3, 5, 6 Girls Restroom 3, 4, 5	ADA
76767	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Girls Restroom 2	ADA
76948	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Locker Room, Girls Locker Room	ADA
76949	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Locker Room, Girls Locker Room	ADA
76951	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls Locker Room	ADA
76952	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls Locker Room	ADA
76953	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Girls locker room	ADA
76954	Winston Churchill High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	PE Office Restroom 141	ADA
88003	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide compliant aisle seats.	Auditorium	ADA
88005	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Common area hallways	ADA
76957	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Men's restroom, Women's restroom	ADA
76958	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Men's restroom	ADA
76959	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Men's restroom	ADA
76960	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Men's restroom, Women's restroom	ADA
76961	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Men's restroom, Women's restroom	ADA
76962	Winston Churchill High School	SHEPHERD STADIUM	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Men's restroom, Women's restroom	ADA
87997	Winston Churchill High School	BUILDING EXTERIOR	Signage	Exterior Accessible Route-Signage	4	Signage directing pedestrians to the nearest accessible building entrance on an accessible route is not present.	Exterior entrances with stairs	ADA
76579	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	DF-1, DF-3	ADA
76580	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	DF-2, DF-4, DF-5, DF-6, DF-9, DF-10, DF-11, DF-12	ADA
76581	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	DF-3	ADA
76595	Winston Churchill High School	BUILDING INTERIOR	Kitchen	Refrigerator/Freezer	4	The clear floor space at the refrigerator/freezer is not positioned for a parallel approach to the space dedicated for the refrigerator/freezer with the centerline of the clear floor or ground space offset 24" maximum from the centerline of the dedicated space.	Staff Lounge	ADA
76839	Winston Churchill High School	BUILDING INTERIOR	Common Areas	Locker Rooms	4	The locker room does not have at least one of the coat hooks within reach range.	Dressing Rooms - Men and Women	ADA
76950	Winston Churchill High School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	Girls Locker Room	ADA