



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Montgomery Blair High School  
51 University Boulevard East  
Silver Spring, Maryland 20901

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**

123821.17R000-178.303

**Date of Report:**

October 29, 2019

**On Site Date:**

October 22-25, 2018



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Montgomery Blair High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Montgomery Blair High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Montgomery Blair High School	60	20	18		35	133
Grand Total	60	20	18		35	133

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
147377	Montgomery Blair High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Tennis Courts	ADA
147378	Montgomery Blair High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Basketball Courts	ADA
147379	Montgomery Blair High School	ATHLETIC FIELDS	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Courts	ADA
151276	Montgomery Blair High School	ATHLETIC FIELDS	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Baseball Field 1	ADA
147342	Montgomery Blair High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 4	ADA
147343	Montgomery Blair High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 3	ADA
147344	Montgomery Blair High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Door 3	ADA
147345	Montgomery Blair High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 2	ADA
147346	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	North Sidewalk near Entrance	ADA
147347	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flare is greater than 1:10 (10%).	Curb Ramp CR8	ADA
147348	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp CR8	ADA
147349	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp CR7	ADA
147354	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR9	ADA
147355	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from CR9 to Auditorium Service Entrance	ADA
147356	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk near CR10	ADA
147357	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR10	ADA
147358	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from CR10 to CR11	ADA
147359	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk near STR13	ADA
147360	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair STR8	ADA
147383	Montgomery Blair High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 15	ADA
147384	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from Door 15 to Football Stadium	ADA
147386	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk between Parking Lot 4 and Football Stadium	ADA
147390	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Sidewalk behind Stadium Bleachers	ADA
147391	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stadium Bleachers	ADA
147394	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk at Baseball Field 2	ADA
147397	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	Curb Ramp CR18 and CR19	ADA
147398	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR17	ADA
147057	Montgomery Blair High School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Girls Dressing Room	ADA
147058	Montgomery Blair High School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Auditorium Ramp R9	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
147071	Montgomery Blair High School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
147336	Montgomery Blair High School	INTERIOR	Interior Access Route	Elevator	1	The elevator does not have compliant two way emergency communication.	Elevator EL1	ADA
147350	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 2: Stall 1	ADA
147351	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 2: Stalls 2 thru 4	ADA
147352	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 2 - Access Aisle 1 and 2	ADA
147353	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2: Stalls 2 and 3	State of Maryland
147361	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 3: Stalls 1 thru 3	ADA
147362	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 3	ADA
147363	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The van parking space is less than 96" wide minimum.	Parking Lot 3: Stall 4	State of Maryland
147364	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: Stall 4	State of Maryland
147365	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: Stalls 1 thru 3	State of Maryland
147366	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2	State of Maryland
147367	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 3: Stalls 5 thru 8	ADA
147368	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 3: Stall 5	ADA
147369	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 3	ADA
147370	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 3	ADA
147371	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 3	ADA
147372	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: Stall 8	State of Maryland
147373	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 3	State of Maryland
147374	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 3: Stalls 5 thru 7	State of Maryland
147399	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Stall 2	ADA
147400	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Stall 1	ADA
147401	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 1	ADA
147402	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The van access aisle is less than 96" wide where the van stall is less than 132" wide.	Parking Lot 1	ADA
147403	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The van parking space is less than 96" wide minimum.	Parking Lot 1	State of Maryland
147404	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1:Stall 3	ADA
147405	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1	State of Maryland
151079	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 4	State of Maryland
151080	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 4	State of Maryland



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
151081	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 4	State of Maryland
151082	Montgomery Blair High School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 4	State of Maryland
147375	Montgomery Blair High School	ATHLETIC FIELDS	Tennis Courts	Bleacher Seating	2	The wheelchair space is not the minimum required dimensions at the bleacher seating for the tennis courts.	Tennis Courts	ADA
147376	Montgomery Blair High School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Tennis Courts	ADA
147393	Montgomery Blair High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball Field 1	ADA
147396	Montgomery Blair High School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball Field 2	ADA
147081	Montgomery Blair High School	EXTERIOR	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Courtyard	ADA
147392	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Football Stadium	ADA
147395	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Gate	2	The gate does not have a smooth surface within 10" of the ground.	Baseball Field 2	ADA
145803	Montgomery Blair High School	INTERIOR	Interior Access Route	Door	2	The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Main Office, Auditorium, Locker Rooms, Weight Room, Gym 1, 2 and 3, Boys and Girls Restrooms	ADA
145804	Montgomery Blair High School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Office and Classroom Doors	ADA
147038	Montgomery Blair High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Financial Services	ADA
147039	Montgomery Blair High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Attendance Office and Guidance Office	ADA
147040	Montgomery Blair High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Main Hall	ADA
147047	Montgomery Blair High School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Art Room 2 and 9	ADA
147049	Montgomery Blair High School	INTERIOR	Interior Access Route	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	Boys Dressing Room	ADA
147056	Montgomery Blair High School	INTERIOR	Interior Access Route	Reach Range	2	At least one each of shelves, clothes rod, drawer, hook, closets or cabinets are not within reach range.	Girls Dressing Room	ADA
147072	Montgomery Blair High School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Room 161	ADA
147079	Montgomery Blair High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria	ADA
147082	Montgomery Blair High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Media Center	ADA
147087	Montgomery Blair High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Stair STR3 Second Floor	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
147043	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Restrooms RR1, RR2, RR3, and RR4	ADA
147337	Montgomery Blair High School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator EL1	ADA
147042	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Restrooms RR4 and RR3	ADA
147044	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR3	ADA
147045	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Restroom RR4	ADA
147046	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Restroom RR4	ADA
147050	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single user / unisex restroom does not have the required clearance.	Boys Dressing Room	ADA
147051	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Dressing Room	ADA
147052	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys and Girls Dressing Rooms	ADA
147054	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys and Girls Dressing Rooms	ADA
147055	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys and Girls Dressing Rooms	ADA
147066	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	A transfer seat is provided but is not compliant.	Physical Education Office 114	ADA
147069	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Boys and Girls Locker Rooms	ADA
147070	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The shower controls are not mounted on the side wall opposite the transfer shower seat.	Boys and Girls Locker Rooms	ADA
147076	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls Restroom RR15	ADA
147331	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Restroom RR25 and RR26	ADA
147387	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Stadium Women's and Men's RR	ADA
147388	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Stadium Women's and Men's RR	ADA
147389	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The accessible dispensers are not at compliant heights.	Stadium Women's and Men's	ADA
147382	Montgomery Blair High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	5	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Sidewalk from tennis Courts to Football Stadium	ADA
147048	Montgomery Blair High School	INTERIOR	Interior Access Route	Sink	5	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Art Room 2	ADA
147059	Montgomery Blair High School	INTERIOR	Employee Work Areas	Locker Rooms	5	The locker room does not have accessible lockers.	Security Office	ADA
147060	Montgomery Blair High School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	5	The locker room does not have a compliant bench.	Security Office and Cafeteria	ADA
147061	Montgomery Blair High School	INTERIOR	Employee Work Areas	Locker Rooms	5	The locker room does not have accessible lockers.	Physical Education Offices 114 and 116	ADA
147062	Montgomery Blair High School	INTERIOR	Restroom	Restroom/Bathroom-Locker	5	The locker area does not have a compliant bench.	Physical Education Offices 114 and 116	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
147083	Montgomery Blair High School	INTERIOR	Interior Access Route	Sink	5	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Workroom	ADA
147335	Montgomery Blair High School	INTERIOR	Common Areas	Vending Machine	5	The vending machines have operable parts which are not within reach range.	333	ADA
147340	Montgomery Blair High School	INTERIOR	Restroom	Restroom/Bathroom-Locker	5	The locker area does not have a compliant bench.	Building Services	ADA
147341	Montgomery Blair High School	INTERIOR	Employee Work Areas	Locker Rooms	5	The locker room does not have accessible lockers.	Building Services	ADA
145805	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Principal's Office	ADA
145806	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Principal's Office	ADA
145807	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Principal's Office	ADA
145808	Montgomery Blair High School	RESTROOMS	Restroom	Protruding Object	5	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Principal's Office	ADA
145809	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Principal's Office	ADA
145810	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	5	The coat hook is not within an allowable reach range.	Principal's Office	ADA
145811	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	5	The provided signage does not have raised or indented characters or pictograph symbols.	Staff Restrooms @ Office	ADA
145812	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Staff Restroom @ Office	ADA
147041	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR4	ADA
147063	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Physical Education Office 114	ADA
147064	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the ambulatory stall is not 17" minimum to 19" maximum from the sidewall.	Physical Education Office 114 and 116	ADA
147065	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	5	The shower controls are not mounted on the side wall opposite the transfer shower seat.	Physical Education Office 116	ADA
147067	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Physical Education Offices 114 and 116, Cafeteria	ADA
147068	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The rear grab bar at the water closet is not compliant.	Physical Education Office 114 and 116	ADA
147073	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Staff RR 12, 13, 17 and 18	ADA
147074	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom RR17 and RR18	ADA
147075	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The accessible dispensers are not at compliant heights.	Staff Restrooms 17 and 18	ADA
147084	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom RR12	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
147085	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom RR12 and RR13	ADA
147086	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Staff Restrooms RR12	ADA
147332	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Restroom RR29	ADA
147333	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Restroom RR29 and RR31	ADA
147334	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Restroom RR27 and RR28	ADA
147338	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The water closet in a single user / unisex restroom does not have the required clearance.	Building Services	ADA
147339	Montgomery Blair High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	5	The spray unit does not have a minimum 59" long hose.	Building Services	ADA