



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Albert Einstein High School
11135 Newport Mill Road
Kensington, Maryland 20895

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-020.303

Date of Report:
October 24, 2019

On Site Date:
November 8-10, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Albert Einstein High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Albert Einstein High School	49	21	43	4		117
Grand Total	49	21	43	4		117

Based on the onsite review, EMG found that barriers to accessibility exist at Albert Einstein High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69066	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1 - Row P1 Stalls 1-3	State of Maryland
69070	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	A van space is not provided.	Parking Lot 1 - Row P1 Stall 4	ADA
69072	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off Area North of Parking Lot 1	ADA
69076	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Student Drop Off Area North of Parking Lot 1	ADA
69080	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk Northeast of Parking Lot 1	ADA
69081	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk Northeast of Parking Lot 1	ADA
69095	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 1, South of Parking Lot 1	ADA
69098	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp 2	ADA
69102	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Curb Ramp 2	ADA
69107	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk East of Parking Lot 1	ADA
69161	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Picnic Table North of Basketball Court	ADA
69180	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	South of Stair 2	ADA
69182	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 2	ADA
69186	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	East of Asphalt Play Courts	ADA
71830	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking lot 1- Row P1 Stall 4	State of Maryland
72051	Bells Mill Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage at the space is not provided.	Parking lot 1- Row P1- Stall 4	State of Maryland
79229	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-5 & 6 (184 stage left and right)	ADA
79231	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-5 & 6 (184 stage left and right)	ADA
79232	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST- Main, 1, 2, 3, 4, 7, 16, 9, 11, 12, 13	ADA
79234	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stain ST-Main	ADA
79235	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R-1, 2, 3	ADA
79236	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-1	ADA
79242	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	All interior doors with closures	ADA
79243	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Interior doors throughout building	ADA
79338	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Rooms 19 & 152	ADA
88428	Albert Einstein High School	BUILDING INTERIOR	Entrance to Building	Building Entrance-Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Majority of interior doors	ADA
88429	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	All interior doors with closures at Public Program	ADA
88430	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Exterior doors throughout building	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
88488	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-3 & 6	ADA
88492	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Room 243	ADA
88493	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-1, 5, 7, 8, 9, 10, girls locker room, boys locker room	ADA
88520	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Exterior doors at Public Program spaces	ADA
69254	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Kitchen Serving Area	ADA
69414	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	ADVISORY: A child's height handrail is not provided.	Stair 1, Stair 2, Center lobby stair	ADA
69435	Bells Mill Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
79172	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Main entry to Auditorium Entry (West side of building), Main entry to Cafeteria ramp (West side of building), Outdoor Seating at Cafeteria to stairs at Cafeteria (South side of building)	ADA
79173	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	From end of public sidewalk to tennis courts, football field, baseball and softball fields	ADA
79184	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-4	ADA
79186	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-4 & 5	ADA
79195	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp R-4	ADA
79196	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-2 & 3	ADA
79197	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp R-2 & 3	ADA
79198	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-19 & 20	ADA
79199	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-14, 15, 16, 17, 18, 19, 20	ADA
79200	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-14	ADA
79203	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball and softball fields	ADA
79213	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-4, 5, 6, 7, 8, 9, 10, 12 and 13	ADA
79214	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1, 2, 3 & 4	ADA
79215	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair ST-2 & 5	ADA
79216	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-5 and 10	ADA
79217	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 1 P2-a	State of Maryland
79218	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1 accessible spaces P1-a, b, c, d, e, f, g; P2-a; P3-a	State of Maryland

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
79219	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1, P2-a Parking Lot 2 Parking Lot 3, P3-a	State of Maryland
79220	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1 all accessible spaces P1-a, b, c, d, e, f, g; P2-a; P3-a	State of Maryland
79221	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1 Accessible spaces P1-a, b, c, d, e, f, g; P2-a; P3-a	ADA
79222	Albert Einstein High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Parking Lot 1	ADA
79223	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Sidewalk at Football stadium visitors side	ADA
79224	Albert Einstein High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-1, 2, 9, 11	ADA
79225	Albert Einstein High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb ramps 3, 4, 6, 9, 10, 11	ADA
79226	Albert Einstein High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student Drop Off at front of building (West side)	ADA
79227	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Picnic area at front of school (west side)	ADA
88247	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2 and 3 P3-a	State of Maryland
88441	Albert Einstein High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Bus Drop-Off at front of Building	ADA
88443	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Stairs have open risers.	Stair ST-12	ADA
88464	Albert Einstein High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-11	ADA
88477	Albert Einstein High School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp R-1	ADA
88478	Albert Einstein High School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1 - P1-a, b, c, d, e, f, g; P3,a Parking Lot 2 Parking Lot 3 - P1-a	State of Maryland
88638	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	Football Field	ADA
69201	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Small School Aged Playground, North of Building	ADA
69154	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Court	ADA
69174	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball/ Soccer Field 1	ADA
69179	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field 2	ADA
69097	Bells Mill Elementary School	BUILDING EXTERIOR	Site Furnishings	Trash Receptacle With Operable Lid	2	Clear ground space is not provided at the trash receptacle with lid requiring operation.	East of Parking Lot 1	ADA
69151	Bells Mill Elementary School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	South of Basketball Court	ADA
79230	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-5 & 6 (184 stage left and right)	ADA
79233	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-7, 9, 12, 13 & 16	ADA
79239	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Signage at all permanent rooms	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
79241	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	All doors with glass	ADA
79336	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	Box Office at Auditorium, ticket sales at Gym, Hall of Fame, Financial Office	ADA
79337	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	All classrooms and workrooms with sinks	ADA
79345	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Laundry- Washer	2	The height of the washing machine is greater than 36" to the top of the unit.	Room 185W	ADA
79346	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Laundry- Dryer	2	The dryer controls are not within reach range.	Room 185W	ADA
87977	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic	Elevator 1	ADA
87986	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridors	ADA
88426	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Signage at all permanent rooms for Public Program	ADA
88427	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	All doors with glass at public program areas	ADA
88479	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Lobby at Gym and Cafeteria	ADA
88480	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Break Rooms	ADA
88501	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	All classrooms and workrooms with sinks at Public Program	ADA
69250	Bells Mill Elementary School	BUILDING INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	All Purpose Room	ADA
69416	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Media Center Office	ADA
69428	Bells Mill Elementary School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
69429	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Staff Lounge	ADA
69929	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34".	Health Suite	ADA
72063	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Exit doors	ADA
79201	Albert Einstein High School	EXTERIOR	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball and Softball fields	ADA
79202	Albert Einstein High School	EXTERIOR	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Baseball and softball fields	ADA
79211	Albert Einstein High School	EXTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Concession stand at Sports fields	ADA
79212	Albert Einstein High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	At Concessions area at Sports fields and tennis courts	ADA
79228	Albert Einstein High School	EXTERIOR	Common Areas	Dining And Work Surface	2	The dining table does not have compliant knee and toe clearance.	Outdoor tables at Cafeteria	ADA
88637	Albert Einstein High School	EXTERIOR	Football Field	Player Seating	2	A wheelchair space is not provided at each team seating for the football field.	Football Field	ADA
69193	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Pre-School Age Playground	ADA
69194	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	Clear ground space is not provided at each ground play component, and each elevated play component connected by a ramp.	Pre-School Age Playground	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69198	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Small School Aged Playground- North of Building	ADA
69203	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Small School Aged Playground- North of Building	ADA
69205	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Small School Aged Playground - North of Building	ADA
69209	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	The ground level component or elevated component accessed by ramp is required to be on an accessible route but is not within a child's reach range.	Large School Aged Playground -North of Building	ADA
69184	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Play Court South of Stair 2	ADA
69187	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Pre-School Playground	ADA
69190	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Pre-School Age Playground	ADA
69211	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Large School Aged Playground - North of Building	ADA
69212	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Large School Aged Playground, North of Building	ADA
69213	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer steps are higher than 8" each.	Large School Aged Playground, North of Building	ADA
69214	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface	2	The ground surface has not been inspected and maintained regularly.	Large School Aged Playground	ADA
79237	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assistive listening signage is not compliant or is not provided.	Auditorium and Gym	ADA
79238	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All exterior doors	ADA
79244	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-19, 20, 21, 117M, 117W, 119, 127, 129, 155W, 187a, 188a, 194d, 194e, 213, 215, 247, 251, 2001, 2002, 3005, 3006	ADA
79246	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-19, 20, 117M, 117W, 119, 127, 129, 155W, 155M, 187a, 194d, 194e, 213, 215, 247, 251, 278,W, 2001, 2002, 3005, 3006	ADA
79310	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom RR- 151a, 2001, 3005, 3006	ADA
79311	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-19, 117W, 117M, 119, 155M, 155W, 187a, 188a, 194d, 194e, 247, 251, 3005, 3006	ADA
79328	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom RR-17	ADA
79329	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-19, 21, 117M, 155W, 155M, 187a, 213, 215,	ADA
79330	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom RR-21, 129, 215	ADA
79331	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-155M, 278W, 278M	ADA
79333	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide compliant aisle seats.	Auditorium	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
79334	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Auditorium	ADA
79339	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not compliant.	Restroom RR-2001, 2002, 194d 194e, 187b, 188b,	ADA
79340	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The shower enclosure is not 30" minimum by 60" minimum.	Boys and girls locker rooms	ADA
79341	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not provided.	Boys and girls locker room	ADA
79342	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	A shower seat is not provided.	Boys and Girls locker room	ADA
79343	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The location of the roll-in shower controls is not compliant.	Boys and girls locker room	ADA
79344	Albert Einstein High School	BUILDING INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Boys and girls locker room, dressing room at dance studio 3001	ADA
87976	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator 1	ADA
87980	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Elevator	3	Visible and audible signal fixtures indicating which car is answering the call and the car's direction of travel are not compliant.	Elevator 1 and 2	ADA
87984	Albert Einstein High School	BUILDING INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Lockers in Hallways	ADA
88481	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	RR-21	ADA
88484	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RR-17	ADA
88485	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom RR-155M, 278m, 278w	ADA
88487	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom RR-128a	ADA
88521	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-16, 116, 128a, 128b, 141, 143, 151a, 229W, 229M, 257, 261	ADA
88522	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-196, 197, MSW, MSM	ADA
88529	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-16, 17, 116, 128a, 128b, 141, 143, 151a, 229W, 229M, 257	ADA
88530	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-196, 197, MSW, MSM	ADA
88532	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom RR- 141, 143, 229W, 257, 261	ADA
88533	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom RR- MSW	ADA
88534	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR-16, 17, 128a, 128b, 141, 143, 151a, 229W, 229M, 257, 261	ADA
88535	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-16, 128a, 141, 143	ADA
88536	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR-MSW, 197	ADA
88537	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom RR-MSM, 197	ADA
88539	Albert Einstein High School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom RR-17	ADA
69256	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Kitchen Restroom	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69257	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Kitchen Restroom	ADA
69259	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Restrooms 142, 140, 113, 230, 204, 206	ADA
69260	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restrooms 142, 140, 113, 115, 23, 230, 204, 206, 220, 224	ADA
69261	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The grab bars are not located per children's specifications in the wheelchair stall used primarily by children.	Restrooms 142, 142, 113, 115, 23, 230, 204, 206, 220, 224	ADA
69262	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms 140, 142, 113, 230, 204, 206, 220, 224	ADA
69263	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms 142, 140, 113, 115, 23, 230, 204, 206, 220	ADA
69387	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 144	ADA
69388	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 144	ADA
69389	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 144	ADA
69390	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 144	ADA
69393	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom 115	ADA
69394	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 111	ADA
69395	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 111	ADA
69396	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 111	ADA
69397	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 111	ADA
69398	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 111	ADA
69399	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 131	ADA
69400	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 131	ADA
69401	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff restroom 131	ADA
69402	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 131	ADA
69403	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff restroom 131	ADA
69404	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 156	ADA
69405	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 156	ADA
69406	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff restroom 156	ADA
69407	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 156	ADA
69408	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom 242	ADA
69409	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom 242	ADA
69410	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 242	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69411	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Restroom 23	ADA
69412	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Girls Restroom 23	ADA
69413	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Boys Restroom 230	ADA
69438	Bells Mill Elementary School	BUILDING INTERIOR	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Room 147E	ADA
69446	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Room 147E	ADA
69448	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Room 147E	ADA
69453	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Room 147E	ADA
69585	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Room 147E	ADA
69590	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Room 147E	ADA
69596	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA
69601	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The grab bars are not located per children's specifications in the wheelchair stall used primarily by children.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA
69688	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	Restrooms 125A, 120A, 129A, 132A, 128A, 164A	ADA
69689	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom 125A, 120A, 129A, 132A, 128A, 164A	ADA
69919	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom 100E	ADA
69921	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom 100E	ADA
69391	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 144	ADA
69392	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom 115	ADA
69922	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom 100E	ADA
69923	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Restroom 100E	ADA
69926	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom 100E	ADA
69931	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Room 102D	ADA
69932	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Room 102D	ADA
69937	Bells Mill Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom 102D	ADA
79204	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restrooms at Sports Fields	ADA
79205	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restrooms at Sports fields	ADA
79206	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restrooms at Sports fields	ADA
79207	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restrooms at Sports fields	ADA
79208	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restrooms at Sports fields	ADA
79209	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms at Sports fields	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
79210	Albert Einstein High School	EXTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Restrooms at Sports fields	ADA
79248	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Turning Space	4	A compliant turning space is not provided.	Restroom RR-20, 21, 127, 129, 213, 215, 247, 251, 2001, 2004, 3005, 3006	ADA
79332	Albert Einstein High School	BUILDING INTERIOR	Kitchen	Kitchen- Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Room #238 (Hospitality Classroom)	ADA
88531	Albert Einstein High School	BUILDING INTERIOR	Interior Access Route	Turning Space	4	A compliant turning space is not provided.	Restroom RR-MSW, MSM	ADA
69424	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classrooms 229, 233, 235, 239, 236, 240, 208, 212, 214, 218, 209, 213, 217, 219, 223, 132, 128, 129, 125, 154, 150, 148, 159, 155, 153, 149, 120, 121, 124	ADA
69425	Bells Mill Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms 229, 233, 235, 239, 236, 240, 208, 212, 214, 218, 209, 213, 217, 219, 223, 132, 128, 129, 125, 154, 150, 148, 159, 155, 153, 149, 120, 121, 124	ADA
79182	Albert Einstein High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route-Passing Area	4	The accessible route is less than 60" wide and longer than 200 LF, but does not have a passing area.	From Home team side to visitors at Football field	ADA
69208	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	4	The play component which has manipulative or interactive features that require reaching is not within the child's reach range.	Small School Aged Playground - North of Building	ADA
69210	Bells Mill Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	4	The play component which has manipulative or interactive features that require reaching is not within the child's reach range.	Large School Aged Playground - North of Building	ADA