Montgomery County Public SchoolsSummary of Contracts - Vendor SequenceBid 974410/09/2024Bid 9744Dam 1 of 8

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 1 of 8 90945

					•	Phone: (240) 740-75
up Item			Unit			
nber Number	Description	Unit	Price	Brand	Model	Vendor Name
42086	Wood Floor Refinishing less than 100 Sq. Ft. (w/water base sealer and finish Arena 50 and	Sq. Ft	9.00	Overtime Rate \$10.35		MASTER CARE
	300)					49797FLOORING INC
42087	Wood Floor Refinishing 100 to 1,000 Sq. Ft.	Sq. Ft	2.60	Overtime Rate \$2.99		MASTER CARE
	(w/water base sealer and finish Arena 50 and 300)	1				49797FLOORING INC
42088	Wood Floor Refinishing 1,001 to 25,000 Sq. Ft.	Sq, Ft	1.80	Overtime Rate \$2.10		MASTER CARE
	(w/water base sealer and finish Arena 50 and 300)					49797FLOORING INC
42089	Repairs of hardwood floating floor (2 ¼" maple	Sq. Ft	13.85	Overtime Rate \$15.93		MASTER CARE
	typical) 0 to 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300)	1				49797FLOORING INC
42090	Repairs of hardwood floating floor (2 ¼" maple	Sq. Ft	11.50	Overtime Rate \$13.23		MASTER CARE
	typical) 100 Sq. Ft. and over (w/water base sealer and finish Arena 50 and 300)	- 1				49797FLOORING INC
42091	Repairs of Anchored Resilient Sleeper Floor	Sq. Ft	15.00	Overtime Rate \$17.25		MASTER CARE
	systems 0 to 100 Sq. Ft. as specified herein	1				49797FLOORING INC
42092	Repairs of Anchored Resilient Sleeper Floor	Sq. Ft	13.65	Overtime Rate \$15.65		MASTER CARE
	System 101 Sq. Ft. and over as specified herein	Ĩ				49797FLOORING INC
42093	Furnish and install New Anchored Resilient	Sq. Ft	13.35	Overtime Rate \$15.30		MASTER CARE
	Sleeper Floor System as specified herein	1				49797FLOORING INC
42094	Repairs of Direct Glue Down Wood Flooring System. 0 to 100 Sg. Ft. as specified herein	Sq. Ft	16.00	Overtime Rate \$18.40		MASTER CARE
	system. 0 to 100 sq. rl. as specified herein	1				49797FLOORING INC
42095	Repairs of Direct Glue Down Wood Flooring	Sq. Ft	15.00	Overtime Rate \$17.25		MASTER CARE
	System. 101 Sq. Ft. and over as specified hereir	1				49797FLOORING INC
42096	Furnish and install New Direct Glue Down Wooc Flooring System as specified herein	Sq. Ft	11.55	Overtime Rate \$13.29		MASTER CARE
	riooning system as specified herein	-				49797FLOORING INC
42097	Repair Direct Glue Down w/shock Pad Wood	Sq, Ft	15.00	Overtime Rate \$17.25		MASTER CARE
	Flooring System 0 to 100 Sq. Ft. as specified herein	*				49797FLOORING INC
42098	Repair Direct Glue Down w/Shock Pad Wood	Sq. Ft	14.50	Overtime Rate \$16.70		MASTER CARE
	Flooring System. 101 Sq. Ft. and over as specified herein	1				49797FLOORING INC
42099	Furnish and install New Direct Glue Down	Sq. Ft	13.20	Overtime Rate \$15.18		MASTER CARE
	w/Shock Pad Wood Flooring System as specified herein	- 1				49797FLOORING INC

Montgomery County Public Schools Summary of Contracts - Vendor Sequence Bid 9744

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 2 of 8 90945

			Term of Contract: 07/0	1/2024 <u>To:</u>	<u>06/30/2025</u>	Buyer: Stephanie Dorah	Phone: (240) 740-753
	Item			Unit			
mber	Number	Description	Unit	Price	Branc	Model	Vendor Name
	42100	Typical rubber cove base along floor perimete	Ln. Ft	9.00	Overtime Rate \$10.	35	MASTER CARE
							49797FLOORING INC
	42101	Typical Rubber Cove Base along Floor	Each	9.00	Overtime Rate \$10.	35	MASTER CARE
		Perimeter	Latin	2.00			49797FLOORING INC
	42102	Typical Wood Base Along Floor Perimeter	Ln. Ft	2.50	Overtime Rate \$2.9	0	MASTER CARE
							49797FLOORING INC
	42103	Typical Steel Angle Base 4" Along Floor	Ln. Ft	19.50	Overtime Rate \$22.	45	MASTER CARE
		Perimeter					49797FLOORING INC
	42104	Typical Aluminum Angle Base 4" Along Floor	Ln. Ft	21.00	Overtime Rate \$24.	15	MASTER CARE
		Perimeter					49797FLOORING INC
	42105	Typical Wood Doorway Threshold	Ln. Ft	5.00	Overtime Rate \$5.7	5	MASTER CARE
							49797FLOORING INC
	42106	Carpentry work (One person) for Unspecified	Per Hr	68.50	Overtime Rate \$102	2.75	MASTER CARE
		Work					49797FLOORING INC
	42107	Paint Game Lines (Layout & Painting Athletic	Ln. Ft	1.25	Overtime Rate \$1.4	5	MASTER CARE
		Courts on Wood Floors) 2" or less in width					49797FLOORING INC
	42108	Solid 1 Color Painted Areas (typical Boarders	Ln. Ft	1.10	Overtime Rate \$1.2	5	MASTER CARE
		w/no Lettering) (Layout and Painting Athletic Courts on Wood Floor Systems					49797FLOORING INC
	42109	Solid Painted Areas including Clear Lettering	Sq. Ft	2.10	Overtime Rate \$2.4	5	MASTER CARE
		up to 36"(Layout and Painting Athletic Courts on Wood Floor Systems)	1				49797FLOORING INC
	42110	Painting of Artwork 1 Color (Logos, Stand-alone Lettering, etc.)	Sq. Ft	13.00	Overtime Rate \$15.	00	MASTER CARE
			*				49797FLOORING INC
	42111	Painting of Artwork (Logos with 3 or more different Colors)	Sq. Ft	25.00	Overtime Rate \$28.	75	MASTER CARE
			-				49797FLOORING INC
	42112	Removal and Disposal of Hazardous Material 0	Sq. Ft	8.50	Overtime Rate \$9.8	0	MASTER CARE
		to ¼"	I				49797FLOORING INC
	42113	Removal and Disposal of Hazardous Material	Sq. Ft	10.00	Overtime Rate \$11.	50	MASTER CARE
		over ¼"	1				49797FLOORING INC

Montgomery County Public Schools Summary of Contracts - Vendor Sequence Bid 9744

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 3 of 8 90945

			01/2024 <u>To:</u>		ephanie Dorah	Phone: (240) 740-753
roup Item			Unit			
umber Number	Description	Unit	Price	Brand	Model	Vendor Name
42114	Shot Blasting	Sq. Ft	.65	Overtime Rate \$.75		MASTER CARE
		•				49797FLOORING INC
42115	Grinding Down Concrete 0 to ½"	Sq. Ft	7 75	Overtime Rate \$8.95		MASTER CARE
			,,,,,			49797FLOORING INC
42116	Self-leveling of Concrete 0 ¼"	Sq. Ft	4 95	Overtime Rate \$5.70		MASTER CARE
-			,0			49797FLOORING INC
42117	Self-leveling of Concrete 1/4" to 1/2"	Sq. Ft	6.25	Overtime Rate \$7.20		MASTER CARE
		54.11	0.20			49797FLOORING INC
42118	Self-leveling of Concrete ½" to 1"	Sq. Ft	7 75	Overtime Rate \$8.95		MASTER CARE
		54.11	1110			49797FLOORING INC
42119	Volleyball Floor Plates Only as specified hereir	n Each	225.00	Overtime Rate \$225.00		MASTER CARE
	Senoh Model KA25-F	Luon	220.00			49797FLOORING INC
42120	Volleyball Floor Sleeves Only as specified	Each	600.00	Overtime Rate \$600.00		MASTER CARE
	herein. Senoh Model KA25	Luon	000.00			49797FLOORING INC
42121	Volleyball Floor Plates and Sleeves as specifie	• Each	860.00	Overtime Rate \$860.00		MASTER CARE
	herein. Senoh Model KA25					49797FLOORING INC
42122	Badminton Floor Plates Only as specified	Each	200.00	Overtime Rate \$200.00		MASTER CARE
	herein. Senoh Model KA45-F					49797FLOORING INC
42123	Badminton Floor Sleeves Only as specified	Each	550.00	Overtime Rate \$550.00		MASTER CARE
	herein. Senoh Model KA45-S					49797FLOORING INC
42124	Badminton Floor Plates and Sleeves as	Each	895.00	Overtime Rate \$895.00		MASTER CARE
	specified herein. Senoh Model KA45-S	2	5,0.00			49797FLOORING INC
42125	Steel Volleyball upright (pin-stop as specified	Each	1,195.00	Overtime Rate \$1195.00		MASTER CARE
	herein. Senoh Model DE11		,			49797FLOORING INC
42126	Steel Badminton upright as specified herein. Senoh Model DE11	Each	370.00	Overtime Rate \$370.00		MASTER CARE
	Senoh Model DE11	Luon	570.00			49797FLOORING INC
42127	Heavy Duty Volleyball upright Net Crank and	Each	425.00	Overtime Rate \$425.00		MASTER CARE
	Handle. Senoh Model HDNR-R	Luch	125.00			49797FLOORING INC

Montgomery County Public SchoolsSummary of Contracts - Vendor SequenceBid 974410/09/2024Bid 9744Bare 4 of 8

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 4 of 8 90945

		Term of Contract:	07/01/2024 <u>To</u>	<u>):</u> 06/30/2025	Buyer:	Stephanie Dorah	Phone: (240) 740-7538
roup Item			Unit				
mber Number	Description	Unit	Price	Bra	nd	Model	Vendor Name
42128	Storage Cart (holds 6 uprights) Senoh Model DU22	Each	1,175.00	Overtime Rate \$	1175.00		MASTER CARE 49797FLOORING INC
42129	Wall Rack (holds 4 uprights) Senoh Model BWR10	Each	230.00	Overtime Rate \$	230.00		MASTER CARE 49797FLOORING INC
42130	Technora Valleyball Net Senoh Model HM50	Each	475.00	Overtime Rate \$	475.00		MASTER CARE 49797FLOORING INC
42131	Shortened Technora Volleyball Net Senoh Model HM50	Each	475.00	Overtime Rate \$	475.00		MASTER CARE 49797FLOORING INC
42132	Badminton Net Senoh Model SGN-20	Each	100.00	Overtime Rate \$	100.00		MASTER CARE 49797FLOORING INC
42133	Shortened Badminton Net Senoh Model SBN-19.5	Each	100.00	Overtime Rate \$	100.00		MASTER CARE 49797FLOORING INC
42135	Typical Aluminum Doorway Threshold	Ln. Ft	19.00	Overtime Rate \$2	21.85		MASTER CARE 49797FLOORING INC
42136	Painting of Artwork 1 Color (Logos, Lettering, Etc.)	Sq. Ft	18.25	; Overtime Rate \$	21.00		MASTER CARE 49797FLOORING INC
44221	Floor Marx	Each	250.00	Overtime Rate \$	250.00		MASTER CARE 49797FLOORING INC
	(6 pack master set)						497977
44294	Carpenters Per Hour	Per Hr	68.50	Overtime Rate \$ \$68.50	102.75	Davis Bacon Rate	MASTER CARE 49797FLOORING INC
44296	Painters	Per Hr	72.45	Overtime Rate \$ \$72.45	108.67	Davis Bacon Rate	MASTER CARE 49797FLOORING INC
	Per Hour						
44298	Unskilled Labor Per Hour	Per Hr	35.00	Overtime Rate \$ \$45.00	52.50	Davis Bacon Rate	MASTER CARE 49797FLOORING INC
42350		Sq. Ft	7.74	OVERTIME RAT	E \$9.17		WEYER'S FLOOR 49952SERVICE, INC.
42351	300) Wood Floor Refinishing 100 to 1,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300)	Sq. Ft	2.78	OVERTIME RAT	E \$3.22		WEYER'S FLOOR 49952SERVICE, INC.

10/09/2024 Montgomery County Public Schools <u>Summary of Contracts - Vendor Sequence</u> <u>Bid</u> 9744

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 5 of 8 90945

roup Item			Unit			
umber Number	Description	Unit	Price	Brand	Model	Vendor Name
42352	Wood Floor Refinishing 1,001 to 25,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300)	Sq. Ft	1.90	OVERTIME RATE \$2.18		WEYER'S FLOOR 49952SERVICE, INC.
42353	Repairs of hardwood floating floor (2 ¼" maple typical) 0 to 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300)	Sq. Ft	16.33	OVERTIME RATE \$19.46		WEYER'S FLOOR 49952SERVICE, INC.
42354	Repairs of hardwood floating floor (2 ¼" maple typical) 100 Sq. Ft. and over (w/water base sealer and finish Arena 50 and 300)	Sq. Ft	13.81	OVERTIME RATE \$17.08		WEYER'S FLOOR 49952SERVICE, INC.
42355	Repairs of Anchored Resilient Sleeper Floor systems 0 to 100 Sq. Ft. as specified herein	Sq. Ft	18.72	OVERTIME RATE \$19.35		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42356	Repairs of Anchored Resilient Sleeper Floor System 101 Sq. Ft. and over as specified herein	Sq. Ft	16.67	OVERTIME RATE \$17.30		WEYER'S FLOOR 49952SERVICE, INC.
42357	Furnish and install New Anchored Resilient Sleeper Floor System as specified herein	Sq. Ft	18.07	OVERTIME RATE \$18.74		WEYER'S FLOOR 49952SERVICE, INC.
42358	Repairs of Direct Glue Down Wood Flooring System. 0 to 100 Sq. Ft. as specified herein	Sq. Ft	15.78	OVERTIME RATE \$16.39		WEYER'S FLOOR 49952SERVICE, INC.
42359	Repairs of Direct Glue Down Wood Flooring System. 101 Sq. Ft. and over as specified hereir	Sq. Ft	15.24	OVERTIME RATE \$15.79		WEYER'S FLOOR 49952SERVICE, INC.
42360	Furnish and install New Direct Glue Down Wooc Flooring System as specified herein	Sq. Ft	14.03	OVERTIME RATE \$17.37		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42361	Repair Direct Glue Down w/shock Pad Wood Flooring System 0 to 100 Sq. Ft. as specified herein	Sq. Ft	17.63	OVERTIME RATE \$18.59		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42362	Repair Direct Glue Down w/Shock Pad Wood Flooring System. 101 Sq. Ft. and over as specified herein	Sq. Ft	17.03	OVERTIME RATE \$18.10		WEYER'S FLOOR 49952SERVICE, INC.
42363	Furnish and install New Direct Glue Down w/Shock Pad Wood Flooring System as specified herein	Sq. Ft	15.81	OVERTIME RATE \$16.89		WEYER'S FLOOR 49952SERVICE, INC.
42364	Typical rubber cove base along floor perimete	Ln. Ft	8.25	OVERTIME RATE \$8.55		WEYER'S FLOOR 49952SERVICE, INC.
42365	Typical Rubber Cove Base along Floor Perimeter	Each	8.25	OVERTIME RATE \$8.55		WEYER'S FLOOR 49952SERVICE, INC.

10/09/2024 Montgomery County Public Schools <u>Summary of Contracts - Vendor Sequence</u> <u>Bid</u> 9744

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 6 of 8 90945

		Term of Contract: 07/01	/ 2024 <u>To:</u>	06/30/2025 <u>Buyer:</u> Step	hanie Dorah	<u>Phone:</u> (240) 740-7538
roup Item			Unit			
umber Number	Description	Unit	Price	Brand	Model	Vendor Name
42366	Typical Wood Base Along Floor Perimeter	Ln. Ft	2.31	OVERTIME RATE \$2.56		WEYER'S FLOOR 49952SERVICE, INC.
42367	Typical Steel Angle Base 4" Along Floor Perimeter	Ln. Ft	30.74	OVERTIME RATE \$35.87		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42368	Typical Aluminum Angle Base 4" Along Floor Perimeter	Ln. Ft	30.74	OVERTIME RATE \$35.87		WEYER'S FLOOR 49952SERVICE, INC.
42369	Typical Wood Doorway Threshold	Ln. Ft	5.12	OVERTIME RATE \$5.64		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42370	Carpentry work (One person) for Unspecified Work	Per Hr	57.39	OVERTIME RATE \$67.63		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42371	Paint Game Lines (Layout & Painting Athletic Courts on Wood Floors) 2" or less in width	Ln. Ft	1.41	OVERTIME RATE \$1.70		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42372	Solid 1 Color Painted Areas (typical Boarders w/no Lettering) (Layout and Painting Athletic Courts on Wood Floor Systems	Ln. Ft	1.13	OVERTIME RATE \$1.31	WEYER'S FLOOR 49952SERVICE, INC.	
42373	Solid Painted Areas including Clear Lettering up to 36"(Layout and Painting Athletic Courts on Wood Floor Systems)	Sq. Ft	2.25	OVERTIME RATE \$2.59		WEYER'S FLOOR 49952SERVICE, INC.
42374	Painting of Artwork 1 Color (Logos, Stand-alon Lettering, etc.)	• Sq. Ft	13.68	OVERTIME RATE \$16.39		WEYER'S FLOOR 49952SERVICE, INC.
42375	Painting of Artwork (Logos with 3 or more different Colors)	Sq. Ft	27.38	OVERTIME RATE \$29.64		WEYER'S FLOOR 49952SERVICE, INC.
42376	Removal and Disposal of Hazardous Material (to ¼"	9 Sq. Ft	9.72	OVERTIME RATE \$10.42		WEYER'S FLOOR 49952SERVICE, INC.
42378	Removal and Disposal of Hazardous Material over 1/4"	Sq. Ft	11.08	OVERTIME RATE \$11.16		WEYER'S FLOOR 49952SERVICE, INC.
42379	Shot Blasting	Sq. Ft	.63	OVERTIME RATE \$.68		WEYER'S FLOOR 49952SERVICE, INC.
42380	Grinding Down Concrete 0 to 1/2"	Sq. Ft	8.19	OVERTIME RATE \$8.61		WEYER'S FLOOR 49952SERVICE, INC.

10/09/2024 Montgomery County Public Schools <u>Summary of Contracts - Vendor Sequence</u> <u>Bid 9744</u>

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 7 of 8 90945

		Term of Contract: 07/0	01/2024 <u>To:</u>	06/30/2025 <u>Buyer:</u> Steph	nanie Dorah	Phone: (240) 740-7538
roup Item			Unit			
umber Number	Description	Unit	Price	Brand	Model	Vendor Name
42381	Self-leveling of Concrete 0 ¼"	Sq. Ft	5.58	OVERTIME RATE \$5.71		WEYER'S FLOOR 49952SERVICE, INC.
42382	Self-leveling of Concrete $\frac{1}{4}$ " to $\frac{1}{2}$ "	Sq. Ft	6.82	OVERTIME RATE \$6.95		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42383	Self-leveling of Concrete $\frac{1}{2}$ " to 1"	Sq. Ft	8.56	OVERTIME RATE \$8.68		WEYER'S FLOOR 49952SERVICE, INC.
42384	Volleyball Floor Plates Only as specified herein Senoh Model KA25-F	n Each	242.84	OVERTIME RATE \$253.84		WEYER'S FLOOR ₄₉₉₅₂ SERVICE, INC.
42385	Volleyball Floor Sleeves Only as specified herein. Senoh Model KA25	Each	619.09	OVERTIME RATE \$650.24		WEYER'S FLOOR 49952SERVICE, INC.
42386	Volleyball Floor Plates and Sleeves as specifie herein. Senoh Model KA25	e Each	861.94	OVERTIME RATE \$860.91		WEYER'S FLOOR 49952SERVICE, INC.
42387	Badminton Floor Plates Only as specified herein. Senoh Model KA45-F	Each	220.75	75 OVERTIME RATE \$231.30		WEYER'S FLOOR 49952SERVICE, INC.
42388	Badminton Floor Sleeves Only as specified herein. Senoh Model KA45-S	Each	619.09	OVERTIME RATE \$650.05		WEYER'S FLOOR 49952SERVICE, INC.
42389	Badminton Floor Plates and Sleeves as specified herein. Senoh Model KA45-S	Each	839.86	OVERTIME RATE \$998.03		WEYER'S FLOOR 49952SERVICE, INC.
42390	Steel Volleyball upright (pin-stop as specified herein. Senoh Model DE11	Each	1,324.55	OVERTIME RATE \$1324.55		WEYER'S FLOOR 49952SERVICE, INC.
42391	Steel Badminton upright as specified herein. Senoh Model DE11	Each	404.71	OVERTIME RATE \$404.71		WEYER'S FLOOR 49952SERVICE, INC.
42392	Heavy Duty Volleyball upright Net Crank and Handle. Senoh Model HDNR-R	Each	470.95	OVERTIME RATE \$470.95		WEYER'S FLOOR 49952SERVICE, INC.
42393	Storage Cart (holds 6 uprights) Senoh Model DU22	Each	1,302.47	OVERTIME RATE \$1302.47		WEYER'S FLOOR 49952SERVICE, INC.
42394	Wall Rack (holds 4 uprights) Senoh Model BWR10	Each	248.58	OVERTIME RATE \$248.58		WEYER'S FLOOR 49952SERVICE, INC.

10/09/2024 Montgomery County Public Schools <u>Summary of Contracts - Vendor Sequence</u> <u>Bid</u> 9744

Sports Wood Flooring System at Various Facilities

Cycle No: 2

Page 8 of 8 90945

			Term of Contract:	07/01/2024 <u>T</u>	<u>o:</u> 06/30/2025	Buyer:	Stephanie Dorah	Phone: (240) 740-7538
Group				Unit				
Number	Number	Description	Unit	Price	e Bra	and	Model	Vendor Name
	42395	Technora Valleyball Net Senoh Model HM50	Each	522.4	5 OVERTIME RA	TE \$522.46		WEYER'S FLOOR 49952SERVICE, INC.
	42396	Shortened Technora Volleyball Net Senoh Model HM50	Each	522.4	5 OVERTIME RA	TE \$522.46		WEYER'S FLOOR 49952SERVICE, INC.
	42397	Badminton Net Senoh Model SGN-20	Each	103.0	OVERTIME RA	TE \$103.01		WEYER'S FLOOR 49952SERVICE, INC.
	42398	Shortened Badminton Net Senoh Model SBN-19.5	Each	103.0	OVERTIME RA	TE \$103.01		WEYER'S FLOOR 49952SERVICE, INC.
	42399	Typical Aluminum Doorway Threshold	Ln. Ft	30.74	1 OVERTIME RA	TE \$33.82		WEYER'S FLOOR 49952SERVICE, INC.
	42401	Painting of Artwork 1 Color (Logos, Lettering, Etc.)	Sq. Ft	20.5	1 OVERTIME RA	TE \$24.58		WEYER'S FLOOR 49952SERVICE, INC.
	44292	Floor Marx (6 pack master set)	Each	308.6	3 OVERTIME RA	TE \$308.63		WEYER'S FLOOR 49952SERVICE, INC.
	44293	Carpenters	Per Hr	61.4	OVERTIME RA RATE \$47.91	TE \$92.23	DAVIS BACON	WEYER'S FLOOR 49952SERVICE, INC.
		Per Hour						49952
	44295	Painters Per Hour	Per Hr	61.4	OVERTIME RA RATE \$40.97	TE \$92.23	DAVIS BACON	WEYER'S FLOOR 49952SERVICE, INC.
	44297	Unskilled Labor	Per Hr	46.1	OVERTIME RA RATE \$37.85	TE \$69.17	DAVIS BACON	WEYER'S FLOOR
		Per Hour						₄₉₉₅₂ SERVICE, INC.