

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|--|--------|------------|-----------------------|-------|-----------------------------------|
| | 42086 | Wood Floor Refinishing less than 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 9.00 | Overtime Rate \$10.35 | | MASTER CARE 49797 FLOORING INC |
| | 42087 | Wood Floor Refinishing 100 to 1,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 2.60 | Overtime Rate \$2.99 | | MASTER CARE 49797 FLOORING INC |
| | 42088 | Wood Floor Refinishing 1,001 to 25,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 1.80 | Overtime Rate \$2.10 | | MASTER CARE 49797 FLOORING INC |
| | 42089 | Repairs of hardwood floating floor (2 1/4" maple typical) 0 to 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 13.85 | Overtime Rate \$15.93 | | MASTER CARE 49797 FLOORING INC |
| | 42090 | Repairs of hardwood floating floor (2 1/4" maple typical) 100 Sq. Ft. and over (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 11.50 | Overtime Rate \$13.23 | | MASTER CARE 49797 FLOORING INC |
| | 42091 | Repairs of Anchored Resilient Sleeper Floor systems 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 15.00 | Overtime Rate \$17.25 | | MASTER CARE 49797 FLOORING INC |
| | 42092 | Repairs of Anchored Resilient Sleeper Floor System 101 Sq. Ft. and over as specified herein | Sq. Ft | 13.65 | Overtime Rate \$15.65 | | MASTER CARE 49797 FLOORING INC |
| | 42093 | Furnish and install New Anchored Resilient Sleeper Floor System as specified herein | Sq. Ft | 13.35 | Overtime Rate \$15.30 | | MASTER CARE 49797 FLOORING INC |
| | 42094 | Repairs of Direct Glue Down Wood Flooring System. 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 16.00 | Overtime Rate \$18.40 | | MASTER CARE 49797 FLOORING INC |
| | 42095 | Repairs of Direct Glue Down Wood Flooring System. 101 Sq. Ft. and over as specified herein | Sq. Ft | 15.00 | Overtime Rate \$17.25 | | MASTER CARE 49797 FLOORING INC |
| | 42096 | Furnish and install New Direct Glue Down Wood Flooring System as specified herein | Sq. Ft | 11.55 | Overtime Rate \$13.29 | | MASTER CARE 49797 FLOORING INC |
| | 42097 | Repair Direct Glue Down w/shock Pad Wood Flooring System 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 15.00 | Overtime Rate \$17.25 | | MASTER CARE 49797 FLOORING INC |
| | 42098 | Repair Direct Glue Down w/Shock Pad Wood Flooring System. 101 Sq. Ft. and over as specified herein | Sq. Ft | 14.50 | Overtime Rate \$16.70 | | MASTER CARE 49797 FLOORING INC |
| | 42099 | Furnish and install New Direct Glue Down w/Shock Pad Wood Flooring System as specified herein | Sq. Ft | 13.20 | Overtime Rate \$15.18 | | MASTER CARE 49797 FLOORING INC |

Sports Wood Flooring System at Various Facilities

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|--------------|---|--------|------------|------------------------|-------|-----------------------------------|
| | 42100 | Typical rubber cove base along floor perimeter | Ln. Ft | 9.00 | Overtime Rate \$10.35 | | MASTER CARE 49797 FLOORING INC |
| | 42101 | Typical Rubber Cove Base along Floor Perimeter | Each | 9.00 | Overtime Rate \$10.35 | | MASTER CARE 49797 FLOORING INC |
| | 42102 | Typical Wood Base Along Floor Perimeter | Ln. Ft | 2.50 | Overtime Rate \$2.90 | | MASTER CARE 49797 FLOORING INC |
| | 42103 | Typical Steel Angle Base 4" Along Floor Perimeter | Ln. Ft | 19.50 | Overtime Rate \$22.45 | | MASTER CARE 49797 FLOORING INC |
| | 42104 | Typical Aluminum Angle Base 4" Along Floor Perimeter | Ln. Ft | 21.00 | Overtime Rate \$24.15 | | MASTER CARE 49797 FLOORING INC |
| | 42105 | Typical Wood Doorway Threshold | Ln. Ft | 5.00 | Overtime Rate \$5.75 | | MASTER CARE 49797 FLOORING INC |
| | 42106 | Carpentry work (One person) for Unspecified Work | Per Hr | 68.50 | Overtime Rate \$102.75 | | MASTER CARE 49797 FLOORING INC |
| | 42107 | Paint Game Lines (Layout & Painting Athletic Courts on Wood Floors) 2" or less in width | Ln. Ft | 1.25 | Overtime Rate \$1.45 | | MASTER CARE 49797 FLOORING INC |
| | 42108 | Solid 1 Color Painted Areas (typical Borders w/no Lettering) (Layout and Painting Athletic Courts on Wood Floor Systems | Ln. Ft | 1.10 | Overtime Rate \$1.25 | | MASTER CARE 49797 FLOORING INC |
| | 42109 | Solid Painted Areas including Clear Lettering up to 36"(Layout and Painting Athletic Courts on Wood Floor Systems) | Sq. Ft | 2.10 | Overtime Rate \$2.45 | | MASTER CARE 49797 FLOORING INC |
| | 42110 | Painting of Artwork 1 Color (Logos, Stand-alone Lettering, etc.) | Sq. Ft | 13.00 | Overtime Rate \$15.00 | | MASTER CARE 49797 FLOORING INC |
| | 42111 | Painting of Artwork (Logos with 3 or more different Colors) | Sq. Ft | 25.00 | Overtime Rate \$28.75 | | MASTER CARE 49797 FLOORING INC |
| | 42112 | Removal and Disposal of Hazardous Material 0 to 1/4" | Sq. Ft | 8.50 | Overtime Rate \$9.80 | | MASTER CARE 49797 FLOORING INC |
| | 42113 | Removal and Disposal of Hazardous Material over 1/4" | Sq. Ft | 10.00 | Overtime Rate \$11.50 | | MASTER CARE 49797 FLOORING INC |

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|---|--------|------------|-------------------------|-------|-----------------------------------|
| | 42114 | Shot Blasting | Sq. Ft | .65 | Overtime Rate \$.75 | | MASTER CARE 49797 FLOORING INC |
| | 42115 | Grinding Down Concrete 0 to 1/2" | Sq. Ft | 7.75 | Overtime Rate \$8.95 | | MASTER CARE 49797 FLOORING INC |
| | 42116 | Self-leveling of Concrete 0 1/4" | Sq. Ft | 4.95 | Overtime Rate \$5.70 | | MASTER CARE 49797 FLOORING INC |
| | 42117 | Self-leveling of Concrete 1/4" to 1/2" | Sq. Ft | 6.25 | Overtime Rate \$7.20 | | MASTER CARE 49797 FLOORING INC |
| | 42118 | Self-leveling of Concrete 1/2" to 1" | Sq. Ft | 7.75 | Overtime Rate \$8.95 | | MASTER CARE 49797 FLOORING INC |
| | 42119 | Volleyball Floor Plates Only as specified herein Senoh Model KA25-F | Each | 225.00 | Overtime Rate \$225.00 | | MASTER CARE 49797 FLOORING INC |
| | 42120 | Volleyball Floor Sleeves Only as specified herein. Senoh Model KA25 | Each | 600.00 | Overtime Rate \$600.00 | | MASTER CARE 49797 FLOORING INC |
| | 42121 | Volleyball Floor Plates and Sleeves as specifiac herein. Senoh Model KA25 | Each | 860.00 | Overtime Rate \$860.00 | | MASTER CARE 49797 FLOORING INC |
| | 42122 | Badminton Floor Plates Only as specified herein. Senoh Model KA45-F | Each | 200.00 | Overtime Rate \$200.00 | | MASTER CARE 49797 FLOORING INC |
| | 42123 | Badminton Floor Sleeves Only as specified herein. Senoh Model KA45-S | Each | 550.00 | Overtime Rate \$550.00 | | MASTER CARE 49797 FLOORING INC |
| | 42124 | Badminton Floor Plates and Sleeves as specified herein. Senoh Model KA45-S | Each | 895.00 | Overtime Rate \$895.00 | | MASTER CARE 49797 FLOORING INC |
| | 42125 | Steel Volleyball upright (pin-stop as specified herein. Senoh Model DE11 | Each | 1,195.00 | Overtime Rate \$1195.00 | | MASTER CARE 49797 FLOORING INC |
| | 42126 | Steel Badminton upright as specified herein. Senoh Model DE11 | Each | 370.00 | Overtime Rate \$370.00 | | MASTER CARE 49797 FLOORING INC |
| | 42127 | Heavy Duty Volleyball upright Net Crank and Handle. Senoh Model HDNR-R | Each | 425.00 | Overtime Rate \$425.00 | | MASTER CARE 49797 FLOORING INC |

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|---|--------|------------|-----------------------------------|------------------|--------------------------------------|
| | 42128 | Storage Cart (holds 6 uprights) Senoh Model DU22 | Each | 1,175.00 | Overtime Rate \$1175.00 | | MASTER CARE 49797 FLOORING INC |
| | 42129 | Wall Rack (holds 4 uprights) Senoh Model BWR10 | Each | 230.00 | Overtime Rate \$230.00 | | MASTER CARE 49797 FLOORING INC |
| | 42130 | Technora Volleyball Net Senoh Model HM50 | Each | 475.00 | Overtime Rate \$475.00 | | MASTER CARE 49797 FLOORING INC |
| | 42131 | Shortened Technora Volleyball Net Senoh Model HM50 | Each | 475.00 | Overtime Rate \$475.00 | | MASTER CARE 49797 FLOORING INC |
| | 42132 | Badminton Net Senoh Model SGN-20 | Each | 100.00 | Overtime Rate \$100.00 | | MASTER CARE 49797 FLOORING INC |
| | 42133 | Shortened Badminton Net Senoh Model SBN-19.5 | Each | 100.00 | Overtime Rate \$100.00 | | MASTER CARE 49797 FLOORING INC |
| | 42135 | Typical Aluminum Doorway Threshold | Ln. Ft | 19.00 | Overtime Rate \$21.85 | | MASTER CARE 49797 FLOORING INC |
| | 42136 | Painting of Artwork 1 Color (Logos, Lettering, Etc.) | Sq. Ft | 18.25 | Overtime Rate \$21.00 | | MASTER CARE 49797 FLOORING INC |
| | 44221 | Floor Marx (6 pack master set) | Each | 250.00 | Overtime Rate \$250.00 | | MASTER CARE 49797 FLOORING INC |
| | 44294 | Carpenters Per Hour | Per Hr | 68.50 | Overtime Rate \$102.75 \$68.50 | Davis Bacon Rate | MASTER CARE 49797 FLOORING INC |
| | 44296 | Painters Per Hour | Per Hr | 72.45 | Overtime Rate \$108.67 \$72.45 | Davis Bacon Rate | MASTER CARE 49797 FLOORING INC |
| | 44298 | Unskilled Labor Per Hour | Per Hr | 35.00 | Overtime Rate \$52.50 \$45.00 | Davis Bacon Rate | MASTER CARE 49797 FLOORING INC |
| | 42350 | Wood Floor Refinishing less than 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 7.55 | Overtime Rate \$8.95 | | WEYER'S FLOOR 49952 SERVICE, INC. |

Sports Wood Flooring System at Various Facilities

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|--|--------|------------|-----------------------|-------|--------------------------------------|
| | 42351 | Wood Floor Refinishing 100 to 1,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 2.71 | Overtime Rate \$3.14 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42352 | Wood Floor Refinishing 1,001 to 25,000 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 1.85 | Overtime Rate \$2.13 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42353 | Repairs of hardwood floating floor (2 1/4" maple typical) 0 to 100 Sq. Ft. (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 15.94 | Overtime Rate \$18.89 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42354 | Repairs of hardwood floating floor (2 1/4" maple typical) 100 Sq. Ft. and over (w/water base sealer and finish Arena 50 and 300) | Sq. Ft | 13.48 | Overtime Rate \$16.67 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42355 | Repairs of Anchored Resilient Sleeper Floor systems 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 18.27 | Overtime Rate \$18.88 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42356 | Repairs of Anchored Resilient Sleeper Floor System 101 Sq. Ft. and over as specified herein | Sq. Ft | 16.27 | Overtime Rate \$16.88 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42357 | Furnish and install New Anchored Resilient Sleeper Floor System as specified herein | Sq. Ft | 17.63 | Overtime Rate \$18.29 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42358 | Repairs of Direct Glue Down Wood Flooring System. 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 15.40 | Overtime Rate \$15.99 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42359 | Repairs of Direct Glue Down Wood Flooring System. 101 Sq. Ft. and over as specified hereir | Sq. Ft | 14.87 | | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42360 | Furnish and install New Direct Glue Down Wood Flooring System as specified herein | Sq. Ft | 13.69 | Overtime Rate \$16.95 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42361 | Repair Direct Glue Down w/shock Pad Wood Flooring System 0 to 100 Sq. Ft. as specified herein | Sq. Ft | 17.20 | Overtime Rate \$18.14 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42362 | Repair Direct Glue Down w/Shock Pad Wood Flooring System. 101 Sq. Ft. and over as specified herein | Sq. Ft | 16.62 | Overtime Rate \$17.66 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42363 | Furnish and install New Direct Glue Down w/Shock Pad Wood Flooring System as specified herein | Sq. Ft | 15.43 | Overtime Rate \$16.48 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42364 | Typical rubber cove base along floor perimeter | Ln. Ft | 8.05 | Overtime Rate \$8.34 | | WEYER'S FLOOR SERVICE, INC. 49952 |

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|---|--------|------------|-----------------------|-------|--------------------------------------|
| | 42365 | Typical Rubber Cove Base along Floor Perimeter | Each | 8.05 | Overtime Rate \$8.34 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42366 | Typical Wood Base Along Floor Perimeter | Ln. Ft | 2.25 | Overtime Rate \$2.50 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42367 | Typical Steel Angle Base 4" Along Floor Perimeter | Ln. Ft | 30.00 | Overtime Rate \$35.00 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42368 | Typical Aluminum Angle Base 4" Along Floor Perimeter | Ln. Ft | 30.00 | Overtime Rate \$35.00 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42369 | Typical Wood Doorway Threshold | Ln. Ft | 5.00 | Overtime Rate \$5.50 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42370 | Carpentry work (One person) for Unspecified Work | Per Hr | 56.00 | Overtime Rate \$66.00 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42371 | Paint Game Lines (Layout & Painting Athletic Courts on Wood Floors) 2" or less in width | Ln. Ft | 1.38 | Overtime Rate \$1.66 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42372 | Solid 1 Color Painted Areas (typical Boards w/no Lettering) (Layout and Painting Athletic Courts on Wood Floor Systems) | Ln. Ft | 1.10 | Overtime Rate \$1.28 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42373 | Solid Painted Areas including Clear Lettering up to 36"(Layout and Painting Athletic Courts on Wood Floor Systems) | Sq. Ft | 2.20 | Overtime Rate \$2.53 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42374 | Painting of Artwork 1 Color (Logos, Stand-alone Lettering, etc.) | Sq. Ft | 13.35 | Overtime Rate \$15.99 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42375 | Painting of Artwork (Logos with 3 or more different Colors) | Sq. Ft | 26.72 | Overtime Rate \$28.92 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42376 | Removal and Disposal of Hazardous Material 0 to 1/4" | Sq. Ft | 9.49 | Overtime Rate \$10.17 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42378 | Removal and Disposal of Hazardous Material over 1/4" | Sq. Ft | 10.81 | Overtime Rate \$10.89 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42379 | Shot Blasting | Sq. Ft | .61 | Overtime Rate \$.66 | | WEYER'S FLOOR SERVICE, INC. 49952 |

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|--|--------|------------|-------------------------|-------|--------------------------------------|
| | 42380 | Grinding Down Concrete 0 to 1/2" | Sq. Ft | 7.99 | Overtime Rate \$8.40 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42381 | Self-leveling of Concrete 0 1/4" | Sq. Ft | 5.45 | Overtime Rate \$5.57 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42382 | Self-leveling of Concrete 1/4" to 1/2" | Sq. Ft | 6.66 | Overtime Rate \$6.78 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42383 | Self-leveling of Concrete 1/2" to 1" | Sq. Ft | 8.35 | Overtime Rate \$8.47 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42384 | Volleyball Floor Plates Only as specified herein Senoh Model KA25-F | Each | 236.97 | Overtime Rate \$247.71 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42385 | Volleyball Floor Sleeves Only as specified herein. Senoh Model KA25 | Each | 604.14 | Overtime Rate \$634.54 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42386 | Volleyball Floor Plates and Sleeves as specified herein. Senoh Model KA25 | Each | 841.12 | Overtime Rate \$840.12 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42387 | Badminton Floor Plates Only as specified herein. Senoh Model KA45-F | Each | 215.42 | Overtime Rate \$225.71 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42388 | Badminton Floor Sleeves Only as specified herein. Senoh Model KA45-S | Each | 604.14 | Overtime Rate \$634.35 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42389 | Badminton Floor Plates and Sleeves as specified herein. Senoh Model KA45-S | Each | 819.58 | Overtime Rate \$973.93 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42390 | Steel Volleyball upright (pin-stop as specified herein. Senoh Model DE11 | Each | 1,292.56 | Overtime Rate \$1292.56 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42391 | Steel Badminton upright as specified herein. Senoh Model DE11 | Each | 394.94 | Overtime Rate \$394.94 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42392 | Heavy Duty Volleyball upright Net Crank and Handle. Senoh Model HDNR-R | Each | 459.58 | Overtime Rate \$459.58 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42393 | Storage Cart (holds 6 uprights) Senoh Model DU22 | Each | 1,271.01 | Overtime Rate \$1271.01 | | WEYER'S FLOOR SERVICE, INC. 49952 |

Term of Contract: **07/01/2023** To: **06/30/2024** Buyer: **Stephanie Dorah** Phone: **(240) 740-7538**

| Group Number | Item Number | Description | Unit | Unit Price | Brand | Model | Vendor Name |
|--------------|-------------|--|--------|------------|----------------------------------|------------------|--------------------------------------|
| | 42394 | Wall Rack (holds 4 uprights) Senoh Model BWR10 | Each | 242.58 | Overtime Rate \$242.58 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42395 | Technora Volleyball Net Senoh Model HM50 | Each | 509.84 | Overtime Rate \$509.84 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42396 | Shortened Technora Volleyball Net Senoh Model HM50 | Each | 509.84 | Overtime Rate \$509.84 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42397 | Badminton Net Senoh Model SGN-20 | Each | 100.52 | Overtime Rate \$100.52 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42398 | Shortened Badminton Net Senoh Model SBN-19.5 | Each | 100.52 | Overtime Rate \$100.52 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42399 | Typical Aluminum Doorway Threshold | Ln. Ft | 30.00 | Overtime Rate \$33.00 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 42401 | Painting of Artwork 1 Color (Logos, Lettering, Etc.) | Sq. Ft | 20.04 | Overtime Rate \$23.99 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 44292 | Floor Marx (6 pack master set) | Each | 301.18 | Overtime Rate \$301.18 | | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 44293 | Carpenters Per Hour | Per Hr | 60.00 | Overtime Rate \$90.00 \$47.91 | Davis Bacon Rate | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 44295 | Painters Per Hour | Per Hr | 60.00 | Overtime Rate \$90.00 \$40.97 | Davis Bacon Rate | WEYER'S FLOOR SERVICE, INC. 49952 |
| | 44297 | Unskilled Labor Per Hour | Per Hr | 45.00 | Overtime Rate \$67.50 \$37.85 | Davis Bacon Rate | WEYER'S FLOOR SERVICE, INC. 49952 |