Montgomery County Public Schools

2018 School Facilities Assessment

School Number	803
School Name	Forest Knolls
School Type	Elementary School
Year Built*	1960
Year of Last Renovation*	1993
GSF*	89,564



Building Level - Key Facility Indicators						
Infrastructure (FCI)						
Building Quality						
Indoor Environment						

Infrastructure - Facility Condition

\bigcirc	A10	Foundations	n/a	C20	Stairs		D50	Electrical
n/a	A20	Basement	\bigcirc	C30	Interior Finishes	\bigcirc	E10	Equipment
	B10	Superstructure	n/a	D10	Conveying Systems	\bigcirc	E20	Furnishings
	B20	Exterior Enclosure		D20	Plumbing		F10	Special Construction
	B30	Roofing	\bigcirc	D30	HVAC			
	C10	Interior Construction		D40	Fire Protection			

Building Characteristics

Building Quality	Indoor Environment
Classroom Shape*	Temperature Control
IMC Size*	🥚 Humidity Control
Cafeteria Size*	Natural Light
Corridor*	Acoustic Features
	Building-Level Power Delivery

*indicates that underlying data v	was provided by MCPS not collected by FEA.	
Information Sources:	(References)	
5/1/2019	Versie	on 4.0