

**Montgomery County Public Schools**

**2018 School Facilities Assessment**

School Number **817**  
 School Name **Glenallan**  
 School Type **Elementary School**  
 Year Built\* **1966**  
 Year of Last Renovation\* **2013**  
 GSF\* **98,700**



**Building Level - Key Facility Indicators**



**Infrastructure - Facility Condition**

- A10 Foundations
- C20 Stairs
- D50 Electrical
- A20 Basement
- C30 Interior Finishes
- E10 Equipment
- B10 Superstructure
- D10 Conveying Systems
- E20 Furnishings
- B20 Exterior Enclosure
- D20 Plumbing
- F10 Special Construction
- B30 Roofing
- D30 HVAC
- C10 Interior Construction
- D40 Fire Protection

**Building Characteristics**

- |  |   |
|--|---|
| <p><b>Building Quality</b></p> <ul style="list-style-type: none"> <li>● Classroom Shape*</li> <li>● IMC Size*</li> <li>● Cafeteria Size*</li> <li>● Corridor*</li> </ul> | <p><b>Indoor Environment</b></p> <ul style="list-style-type: none"> <li>● Temperature Control</li> <li>● Humidity Control</li> <li>● Natural Light</li> <li>● Acoustic Features</li> <li>● Building-Level Power Delivery</li> </ul> |
|--|---|

\*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------