

Montgomery County Public Schools

2018 School Facilities Assessment

School Number **788**
 School Name **Wheaton Woods**
 School Type **Elementary School**
 Year Built* **1952**
 Year of Last Renovation* **1976**
 GSF* **66,763**



Building Level - Key Facility Indicators



Infrastructure - Facility Condition

- A10 Foundations
- A20 Basement
- B10 Superstructure
- B20 Exterior Enclosure
- B30 Roofing
- C10 Interior Construction
- C20 Stairs
- C30 Interior Finishes
- D10 Conveying Systems
- D20 Plumbing
- D30 HVAC
- D40 Fire Protection
- D50 Electrical
- E10 Equipment
- E20 Furnishings
- F10 Special Construction

Building Characteristics

- | Building Quality | Indoor Environment |
|--------------------|---------------------------------|
| ● Classroom Shape* | ● Temperature Control |
| ● IMC Size* | ● Humidity Control |
| ● Cafeteria Size* | ● Natural Light |
| ● Corridor* | ● Acoustic Features |
| | ● Building-Level Power Delivery |

*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------