



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Laytonsville Elementary
21401 Laytonsville Road
Gaithersburg, Maryland 20882

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-062.303

Date of Report:

October 25, 2019

On Site Date:

October 24, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Laytonsville Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Laytonsville Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Laytonsville Elementary School	53	16	33	3		105
Grand Total	53	16	33	3		105

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76493	Laytonsville Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Entrance Doors - DR1, DR14 and DR18	ADA
76497	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	All doors throughout the school	ADA
76505	Laytonsville Elementary School	BUILDING INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Classrooms CR3, CR4, CR5, CR6, CR7, CR8, CR10, CR13 and CR16 and two wheelchair lifts	ADA
76517	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects obstruct the required clear width of the accessible route.	Emergency Telephone Adjacent to Main Office	ADA
76538	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	All Purpose Room - Stage	ADA
76548	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Interior Ramps R2 and R3	ADA
76549	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Interior Stairs - STR1, STR3 and STR4	ADA
76494	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Route	Curb Ramp	1	The curb ramp does not have compliant flared sides.	Curb Ramp CR1	ADA
76495	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR1 Landing	ADA
76498	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR2	ADA
76499	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Accessible route at the northeast end of the school building	ADA
76503	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus loading and unloading zone	ADA
76508	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	School bus loading/unloading	ADA
76509	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1	State of Maryland
76510	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
76511	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1	State of Maryland
76512	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1, Standard Accessible Space P1B and P1C	ADA
76536	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Stairs	1	Handrails are not compliant.	Site Stair STR1	ADA
76560	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible route near Entrance DR18	ADA
76564	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Courts	ADA
76565	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-A at Bus loading and unloading zone	ADA
76566	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1 - Van access aisle adjacent to P1A	State of Maryland
76567	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1; Access aisle adjacent to accessible space P1C and P1D	ADA
76568	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1; Standard accessible space P1D and P1E	ADA
76575	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Softball Field #1	ADA
76608	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Loading/Unloading Zone	1	The loading/unloading zone is not 96" wide by 20' long with vertical clearance of 114".	Parent loading and unloading zone	ADA
76637	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR3 Landing	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76652	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route from CR3 to CR4	ADA
76655	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Accessible route approaching CR2	ADA
76656	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route adjacent to entrance DR2	ADA
76659	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route approaching CR2	ADA
76660	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route approaching CR3	ADA
76661	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR3 Landing	ADA
76664	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Accessible route approaching Playground #1	ADA
76665	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route leading to the playing fields	ADA
76667	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Accessible route leading to Playground #4	ADA
76672	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-B	ADA
76676	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp run rises greater than 6", however no edge protection is provided.	Accessible route leading to the playfields	ADA
76678	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Accessible route from the west driveway entrance	ADA
76679	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route adjacent to CR1 and school entry	ADA
76693	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Stairs	1	Handrails are not compliant.	Site Stair STR2	ADA
76741	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	The parking space slope is greater than 1:50 (2%).	Parking Lot 1 - Van accessible stall P1A	ADA
76742	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: The access aisle slope is greater than 1:50 (2%).	Parking Lot 1 - Van access aisle	State of Maryland
76744	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot 1 - Van access aisle adjacent to P1A	State of Maryland
76746	Laytonsville Elementary School	GENERAL SITEWORK	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1; Access aisle adjacent to accessible space P1E	ADA
88386	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Cubr Ramp CR-2	ADA
88387	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Stair STR-1, STR-2	ADA
88388	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Stair STR-1, STR-2	ADA
88389	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route approaching CR2	ADA
88390	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route approaching Playground #1	ADA
88391	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise in excess of 30".	Accessible route leading to the playing fields	ADA
88392	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route leading to Playground #4	ADA
88393	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route from the west driveway entrance	ADA
76729	Laytonsville Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Entrance Doors - DR3, DR4 and DR17	ADA
76515	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	All signage, other than restrooms throughout the entire school building.	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76516	Laytonsville Elementary School	BUILDING INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
76540	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	All Student Restrooms	ADA
76728	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	All the corridor doors throughout the school	ADA
76730	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Staff Lounge	ADA
76813	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Light switches throughout the school	ADA
76826	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Staff Restroom - RR5	ADA
76504	Laytonsville Elementary School	GENERAL SITEWORK	Playground	Exterior Accessible Route	2	An accessible route to at least one of each type of ground component within the play area has not been provided.	Bucket Ball adjacent to Playground #1	ADA
76562	Laytonsville Elementary School	GENERAL SITEWORK	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	Trash Receptacles adjacent to Playground #1	ADA
76563	Laytonsville Elementary School	GENERAL SITEWORK	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic tables adjacent to Playground #1	ADA
76573	Laytonsville Elementary School	GENERAL SITEWORK	Playground	Transfer System	2	The transfer platform for connecting to elevated play elements has non-compliant dimensions.	Playground #1 - Transfer Platform	ADA
76574	Laytonsville Elementary School	GENERAL SITEWORK	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground #1	ADA
76596	Laytonsville Elementary School	GENERAL SITEWORK	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic table adjacent to Playground #3	ADA
76618	Laytonsville Elementary School	GENERAL SITEWORK	Playground	Exterior Accessible Route	2	An accessible route to at least one of each type of ground component within the play area has not been provided.	Bucket Ball adjacent to northeast end of the building	ADA
76621	Laytonsville Elementary School	GENERAL SITEWORK	Playground	Exterior Accessible Route	2	An accessible route to at least one of each type of ground component within the play area has not been provided.	Maypole adjacent to northeast end of the building	ADA
76492	Laytonsville Elementary School	BUILDING INTERIOR	Common Areas	Assembly Area	3	An assistive listening system is required, but not provided.	All Purpose Room	ADA
76513	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All exterior egress doors DR1 to DR18	ADA
76514	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	All staff restroom signage throughout the entire school building.	ADA
76520	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Student Restroom - RR1,RR15, RR16, RR17, K1, K2, K3 and K4	ADA
76521	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Gymnasium Restroom - RR9	ADA
76522	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Gymnasium Restroom - RR9	ADA
76523	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Gymnasium Restroom - RR9	ADA
76525	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Student Restrooms - RR13, RR15, RR16, RR19, K1 and K4	ADA
76526	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34".	Student Restrooms - RR6, RR7, RR10, RR11 and RR13	ADA
76527	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms - RR4, RR5, RR8, RR9, RR20 and RR21	ADA
76528	Laytonsville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Staff Restrooms - RR8 and RR20	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76529	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Student Restrooms - RR2, RR7 RR13, RR14, RR15 and RR19	ADA
76533	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Gymnasium Restroom - RR9	ADA
76535	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Student Restroom - RR-1, RR6, RR-10 and RR13	ADA
76541	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Building Services Restroom	ADA
76542	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Building Services Restroom	ADA
76543	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Building Services Restroom	ADA
76544	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Building Services Restroom	ADA
76553	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restrooms - RR4, RR5, RR8, RR9, RR20 and RR21	ADA
76554	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Student Restrooms - RR1, RR14, RR15, RR16, RR19, K1, K2, K3 and K4	ADA
76555	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restroom - RR8	ADA
76556	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom - RR1	ADA
76558	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Student Restrooms - RR1, RR3, RR10, RR11, RR12, K2 and K3	ADA
76559	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Student Restrooms - RR3, RR7, RR10, RR11, K2 and K1	ADA
76823	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom - RR20	ADA
76825	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Restroom - RR5, RR8, RR9 and RR20	ADA
76830	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom - RR8	ADA
76831	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom - RR8	ADA
76832	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restrooms - RR14, K2 and K3	ADA
76837	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restrooms - RR15, RR16 and RR17	ADA
76846	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Student Restrooms - K1, K2, K3 and K4	ADA
76850	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Student Restrooms - RR12 and K4	ADA
76851	Laytonville Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Student Restroom - K3	ADA
76545	Laytonville Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-1, DF-2, DF-3, DF-4	ADA
76550	Laytonville Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms - K1, K2, K3 K4, CR1, CR2, CR3A, CR4, CR5 CR6, CR7, CR8, CR9, CR10, CR11, CR12, CR13, CR14, CR15, CR16, CR17 CR18, CR19 and CR20	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
76551	Laytonsville Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classrooms - K1, K2, K3 K4, CR1, CR2, CR3A, CR4, CR5 CR6, CR7, CR8, CR9, CR10, CR11, CR12, CR13, CR14, CR15, CR16, CR17 CR18, CR19 and CR20	ADA