



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Clopper Mill Elementary School
18501 Cinnamon Drive
Germantown, Maryland 20874

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-126.303

Date of Report:
October 28, 2019

On Site Date:
May 23, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at the Clopper Mill Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at the Clopper Mill Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Clopper Mill Elementary School	48	18	33	4		103
Grand Total	48	18	33	4		103

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106301	Clopper Mill Elementary School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Softball Field and Soccer Field	ADA
106345	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Accessible route AR2	ADA
106346	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route AR1	ADA
106347	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible route at the portable classrooms	ADA
106349	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR4	ADA
106350	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR2 and CR3 shared Landing	ADA
106377	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The bus stop boarding and alighting area is not compliant.	Bus loading and unloading zone	ADA
106378	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Parent loading and unloading zone	ADA
106467	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The parent boarding and alighting area is not compliant.	Parent loading and unloading zone	ADA
106482	Clopper Mill Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Building Entrances - DR1, DR2, DR4, DR5 and DR6	ADA
106484	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Entrance DR3	ADA
106498	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR2	ADA
106501	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Exterior Stair - STR3	ADA
106503	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Exterior Stair - STR3	ADA
106504	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Exterior Stair - STR2	ADA
106531	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramps at Portables - R2 and R3	ADA
106542	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramps at Portables - R2 and R3	ADA
107664	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-A - Access to the playground areas	ADA
107665	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Ramp - R3	ADA
107881	Clopper Mill Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-A - Access to the playground areas	ADA
106373	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Public Interior Doors	ADA
106374	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Ramp	1	Handrail heights are not compliant.	Ramp R1	ADA
106442	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	All Interior Office Doors	ADA
106446	Clopper Mill Elementary School	INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
106447	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Cafeteria Serving Line	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106448	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Kitchen Serving Line	ADA
106460	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	All Purpose Room	ADA
106492	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Public Interior Doors	ADA
106357	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Interior Classroom Doors	ADA
106358	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	All Interior Classroom Doors	ADA
106359	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Interior Office Doors	ADA
106493	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Doors to SR3 and SR14	ADA
106495	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Doors to Classrooms 8 and 15	ADA
107672	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking fountains DF3 and DF5	ADA
107673	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Ramp	1	Handrails are not located with 1.5" minimum clear space between the handrails and adjacent surfaces.	Ramp - R1	ADA
106381	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1 - Stall P1A	ADA
106382	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1 - Stall P1A	State of Maryland
106383	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1 - Stall P1A	State of Maryland
106384	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1 - Stall P1A	State of Maryland
106472	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
106473	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Car	1	MARYLAND: Signage is not located at a compliant height.	Parking Lot 1	State of Maryland
106476	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2	State of Maryland
106477	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 2	State of Maryland
106478	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 2	ADA
106479	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2	State of Maryland
106481	Clopper Mill Elementary School	PARKING LOT	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1 - Stalls P1A to P1C	ADA
106444	Clopper Mill Elementary School	PLAYGROUND	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Court	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
107669	Clopper Mill Elementary School	PLAYGROUND	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Accessible route from play court surface to two sections of PG1	ADA
106370	Clopper Mill Elementary School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Staff Workroom, Staff Lounge and Mailroom	ADA
106375	Clopper Mill Elementary School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
106436	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	All classrooms throughout the building	ADA
106438	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Public Restroom - SR3	ADA
106362	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	All offices throughout the building	ADA
107666	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Corridor Fire Control Doors	ADA
106392	Clopper Mill Elementary School	PLAYGROUND	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground PG3	ADA
106393	Clopper Mill Elementary School	PLAYGROUND	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground PG1	ADA
107670	Clopper Mill Elementary School	PLAYGROUND	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playgrounds - PG1 - Transfer Platform	ADA
106401	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Child's Restroom - CR2	ADA
106408	Clopper Mill Elementary School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	2	The required number of accessible locker and dressing/fitting rooms are not provided.	Building Services Office - SR7	State of Massachusetts
106413	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Classroom Restroom - CR2 and CR18	ADA
106414	Clopper Mill Elementary School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	2	The required number of accessible locker and dressing/fitting rooms are not provided.	Gym Office- SR8	State of Massachusetts
106429	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restroom - SR7	ADA
106430	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restroom - SR9	ADA
106431	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restrooms - SR1 and SR14	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106576	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restroom - SR1	ADA
106604	Clopper Mill Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Public Restroom - SR3	ADA
106356	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All exterior egress doors DR1 to DR10	ADA
106360	Clopper Mill Elementary School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	All Purpose Room	ADA
107884	Clopper Mill Elementary School	INTERIOR	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Restrooms - SR1, SR4, SR7, SR8, SR9 and SR14	ADA
107886	Clopper Mill Elementary School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Public Restroom - SR3	ADA
106398	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Boy's Restrooms - B5, B10 and B13 Girl's Restrooms - G6, G11 and G12 Classroom Restrooms - CR2, CR15, CR16, CR17 and CR18	ADA
106400	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Boy's Restroom - B5 Classroom Restrooms - CR2, CR15, CR16, CR17 and CR18	ADA
106404	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Building Services and Gym Restrooms	ADA
106405	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Building Services and Gym Restrooms	ADA
106406	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Building Services and Gym Restrooms	ADA
106407	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Building Services and Gym Restrooms	ADA
106410	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The grab bars at the water closet are not present.	Classroom Restrooms CR2	ADA
106411	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Classroom Restrooms - CR2, CR17 and CR18	ADA
106417	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not present.	Public Restroom - SR3	ADA
106418	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Restroom - SR4	ADA
106422	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Public Restroom - SR3	ADA
106423	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Staff Restrooms - SR1, SR4, SR7, SR8, SR9, SR14 and Kitchen	ADA
106424	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restrooms - SR1, SR4, SR7, SR8, SR9 and SR14	ADA
106426	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms - SR1, SR4, SR7, SR8, SR9 and SR14	ADA
106428	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restrooms - SR9	ADA
106572	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Public Restroom - SR3	ADA
106597	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms - CR2	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106606	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not present.	Staff Restrooms - SR1, SR4, SR7, SR8 and SR14	ADA
106607	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Restrooms - SR1, SR8, SR9 and SR14	ADA
106608	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Staff Restroom - SR9	ADA
106609	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory faucet hardware is not compliant.	Staff Restroom - SR4	ADA
106610	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom - SR7	ADA
106611	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Classroom Restrooms - CR17	ADA
106612	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boy's Restrooms - B5, B10, B13	ADA
106613	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Classroom Restrooms - CR15, CR16, CR17 and CR18	ADA
106614	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Classroom Restroom - CR18	ADA
106615	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Staff Restroom - SR7	ADA
106616	Clopper Mill Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restroom - SR9	ADA
107671	Clopper Mill Elementary School	RESTROOMS	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services Office and Gym Staff Office	ADA
106363	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Hallway Drinking Fountains - DF2, DF3, DR4 and DF5	ADA
106364	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Classroom Drinking Fountains - DF6, DF7, DF8 and DF9	ADA
106366	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classroom Drinking Fountains - DF6, DF7, DF8 and DF9	ADA
107883	Clopper Mill Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Hallway Drinking Fountains - DF1, DF2, DF3, DR4 and DF5	ADA