



# ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## ADA TITLE II ASSESSMENT

Judith A. Resnik Elementary School  
7301 Hadley Farms Drive  
Gaithersburg, Maryland 20879

### PREPARED BY:

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### EMG CONTACT:

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

### EMG Project Number:

123821.17R000-015.303

### Date of Report:

October 24, 2019

### On Site Dates:

July 24-25, 2017



# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Judith A Resnik Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Judith A Resnik Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Judith A. Resnik Elementary School	46	11	35	8		100
Grand Total	46	11	35	8		100

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66306	Judith A. Resnik Elementary School	BUILDING INTERIOR	Accessible Route	Ramp	1	The running slope of the ramp is greater than 1:12 (8.33%).	Ramp at rear of stage	ADA
66345	Judith A. Resnik Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gym	ADA
66401	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Phone in Corridor next to Gym & Exit Doors	ADA
68470	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	2 ramps to stage from multipurpose room	ADA
68471	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	Handrail heights are not compliant, and a children's second set of rails is not provided where children are the primary users.	3 ramps to stage (1 ramp at rear and 2 ramps from multipurpose room)	ADA
65986	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Van	1	MARYLAND: A van space is not provided.	Parking Lot 1: Stalls 1 and 2	State of Maryland
65991	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1- access aisle 1 (first access aisle from left)	State of Maryland
66029	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1- access aisle 2 (second access aisle from west)	ADA
66040	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot 1- car accessible space 4 (4th stall from west)	ADA
66041	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1- access aisle 3 (3rd access aisle from west)	ADA
66271	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Front door at southeast corner of building	ADA
66272	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 4 south side of building	ADA
66277	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Parking Lot 1 - access aisle 3 curb ramp (3rd access aisles from west)	ADA
66278	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Parking Lot 1- access aisle 2 curb ramp (2nd access aisle from west)	ADA
66279	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1 adjacent accessible parking spaces at front parking lot	ADA
66280	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 2 at cross walk from front accessible parking lot	ADA
66282	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The route has gaps in the surface greater than 1/2".	Sidewalks on south side of building	ADA
66283	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has areas in excess of 1:50 (2%) cross slope.	Front sidewalk from curb ramp 3 heading to curb ramp 4	ADA
66284	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 4 in front of southeast building entrance	ADA
66286	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has areas in excess of 1:50 (2%) cross slope.	Between curb ramps CR-5 & CR-6 on south elevation of building	ADA
66293	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Front sidewalk south of playground 1	ADA
66296	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 7 Front of school towards the left side	ADA
66300	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has areas in excess of 1:50 (2%) cross slope.	Cross aisle at drive lane to left side of school between curb ramps 7 and 8.	ADA
66301	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 8 across drive aisle from curb ramp 7	ADA
66303	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp 7 Front of school towards the left side	ADA
66304	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has greater than 1:20 (5%) running slope and 1:50 (2%) cross slope.	Accessible route from southwest entrance to curb ramp 8	ADA
66418	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Ramp	1	A ramp is required but not provided.	West side of school to Door 7	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66420	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 7 west side of building	ADA
66421	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 9 west side of building	ADA
66422	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 10 west side of building	ADA
66424	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	1	The accessible route has areas in excess of 1:50 (2%) cross slope.	Door 7 heading north along west building elevation	ADA
66431	Judith A. Resnik Elementary School	GENERAL SITE	Employee Work Areas	Interior Ramp	1	The ramp has no handrails.	Ramp 3 at Door 11 (west side of building)	ADA
66434	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 3 at Door 11 (west side of building)	ADA
66437	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Ramp	1	The ramp has running slopes in excess of 1:12.	Ramp 3 at Door 11 (west side of building)	ADA
66438	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair 1 Handrails adjacent to Ramp 3 at Door 11 (west side of building)	ADA
66440	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair 2 handrails adjacent loading dock (west side of building)	ADA
66449	Judith A. Resnik Elementary School	GENERAL SITE	Interior Access Route	Ramp	1	Handrail heights are not compliant and a children's second set of rails is not provided where children are the primary users.	Exterior wood ramp 1 to portable classrooms	ADA
66450	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Ramp	1	The ramp has running slopes in excess of 1:12.	Exterior wood ramp 2 to portable classrooms 1 and 2	ADA
66451	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The threshold at the accessible door is greater than 1/2" in height.	Portable Classrooms 1 & 2	ADA
66453	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Exterior Accessible Route	1	A compliant sidewalk is not provided from the public access to the amenity.	Courtyard	ADA
66454	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Ramp	1	The ramp has running slopes in excess of 1:12.	Courtyard	ADA
66455	Judith A. Resnik Elementary School	GENERAL SITE	Interior Access Route	Ramp	1	Handrail heights are not compliant or a children's second set of rails is not provided where children are the primary users.	Courtyard	ADA
68501	Judith A. Resnik Elementary School	GENERAL SITE	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Portable Classroom 2	ADA
68726	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Parking	Parking Space-Van	1	MARYLAND: Van and car signage is not compliant.	Parking Lot 1 accessible stalls	State of Maryland
68728	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	West elevation of school from curb ramp CR-7 north toward Door 7	ADA
68771	Judith A. Resnik Elementary School	GENERAL SITE	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Parent loading/unloading zone	ADA
66330	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Hand dryers in restrooms: Boys 1, 2, 4 & 5 and Girls 1, 2, 4 & 5	ADA
66452	Judith A. Resnik Elementary School	BUILDING INTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	All portable classrooms	ADA
66051	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 1 (front of school)	ADA
66055	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playground 2 (rear of school)	ADA
66072	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Ramp	2	The ramp within the play area connecting elevated components has a rise greater than 12" maximum.	Playground 2 (rear of school)	ADA
66078	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Playground 2 (rear of school)	ADA
66080	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	The ground level component or elevated component accessed by ramp is required to be on an accessible route but is not within a child's reach range.	Playground 2 (rear of school)	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66082	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Play Component	2	The ground level component or elevated component accessed by ramp is required to be on an accessible route but is not within a child's reach range.	Playground 2 (rear of school)	ADA
66086	Judith A. Resnik Elementary School	EXTERIOR ATHLETIC FACILITIES	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Playground 1 (front of school)	ADA
66281	Judith A. Resnik Elementary School	GENERAL SITE	Accessible Route	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	Trash and recycle containers at main building entrance	ADA
66290	Judith A. Resnik Elementary School	GENERAL SITE	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Courtyard	ADA
65962	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom and Building Services Restroom.	ADA
65963	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not between 17" to 19".	Restrooms: Girls 4 & 5 and Health restroom 1	ADA
66315	Judith A. Resnik Elementary School	BUILDING INTERIOR	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Lockers: Service Corridor and Coaches Restroom	ADA
66326	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66327	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66328	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Soap Dispensers in Restrooms: Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66329	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The toilet paper dispenser is not in a compliant location.	Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66331	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom 2	ADA
66332	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within reach range.	Staff Main Office Restroom	ADA
66335	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	Restrooms: K2, K3, K4 and K5	ADA
66339	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet does not have the required clearance.	K1 Restroom	ADA
66346	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66347	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Health room and Restrooms: K1, K2, K3, K4, K5, Boys 4 & 5, Girls 4 & 5, Health Restroom 1 & 2, Changing Room/Restroom 1 & 2, Classroom 8 Restroom and Classroom 35 Restroom (PT).	ADA
66397	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Faucets are not compliant.	Restrooms: Classroom 8 restroom, K1, K2 and K3 restrooms	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
66398	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Health Room and Boys 1 & 2 and Girls 5 Restrooms	ADA
66399	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Health Room Restroom 2 and Changing Room/Restroom 1	ADA
66400	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A transfer seat is provided but is not compliant.	Health Room Restroom 2 and Changing Room/Restroom 1	ADA
68527	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68531	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys 1 and 2; Girls 1 and 2	ADA
68532	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68533	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys 1 and 2; Girls 1 and 2	ADA
68534	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Soap Dispensers in Restrooms: Boys 1 and 2; Girls 1 and 2	ADA
68535	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The toilet paper dispenser location is not compliant.	Restrooms: Boys 1 and 2; Girls 1 and 2	ADA
68536	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68537	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Soap Dispensers: Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68538	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The toilet paper dispensers are not compliant.	Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68543	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	Girls Restroom 2	ADA
68544	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restrooms: Staff 1 (Lobby), Staff 4 and Coach Restroom	ADA
68547	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall for adults and does not meet the children's specifications.	Restrooms: Boys 2 and Girls 1 & 2	ADA
66405	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restrooms: Health restrooms 1 & 2, Changing Room/Restroom 2, K1, Boys 4 & 5 and Classroom 8 & 35 restrooms	ADA
68479	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys 1 and 2; Girls 1 and 2	ADA
68480	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Principal Restroom, Staff Main Office Restroom, Staff Restrooms 1, 2, 3, 4, 5 & 6, Coaches Restroom, Building Services Restroom	ADA
68526	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Bathroom/Shower Room-Dispenser	3	The height of controls are not compliant.	Boys 1 and 2; Girls 1 and 2	ADA
68548	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Coach Restroom	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
68550	Judith A. Resnik Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Faucets are not compliant.	Staff restrooms 1, 2, 3, 4, & 5, Staff Main Office Restroom and Building Services Restroom	ADA
66310	Judith A. Resnik Elementary School	BUILDING INTERIOR	Signage	Exterior Accessible Route-Signage	4	Signage with tactile lettering is located lower than 48" measured to the baseline of the lowest tactile character, or higher than 60" measured to the baseline of the highest tactile character.	Room signs throughout building	ADA
66313	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	Classrooms 15, 16, 17, 19, 23, 24, 26, 27, 29, 30, 31, 32, 33, 40, 41, 42, 43 and K1 through K5	ADA
66314	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	Corridor adjacent to Gym	ADA
68472	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided.	Classrooms 15, 16, 17, 19, 23, 24, 26, 27, 29, 30, 31, 32, 33, 40, 41, 42, 43 and K1 through K5	ADA
68483	Judith A. Resnik Elementary School	BUILDING INTERIOR	Kitchen	Storage	4	The storage does not have at least 50% of cabinet shelf space within reach ranges (15" minimum to 48" maximum; 46" maximum when shelving is 10" deep).	Staff Lounge	ADA
68504	Judith A. Resnik Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided.	Corridor adjacent to Gym	ADA
68491	Judith A. Resnik Elementary School	GENERAL SITE	Interior Access Route	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	Directional Sign at exterior wood ramp 2 to portable classrooms 1 and 2	ADA
68500	Judith A. Resnik Elementary School	GENERAL SITE	Interior Access Route	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	Front sidewalk south of front playground 1	ADA