



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Goshen Elementary
8701 Warfield Road
Gaithersburg, Maryland 20882

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-050.303

Date of Report:

October 24, 2019

On Site Date:

September 11, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Goshen Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Goshen Elementary. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Goshen Elementary School	51	13	55	3		122
Grand Total	51	13	55	3		122

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
70784	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp 5 and 6	ADA
70826	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1: Stall P1 - P4	ADA
70828	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot 1: Access Aisles 1 to 4	ADA
72068	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1	State of Maryland
72285	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2	State of Maryland
72286	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Playground 1	ADA
72292	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Baseball Field's 1 and 2	ADA
72294	Goshen Elementary School	BUILDING EXTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Exterior Basketball Courts	ADA
72295	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair 5	ADA
72296	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp 2	ADA
72297	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp 2	ADA
72298	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Ramp 3	ADA
72299	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 1	ADA
72300	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Playground 3 Sidewalk	ADA
72634	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from accessible parking to the public facility entrance.	Accessible route adjacent Ramp 2	ADA
72635	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Accessible route adjacent Ramp 2	ADA
72636	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from Portable 2 to CR1	ADA
72637	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR2	ADA
72638	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route Main Entrance	ADA
72639	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR3	ADA
72640	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Bus Unloading Zone	ADA
72642	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide and vertical surface changes greater than 1/4" that are not beveled.	Student drop off by Main Entrance	ADA
72643	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not at the same level as the loading/unloading area.	Bus Unloading Zone	ADA
72644	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The loading/unloading zone is not 96" wide by 20' long with vertical clearance of 114".	Bus Drop Off Area	ADA
72645	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Accessible Route CR2 towards flag pole	ADA
72646	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Bus Unloading/Loading Zone	ADA
72647	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Zig-zag path north of bus drop off area	ADA
72648	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Zig-zag path north of bus drop off area	ADA
72649	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Path from bike rack to street access	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
75841	Goshen Elementary School	BUILDING EXTERIOR	Interior Access Route	Ramp	1	Handrails are not compliant - handrail edges are not free of sharp edges and abrasive elements. The bottom of gripping surfaces are interrupted by newel posts, other construction elements or obstructions for more than 20% of rail length.	Stair 5	ADA
75903	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 2	State of Maryland
75909	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1 and 2 Newly Installed VAN Accessible Stalls	State of Maryland
75912	Goshen Elementary School	BUILDING EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1 and 2 newly installed VAN accessible stalls	State of Maryland
75938	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp 3	ADA
75943	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR2	ADA
75947	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb ramp CR3	ADA
75952	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Student drop off area	ADA
76012	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Path from bike rack to street access	ADA
76022	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Zig zag path north of bus drop off area	ADA
76036	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Accessible route adjacent Ramp 2	ADA
73779	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 3	ADA
73780	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 4	ADA
76043	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Ramp 1	ADA
73521	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	All Interior Room Doors	ADA
73749	Goshen Elementary School	BUILDING INTERIOR	Basketball Court	Sport Court	1	An accessible route does not directly connect each side of the court outside of play lines.	Gymnasium	ADA
73763	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp 1	ADA
73764	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Staff Restroom SR 7	ADA
73771	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 1	ADA
73772	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 1	ADA
73773	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair 2	ADA
73774	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair 2	ADA
70829	Goshen Elementary School	BUILDING EXTERIOR	Playground	Ground Surface	2	The ground surface within the use zone does not comply with ASTM F 1292.	Playgrounds 1 - 3	ADA
72287	Goshen Elementary School	BUILDING EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Playground 3	ADA
72288	Goshen Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground 2	ADA
72289	Goshen Elementary School	BUILDING EXTERIOR	Playground	Transfer System	2	The transfer platform connecting elevated play elements has non-compliant height lower than 11" or higher than 18".	Playground 2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72291	Goshen Elementary School	BUILDING EXTERIOR	Entrance to Building	Building Entrance-Door	2	The bottom of the entry door vision light is higher than 43" maximum.	Portable's 1 and 2	ADA
72293	Goshen Elementary School	BUILDING EXTERIOR	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	Baseball Field's 1 and 2	ADA
72301	Goshen Elementary School	BUILDING EXTERIOR	playground	Play Component	2	The number of existing types of ground level components is less than the required minimum.	Playground 2	ADA
72641	Goshen Elementary School	BUILDING EXTERIOR	Playground	Play Component	2	Clear ground space is not provided at each ground play component, and each elevated play component connected by a ramp.	Playground	ADA
76002	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Exit doors and area of refuge	ADA
73507	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	All Classroom and Restroom Doors and Stairwells	ADA
73510	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	All Staff Restroom's, Kitchen RR, Health Suite RR, and Restroom RR X	ADA
73734	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Majority of Interior and Restroom Doors	ADA
73762	Goshen Elementary School	BUILDING INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Multipurpose Room (Cafeteria)	ADA
73782	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Boys Restroom 5	ADA
73783	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys Restroom 5	ADA
73784	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Boys Restrooms 1, 4 and Girls Restrooms 2, 3	ADA
73788	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Boys Restroom 7 and Girls Restroom 6, 8	ADA
73790	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	PE Office RR	ADA
73791	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	PE Office RR	ADA
73792	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	PE Office RR	ADA
75956	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Health Suite RR	ADA
75987	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom 5	ADA
76038	Goshen Elementary School	BUILDING INTERIOR	Common Areas	Assembly Area	3	An assistive listening system is required, but not provided.	Multipurpose room / Stage	ADA
72650	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Kindergarten Restroom's K1 - K4	ADA
72651	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Kindergarten Restrooms K1 - K4	ADA
72652	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kindergarten Restroom's K1 - K4	ADA
72653	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Kindergarten Restroom's K3 and K4	ADA
72654	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Health Suite RR, Restroom SR 4, and Restroom RR X	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
72655	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	PE Office RR, Kitchen RR, Building Services RR, SR 1, SR 2, SR 4, SR 5, SR 7 and Restroom RR X	ADA
72656	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Kindergarten Restroom's K1 - K4	ADA
72657	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Kitchen RR, Restroom RR X, Build Services RR, SR 1, SR 2, and SR 4	ADA
72658	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	Kindergarten Restroom's K1 - K4	ADA
72659	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Kindergarten Restroom's K1 - K4	ADA
72660	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	Kindergarten Restroom's K1 - K4	ADA
72661	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Kindergarten RR K2	ADA
72662	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Kindergarten Restroom's K1 - K4	ADA
72663	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Kindergarten Restroom's K1 and K4	ADA
72664	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Kindergarten Restroom's K2 and K3	ADA
72665	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Kindergarten Restroom K1	ADA
72666	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restrooms SR 1 and SR 2	ADA
72667	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	SR 1, SR 2, SR 4, Restroom RR X, Kitchen RR, PE Office RR, and Build Services RR	ADA
72668	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	SR 1, SR 2, SR 4, Kitchen RR, Build Services RR, PE Office RR, and Restroom RR X	ADA
73560	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Staff Restrooms SR 3 and SR 6	ADA
73561	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Health Suite Restroom	ADA
73562	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Health Suite Restroom	ADA
73563	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom SR 2, SR 4, and SR 7	ADA
73564	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restrooms SR 1, SR 2, and SR 4	ADA
73724	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom RR X	ADA
73750	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restrooms SR 3 and SR 5	ADA
73751	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom SR 5 and SR 7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
73752	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom SR 5 and SR 7	ADA
73753	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom SR 5, SR 6, and SR 7	ADA
73754	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Restrooms 1, 4, 5, 7 and Girls Restroom 2, 8	ADA
73756	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Girls Restroom 2	ADA
73757	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Boys Restroom 1 and 7 and Girls Restroom 2	ADA
73758	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Girls Restrooms 2 and 3	ADA
73759	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Boys Restroom 5	ADA
73760	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom 5	ADA
73765	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom RR X	ADA
73766	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Restroom	ADA
73767	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Building Services Restroom	ADA
73768	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Building Services Restroom and PE Office RR	ADA
73769	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Building Services Restroom and PE Office RR	ADA
73770	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Building Services Restroom and PE Office RR	ADA
73775	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Staff Restroom SR 5 and PE Office RR	ADA
73776	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom SR 5	ADA
73777	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom SR 6	ADA
73778	Goshen Elementary School	BUILDING INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom SR 3	ADA
75966	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the lower level drinking fountain is located more than 5" from the front edge of the fountain.	All classroom drinking fountains	ADA
73748	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Hallway and Gymnasium Drinking Fountains	ADA
73761	Goshen Elementary School	BUILDING INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	All Classroom Drinking Fountains	ADA

