

ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Cedar Grove Elementary School
24001 Ridge Road
Germantown, Maryland 20876

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-124.303

Date of Report:

October 28, 2019

On Site Date:

May 22, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at the Cedar Grove Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at the Cedar Grove Elementary School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Cedar Grove Elementary School	72	13	30	3		118
Grand Total	72	13	30	3		118

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106040	Cedar Grove Elementary School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Soccer Field	ADA
106041	Cedar Grove Elementary School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Accessible Route AR5 to Baseball/Softball Field	ADA
106006	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp - CR3	ADA
106008	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp - CR1	ADA
106010	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp - CR4	ADA
106032	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp - CR4	ADA
106033	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramp - CR3	ADA
106184	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR3	ADA
106187	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible Route AR3	ADA
106188	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible Route adjacent to AR3	ADA
106189	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Sidewalk leading to STR4	ADA
106190	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Sidewalk at entrance to the portables	ADA
106191	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	Sidewalk leading to R2	ADA
106192	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible Route adjacent to STR1	ADA
106193	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Courtyard Garden area	ADA
106194	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR2	ADA
106195	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - STR2	ADA
106196	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106197	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - STR1	ADA
106198	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp - R1	ADA
106199	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrail height is not compliant.	Ramp - R1	ADA
106200	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp - R1	ADA
106201	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route at the wooden portable walkway	ADA
106202	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - STR4	ADA
106203	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR3	ADA
106204	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - STR3	ADA
106205	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR5	ADA
106206	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair - STR5	ADA
106207	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR6	ADA
106208	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair - STR4	ADA
106209	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramps - R2 and R3	ADA
106210	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp - R4	ADA
106211	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair - STR3	ADA
106212	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrail height is not compliant.	Ramp - R4	ADA
107605	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	Accessible route AR2	ADA
107918	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp - CR	ADA
105871	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:20 (5%).	Accessible route AR1	ADA
105872	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible route AR2	ADA
105873	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Ramp - R1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
105874	Cedar Grove Elementary School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Entrance Door - DR1	ADA
105875	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Ramp	1	The handrails are not compliant.	Ramp - R1	ADA
105938	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR4 Landing	ADA
105942	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	A compliant accessible route is not provided from the passenger loading/unloading zone to the public facility entrance.	Parent loading/unloading zone	ADA
105996	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramps - CR1	ADA
105998	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramps - CR2	ADA
106003	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp CR2 Landing	ADA
106005	Cedar Grove Elementary School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp - CR2	ADA
105879	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	All Interior Classroom Doors	ADA
105880	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	All Interior Classroom Doors	ADA
105881	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	All Interior Office Doors	ADA
105883	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	All Purpose Room - Stage	ADA
105897	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Interior Stairs - STR1	ADA
105966	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Student Restroom Doors	ADA
105967	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Room 1A and Restroom RR3	ADA
105973	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain - DF5	ADA
105975	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	Interior Stair - STR1	State of Massachusetts

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
105943	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 1	ADA
105944	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1	ADA
105945	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1	State of Maryland
105946	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1	State of Maryland
105947	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
105948	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1; Accessible Space P1A	ADA
105949	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1; Accessible space P1B	ADA
105950	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot 1; Accessible space P1C	ADA
107916	Cedar Grove Elementary School	PARKING LOTS	Accessible Parking	Parking Spaces-General	1	The accessible parking stalls and/or aisles are located in the vehicular way.	Vehicular Way adjacent to CR2	ADA
105935	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Bench adjacent to the play court area	ADA
105952	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Picnic table adjacent to the play court area	ADA
106035	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Bench adjacent to Playground PG1	ADA
106036	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Picnic table adjacent to Playground PG3	ADA
106037	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Bench adjacent to Playground PG3	ADA
106038	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Court	ADA
106043	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Playground PG3 - Bucket Ball	ADA
105957	Cedar Grove Elementary School	ATHLETIC FIELDS	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the sports fields.	Baseball/Softball and Soccer Fields	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
105884	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	All rooms throughout the building	ADA
105924	Cedar Grove Elementary School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
105953	Cedar Grove Elementary School	PLAYGROUNDS	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playgrounds - PG1 - Transfer Platform	ADA
106039	Cedar Grove Elementary School	PLAYGROUNDS	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	Playgrounds - PG1, PG2 and PG3	ADA
106042	Cedar Grove Elementary School	PLAYGROUNDS	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground - PG2	ADA
106044	Cedar Grove Elementary School	PLAYGROUNDS	Exterior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Playgrounds - PG2 and PG3	ADA
106045	Cedar Grove Elementary School	PLAYGROUNDS	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	Playground - PG3	ADA
106046	Cedar Grove Elementary School	PLAYGROUNDS	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	Playground - PG3	ADA
105889	Cedar Grove Elementary School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	2	The required number of accessible locker and dressing/fitting rooms are not provided.	Building Services Office	State of Massachusetts
105915	Cedar Grove Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Student Restrooms - CR2, CR11, CR12 and CR13	ADA
105918	Cedar Grove Elementary School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restrooms - SR1, W7, M8, SR9, SR10, SR16, M19 and W20	ADA
105980	Cedar Grove Elementary School	RESTROOMS	Interior Access Route	Signage	2	The provided signage does not have the International Symbol of Accessibility, where not all elements of the same type are accessible.	Restrooms - RR1, RR7, RR8, RR9, RR10, RR16, RR19 and RR20	ADA
105878	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All exterior egress doors DR1 to DR18	ADA
105882	Cedar Grove Elementary School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	All Purpose Room	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
105886	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Restrooms - SR10 and SR16	ADA
105887	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Restrooms - SR10 and SR16	ADA
105888	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Restrooms - SR10 and SR16	ADA
105911	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The grab bars at the water closet are not present.	Staff Restrooms - W7, M8, SR9, SR10, SR16, M19 and W20	ADA
105912	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restrooms - B5	ADA
105925	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not present.	Student Restrooms - CR11, CR12 and CR13	ADA
105926	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restrooms - SR1, W7 and SR10	ADA
105927	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restrooms - SR1, W7, M8, SR9, SR10, SR16 M19 and W20	ADA
105928	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Staff Restrooms - SR1, W7, M8, SR9, SR10, SR16, M19, W20 and Kitchen	ADA
105930	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms - W7, M8, SR9, SR16, M19 and W20	ADA
105931	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restrooms - M3 and W4	ADA
105932	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Student Restrooms - CR2, B5, G6, CR11, CR12, CR13, B14, G15, B17, G18 and CR21	ADA
105933	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Student Restrooms - G6, B14, G15, B17 and G18	ADA
106062	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restrooms - M3 and W4	ADA
106063	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Student Restrooms - CR2, B5, CR12 and CR13	ADA
106067	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Staff Restrooms - M3 and W4	ADA
106074	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restroom - W4	ADA
106075	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restrooms - SR1, W7, SR16 and M19	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
106098	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restrooms - CR2, CR11, CR12 and CR13	ADA
106106	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated	Student Restrooms - CR11, CR12 and WCR13	ADA
106111	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Student Restrooms - CR12, CR13 and CR21	ADA
106113	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Student Restroom - CR2	ADA
106114	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restroom - CR21	ADA
106116	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Restrooms - SR1, M8, SR9, SR10 and SR16	ADA
106118	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Restrooms - M3 and W4	ADA
106122	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The grab bars at the water closet are not present.	Staff Restrooms - M3 and W4	ADA
106124	Cedar Grove Elementary School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Staff Restrooms - SR10 and SR16	ADA
107622	Cedar Grove Elementary School	RESTROOMS	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services Office	ADA
105890	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain, DF1, DF2, DF3, DF4 and DF5	ADA
105891	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain - DF6, DF7 and DF8	ADA
105971	Cedar Grove Elementary School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	Drinking Fountains - DF6, DF7 and DF8	ADA