



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Julius West Middle School
651 Great Falls Road
Rockville, Maryland 20850

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-131.303

Date of Report:

October 28, 2019

On Site Date:

April 30 – May 2, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity’s programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the “2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design.” The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Julius West Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Julius West Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG’s assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Julius West Middle School	90	29	72	4		195
Grand Total	90	29	72	4		195

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102656	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-21	ADA
102658	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-21	ADA
102717	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Bleachers at playing fields on southwest side of site	ADA
102719	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Courts	ADA
102720	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Routes Around Southwest and Southeast Side and of Ball Fields	ADA
102621	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-17	ADA
102623	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-17	ADA
102625	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-18	ADA
102626	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-18	ADA
102627	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-18, ST-19	ADA
102628	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-19	ADA
102629	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-19	ADA
102630	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-20, ST-22	ADA
102633	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-20, ST-22	ADA
102649	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	Stair ST -22	ADA
102651	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	Stair ST- 20	ADA
102652	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-23	ADA
102653	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-23	ADA
102654	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-24	ADA
102657	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-17, ST-20, ST-22, ST-24	ADA
102660	Julius West Middle School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-18, ST-19, ST-23	ADA
102661	Julius West Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Ramp R-2	ADA
102663	Julius West Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-1	ADA
102664	Julius West Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-1	ADA
102666	Julius West Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-5	ADA
102735	Julius West Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door D-2	ADA
102740	Julius West Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-9	ADA
102742	Julius West Middle School	EXTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-9	ADA
102743	Julius West Middle School	EXTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Ramp R-10	ADA
102747	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stair ST-18 to Curb Ramp CR-5	ADA
102748	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Stair ST-18 to Curb Ramp CR-5	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102749	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	Stair ST-18 to Curb Ramp CR-5	ADA
102750	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Northwest Side of Building	ADA
102751	Julius West Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Stair ST-20, ST-22	ADA
102752	Julius West Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Stair ST-20, ST-22	ADA
102763	Julius West Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	General ROARyard Courtyard	ADA
102232	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1	ADA
102238	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-2	ADA
102241	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-3	ADA
102244	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-4	ADA
102247	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-5	ADA
102250	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-6	ADA
102256	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-7	ADA
102258	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-8	ADA
102263	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	The rear of the stairs is open.	Stair ST-6	ADA
102276	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stairs St-1, ST-2, ST-3, ST-4, ST-5, ST-6, ST-7, ST-8	ADA
102284	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stairs St-1, ST-2, ST-3, ST-4, ST-5, ST-6, ST-7, ST-8	ADA
102292	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-11	ADA
102298	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-15	ADA
102300	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-9, ST-10, ST-11, ST-15, ST-16	ADA
102301	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-9, ST-10, ST-11, ST-15, ST-16	ADA
102304	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-12, ST-13	ADA
102307	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-12, ST-13	ADA
102308	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-12, ST-13	ADA
102310	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Stair ST-14	ADA
102315	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp R-2	ADA
102316	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp R-3	ADA
102318	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp R-5	ADA
102319	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	The clear width of the ramp is less than 36".	Ramp R-6	ADA
102349	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrail heights are not compliant.	Ramp R-2, R-3, R-5	ADA
102353	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-2, R-4, R-5, R-6	ADA
102357	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R-4	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102370	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp R-3	ADA
102375	Julius West Middle School	INTERIOR	Interior Access Route	Ramp	1	Ramp landings at the top and bottom of ramp runs are not compliant.	Ramp R-4	ADA
102376	Julius West Middle School	INTERIOR	Interior Access Route	Floor Surface	1	The floor surface has openings in the surface greater than 1/2".	Ramp R-2	ADA
102382	Julius West Middle School	INTERIOR	Fitness Course	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	Room 03 - Central Jaguar Weight Training	ADA
102424	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-5	ADA
102503	Julius West Middle School	INTERIOR	Interior Access Route	Platform Lift	1	The platform lift is not compliant.	Room 138	ADA
102518	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Girls PE Office in Room 142, Boys PE Office in Room 142A	ADA
102710	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Room A128 - Auxiliary Gym	ADA
102764	Julius West Middle School	INTERIOR	Entrance to Building	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Throughout Building	ADA
102765	Julius West Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	75% of All Doors to Classrooms, Offices, Workrooms, Team Rooms that Require Pushing to Exit Room	ADA
102766	Julius West Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	75% of All Doors to Classrooms, Offices, Workrooms, Team Rooms that Require Pulling to Exit Room	ADA
102768	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Cafeteria	ADA
102771	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Cafeteria Stage	ADA
102773	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Kitchen	ADA
102774	Julius West Middle School	INTERIOR	Interior Access Route	Interior Accessible Route	1	Clear widths are less than 36" minimum, including protruding objects.	Kitchen	ADA
102780	Julius West Middle School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Interior doors throughout building	ADA
102781	Julius West Middle School	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Throughout Building	ADA
102785	Julius West Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Banners at Main Entry	ADA
102787	Julius West Middle School	INTERIOR	Interior Access Route	Vertical Clearance	1	Objects along the interior accessible route suspend from the ceilings lower than 80" AFF.	Room 219	ADA
102788	Julius West Middle School	INTERIOR	Interior Access Route	Vertical Clearance	1	Objects along the interior accessible route suspend from the ceilings lower than 80" AFF.	Media Center	ADA
102680	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The van parking space is less than 96" wide minimum.	Parking Lot Space P1-D, P1-E	State of Maryland
102681	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Lot A Space P1-D, P1-E	State of Maryland
102692	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The parking space is less than 96" wide.	Parking Lot A Space P1-A, P1-B, P1-C	ADA
102694	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot A Space P1-A, P1-B	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102695	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The slope of the parking space is greater than 1:50 (2%).	Parking Lot A Space P10-A	ADA
102697	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle slope is greater than 1:50 (2%).	Parking Lot A Space P10-A	ADA
102699	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot A Space P10-A	State of Maryland
102700	Julius West Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot B Space P12-A	State of Maryland
102655	Julius West Middle School	ATHLETIC FIELDS	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Tennis Courts	ADA
102718	Julius West Middle School	ATHLETIC FIELDS	Baseball/Softball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	Bleachers at playing fields on southwest side of site	ADA
102790	Julius West Middle School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	Door D-1	ADA
102266	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-1, ST-2, ST-3, ST-7, ST-8	ADA
102299	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-10, ST-11, ST-15, ST-16	ADA
102306	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-12, ST-13	ADA
102309	Julius West Middle School	INTERIOR	Interior Access Route	Stairs	2	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair ST-14	ADA
102312	Julius West Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
102767	Julius West Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	Tray slides or buffet counters in food service lines are not 28" minimum and 34" maximum height above finish floor or ground.	Cafeteria	ADA
102769	Julius West Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Cafeteria	ADA
102770	Julius West Middle School	INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Cafeteria	ADA
102772	Julius West Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	Cafeteria	ADA
102775	Julius West Middle School	INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	School Store	ADA
102776	Julius West Middle School	INTERIOR	Concession Stand	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	Main Office and Guidance Office	ADA
102778	Julius West Middle School	INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Rooms 116, 120, 231, 208	ADA
102779	Julius West Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Rooms ADM Workroom, Media Workroom, A131, 131, A112, 228, 227A, 234A, 204, 222A	ADA
102782	Julius West Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Throughout Building	ADA
102783	Julius West Middle School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Throughout Building	ADA
104152	Julius West Middle School	INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Rooms 202, 210, 212	ADA
104176	Julius West Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Rooms Tech Lab 02, 146, 229	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
104177	Julius West Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Rooms 104A, Tech Lab 05, Tech Lab 03, 132, 200	ADA
104202	Julius West Middle School	INTERIOR	Kitchen	Sink	2	The accessible sink does not have push/lever hardware.	Room - ADM Workroom, 228	ADA
104204	Julius West Middle School	INTERIOR	Kitchen	Sink	2	The accessible sink does not have push/lever hardware.	Room - Tech Lab 05, Tech Lab 03	ADA
104207	Julius West Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Throughout Building	ADA
104208	Julius West Middle School	INTERIOR	Exterior Access Route	Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Throughout Building	ADA
104209	Julius West Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	Rooms 143, 114, 200	ADA
102442	Julius West Middle School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229-A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's RR-142, Staff Men's RR-142A	ADA
102471	Julius West Middle School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restroom - Girls RR-01B, Boys RR-01D, Girls 105A, Boys RR-105B, Girls RR-113A, Boys RR-113B, Boys RR-123A, Girls RR-123B, Boys RR-223A, Girls RR-223B, Girls RR-205C, Boys RR-205A, Girls RR-213A, Boys RR-213B	ADA
102472	Julius West Middle School	RESTROOMS	Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	Restroom - Girls RR-21, Girls RR-A116	ADA
102745	Julius West Middle School	EXTERIOR	Exterior Access Route	Clear Space	3	Clear space is not provided at the operable part.	Trash cans at Door D-15	ADA
102501	Julius West Middle School	INTERIOR	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Restroom - Staff RR-150B	ADA
102707	Julius West Middle School	INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Central Jaguar Gym	ADA
102777	Julius West Middle School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Hallways	ADA
102784	Julius West Middle School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All stairs and exterior doors	ADA
102786	Julius West Middle School	INTERIOR	Interior Access Route	Elevator	3	The hoistway signage is not compliant.	Elevator E-1	ADA
104211	Julius West Middle School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	Central Jaguar Gym	ADA
102222	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229-A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's RR-142, Staff Men's RR-142A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102225	Julius West Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229-A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's RR-142, Staff Men's RR-142A	ADA
102425	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Restroom Staff Women's RR-01E	ADA
102426	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom Staff Men's RR-01C, Staff Women's RR-126A, Staff Men's RR-126-B, Staff Women's RR-229A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B	ADA
102429	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Floor Space	3	The required turning space within the restroom is not provided.	Restroom Staff Women's RR-142, Staff Men's RR-142B, Staff RR-1	ADA
102430	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom Staff RR-2, Staff RR-ADMJ	ADA
102431	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom Staff Men's RR-126B, Staff Women's RR-229A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ	ADA
102432	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102433	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102434	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom Staff RR-1, Staff RR-2	ADA
102435	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229-A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's 142, Staff Men's 142A	ADA
102436	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Staff Women's RR-18	ADA
102437	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom - Staff RR-A125, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-218A, Staff RR-ADMJ	ADA
102438	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102439	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Restroom Staff Women's RR-126A, Staff Women's RR-142, Staff Men's RR-126A, Staff RR-1	ADA
102440	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's RR-229A, Staff RR-105B	ADA
102441	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom Staff RR-18, Staff RR-A125, Staff Men's RR-126B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-2, Staff RR-ADMJ	ADA
102443	Julius West Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Staff RR-1, Staff Women's RR-142, Staff Men's RR-142A	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102444	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Restroom Staff RR-ADMJ, Staff Men's RR-126B	ADA
102445	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102446	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102447	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102448	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102449	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102450	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Restroom Staff Women's RR-142, Staff Men's RR-142A, Staff RR-1	ADA
102451	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Restroom Girls RR-142, Boys RR-142A	ADA
102452	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant or are not provided in the transfer shower stall.	Restroom Girls RR-142, Boys RR-142A	ADA
102453	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Restroom Girls RR-142	ADA
102454	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Restroom Boys RR-142A	ADA
102455	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Restroom - Girls RR-21, Girls RR-105A, Boys RR-105B, Girls RR-113A, Boys RR-113B, Boys RR-A118, Boys RR-23A, Girls RR-213A, Boys RR-213B, Girls RR-142,	ADA
102456	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory faucet hardware is not compliant.	Restroom - Boys 205A	ADA
102457	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Restroom - Girls RR-113A, Girls RR-142, Boys RR-142A	ADA
102458	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Restroom - Boys RR-223A	ADA
102459	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Restroom - Girls RR-105A, Boys RR-105B, Boys RR-223A, Girls RR-205A, Boys RR-142A	ADA
102461	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Girls RR-01B, Boys RR-01D, Girls 105A, Boys RR-105B, Girls RR-113A, Boys RR-113B, Boys RR-123A, Girls RR-123B, Boys RR-223A, Girls RR-205C, Boys RR-205A, Girls RR-213A, Boys RR-213B, Girls RR-142, Boys RR-142A	ADA
102462	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Restroom Boys RR-205B	ADA
102463	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Restroom - Staff RR-2, Staff RR-ADMJ	ADA
102464	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom - Boys RR-104C, Girls RR-104D	ADA
102465	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Restroom - Boys RR-104C, Girls RR-104D	ADA
102466	Julius West Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Boys RR-104C, Girls RR-104D	ADA
102467	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Restroom - Girls RR-104D	ADA
102468	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Restroom - Boys RR-104C, Girls RR-104D	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102469	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Restroom - Boys RR-104C	ADA
102470	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Boys RR-104C, Girls RR-104D	ADA
102473	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bars are not compliant in the ambulatory stall.	Restroom - Girls RR-105A	ADA
102474	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff RR-ADMJ, Staff RR-2	ADA
102475	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Restroom - Boys RR-105B, Boys RR-123A, Boys RR-205A	ADA
102476	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Restroom - Boys RR-19	ADA
102477	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Restroom - Girls RR-21, Boys RR-19, Girls RR-105A, Girls RR-113A, Girls RR-A116, Boys RR-A118, Boys RR-223A, Girls RR-205C, Boys RR-205A, Boys RR-213B, Boys RR-A213, Girls RR-A211	ADA
102481	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Restroom - Boys RR-01D, Girls RR-21, Boys RR-19, Girls RR-113A, Boys RR-113B, Girls RR-A116, Boys RR-123A, Boys RR-223A, Girls RR-223C, Girls RR-205C, Boys RR-205A, Girls RR-13A, Boys RR-A213, Girls RR-A211, Boys RR-213B, Girls RR-142	ADA
102483	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Restroom - Girls RR-21, Boys RR-19, Girls RR-A116, Boys RR-A118, Boys RR-A213, Girls RR-A211	ADA
102486	Julius West Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Room 142 (Girls Locker Room), Room 142A (Boys Locker Room)	ADA
102487	Julius West Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Room 142 (Girls Locker Room), Room 142A (Boys Locker Room)	ADA
102499	Julius West Middle School	RESTROOMS	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Restroom - Staff RR-142, Staff RR-142A, Staff RR-150B	ADA
102753	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229-A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's RR-142, Staff Men's RR-142A, Staff RR-18, Staff RR-A125	ADA
102754	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Restroom - Girls RR-01B, Boys RR-01D, Girls 105A, Boys RR-105B, Girls RR-113A, Boys RR-113B, Boys RR-123A, Girls RR-123B, Boys RR-223A, Girls RR-205C, Boys RR-205A, Girls RR-213A, Boys RR-213B, Girls RR-142, Boys RR-142A, Girls RR-21, Boys RR-19, Girls R-A116, Boys RR-A118,	ADA
102756	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Restroom - Girls RR-104D, Boys RR-104C	ADA
102757	Julius West Middle School	RESTROOMS	Restroom	Controls And Dispensers	3	The height of controls are not compliant.	Restroom - Girls RR-142, Boys RR-142A	ADA
102758	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Restroom - Girls RR-104D, Boys RR-104C	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102759	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom - Girls RR-104D, Boys RR-104C	ADA
102760	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom - Staff Women's RR-01E, Staff Men's RR-01C, Staff Women's 126A, Staff Men's 126B, Staff Women's RR-229A, Staff Men's RR-229B, Staff Women's RR-218A, Staff Men's RR-218B, Staff RR-150B, Staff RR-1, Staff RR-ADMJ, Staff RR-2, Staff Women's RR-142, Staff Men's RR-142A	ADA
102761	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Restroom - Girls RR-01B, Boys RR-01D, Girls 105A, Boys RR-105B, Girls RR-113A, Boys RR-113B, Boys RR-123A, Girls RR-123B, Boys RR-223A, Girls RR-205C, Boys RR-205A, Girls RR-213A, Boys RR-213B, Girls RR-142, Boys RR-142A,	ADA
102762	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Restroom - Restroom Girls RR-142, Boys RR-142A Shower Area	ADA
104150	Julius West Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The automatic faucet, when activated, does not remain on for minimum 10 seconds.	Restroom - Boys RR-19	ADA
104151	Julius West Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Restroom - Staff RR-142, Staff RR-142A, Staff RR-150B	ADA
102420	Julius West Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-1, DF-3, DF-4, DF-5, DF-6, DF-7, DF-10, DF-11, DF-12, DF-14, DF-15	ADA
102421	Julius West Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain DF-1, DF-3, DF-4, DF-6, DF-7, DF-10, DF-12	ADA
102422	Julius West Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain DF-2, DF-8, DF-9, DF-13	ADA
102423	Julius West Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	Drinking Fountain DF-2, DF-8, DF-9, DF-13	ADA