



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Sligo Middle School
1401 Dennis Avenue
Silver Spring, Maryland 20902

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:
123821.17R000-119.303

Date of Report:
October 28, 2019

On Site Date:
April 26-27, 2018



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Sligo Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Sligo Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Sligo Middle School	70	33	89	4		196
Grand Total	70	33	89	4		196

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102165	Sligo Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp 2	ADA
102168	Sligo Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp 3	ADA
102169	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk adjacent to Door 6	ADA
102174	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 6	ADA
102175	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 8	ADA
102176	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 9	ADA
102177	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 10	ADA
102184	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 19	ADA
102185	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 24	ADA
102186	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 25	ADA
102187	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Door 26	ADA
102268	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete sidewalk between Parking Lot 1 and building	ADA
102277	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	North side of building adjacent to Basketball Court 1	ADA
102279	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	North side of building adjacent to Locker Rooms	ADA
102282	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	North side of building adjacent to Girls Locker Room	ADA
102286	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Concrete walkway adjacent to Doors 15 and 16	ADA
102288	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Asphalt walkway north of Doors 17 and 18	ADA
102294	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp 4: Door 19 to Basketball Court 2	ADA
102296	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	East Courtyard	ADA
102297	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	East Courtyard	ADA
102302	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Parking Lot 2 to Concrete walk on east side of building	ADA
102303	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Concrete sidewalk at east side of building	ADA
102305	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete sidewalk at east side of building	ADA
102311	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Sidewalk from accessible parking stalls P2A-B to adjacent lower level entrance	ADA
102314	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Concrete walk from Dennis Ave to toward Curb Ramp 2	ADA
102336	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Concrete walk from Dennis Ave to toward Curb Ramp 2	ADA
102338	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Concrete sidewalk west of Ramp 1	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102350	Sligo Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Main Entrance	ADA
102354	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Courtyard	ADA
102358	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	Courtyard	ADA
102363	Sligo Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 4	ADA
102364	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Stair 4	ADA
102366	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Soccer field	ADA
102369	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field	ADA
102377	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp 2	ADA
102381	Sligo Middle School	EXTERIOR	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Basketball Court 2	ADA
102390	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp 3	ADA
102394	Sligo Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 5	ADA
102395	Sligo Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stair 5	ADA
102398	Sligo Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair 5	ADA
102399	Sligo Middle School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Stair 4, Stair 5	ADA
102403	Sligo Middle School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Parking Lot 2: Student Drop Off	ADA
105566	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	Stair 4	ADA
105568	Sligo Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Stair 4	ADA
102407	Sligo Middle School	INTERIOR	Interior Access Route	Elevator	1	The re-opening device is not compliant.	Elevator	ADA
102415	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	Stair 2, Stair 3	ADA
102419	Sligo Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 2	ADA
102478	Sligo Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 3	ADA
102479	Sligo Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair 1	ADA
102480	Sligo Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Music Area stairs	ADA
102482	Sligo Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Music Area stairs, Gymnasium stage stairs	ADA
102485	Sligo Middle School	INTERIOR	Exterior Access Route	Platform Lift	1	The platform lift is not compliant.	Incline Platform Lift at Music Area stairs and Gymnasium stage stairs	ADA
102823	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Interior doors throughout	ADA
102824	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Interior doors throughout	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102825	Sligo Middle School	INTERIOR	Interior Access Route	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	Rooms 015, 023, 030, 031, 111A, 113A, 121, 124, 125, 127, 130, 131, 212, 217, 221	ADA
102836	Sligo Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Gymnasium, Cafeteria	ADA
102839	Sligo Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Gymnasium stage stairs	ADA
102860	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Main Office	ADA
102863	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Assistant Principal's Office, Communications Center, Room 101	ADA
102870	Sligo Middle School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Interior doors throughout	ADA
102233	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 1	State of Maryland
102234	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1	State of Maryland
102235	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 1	State of Maryland
102236	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Van	1	MARYLAND: Signage indicating "No Parking in Access Aisle" at van access aisle is not provided.	Parking Lot 1	State of Maryland
102245	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 1: P1A-P1D	State of Maryland
102248	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	The access aisle is less than 60" wide.	Parking Lot 1	ADA
102249	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	An access aisle is not provided.	Parking Lot 1	ADA
102255	Sligo Middle School	PARKING LOTS	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2	State of Maryland
102259	Sligo Middle School	PARKING LOTS	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not marked.	Parking Lot 1: Special needs children loading/unloading zone	ADA
102516	Sligo Middle School	RESTROOMS	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Girls Locker Room, Boys Locker Room	ADA
102274	Sligo Middle School	EXTERIOR	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Infants and Toddlers - West side of building	ADA
102341	Sligo Middle School	EXTERIOR	Exterior Access Route	Reach Range	2	Items requiring an obstructed forward reach motion are higher than 48" maximum height where the depth of the obstruction is 20" maximum, or greater than 44" maximum height where the depth of the obstruction is 20" to 25" maximum, or lower than minimum 15" height above finish floor.	Flag Pole	ADA
102348	Sligo Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	Flag Pole	ADA
102372	Sligo Middle School	EXTERIOR	Site Furnishings	Trash Receptacle Without Operable Lid	2	A trash receptacle is not located on an accessible route and within reach range.	Baseball Field	ADA
102404	Sligo Middle School	INTERIOR	Interior Access Route	Elevator	2	The elevator operation is not automatic	Elevator	ADA
102405	Sligo Middle School	INTERIOR	Interior Access Route	Elevator	2	No characters or numbers are present on the hoist ways.	Elevator	ADA
102416	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Stair 1, Stair 2, Stair 3	ADA
102417	Sligo Middle School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Stair 1, Stair 2, Stair 3	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102418	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Stair 1, Stair 2, Stair 3	ADA
102832	Sligo Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance.	Room 214, Room 216	ADA
102833	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	2nd Floor Program Assistant, Building Services, Team Room C, 6th Grade Team Room	ADA
102834	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	2nd Floor Program Assistant, Team Room A, Team Room C, Building Services, Office Staff Workroom, Media Center Workroom, Staff Workroom, 6th Grade Team Room	ADA
102837	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Gymnasium	ADA
102840	Sligo Middle School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	Exit doors throughout	ADA
102841	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Room 024, Room 027	ADA
102842	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Room 027	ADA
102843	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Corridor fire doors	ADA
102844	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Science Rooms 013, 023, 025, 123 and 125	ADA
102845	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Science Rooms 013, 023, 025, 123 and 125	ADA
102854	Sligo Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria	ADA
102855	Sligo Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria, Corridor outside Cafeteria	ADA
102857	Sligo Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Room 113	ADA
102858	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 113	ADA
102859	Sligo Middle School	INTERIOR	Interior Access Route	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	Main Office area	ADA
102861	Sligo Middle School	INTERIOR	Common Areas	Service Counter	2	The service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Main Office	ADA
102864	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Suite, Room 102, Room 113B, Room 104	ADA
102865	Sligo Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Room 101	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102866	Sligo Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Staff Lounge	ADA
102867	Sligo Middle School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Staff Lounge	ADA
102868	Sligo Middle School	INTERIOR	Common Areas	Service Counter	2	The service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	School Store	ADA
102871	Sligo Middle School	INTERIOR	Interior Access Route	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	Interior Rooms throughout	ADA
102795	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Unisex	2	Clear widths are not 36" minimum (including protruding objects). Smaller widths of 32" min. to 36" a max. length of 24" and not separated by segments a min. of 48" long and 36" wide min.	Girls Restroom 5	ADA
102818	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	Girls Restroom 8	ADA
102408	Sligo Middle School	INTERIOR	Interior Access Route	Elevator	3	Visible and audible signal fixtures indicating which car is answering the call and the car's direction of travel are not compliant.	Elevator	ADA
102410	Sligo Middle School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator	ADA
102835	Sligo Middle School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Corridor lockers	ADA
102838	Sligo Middle School	INTERIOR	Common Areas	Assembly Area	3	An assistive listening system is required, but not provided.	Gymnasium	ADA
102856	Sligo Middle School	INTERIOR	Common Areas	Assembly Area	3	An assistive listening system is required, but not provided.	M-1	ADA
102869	Sligo Middle School	INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Gymnasium	ADA
102797	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Boys Restroom 5	ADA
102798	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Boys Restroom 5	ADA
102799	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Girls Restroom 6, Boys Restroom 6, Girls Restroom 7, Boys Restroom 7	ADA
102800	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Girls Restroom 6	ADA
102802	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Girls Restroom 6	ADA
102803	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls Restroom 6	ADA
102804	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls Restroom 6, Boys Restroom 6, Girls Restroom 7, Boys Restroom 7	ADA
102488	Sligo Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	Girls Locker Room, Boys Locker Room	ADA
102489	Sligo Middle School	RESTROOMS	Locker and Dressing Rooms	Locker and Dressing Rooms	3	The locker room does not have accessible lockers.	Girls Locker Room, Boys Locker Room	ADA
102490	Sligo Middle School	RESTROOMS	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Girls Coach Office, Boys Coach Office	ADA
102491	Sligo Middle School	RESTROOMS	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Girls Coach Office, Boys Coach Office	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102492	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Girls Locker Room, Boys Locker Room	ADA
102493	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The shower enclosure is not 30" minimum by 60" minimum.	Girls Locker Room, Boys Locker Room	ADA
102494	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	Grab bars are not compliant.	Girls Locker Room, Boys Locker Room	ADA
102495	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	The location of the roll-in shower controls is not compliant.	Girls Locker Room, Boys Locker Room	ADA
102496	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Locker Room	ADA
102502	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Girls Locker Room	ADA
102504	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Girls Locker Room, Boys Locker Room	ADA
102505	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Girls Locker Room	ADA
102571	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys Locker Room	ADA
102572	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Girls Coach Office, Boys Coach Office	ADA
102573	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not compliant.	Girls Coach Office, Boys Coach Office, Building Services	ADA
102587	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Girls Coach Office, Boys Coach Office	ADA
102588	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Girls Coach Office, Boys Coach Office, Building Services	ADA
102589	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls Coach Office, Boys Coach Office	ADA
102590	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Girls Coach Office, Boys Coach Office	ADA
102591	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Staff Restrooms throughout	ADA
102592	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Staff Restroom 1: Men's and Women's, Staff Restroom 2; Men's and Women's, Building Services, Kitchen Staff, Health Staff, Staff Restroom 4A, Staff Restroom 4B	ADA
102593	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The opening force of the interior, non-fire, hinged, sliding, and folding door or gate is more than 5 pounds.	Staff Restroom 1: Men's and Women's, Staff Restroom 2; Men's and Women's	ADA
102594	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom 1: Men's and Women's, Staff Restroom 2; Men's and Women's, Staff Restroom 4A, Staff Restroom 4B	ADA
102608	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Staff Restroom 1: Men's and Women's, Staff Restroom 2; Men's and Women's, Health Staff, Staff Restroom 4A, Staff Restroom 4B	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102610	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Staff Restroom 1: Men's, Staff Restroom 2: Men's, Kitchen Staff, Health Staff	ADA
102612	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 1: Men's and Women's, Staff Restroom 2; Men's	ADA
102615	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff Restroom 1: Men's and Women's, Staff Restroom 2: Women's, Staff Restroom 4A, Staff Restroom 4B	ADA
102617	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 1: Women's, Building Services	ADA
102619	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Staff Restroom 2: Women's, Kitchen Staff	ADA
102624	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Restroom 2: Women's	ADA
102631	Sligo Middle School	RESTROOMS	Employee Work Areas	Locker Rooms	3	The locker room does not have accessible lockers.	Building Services, Kitchen Staff	ADA
102632	Sligo Middle School	RESTROOMS	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services, Kitchen Staff	ADA
102634	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Building Services, Boys Coach Office, Girls Coach Office	ADA
102635	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Building Services	ADA
102636	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Building Services	ADA
102637	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Building Services	ADA
102639	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The push side of the door does not have the required maneuvering clearances.	Kitchen Staff	ADA
102640	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Kitchen Staff	ADA
102641	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Kitchen Staff	ADA
102642	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Kitchen Staff	ADA
102643	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Kitchen Staff	ADA
102644	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Kitchen Staff	ADA
102645	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Kitchen Staff	ADA
102646	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Main Office Restroom	ADA
102647	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Staff	ADA
102648	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Health Staff	ADA
102650	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	Staff Restroom 3A and 3B	ADA
102670	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom 4A, Staff Restroom 4B	ADA
102671	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom 4A, Staff Restroom 4B	ADA
102673	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Staff Restroom 4A, Staff Restroom 4B	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102675	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Staff Restroom 4A, Staff Restroom 4B	ADA
102696	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	Student Restrooms throughout	ADA
102698	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than ½" in height.	Boys Restroom 1, 2, 3, 4 and 5, Girls Restroom 1, 2, 3, 4 and 5, Girls Restroom 8	ADA
102701	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Boys Restroom 1, Girls Restroom 1, Girls Restroom 4	ADA
102702	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Boys Restroom 1	ADA
102703	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boys Restroom 1, Boys Restroom 4, Girls Restroom 1, Girls Restroom 4	ADA
102705	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	Boys Restroom 1, 2, 3, 4 and 5, Girls Restroom 1, 2, 3, 4, 5 and 8, SCB Restroom 107	ADA
102706	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	Girls Restroom 1, Girls Restroom 4, Girls Restroom 8	ADA
102721	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Girls Restroom 2	ADA
102725	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Student Health Restroom	ADA
102731	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Health Restroom	ADA
102733	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Student Health Restroom, Girls Restroom 3	ADA
102734	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Student Health Restroom, SCB Restroom 107	ADA
102736	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Student Health Restroom	ADA
102737	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	Student Health Restroom	ADA
102744	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	SCB Restroom 107	ADA
102746	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom 3, Boys Restroom 4, Boys Restroom 5	ADA
102792	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Girls Restroom 3	ADA
102793	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Boys Restroom 4	ADA
102794	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Girls Restroom 4	ADA
102796	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	Girls Restroom 5	ADA
102805	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Girls Restroom 6	ADA
102806	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	Boys Restroom 6	ADA
102808	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom 6	ADA
102809	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Boys Restroom 6, Girls Restroom 7, Boys Restroom 7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
102815	Sligo Middle School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Boys Restroom 7	ADA
102411	Sligo Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The spout of the standing height drinking fountain is not between 38" minimum and 43" maximum.	Drinking Fountains 1, 2, 3, 4, 5, 6	ADA
102862	Sligo Middle School	INTERIOR	Common Areas	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	Office Staff Workroom, Staff Workroom	ADA
102565	Sligo Middle School	RESTROOMS	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Boys Locker Room	ADA
102638	Sligo Middle School	RESTROOMS	Common Areas	Locker Rooms	4	The locker room does not have at least one of the coat hooks within reach range.	Kitchen Staff	ADA