



ADA TITLE II ASSESSMENT



Prepared for:

Montgomery County Public Schools
45 West Gude Drive, Suite 4100
Rockville, Maryland 20850

ADA TITLE II ASSESSMENT

Newport Mill Middle School
11311 Newport Mill Road
Kensington, Maryland 20895

PREPARED BY:

EMG
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Michael Nelson
Program Manager
800.733.0660 x6244
mnelson@emgcorp.com

EMG Project Number:

123821.17R000-068.303

Date of Report:

October 25, 2019

On Site Date:

August 8-9, 2017



1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Newport Mill Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Newport Mill Middle School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Newport Mill Middle School	100	24	95	9		233
Grand Total	100	24	95	9		233

1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
70048	Newport Mill Middle School	EXTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	Parking Lots A, B	ADA
69089	Newport Mill Middle School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	Building Services 204	ADA
69375	Newport Mill Middle School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	Boy's and Girl's Lockers	ADA
69376	Newport Mill Middle School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	Restroom 107B	ADA
69271	Newport Mill Middle School	INTERIOR	Amenity Not Evaluated	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	Hall Lockers	ADA
70049	Newport Mill Middle School	EXTERIOR	Accessible Parking	Parking Space-Van	1	MARYLAND: The van access aisle is less than 96" wide.	Parking Space P-1C	State of Maryland
70050	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 8	ADA
70051	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Sidewalk between Curb Ramp CR-1 to Stair ST-10	ADA
70107	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-10	ADA
70108	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-9	ADA
70109	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Exterior Door 9	ADA
70110	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-4	ADA
70111	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-11	ADA
70112	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-11	ADA
70113	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The access aisle is not at the same level as the loading/unloading area.	Car Loading/Unloading Zone	ADA
70114	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Northwest Entrance to the Tennis Courts	ADA
70115	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Exterior Door 12	ADA
70116	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route between Tennis Court and South East corner of the building	ADA
70117	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route starting at Exterior Door 12 going west 45 linear feet.	ADA
70118	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field	ADA
70119	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Exterior Door 15	ADA
70120	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-5	ADA
70121	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-12	ADA
70122	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	The sidewalk at Exterior Door 19	ADA
70123	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	Sidewalk does not meet the 36" minimum clear width requirement (60" minimum where passing areas are present).	Chain Link Fence Southwest corner of the gym	ADA
70124	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk southwest corner of the gym.	ADA
70128	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Exterior Door 1	ADA
70129	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-13	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
70130	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-7	ADA
70131	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-13	ADA
70132	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramp CR-2	ADA
70133	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-3	ADA
70134	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-3	ADA
70135	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR-4	ADA
70136	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR-4	ADA
70137	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The slope of the curb ramp flares is greater than 1:10 (10%).	Curb Ramp CR-4	ADA
72621	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 1	ADA
72622	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-8	ADA
72623	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has cross slopes in excess of 1:48 (2.08%).	Ramp R-8	ADA
72624	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A level turning space is not provided at a turn in the accessible route.	Bus Drop off zone.	ADA
72625	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R-9	ADA
72626	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-9	ADA
72630	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Sidewalk from Parking Lot 2 to the chillers	ADA
72631	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Cur Ramps CR-5, CR-6	ADA
72632	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stairs ST-14	ADA
72633	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Stairs ST-14	ADA
72804	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 7	ADA
72807	Newport Mill Middle School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Door 6	ADA
72808	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	The accessible route throughout the outdoor dining area between Exterior Doors 6 and 7.	ADA
72819	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-10	ADA
72820	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a rise greater than 6"; however, handrails are not provided.	Ramp R-10	ADA
72821	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Stair ST-15	ADA
72822	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-15	ADA
72824	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Stair ST-15	ADA
72825	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Courtyard	ADA
72826	Newport Mill Middle School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Courtyard	ADA
69340	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-7	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69082	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Team Room 211	ADA
69084	Newport Mill Middle School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Staff Restroom RR-203	ADA
69085	Newport Mill Middle School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Classroom 200, 202	ADA
69087	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Building Services 204	ADA
69111	Newport Mill Middle School	INTERIOR	Common Areas	Interior Doors	1	The pull side of the accessible door does not have the required maneuvering clearances.	Health Suite 209	ADA
69342	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stairs ST-7	ADA
69346	Newport Mill Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp is required but not provided.	Ramp R-8	ADA
69369	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Main Gym 103	ADA
69370	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-8	ADA
69371	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	The underside of the nosings are abrupt, not curved or beveled.	Stair ST-8	ADA
69372	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-8	ADA
69373	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stairs ST-9	ADA
69374	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Platform Lift PL-2	ADA
69441	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-8	ADA
69122	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Girls Restroom RR-206, RR-405, RR-1208	ADA
69139	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Girls Restroom RR-206	ADA
69183	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Boy's Restroom RR-208	ADA
69185	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Boys Restroom RR-208	ADA
69189	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Classroom 210, 216, 217, 219, 220, 221, 223, 305, 306, 307, 309, 402, 407, 409, 411, 412, 413, 414, 1201, 1203, 1205, 1206, 1207, 1216, 1217, 1218, 1219, 1220, 1221, 1222, 1223, 1225	ADA
69600	Newport Mill Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R-1	ADA
69604	Newport Mill Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-1	ADA
70013	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Team Room 1200	ADA
69246	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Drinking Fountain DF-3, DF-5	ADA
69266	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided on the stairs.	Classroom 400 ST-5	State of Massachusetts
69268	Newport Mill Middle School	INTERIOR	Exterior Access Route	Ramp	1	The accessible route to the facility has a stairway, which does not comply with vertical rise requirements.	Classroom 400 R-2	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69276	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1	ADA
69277	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-1	ADA
69278	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	The underside of the nosings are abrupt, not curved or beveled.	Stair ST-1	ADA
69288	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Cafeteria 104	ADA
69290	Newport Mill Middle School	INTERIOR	Employee Work Areas	Locker Rooms	1	The locker rooms are not accessible.	Locker Room 104D	ADA
69310	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Boys Restroom RR-106	ADA
70038	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Boys Restroom RR-1210	ADA
70039	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-1	ADA
70040	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-1, ST-2, ST-3	ADA
70041	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	The underside of the nosings are abrupt.	Stair ST-1, ST-3	ADA
70042	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-3	ADA
70043	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Stair ST-2	ADA
70044	Newport Mill Middle School	INTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-3	ADA
70045	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	Stair ST-3	ADA
70046	Newport Mill Middle School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	AED located outside the 1st-floor door to Stair ST-3.	ADA
72834	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The opening force of the accessible, hinged, non-fire door is more than 5 pounds.	All interior doors.	ADA
72835	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	Interior doors with door closers	ADA
69327	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Girls Restroom RR-108	ADA
69330	Newport Mill Middle School	INTERIOR	Common Areas	Platform Lift	1	The platform lift requires a key for operation.	Platform Lift P-1, P-2	ADA
69332	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	The underside of the nosings are abrupt, not curved or beveled.	Stair ST-6	ADA
69335	Newport Mill Middle School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Stair ST-6	ADA
69336	Newport Mill Middle School	INTERIOR	Interior Access Route	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	Ramp R-3	ADA
69337	Newport Mill Middle School	INTERIOR	Interior Access Route	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	Ramp R-3	ADA
69058	Newport Mill Middle School	INTERIOR	Site Furnishings	Vending Machine	2	The vending machines are not accessible.	Team Room 207	ADA
69061	Newport Mill Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Team Room 207, 1200, 1202	ADA
69112	Newport Mill Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Health Suite 209	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69367	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Main Gym 103	ADA
69188	Newport Mill Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Media Center support	ADA
69191	Newport Mill Middle School	INTERIOR	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	Art Room 309	ADA
69192	Newport Mill Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Art Room 309	ADA
69199	Newport Mill Middle School	INTERIOR	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Classroom 304	ADA
69202	Newport Mill Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Science Room 302, 402, 407, 409, 411, 413, 414	ADA
69204	Newport Mill Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Science Room 302, 402, 407, 409, 411, 414	ADA
69206	Newport Mill Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Classroom 304	ADA
69207	Newport Mill Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Science Room 302, 407, 409, 411	ADA
69244	Newport Mill Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	The dining or work surface does not have a minimum 28" and maximum 34" height with knee and toe clearance.	Science Room 302, 402, 407, 409, 441, 413	ADA
69245	Newport Mill Middle School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Science Room 402, 409	ADA
69247	Newport Mill Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Computer Lab 414	ADA
69248	Newport Mill Middle School	INTERIOR	Common Areas	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	Applied Tech Lab 412	ADA
69251	Newport Mill Middle School	INTERIOR	Classroom	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	Applied Tech Room 412	ADA
69252	Newport Mill Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Applied Tech Room 412	ADA
69283	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Cafeteria 104	ADA
69285	Newport Mill Middle School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Cafeteria 104, Gym Lobby	ADA
69286	Newport Mill Middle School	INTERIOR	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Cafeteria 104	ADA
69289	Newport Mill Middle School	INTERIOR	Common Areas	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	Cafeteria 104	ADA
69306	Newport Mill Middle School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Kitchen Restroom RR-104A	ADA
72830	Newport Mill Middle School	INTERIOR	Interior Access Route	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	2nd-floor entrance to stairwells and 1st-floor egress doors.	ADA
69045	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Staff Restroom RR-125B, RR-203, RR205, RR-211A, RR-211B RR-1213	ADA
69046	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Staff Restroom RR-211A, RR211B	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69047	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Staff Restroom RR-125B, RR-211A, RR211B	ADA
69048	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Kitchen Restroom RR-140A, Staff Restroom RR-211A	ADA
69049	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Kitchen Restroom RR-140A, Staff Restroom RR-125B, RR-221A, RR-211B	ADA
69050	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Kitchen Restroom RR-140A, Staff Restroom RR-125B, RR-211A, RR-211B	ADA
69054	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Staff Restroom RR203, RR-205, RR-211A, RR-211B	ADA
69055	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Staff Restroom RR-211A, RR-211B	ADA
69056	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Staff Restroom RR-203, RR-205, RR-211B RR-1213	ADA
69057	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom RR-211B	ADA
69068	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom RR-203, RR-205	ADA
69069	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom RR-205	ADA
69071	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Staff Restroom RR-205	ADA
69073	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom RR-211A	ADA
69074	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom RR-211B	ADA
69078	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Staff Restroom RR-203	ADA
69079	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom RR-203	ADA
69090	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Building Services	ADA
69092	Newport Mill Middle School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services 204	ADA
69099	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Building Services RR-204D, RR-211A, RR211B	ADA
69101	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Building Service RR-204D	ADA
69103	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Building Services RR-204D	ADA
69104	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Building Services RR-204D Staff RR-125D	ADA
69106	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Building Services RR-204D	ADA
69108	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Building Services RR-204D, Staff Rr-125D	ADA
69109	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Building Services RR-204D, Staff RR-125D	ADA
69110	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Building Services RR-204D, Staff RR-125D	ADA
69113	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	Heath Suite RR-209A	ADA
69114	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Health Suite RR-209A	ADA
69115	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Health Suite, RR-209A	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69368	Newport Mill Middle School	INTERIOR	Common Areas	Assembly Area	3	Assembly areas do not provide wheelchair spaces.	Main Gym 103	ADA
69377	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Restroom RR-125B	ADA
69379	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom RR-125	ADA
69381	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom RR-125	ADA
69383	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall door is not compliant.	Boys Restroom RR-125, RR-208, RR-401 RR-1210, Girls Restroom RR-107, RR-206, RR-405, RR-1208	ADA
69384	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Restroom RR-125B	ADA
69417	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The transfer shower is not exactly 36" by 36".	Locker Room 107, 125	ADA
69418	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Locker Room 125	ADA
69419	Newport Mill Middle School	INTERIOR	Common Areas	Locker Rooms	3	The locker room does not have a compliant bench.	Locker Room 107, 125	ADA
69420	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not compliant	Locker Room 107, 125	ADA
69421	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A transfer seat is provided but is not compliant.	Locker Room 107, 125	ADA
69422	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The required clearance at the entry to the transfer stall is not provided.	Locker Room 107, 125	ADA
69433	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Locker Room 107, 125	ADA
69454	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Girls Restroom RR-107	ADA
69457	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Girls Restroom RR-107	ADA
69591	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Girls Restroom 107	ADA
69119	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Health Suite RR-209A	ADA
69120	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The threshold at the accessible door is greater than 1/2" in height.	Health Services RR-209A	ADA
69124	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Boys Restroom RR-401, Girls Restroom RR-206, RR-405, RR-1208	ADA
69125	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys Restroom RR-208, RR-401, RR-1210, Girls Restroom RR-206, RR-405 RR-1208	ADA
69126	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys Restroom RR-125, RR-208, RR-401, RR-1210, Girls Restroom RR-107, RR-206, RR-405, RR-1208	ADA
69127	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Boy's Restroom RR-208, RR-401, RR-1210, Girls Restroom RR-206, RR-405, RR-1208	ADA
69128	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boy's Restroom RR-125, RR-208, RR-401, Girls Restroom RR-206, RR-405	ADA
69129	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys Restroom RR-125, RR-208, RR-401, RR-1210, Girls Restroom RR-206, RR-405, RR-1208	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69130	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom RR-125, RR-208, RR-401 RR-1210, Girls Restroom RR-206, RR-405 RR-1208	ADA
69131	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Girls restroom RR-206, RR-405	ADA
69133	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Restroom RR-125, RR-208, RR-401, RR-1210 Girls Restroom RR-206, RR-405, RR-1208	ADA
69134	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys Restroom RR-208, RR-401, Girls Restroom RR-206, RR-405	ADA
69175	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Boys Restroom RR-125, RR-208, RR-401, RR-1210, Girls Restroom RR-107, RR-206, RR-405, RR-1208	ADA
69176	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom RR-208, RR-401	ADA
69177	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom RR-208, RR-1210	ADA
69178	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Boys Restroom RR-208, Girls Restroom RR-405	ADA
69181	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Boys Restroom RR-208, RR-401	ADA
69594	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Shower	3	The shower spray unit is not compliant.	Locker Room 107	ADA
70014	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff RR-1213	ADA
70015	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Staff Restroom RR-1213	ADA
70016	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Staff Restroom RR-1213	ADA
70017	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Staff Restroom RR-1213	ADA
70032	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Girls Restroom RR-1208	ADA
70033	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Girls Restroom RR-1208	ADA
70034	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Girls Restroom RR-1208	ADA
70036	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Boy's Restroom RR-1210	ADA
70037	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Boy's Restroom RR-1210	ADA
69243	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Boys Restroom RR-401	ADA
69287	Newport Mill Middle School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	Main Gym 103 / Stage	ADA
69291	Newport Mill Middle School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Locker Room 104D	ADA
69298	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Kitchen Restroom RR-104A	ADA
69300	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	Kitchen Restroom RR-104A	ADA
69301	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Kitchen Restroom RR-104A	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69302	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Kitchen Restroom RR-104A	ADA
69303	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a single/user or unisex restroom does not have the required clearance.	Kitchen Restroom RR-104A	ADA
69308	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Boys Restroom RR-106	ADA
69309	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	Boys Restroom R-106, Girls Restroom RR-108	ADA
69311	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Boys Restroom RR-106, RR-1210	ADA
69312	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69313	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required knee clearance.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69314	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69315	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69316	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69317	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69318	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69319	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Boys Restroom RR-106, Girls Restroom RR-108	ADA
69323	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	Girls Restroom RR-108	ADA
70047	Newport Mill Middle School	INTERIOR	Interior Access Route	Elevator	3	A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level.	Elevator	ADA
69326	Newport Mill Middle School	INTERIOR	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Girls Restroom RR-108	ADA
72629	Newport Mill Middle School	EXTERIOR	Signage	Exterior Accessible Route-Signage	4	Signage directing pedestrians to the nearest accessible building entrance on an accessible route is not present.	Ramp R-6	ADA
69060	Newport Mill Middle School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	Team Room 207	ADA
69439	Newport Mill Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-6	ADA
69173	Newport Mill Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-1, DF-2, DF-9	ADA
70018	Newport Mill Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	Drinking Fountain DF-8	ADA
69196	Newport Mill Middle School	INTERIOR	Kitchen	Kitchen- Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	Classroom 304	ADA
69197	Newport Mill Middle School	INTERIOR	Kitchen	Kitchen- Oven/ Public	4	The oven or built-in microwave does not have an adjacent work surface which is a minimum height of 28" and maximum height of 34" and minimum 30" wide, with knee and toe clearance.	Classroom 304	ADA
69249	Newport Mill Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-4	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
69272	Newport Mill Middle School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Drinking Fountain DF-5	ADA