

# **(emg)** ADA TITLE II ASSESSMENT



Prepared for:

**Montgomery County Public Schools**  
45 West Gude Drive, Suite 4100  
Rockville, Maryland 20850

## **ADA TITLE II ASSESSMENT**

Sherwood High School  
300 Olney-Sandy Spring Road  
Sandy Spring, Maryland 20860

### **PREPARED BY:**

EMG  
10461 Mill Run Circle, Suite 1100  
Owings Mills, Maryland 21117  
800.733.0660  
[www.EMGcorp.com](http://www.EMGcorp.com)

### **EMG CONTACT:**

Michael Nelson  
Program Manager  
800.733.0660 x6244  
[mnelson@emgcorp.com](mailto:mnelson@emgcorp.com)

**EMG Project Number:**  
123821.17R000-152.303

**Date of Report:**  
October 29, 2019

**On Site Date:**  
June 20-22, 2018

# 1 Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of the government entity's programs, services, and facilities on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG), and applicable state and local accessibility regulations.

Buildings completed and occupied after January 26, 1992 are required to comply fully with ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of complying to the extent allowed by structural feasibility and the financial resources available, or a reasonable accommodation must be made. The ADA guidelines were clarified and amended in 2010 based on a clarification by the Department of Justice known as the "2011 Site Construction Tolerances Addendum to the 2010 ADA Standards for Accessible Design." The aforementioned document defines the acceptable and allowed construction tolerances above or below the requirements established in the 2010 ADA Standards for barriers related to:

- Accessible Parking
- Pedestrian Path of Travel
- Building Entrances
- Interior Spaces

The scope of the ADA Assessment, as defined in the scope of work, is limited to exterior and interior areas covered by the ADA.

Based on the onsite review, EMG found that barriers to accessibility exist at Sherwood High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

## 1.1 Accessibility Summary Table

Based on the onsite review, EMG found that barriers to accessibility exist at Sherwood High School. The observed elements were analyzed using the 2010 ADA Standards for Accessible Design and state accessibility codes.

EMG's assessment of the subject property identified the following areas of concern:

Facility / Building	Priority 1 Items	Priority 2 Items	Priority 3 Items	Priority 4 Items	Priority 5 Items	Total Items
Sherwood High School	74	18	43	3	21	159
Grand Total	74	18	43	3	21	159

## 1.2 Barrier Summary Table

The following table summarizes the barriers that were identified. The costs provided are order of magnitude estimates. Costs will vary depending upon the location and volume of work performed. Individual observation details may be found in Appendix A.

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109314	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Football Practice Field	ADA
109315	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Route to baseball field from accessible route	ADA
109414	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Route to baseball batting cages from accessible route	ADA
109415	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Basketball Court	1	An accessible route does not directly connect each side of the court outside the play lines.	Exterior Basketball Courts	ADA
109416	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Exterior Basketball Court	ADA
109343	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A landing at the top of the curb ramp is not present.	Curb Ramp CR2 Landing	ADA
109357	Sherwood High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The loading/unloading zone is not 96" wide by 20' long with vertical clearance of 114".	Parent Loading/Unloading zone	ADA
109400	Sherwood High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The space between two doors (in a series) is less than 48" clear with doors open 90 degrees.	Building Entrances DR4 and DR5	ADA
109421	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR13 Landing	ADA
109423	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR12 Landing	ADA
109424	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR15 Landing	ADA
109425	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR14 Landing	ADA
109426	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR5	ADA
109427	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The counter slopes of adjoining gutters and streets at the curb ramp are greater than 1:20 (5%).	Curb Ramps - CR14	ADA
109431	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Courtyard-2 Bench	ADA
109432	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Courtyard-3 Picnic Tables	ADA
109433	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Accessible Route in Courtyard-2	ADA
109434	Sherwood High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Courtyard-6 Entrance from Building	ADA
109435	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	Football and Track Stadium Concession Stand	ADA
109437	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR1	ADA
109439	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR4	ADA
109440	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR3	ADA
109441	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR2	ADA
109442	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	Accessible Route AR10	ADA
109443	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR9	ADA
109444	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR7	ADA
109445	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR6	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109447	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR8	ADA
109448	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Along Accessible route AR8	ADA
109449	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	Parking Lot 4 Trash Receptacles	ADA
109454	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair - STR5	ADA
109455	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Exterior Stair - STR5	ADA
109456	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	The stair treads and edge of top landing do not have visual contrast on the leading edge.	Exterior Stair - STR5	ADA
109457	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Exterior Stair - STR6	ADA
109458	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrails are not provided.	Exterior Stair - STR4	ADA
109459	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	Exterior Stair - STR4	ADA
111601	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	Curb Ramp CR4 Landing	ADA
111602	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR3	ADA
111603	Sherwood High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Exterior Doors DR11, DR15, DR16, DR21, DR31 and DR32	ADA
111604	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	The curb ramp does not meet the slope requirements.	Curb Ramp CR13	ADA
111605	Sherwood High School	EXTERIOR	Exterior Access Route	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	Curb Ramps CR-A and CR-B	ADA
111606	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Accessible route AR4	ADA
111607	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	Along Accessible Route AR4	ADA
111609	Sherwood High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Ramp R1	ADA
111610	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR5	ADA
111611	Sherwood High School	EXTERIOR	Exterior Access Route	Exterior Accessible Route	1	The accessible route has cross slopes greater than 1:50 (2%).	Accessible Route AR11	ADA
111612	Sherwood High School	EXTERIOR	Exterior Access Route	Stairs	1	Handrail extensions are not compliant.	Exterior Stairs - STR3 and STR5	ADA
111613	Sherwood High School	EXTERIOR	Exterior Access Route	Loading/Unloading Zone	1	The loading/unloading zone is not 96" wide by 20' long with vertical clearance of 114".	Bus Loading/Unloading zone	ADA
111614	Sherwood High School	EXTERIOR	Entrance to Building	Building Entrance-Door	1	The maneuvering clearance at the accessible door is not level and clear.	Courtyard - 2 Entrance	ADA
111615	Sherwood High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp is required but not provided.	Entrances DR23, DR34, DR35 and DR36	ADA
111616	Sherwood High School	EXTERIOR	Exterior Access Route	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	Football Stadium Ramps R2 and R3	ADA
109323	Sherwood High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not provided.	Auditorium 131 - Stage	ADA
109409	Sherwood High School	INTERIOR	Interior Access Route	Ramp	1	The ramp run rises 6" or greater but has no handrails.	Interior Ramps - R1, R2, R3 and R4	ADA
109412	Sherwood High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Cafeteria	ADA
109477	Sherwood High School	INTERIOR	Interior Access Route	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	Classroom Doors	ADA

Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109480	Sherwood High School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Classroom Door Hardware	ADA
109481	Sherwood High School	INTERIOR	Interior Access Route	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Public Door Hardware	ADA
110052	Sherwood High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Interior Stair STR6	ADA
111591	Sherwood High School	INTERIOR	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Gymnasium 101	ADA
111592	Sherwood High School	INTERIOR	Interior Access Route	Ramp	1	The ramp exceeds 8.3% in some areas.	Interior Ramp R4	ADA
111594	Sherwood High School	INTERIOR	Exterior Access Route	Stairs	1	Handrails are not compliant.	Interior Stairs STR1, STR2, STR3 and STR4	ADA
111596	Sherwood High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Interior Stair STR5, STR6 and STR8	ADA
111597	Sherwood High School	INTERIOR	Interior Access Route	Stairs	1	Handrails are not compliant.	Interior Stair STR6	ADA
111600	Sherwood High School	INTERIOR	Interior Access Route	Stairs	1	Handrail extensions are not compliant.	Interior Stairs STR9 and STR10	ADA
109418	Sherwood High School	PARKING	Accessible Parking	Parking Space-Car	1	MARYLAND: Signage is not located at a compliant height.	Parking Lot 3 - Accessible Spaces P3I and P3J	State of Maryland
111573	Sherwood High School	PARKING	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 2	State of Maryland
111574	Sherwood High School	PARKING	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 2	State of Maryland
111575	Sherwood High School	PARKING	Accessible Parking	Parking Space-Car	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 2	State of Maryland
111576	Sherwood High School	PARKING	Accessible Parking	Parking Space-Van	1	MARYLAND: A van access aisle is not provided.	Parking Lot 4	State of Maryland
111577	Sherwood High School	PARKING	Accessible Parking	Parking Space-Van	1	MARYLAND: A "Van" space is not provided.	Parking Lot 4	State of Maryland
111578	Sherwood High School	PARKING	Accessible Parking	Parking Space-Van	1	MARYLAND: Compliant signage is not provided at the space.	Parking Lot 4	State of Maryland
109556	Sherwood High School	RESTROOMS	Interior Access Route	Interior Accessible Route	1	The interior accessible route has less than 36" clear width.	Student Restrooms - 126 W and 236 M	ADA
109511	Sherwood High School	RESTROOMS	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Student Restroom's - 122 Unisex, 126 Unisex, 209 M, 216 Unisex, 235 M and 275 M and 275 W	ADA
109521	Sherwood High School	RESTROOMS	Interior Access Route	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Public Restroom's - 133 W, 291 M&W and Gym Lobby Restrooms	ADA
111617	Sherwood High School	ATHLETIC FIELDS	Baseball/Softball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball fields.	Baseball Field	ADA
109356	Sherwood High School	EXTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Stadium Concession Stands and Stadium Ticket Office	ADA
109428	Sherwood High School	EXTERIOR	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic Tables - Courtyard-2, Courtyard-3, Courtyard-4, Dining areas at exterior of Cafeteria	ADA
111608	Sherwood High School	EXTERIOR	Exterior Access Route	Gate	2	The swinging gate does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the gate.	Access to the football stadium, tennis courts, basketball courts and baseball field	ADA
109401	Sherwood High School	INTERIOR	Entrance to Building	Building Entrance-Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	Doors to Courtyard-2	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109452	Sherwood High School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Science Classrooms - 202, 204, 205, 207, 208, 210, 211, 212, 213, 278, 279, 281, 282 and 283	ADA
109453	Sherwood High School	INTERIOR	Interior Access Route	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	Art Classrooms - 123, 125, 128, 130, 134 and 135	ADA
109472	Sherwood High School	INTERIOR	Interior Access Route	Signage	2	The provided signage is not mounted at the latch side of the door or at a compliant height.	Classroom Signage throughout the school	ADA
109482	Sherwood High School	INTERIOR	Interior Access Route	Door	2	The surface of the door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	The corridor fire control doors	ADA
111590	Sherwood High School	INTERIOR	Common Areas	Vending Machine	2	The vending machines have operable parts which are not within reach range.	Corridors	ADA
111595	Sherwood High School	INTERIOR	Common Areas	Assembly Area	2	Assembly areas do not provide wheelchair spaces.	Gymnasium 101	ADA
111598	Sherwood High School	INTERIOR	Common Areas	Counters	2	Service counter does not have 36" wide section that is 36" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 30" wide section that is 36" maximum, with knee and toe clearance, that is oriented for a forward approach.	Attendance Office and Theater Ticket Office	ADA
109346	Sherwood High School	PLAYGROUNDS	Playground	Transfer System	2	The side of the transfer platform used for transfer is obstructed.	Playground - PG1 - Transfer Platform	ADA
109395	Sherwood High School	PLAYGROUNDS	Playground	Exterior Accessible Route	2	An accessible route within the play area has not been provided.	Playground - PG1	ADA
109396	Sherwood High School	PLAYGROUNDS	Playground	Exterior Accessible Route	2	An accessible route within the play area has not been provided.	Playground - PG1	ADA
109333	Sherwood High School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Public Restroom 140	ADA
109334	Sherwood High School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restroom's - 234 M and 287 M&W	ADA
109335	Sherwood High School	RESTROOMS	Interior Access Route	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Public Restroom's - Stadium W and 133 M&W	ADA
110053	Sherwood High School	ATHLETIC FIELDS	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	Football Stadium and Baseball Field	ADA
109316	Sherwood High School	INTERIOR	Common Areas	Assembly Area	3	The assistive listening device is not compliant or is not provided.	Auditorium 131 and Gymnasium 158	ADA
109321	Sherwood High School	INTERIOR	Employee Work Areas	Locker Rooms-Bench	3	The locker room does not have a compliant bench.	Building Services, Gym and Kitchen Offices	ADA
109340	Sherwood High School	INTERIOR	Interior Access Route	Signage	3	Means of egress signage is not provided.	All exterior egress doors DR1 to DR35	ADA
109474	Sherwood High School	INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Student Restrooms	ADA
109476	Sherwood High School	INTERIOR	Restroom	Restroom/Bathroom-Signage	3	The provided signage is not mounted at the latch side of the door or at a compliant height.	Public Restrooms	ADA
111593	Sherwood High School	INTERIOR	Restroom	Restroom/Bathroom-Locker	3	The locker areas do not have a compliant bench.	Locker Rooms - Boy's 156 and Girl's 157	ADA
109557	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Student Restrooms - 126 W, 157 W, 156 M and 235 M	ADA
109559	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	Student Restroom - 112 M	ADA
109560	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restroom - 112 W	ADA
109561	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Student Restroom - 155 M	ADA
111567	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Public Restroom - 291 M and Gym Lobby Men,	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
111568	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Student Restroom's - 112 M, 122 Unisex, 124 Unisex, 209 W and 235 M	ADA
111570	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Public Restroom's - Gym Lobby Restrooms M&W, 290 M and 291 M	ADA
109324	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The curb is more than 1/2" high.	Building Services Office 105 M&W and Gym Office 156A	ADA
109325	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	A seat is not provided in the transfer shower stall.	Building Services Office 105 M&W and Gym Office 156A	ADA
109326	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	Grab bars are not provided in the transfer shower stall.	Building Services Office 105 M&W and Gym Office 156A	ADA
109327	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Transfer Shower Stall	3	The spray unit does not have a minimum 59" long hose.	Building Services Office 105 M&W and Gym Office 156A	ADA
109328	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The wheelchair stall with a floor mounted water closet, in a multi-stall restroom, is less than 60" wide and 59" deep.	Staff Restroom - 291 M&W	ADA
109347	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Student Restroom's - 155 M, 157 W, 267 W	ADA
109486	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Public Restroom's - Stadium Men's Room, 291M&W, Gym Lobby Women's	ADA
109487	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	3	The bottom of the reflective surface of the mirror is mounted higher than 40".	Student Restroom's - 10 Unisex, 156 M, 216 Unisex and 235M	ADA
109489	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	Public Restroom's - Stadium M&W and 290 W	ADA
109504	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Staff Restroom's - 154 M	ADA
109509	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	Student Restroom's - 126 M, 155 M, 209 M, 235 M and 267 M	ADA
109524	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Public Restroom - Gym Lobby Women	ADA
109525	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	Public Restroom - Gym Lobby Women	ADA
109526	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Public Restroom - Gym Lobby Women	ADA
109527	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	Public Restroom - 133 W	ADA
109528	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Public Restroom - 290 W	ADA
109529	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	Public Restroom - 290 W	ADA
109531	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Public Restroom - 290 W	ADA
109546	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Staff Restroom - 113 W	ADA
109547	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Public Restroom - Gym Lobby Men	ADA
109548	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	Student Restroom - 112 M, 156 M and 267 M	ADA
109550	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	3	Knee clearance is not provided.	Student Restroom - 216 Unisex	ADA
109551	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restroom - 216 Unisex	ADA
109552	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The centerline of the toilet in the wheelchair stall is not 16" minimum to 18" maximum from the sidewall.	Student Restroom - 216 Unisex	ADA
109553	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Student Restroom - 209 W	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109554	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	Student Restrooms - 122 Unisex and 124 Unisex	ADA
109555	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	Student Restrooms - 122 Unisex, 124 Unisex, 156 M	ADA
111571	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	Staff Restroom's - 105 M, 113 W, 154 M and 156A	ADA
111572	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	Public Restroom's - Stadium M&W, 291 M&W, 290 M&W, 133 W, Gym Lobby M&W	ADA
109484	Sherwood High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	Drinking Fountain - DF2	ADA
109485	Sherwood High School	INTERIOR	Interior Access Route	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	Corridor Drinking Fountains	ADA
111599	Sherwood High School	INTERIOR	Common Areas	Locker Rooms	4	The locker room does not have accessible lockers.	The Boy's Room 156	ADA
109413	Sherwood High School	ATHLETIC FIELDS	Exterior Access Route	Exterior Accessible Route	5	A compliant accessible route is not provided from the public access to the amenity.	Baseball Field	ADA
109429	Sherwood High School	EXTERIOR	Picnic Area	Picnic Table	5	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	Picnic Table - Employee dining area	ADA
109473	Sherwood High School	INTERIOR	Interior Access Route	Signage	5	The provided signage is not mounted at the latch side of the door or at a compliant height.	Staff office spaces signage	ADA
109475	Sherwood High School	INTERIOR	Restroom	Restroom/Bathroom-Signage	5	The provided signage is not mounted at the latch side of the door or at a compliant height.	Staff Restrooms	ADA
109478	Sherwood High School	INTERIOR	Interior Access Route	Door	5	The push side of the accessible door does not have the required maneuvering clearances.	Building Services Restroom Door	ADA
109479	Sherwood High School	INTERIOR	Interior Access Route	Door	5	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	Office Door Hardware	ADA
109483	Sherwood High School	INTERIOR	Interior Access Route	Door	5	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	Office Doors	ADA
109558	Sherwood High School	INTERIOR	Kitchen	Sink	5	The accessible sink does not have push/lever hardware.	Classroom 122	ADA
111566	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	5	The urinal dimensions are not compliant.	Staff Restroom - 113 M, 154 M and 234 M	ADA
111569	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The toilet paper dispenser is not at a compliant location.	Staff Restroom's - 209 W, 247 W, 234 W, 105 M&W and 113 M&W	ADA
109349	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	Staff Restroom's - 154 M	ADA
109488	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Mirror	5	The bottom of the reflective surface of the mirror is mounted higher than 40".	Staff Restroom's - 162 M & W, 275 M and 277 M	ADA
109490	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	5	Pipes are not insulated.	Staff Restroom's - 105 M&W, 113 M and 162 W	ADA
109491	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Lavatory	5	Pipes are not insulated.	Student Restroom's - 124 Unisex, 156 M, 157 W, 162 M&W, 235 Unisex and 267 M&W	ADA
109492	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The toilet paper dispenser is not at a compliant location.	Student Restroom's - 112 M&W, 124 Unisex	ADA
109534	Sherwood High School	RESTROOMS	Interior Access Route	Protruding Object	5	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	Staff Restroom's - 154 M&W, 162 M&W, 234 M&W and 287	ADA
109542	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Urinal	5	The clear floor space at the urinal is less than minimum 30" by minimum 48".	Staff Restroom - 234 M	ADA
109543	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The side grab bar at the water closet is not compliant.	Staff Restroom - 234 M	ADA



Id	Facility	Building	Assembly	Type	Barrier Priority	Detail	Location Description	ADA
109544	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The grab bars at the water closet are not compliant.	Staff Restroom - 105 M&W and 156A	ADA
109545	Sherwood High School	RESTROOMS	Interior Access Route	Reach Range	5	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	Staff Restroom's - 162 M&W	ADA
109549	Sherwood High School	RESTROOMS	Restroom	Restroom/Bathroom-Water Closet	5	The side grab bar at the water closet is not compliant.	Student Restroom - 235 M	ADA