


Montgomery County Public Schools

2018 School Facilities Assessment

School Number **517**
 School Name **Sligo Creek**
 School Type **Elementary School**
 Year Built* **1934**
 Year of Last Renovation* **1999**
 GSF* **98,799**



Building Level - Key Facility Indicators



Infrastructure - Facility Condition

- A10 Foundations
- C20 Stairs
- D50 Electrical
- n/a A20 Basement
- C30 Interior Finishes
- E10 Equipment
- B10 Superstructure
- D10 Conveying Systems
- E20 Furnishings
- B20 Exterior Enclosure
- D20 Plumbing
- F10 Special Construction
- B30 Roofing
- D30 HVAC
- C10 Interior Construction
- D40 Fire Protection

Building Characteristics

- | Building Quality | Indoor Environment |
|---|--|
| <ul style="list-style-type: none"> ● Classroom Shape* ● IMC Size* ● Cafeteria Size* ● Corridor* | <ul style="list-style-type: none"> ● Temperature Control ● Humidity Control ● Natural Light ● Acoustic Features ● Building-Level Power Delivery |

*indicates that underlying data was provided by MCPS not collected by FEA.

Information Sources:	(References)
----------------------	--------------